



Judicial Council of California

455 Golden Gate Avenue · San Francisco, California 94102-3688
www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

Item No.: 25-081

For business meeting on April 25, 2025

Title

Judicial Council Update: Trial Court Facility
Modifications Report for Quarter 2 of Fiscal
Year 2024–25

Report Type

Information

Date of Report

March 27, 2025

Submitted by

Trial Court Facility Modification Advisory
Committee

Hon. Donald Cole Byrd, Chair

Hon. William F. Highberger, Vice-Chair

Contact

Tamer Ahmed, 916-643-6917

tamer.ahmed@jud.ca.gov

Jagan Singh, 415-865-7755

jagandeep.singh@jud.ca.gov

Executive Summary

This informational report to the Judicial Council outlines the allocations of facility modification funding made to improve trial court facilities in the second quarter (October through December) of fiscal year 2024–25. To determine allocations, the Trial Court Facility Modification Advisory Committee reviews and approves facility modification requests from across the state in accordance with the council’s *Trial Court Facility Modifications Policy*.

Relevant Previous Reporting or Action

This report is submitted quarterly as required by the Judicial Council’s *Trial Court Facility Modifications Policy* (see Link A).¹ Most recently, on February 21, 2025, the council received the quarterly report for the first quarter of fiscal year (FY) 2024–25 (see Link B).

Analysis/Rationale

Funding decisions were based on the prioritization and ranking methodologies of the *Trial Court Facility Modifications Policy*. There are six priority categories of facility modifications (FMs):

¹ Per this policy, each quarterly report includes a list of all facility modifications funded during the quarter as well as any reallocation of funds between the funding categories (i.e., facility modification priority categories 1–6).

- Priority 1. Immediately or potentially critical
- Priority 2. Necessary, but not yet critical
- Priority 3. Needed
- Priority 4. Does not meet current codes or standards
- Priority 5. Beyond rated life, but serviceable
- Priority 6. Hazardous materials, managed but not abated

The current level of funding allows the Trial Court Facility Modification Advisory Committee (TCFMAC) to address only the most critically needed Priority 1 or 2 facility modifications statewide.

FM requests are also reviewed and approved in accordance with the Judicial Council’s *Court-Funded Facilities Request Policy* (see Link C). This policy presents the procedures and requirements to allow trial courts to make court-funded facilities requests (CFRs). Trial courts may assist with the funding of certain facilities costs (e.g., facility modifications and lease-related costs) by contributing funds toward urgent facilities costs—not including capital outlay expenses—through allocation reductions from the Trial Court Trust Fund.

Allowable facilities costs that a trial court can fund through a CFR include (1) FMs as defined in the *Trial Court Facility Modifications Policy*; (2) court operations costs allowable under rule 10.810 of the California Rules of Court, such as equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, and records storage; and (3) lease-related costs, such as lease payments and operating costs, repairs, and modifications authorized by a lease. CFRs are approved by Judicial Council staff, with the following exceptions, which require TCFMAC review and approval: ongoing operational cost increases to the Judicial Council beyond the initial outlay for the project (e.g., additional utility or maintenance costs); staff concerns about whether the CFR meets the policy’s criteria or whether the proposed budget is accurate; and appeals of staff determinations.

Fiscal Impact and Policy Implications

Second quarter of fiscal year 2024–25

During the second quarter of FY 2024–25, the TCFMAC reviewed and approved 524 FMs for a total estimated cost of \$19.1 million (see Attachment A). Of these, 274 were Priority 1 FMs, and 250 were Priority 2 FMs. The Judicial Council’s Facility Modification Program’s share of the estimated cost was \$16.6 million, with the affected counties responsible for the balance. Most of these FMs involved repairs or replacements of plumbing; heating, ventilation, and air conditioning (HVAC); elevators and escalators; and interior finishes.

Figure 1 and Table 1 present the distribution by project type and county for all 524 FMs approved in the second quarter of FY 2024–25. Also shown in Figure 1 is the sum of the preliminary estimate and the program’s share for each project type. Table 1 shows the preliminary estimate and the program’s share by county. Figure 2 shows how the program’s share is divided by each project type. Attachment A presents the details of each approved FM.

Figure 1. All FMs Approved in Quarter 2 of FY 2024–25 by Project Type





Table 1. All FMs Approved in Quarter 2 of FY 2024–25 by County

County	Number of FMs	Preliminary Estimate	FM Program Share
Alameda	14	\$ 193,627	\$ 183,629
Butte	3	\$ 29,261	\$ 29,261
Calaveras	2	\$ 8,801	\$ 8,801
Contra Costa	3	\$ 65,907	\$ 65,907
Del Norte	4	\$ 86,042	\$ 69,330
El Dorado	2	\$ 7,879	\$ 7,880
Fresno	9	\$ 344,733	\$ 344,081
Humboldt	2	\$ 10,240	\$ 10,240
Imperial	3	\$ 13,913	\$ 13,913
Kern	13	\$ 158,546	\$ 114,971
Kings	2	\$ 64,584	\$ 64,584
Lake	1	\$ 45,000	\$ 45,000
Lassen	1	\$ 4,141	\$ 4,141
Los Angeles	242	\$ 12,146,960	\$ 10,228,897
Madera	2	\$ 10,031	\$ 10,031
Mendocino	1	\$ 13,756	\$ 13,756
Merced	5	\$ 45,921	\$ 45,921
Mono	4	\$ 30,562	\$ 30,562
Monterey	1	\$ 8,303	\$ 8,303
Napa	1	\$ 12,921	\$ 12,921

County	Number of FMs	Preliminary Estimate	FM Program Share
Orange	25	\$ 2,142,843	\$ 1,927,099
Riverside	18	\$ 203,161	\$ 161,693
Sacramento	7	\$ 64,405	\$ 64,405
San Benito	1	\$ 8,358	\$ 8,358
San Bernardino	30	\$ 470,747	\$ 456,557
San Diego	68	\$ 1,394,824	\$ 1,344,849
San Francisco	2	\$ 14,515	\$ 14,515
San Joaquin	15	\$ 269,910	\$ 269,910
San Mateo	3	\$ 80,847	\$ 78,004
Santa Barbara	6	\$ 82,119	\$ 62,734
Santa Clara	12	\$ 139,648	\$ 139,648
Shasta	3	\$ 371,325	\$ 259,939
Sierra	2	\$ 6,244	\$ 6,245
Solano	3	\$ 132,818	\$ 107,199
Stanislaus	5	\$ 35,720	\$ 20,304
Sutter	3	\$ 350,642	\$ 350,642
Tehama	1	\$ 4,748	\$ 4,748
Tulare	3	\$ 10,499	\$ 10,499
Ventura	2	\$ 17,452	\$ 14,483
Grand Total	524	\$ 19,101,955	\$ 16,613,958

Figure 2. FM Program's \$16.6 Million Share in Quarter 2 of FY 2024–25 Divided by Project Type



Court-funded facilities requests

In the second quarter of FY 2024–25, as shown in Table 2, council staff approved and the TCFMAC reviewed 22 CFRs (all FMs) totaling approximately \$7.3 million. Attachment B presents the details of each approved CFR.

Table 2. All CFRs Approved in Quarter 2 of FY 2024–25 by County

County	Facility Modification	Lease	Approved Amount
Alameda	1	-	\$ 4,005
Contra Costa	2	-	\$ 28,000
Calaveras	1	-	\$ 1,363
El Dorado	1	-	\$ 250,000
Kings	1	-	\$ 1,166,786
Los Angeles	3	-	\$ 860,000
Napa	1	-	\$ 20,000
Orange	1	-	\$ 7,660
Placer	1	-	\$ 175,000
Sacramento	1	-	\$ 50,000
San Diego	1	-	\$ 300,000
San Joaquin	1	-	\$ 3,344
San Mateo	1	-	\$ 4,200,000
Shasta	2	-	\$ 100,000
Stanislaus	2	-	\$ 76,829
Tehama	1	-	\$ 15,000
Yolo	1	-	\$ 30,000
Grand Total	22	0	\$ 7,287,987

Completed project spotlight

Examples of FM projects completed during the second quarter of FY 2024–25 are described below and shown in Figures 3a–d and 4a–d.


Priority 1: Plumbing—Flooded Basement at B. F. Sisk Courthouse, Fresno County

A domestic water valve failed due to age, causing flooding in multiple areas of the building's basement. The project required replacement of a 3/4-inch ball valve, a light pack, an oil return pump, the variable frequency drive on an air handler, and two electrical outlets in addition to 7,633 square feet of drywall and insulation, 1,055 linear feet of cove base, and two 120-square-foot galvanized metal panels. Fifty-nine air scrubbers and ten dehumidifiers were involved in completing the project. The final project cost was \$293,517.

Figure 3a–d. B. F. Sisk Courthouse, Fresno County

Flooded
basement
areas from
failed water
valve

3a



Before

3b




After

3c



Newly
replaced
water valve
(L) and clean,
dried areas
(R)

3d



Priority 1: Interior Finishes—Flooded Juvenile Court Department 9, San Diego County

The storm drain adjacent to the modular building that houses the juvenile court's Department 9 failed to discharge rainwater from the site and flooded the building. Repairs included replacement of 236 square feet of drywall, 84 linear feet of four-inch cove base, and 1,440 square feet of carpet in addition to the cleaning, drying, and sanitizing of the courtroom's bench, well, and spectator seating areas; judge's chambers; and court reporter's office. The final project cost was \$174,509.

Figure 4a–d. Juvenile Court Department 9, San Diego County


Before

4a



Courtroom
spectator
seating area
carpet being
replaced
and space
dried from
flooding

4b




After

4c



Newly
replaced
carpet and
clean, dried
courtroom
spectator
seating area

4d



Attachments and Links

1. Attachment A: *TCFMAC-Funded Project List: Quarter 2, Fiscal Year 2024–25*
2. Attachment B: *Court-Funded Facilities Requests (CFRs): Quarter 2, Fiscal Year 2024–25*
3. Link A: *Trial Court Facility Modifications Policy* (revised March 15, 2019),
<https://courts.ca.gov/system/files/jc-facility-modification-policy.pdf>
4. Link B: *Judicial Council Update: Trial Court Facility Modifications Report for Quarter 1 of Fiscal Year 2024–25* (January 15, 2025),
<https://jcc.legistar.com/View.ashx?M=F&ID=13703629&GUID=A840FC30-7A78-4DA0-B52F-C26327B2EDB8>
5. Link C: *Court-Funded Facilities Request Policy* (August 26, 2016),
<https://courts.ca.gov/system/files/file/court-funded-facilities-request-policy.pdf>



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
1	FM-2007638	Shasta	Main Courthouse	45-A1	1	HVAC	HVAC - Replace (1) 3/4 inch copper fitting, 5,773 SF of carpet tiles, 3015 SF of linoleum flooring, 600 SF of ceiling tile, 500 SF of drywall, and 1,600 LF of cove base on the 1st floor office and public space and 2nd floor office and public space. The fitting failed due to age allowing water to leak from the supply line flooding the area. The building is unoccupied and the leak was not discovered for at least 24 hours. Work required before transferring building over to the county. Environmental oversight and remediation required for ACM and category 2 water.	\$ 359,520	\$ 250,621	69.71
2	FM-2007648	Los Angeles	Beverly Hills Courthouse	19-AQ1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 20 LF of 2 inch cast iron drain line serving second floor drinking fountain and install a 24 inch x 24 inch access panel. Cast iron drain line cracked due to age and leaked above the exterior stucco ceiling. Work includes cutting a 24 inch x 24 inch access hole in stucco overhang to access the pipe and Install the access panel. Environmental oversight and remediation required for category 2 water. Erect (1) 6 ft x 12 ft x 16 ft critical barrier. Clean dry and sanitize 360 SF of concrete.	\$ 28,705	\$ 22,826	79.52
3	FM-2007683	San Diego	Kearny Mesa Court	37-C1	1	Electrical	Electrical - Replace (247) 4 ft bulbs, 1,000 ft of 18 gauge wiring, and 173 ballast test switches for the emergency lighting system. The emergency lighting system failed due to age and was discovered during an unplanned power outage.	\$ 31,287	\$ 31,287	100
4	FM-2007700	Los Angeles	Inglewood Courthouse	19-F1	1	Plumbing	Plumbing - Sewer line leak - Replace 10 LF of 2 inch cast iron pipe, (1) 2 inch medium sweep, (3) 2 inch no hub couplings, 5 LF of 3 inch cast iron pipe and (3) 3 inch no hub couplings. Sewer line failed due to age and caused a leak in the 3rd floor public hallway. Removal of tile and mop sink required to access leak within wall. Environmental oversight and remediation required for category 2 water. Erect (1) 6 ft x 8 ft moisture barrier, and (1) 3 ft x 6 ft decontamination chamber. Clean, dry and sanitize 200 SF of concrete and terrazzo flooring.	\$ 29,622	\$ 22,086	75
5	FM-2007703	Los Angeles	Santa Monica Courthouse	19-AP1	1	Plumbing	Plumbing - Domestic water leak - Replace (1) 1 1/2 inch and (2) 1 1/4 inch isolation valves, 30 LF of 1 1/2 inch copper piping, 10 LF of 1 1/4 inch copper piping, and (1) 1/2 inch isolation valve. Water supply line failed due to age allowing water to leak through the plaster ceiling in the 1st floor courtroom and jury restroom. Environmental oversight and remediation required ACM and category 2 water. Clean and sanitize 16 SF of vinyl floor tile.	\$ 17,970	\$ 14,104	78
6	FM-2007705	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) isolation valve in the 4th floor womens jury room restroom. Valve failed due to age allowing water to leak onto the restroom floor. Work is to be performed after-hours as the water to multiple floors need to be shut off.	\$ 2,554	\$ 2,554	100.00
7	FM-2007748	Los Angeles	Metropolitan Courthouse	19-T1	1	HVAC	HVAC - Mechanical System Leak - Clear 1 LF of 1 inch HVAC PVC condensate drain pan line and replace (8) 1 ft x 1 ft ceiling tile, and 8 SF of carpet. The line was blocked with debris allowing water to leak from the 2nd floor air handler drain pan down to the 1st floor Court office. Environmental oversight and remediation required for category 2 water. Erect (1) 8 ft x 8 ft containment and clean, dry, and sanitize, 8 SF of concrete floor.	\$ 21,962	\$ 20,762	94.54
8	FM-2007754	San Bernardino	Fontana Courthouse	36-C1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) electronic door sensor on public elevator. The sensor failed due to age resulting in the elevator getting stuck on the 2nd floor with doors opening and closing.	\$ 6,059	\$ 5,037	83



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
9	FM-2007755	Kings	Kings Superior Court	16-A5	1	HVAC	HVAC - Replace (1) 6.7 ton compressor. Compressor failed due to age, impacting cooling to the basement UPS room.	\$ 19,376	\$ 19,376	100.00
10	FM-2007757	Orange	Central Justice Center	30-A1	1	HVAC	HVAC - Replace (1) 3 inch and (1) 4 inch steam regulators and (2) pilot valves. The regulators failed due to age not allowing steam through the pilot valves, causing the pressure release valve activation.	\$ 29,432	\$ 26,833	91
11	FM-2007759	Riverside	Larson Justice Center	33-C1	1	Plumbing	Plumbing - Replace (1) 1 1/2 inch backflow device. The unit failed due to age and was discovered during annual preventative maintenance work.	\$ 3,200	\$ 3,116	97.39
12	FM-2007766	Del Norte	Del Norte County Superior Court	08-A1	1	HVAC	HVAC - Replace (1) roof mounted condenser unit on AC Unit 2 for courtroom 2. Crane required for removal of old and placement of new. This unit failed due to age and weathering due to close proximity to ocean.	\$ 21,239	\$ 21,239	100
13	FM-2007768	Del Norte	Del Norte County Superior Court	08-A1	1	HVAC	HVAC - Replace (1) roof mounted condenser unit on AC Unit 1 for courtroom 1. Crane required for removal of old and placement of new. This unit failed due to age and weathering due to close proximity to ocean.	\$ 21,652	\$ 21,652	100.00
14	FM-2007771	Del Norte	Del Norte County Superior Court	08-A1	1	Roof	Roof - Install (30) 48 inch x 120 ft of sheet metal over the top of existing roof, replace all side flashing, and apply sealant where needed. The roof was damaged during a wind storm allowing water to leak into the building.	\$ 40,382	\$ 24,742	61.27
15	FM-2007772	San Bernardino	San Bernardino Justice Center	36-R1	1	and Pa	Grounds and Parking Lot - Replace (2) drive wheel kits on the exit gate door operator in the secured parking lot. The gate failed due to age preventing staff from leaving.	\$ 8,134	\$ 8,134	100.00
16	FM-2007773	San Bernardino	Barstow Courthouse	36-J1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 4 LF of 2 inch cast iron pipe and (4) couplings on the P-trap for the floor drain on the 2nd floor womens restroom. The pipe failed due to age allowing water to leak through a can ceiling light in the 1st floor womens restroom.	\$ 2,722	\$ 2,722	100.00
17	FM-2007776	Los Angeles	Bellflower Courthouse	19-AL1	1	erior S	Exterior Shell - Replace (1) 11 ft x 15 ft roll up curtain, (1) 11 ft safety edge and all associated hardware for the sallyport bus bay door. Sheriffs bus struck the roll up curtain preventing the curtain from opening. The curtain had to be removed to release the bus from the area and a temporary gate was installed to secure bus bay until the new curtain was installed. Restitution will be sought from LA County Sheriffs Department.	\$ 65,200	\$ 65,200	100
18	FM-2007779	Kern	Delano/North Kern Court	15-D1	1	HVAC	HVAC - Replace (1) compressor, (1) filter drier, (1) contactor, and (1) disconnect switch with fuses for package unit 7. Compressor and parts failed due to age impacting cooling to the building. Recover and charge refrigerant to reform compressor replacement and execute leak check.	\$ 9,516	\$ 7,673	80.64
19	FM-2007780	San Diego	Central Courthouse	37-L1	1	Security	Security - Restore the State street vehicle gate. The gate was struck be a delivery truck and cannot be secured. Work occurred after hours and insurance reimbursement is being sought.	\$ 3,550	\$ 3,550	100
20	FM-2007783	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Electric	Electrical - Restore the generator 1 heat exchanger. The heat exchanger failed due to age. Work includes isolating the generator heat exchanger from cold loop, draining coolant, removing the heat exchanger and transporting it for restoration. Generator failed annual preventative maintenance due to high temperatures.	\$ 23,705	\$ 16,306	69



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
21	FM-2007784	Los Angeles	Compton Courthouse	19-AG1	1	Interior Fin	Interior Finishes - Replace (8) 4 inch x 4 inch ceramic tiles and (2) SF of thinset on the 12th floor womens jury restroom. Tiles failed due to age, causing them to fall to the floor. Environmental testing and oversight required including sanitizing 5 SF of hard surfaces.	\$ 6,776	\$ 6,776	100.00
22	FM-2007786	Los Angeles	Norwalk Courthouse	19-AK1	1	Vandalism	Vandalism - Replace (1) 40 inch x 107 inch tempered glass exterior window located in the 1st floor public defenders office. Window was shattered by unknown individual. Window was boarded until glazing was procured.	\$ 5,012	\$ 5,012	100.00
23	FM-2007787	Los Angeles	Burbank Courthouse	19-G1	1	HVAC	HVAC - Replace (1) 7 HP 480V motor, (2) drive assemblies and all associated parts on AHU 1. The motor failed due to age, affecting the cooling to north side of the building.	\$ 6,528	\$ 5,925	90.76
24	FM-2007788	Los Angeles	Compton Courthouse	19-AG1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) electronic door edge on elevator 1. Door edge failed due to age affecting the elevators ability to operate. Issue was discovered during preventative maintenance	\$ 3,662	\$ 2,422	66.13
25	FM-2007793	Stanislaus	Hall of Records	50-A2	1	Landscaping	Grounds and Parking Lot - Replace 225 SF of 4 inch concrete sidewalks. Concrete is raised and cracked due to tree roots, resulting in a trip and fall incident. Roots will be removed during concrete replacement.	\$ 22,869	\$ 10,696	47
26	FM-2007794	Orange	Stephen K. Tamura Courthouse	30-D1	1	Plumbing	Plumbing - Replace (2) 1 1/2 hp pump system with pumps, floats, control panel, basin lid, float bracket, check valve, pipes and fittings. The pumps failed due to age and require replacement to prevent ground water from flooding the detention tunnels and electrical room.	\$ 28,957	\$ 26,258	90.68
27	FM-2007798	Riverside	Southwest Justice Center	33-M1	1	Vandalism	Vandalism - Replace (1) 57 inch x 43 inch x 1 inch insulated window pane. Window was damaged by unknown individual. Work includes installing a temporary plywood board while replacement glazing is procured.	\$ 2,980	\$ 2,980	100.00
28	FM-2007802	Los Angeles	Downey Courthouse	19-AM1	1	Security	Security - Replace (1) 1 hp master operator and (1) key switch for the sally port exterior gate. Operator and switch failed due to age, affecting the gates ability to function properly.	\$ 11,068	\$ 11,068	100.00
29	FM-2007807	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) sink and associated parts on the 11th floor in west side lockup. Sink failed due to age allowing water to constantly run.	\$ 7,466	\$ 7,466	100.00
30	FM-2007808	Los Angeles	Pomona Courthouse North	19-W2	1	HVAC	HVAC - Replaced (1) 3/4 HP 480V blower motor, (2) valve cores, and 4 lbs of refrigerant on package unit 1. The blower motor and valve cores failed due to age affecting the cooling of the southwest side of the 1st floor.	\$ 4,914	\$ 4,730	96.25
31	FM-2007811	Los Angeles	East Los Angeles Courthouse	19-V1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 10 LF of a 2 inch cast iron pipe, (1) 90 degree bend, (4) 2 inch no hub couplings, and 4 SF of drywall in the basement fire pump room. Parts failed due to age flooding the basement fire pump room. Remediation and environmental oversight required for category 2 water. Extract 100 gallons of water and clean, dry, and sanitize 24 SF of concrete wall, 300 SF of concrete floor, and 10 framing studs.	\$ 28,299	\$ 21,994	77.72
32	FM-2007813	Los Angeles	East Los Angeles Courthouse	19-V1	1	Plumbing	Plumbing - Domestic Water Line leak - Replace (1) 2 1/2 inch coupling, (2) 2 1/2 inch 45-degree elbows, (1) 2 1/2 inch adapter, and 10 LF of 2 1/2 inch copper pipe in judges secured parking. The pipe failed due to age flooding the judges secures parking. Work includes extracting 2,000 gallons of water.	\$ 9,317	\$ 7,241	78



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
33	FM-2007814	Los Angeles	Compton Courthouse	19-AG1	1	Plumbin	Plumbing - Storm Drain leak - Replace 20 LF of 3 inch cast iron pipe, 20 LF of 4 inch cast iron pipe, and associated fittings in the basement sally port and AHU room. Pipe failed due to age, allowing water to leak onto the basement floor.	\$ 8,097	\$ 5,355	66.13
34	FM-2007815	Los Angeles	Airport Courthouse	19-AU1	1	Plumbin	Plumbing - Domestic Water Pipe Leak - Replace (1) 3/4 inch strainer and pressure trap, and 5 LF of 3/4 inch copper piping. The strainer and trap failed due to age. Environmental testing and remediation required for category 2 water. Erect (1) 6 ft x 3 ft x 10 ft containment. Clean and sanitize 10 SF of ceramic floor and 8 LF of metal T-Bar.	\$ 19,842	\$ 15,312	77.17
35	FM-2007818	Los Angeles	Alhambra Courthouse	19-I1	1	Securit	Security - Replace (1) 13 ft rollup door safety edge and all associated hardware for the sally port bus entrance gate. The safety edge failed due to age, affecting the gates operation.	\$ 2,902	\$ 2,902	100.00
36	FM-2007819	Los Angeles	Pasadena Courthouse	19-J1	1	Plumbin	Plumbing - Sewer Line Leak - Replace 50 LF of 2 inch cast iron pipe, 20 LF of 4 inch cast iron pipe, (8) 2 x 2 ft ceiling tiles and all associated fittings. The cast iron pipe was cracked due to age, leaking water into 4th floor court reporters office. Environmental and remediation oversite required for ACM and category 2. Erect (1) 10 ft x 10 ft x 9 ft containment, (1) 3 ft x 7 ft decontamination chamber, and clean, dry and sanitize 800 SF of floors and walls.	\$ 55,025	\$ 38,160	69
37	FM-2007821	Los Angeles	Alhambra Courthouse	19-I1	1	HVAC	HVAC - Replace (1) vibration switch, (2) pillow block bearings, (1) shaft, (1) drive pulley, (1) belt and (1) fan blade assembly and all associated hardware for cooling tower 1. The bearings and vibration switch failed due to age impacting all other components and cooling throughout the building.	\$ 29,580	\$ 25,438	86.00
38	FM-2007823	Los Angeles	Inglewood Courthouse	19-F1	1	Securit	Security - Grounds and Parking Lot - Replace 500 LF of electrical wiring from the electrical panel to the secured parking gate. Wiring has failed due to age and corrosion, impacting the gates operation.	\$ 3,826	\$ 2,852	74.56
39	FM-2007824	Los Angeles	Inglewood Courthouse	19-F1	1	Protect	Fire Protection - Replace (1) engine block heater thermostat and (1) engine thermostat including gasket and seal on the fire pump. Components failed due to age and were discovered during preventative maintenance.	\$ 4,785	\$ 3,567	74.56
40	FM-2007826	Los Angeles	Beverly Hills Courthouse	19-AQ1	1	Securit	Security - Replace (1) gear head motor operator assembly to judges gate. Motor assembly failed due to age impacting the gates operation.	\$ 8,012	\$ 8,012	100
41	FM-2007827	Los Angeles	Inglewood Courthouse	19-F1	1	and Pa	Grounds and Parking Lot - Replace (2) double flanged track rollers on parking garage gate. Rollers failed due to age impacting the gates operation.	\$ 5,354	\$ 3,992	74.56
42	FM-2007828	Los Angeles	Santa Monica Courthouse	19-AP1	1	Plumbin	Plumbing - Domestic Water Line Leak - Replace 5 LF of 1 inch copper pipe and (1) 1 inch isolation valve. Domestic hot water line failed due to corrosion allowing water to leak onto the roof which was discovered during rounds and readings. Work includes the removal and re-installation of metal jacket pipe insulation.	\$ 3,758	\$ 2,949	78



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
43	FM-2007831	Kern	Metropolitan Division	15-A1	1	and Pa	Grounds and Parking Lot - Replace (1) irrigation valve and 30 low flow sprinkler heads and (1) 1 ft x 1 ft ceiling tiles in the basement staff office. Irrigation valve failed due to age which allowed the sprinklers to stay on, allowing water to travel through the exhaust ducting and flooding the basement staff office. Environmental oversight and remediation required for category 2 water. Erect (2) 3 ft x 4 ft containments. Clean, dry and sanitize 6 SF of drywall, 15 SF of carpet, 1 light fixture, 15 SF of drywall ceiling, and 8 SF of metal cubicle cabinetry.	\$ 29,977	\$ 18,736	63
44	FM-2007832	Los Angeles	Alhambra Courthouse	19-11	1	lumbir	Plumbing - Sewer Link Leak - Mechanically clear 60 LF of sewer line. Sewer line was blocked affecting the 2nd floor womens public restroom. Debris was punched through and not recovered. Environmental and remediation protocols required due to category 3 water. Erect (1) 3 ft x 7 ft critical barrier clean, dry, and sanitized 600 SF surfaces tile flooring.	\$ 12,493	\$ 10,744	86.00
45	FM-2007833	Kern	Bakersfield Juvenile Center	15-C1	1	HVAC	HVAC - Replace (1) 400 amp 3-pole breaker for chiller 2. Breaker failed due to age, causing no power to the chiller.	\$ 6,498	\$ 4,338	66.76
46	FM-2007846	Los Angeles	Pasadena Courthouse	19-J1	1	HVAC	HVAC - Replace (3) igniters, (3) fresh air filters, (1) fan control relay and associated part for boiler 1. Parts failed due to age affecting the HVAC heating through the entire building.	\$ 4,083	\$ 2,832	69.35
47	FM-2007847	San Bernardino	Historic Courthouse	36-A1	1	escalate	Elevators, Escalators, & Hoists - Replace (1) rope gripper on elevator 1 and (1) rope gripper on elevator 2. Rope grippers failed due to age, preventing use of the elevators. Deficiency was found during preventative maintenance.	\$ 78,163	\$ 75,201	96.21
48	FM-2007849	Los Angeles	Pomona Courthouse North	19-W2	1	and Pa	Ground and Parking Lot - Replace (1) gate limit assembly and all associated fittings to north side Judges secured parking gate. The limit assembly failed due to age impacting the gates operation.	\$ 2,174	\$ 2,092	96
49	FM-2007853	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	ior Fin	Interior Finishes - Restore (2) window seals on the 19th floor and replace (4) 12 inch x 12 inch ceiling tiles in the 17th floor county offices. The window seals failed due to age allowing rainwater into the County offices on the 19th and 17th floors, the "P" level court Exhibits, and the "S" level AHU room and Court file storage room. Environmental oversight and remediation required for category 2 water and ACM. Erect (1) 3 ft x 10 ft critical barrier, (1) 6 ft x 5 ft x 10 ft containment and (4) water diverters. Clean, dry, and sanitize 3,450 SF of hard surfaces, including VCT, terrazzo, and concrete.	\$ 61,363	\$ 42,211	68.79
50	FM-2007856	Los Angeles	Mental Health Court	19-P1	1	andalis	Vandalism - Restore (1) entry way door and (1) chain link fence. The exterior door and fencing were damaged due to vandalism by unknown individual.	\$ 7,629	\$ 5,440	71.31
51	FM-2007864	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	lumbir	Plumbing - Sewer Line Leak - Mechanically clear 25 LF of sewer line at the 8th floor mop sink and replace (5) 2 ft x 2 ft ceiling tiles in the 7th floor public hallway. The mop sink drain line was blocked allowing water to leak down to the 7th floor. The blockage was not recovered. Environmental oversight and remediation required for Category 2 water. Erect (1) 12 ft x 14 ft containment, (1) 40 inch x 90 inch door barrier. Clean, dry, and sanitize 300 SF of tile and terrazzo flooring.	\$ 35,016	\$ 24,088	68.79



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
52	FM-2007865	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Sewer line Leak - Mechanically clear 50 LF of main drain line in "S" level holding cell and replace 25 SF of plaster ceiling in the "P" level restroom. Blockage resulted in the holding cell flooding allowing water to leak down to the "P" level restroom. The blockage was not recovered. Environmental oversight and remediation required for category 2 water. Erect (2) 40 inch x 90 inch door barriers, and clean, dry, and sanitize 100 SF of concrete and tile surface.	\$ 33,356	\$ 22,946	68.79
53	FM-2007866	Santa Barbara	Santa Maria Courts Bldgs C + D	42-F1	1	HVAC	HVAC - Replace (1) 6 ton HVAC package unit 1. Package unit failed, and parts are obsolete impacting cooling to courtroom 3.	\$ 33,383	\$ 13,998	41.93
54	FM-2007867	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Domestic Water Supply Leak - Replace (1) 1/2 inch copper valve in the 11th floor pipe chase and 6 SF of carpet in the 9th floor courtroom. The valve failed due to age allowing water to leak down to a 9th floor courtroom. Scaffolding required to complete the work. Environmental oversight and remediation required for category 2 water. Erect (1) 8 ft x 8 ft containment and (1) 5 ft x 3 ft containment. Clean and sanitize 128 SF of vinyl floor tile and 9 SF of carpet.	\$ 36,569	\$ 25,156	68.79
55	FM-2007868	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Holding Cell	Holding Cell - Replace (1) locking assembly, remove rust, and readjusted locking rod assembly for holding cell 5. The locking assembly failed due to age, preventing the Holding cell door from opening.	\$ 2,719	\$ 2,719	100.00
56	FM-2007875	San Diego	Hall of Justice	37-A2	1	HVAC	HVAC - Replace (2) motor pump assemblies, (2) triple duty valves, (2) strainers, (2) pressure gauges, and (1) chilled water actuator valve on computer room air conditioning unit 1. Chill water booster pumps motors 1 and 2 failed on high heat due to age, causing data center critical high temperatures.	\$ 67,499	\$ 67,499	100.00
57	FM-2007877	Fresno	Fresno County Courthouse	10-A1	1	Security	Security - Vandalism - Replace (1) 55 inch x 67 inch sheet of clear tempered glass with a reflective film inside basement level 1 courtroom. Glazing was broken by in-custody. Window is currently secured, and restitution being sought.	\$ 4,796	\$ 4,796	100.00
58	FM-2007883	Los Angeles	Torrance Courthouse	19-C1	1	HVAC	HVAC - Replace (3) contactors for cooling tower VFD motor. The VFD failed due to an electrical short and was discovered during rounds and readings.	\$ 4,090	\$ 3,482	85.14
59	FM-2007884	Los Angeles	Airport Courthouse	19-AU1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) pickup roller on custody elevator 5. Pickup roller failed due to mechanical failure with door operation.	\$ 2,270	\$ 1,752	77
60	FM-2007885	Los Angeles	Torrance Courthouse	19-C1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) waste gasket and (1) concealed valve on the basement lockup quarters toilet. Components have failed due to age, resulting in water leaking from the toilet.	\$ 2,852	\$ 2,852	100.00
61	FM-2007889	Los Angeles	Whittier Courthouse	19-AO1	1	HVAC	HVAC - Replace (1) 6 ft x 9 ft sheet metal panel for the return fan room. The panel failed due to return air dampers malfunctioning, creating a vacuum while the fan was on, pulling the panel off the wall. The dampers were corrected under a separate TO.	\$ 3,080	\$ 2,662	86
62	FM-2007891	San Bernardino	Barstow Courthouse	36-J1	1	Plumbing	Plumbing - Domestic Water Line Leak - Replace 20 LF of 3/4 inch copper pipe in ceiling plenum space on the first floor public hallway. The pipe failed due to age.	\$ 3,925	\$ 3,925	100.00
63	FM-2007894	Santa Barbara	Figueroa Division	42-B1	1	Grounds and Parking	Grounds and Parking Lot - Restore 50 SF of plaster wall. A unhoused person was cooking and caught their personal property on fire. The Police and Fire Department were dispatched.	\$ 3,886	\$ 3,886	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
64	FM-2007895	San Bernardino	Historic Courthouse	36-A1	1	plumbing	Plumbing - Sewer Line Leak - Mechanically clear 75 LF of drain line in the 2nd floor mens public restroom, and mechanically clear 75 LF of drain line in the 2nd floor womens restroom. A blockage in the drain line caused water to leak through the concrete floor impacting the 1st floor mens public restroom. Blockage was not recovered. Environmental and remediation oversight used for category 3 water. Erect (1) 40 inch x 90 inch containment, (1) 16 ft x 16 ft x 12 ft containment, (2) 20 LF diverters, and cleaned, dry and sanitized 414 SF of hard surface. Restrooms are being renovated, which allowed the water to leak through the concrete sub-floor.	\$ 24,164	\$ 23,248	96.21
65	FM-2007897	Sacramento	Gordon Schaber Sacramento Superior Court	34-A1	1	plumbing	Plumbing - Mechanical Systems Leak - Replace mechanical seal, bearings, and perform satisfactory operational testing for Hot water pump 2. Mechanical seal and bearings failed due to age and was discovered during preventative maintenance.	\$ 4,759	\$ 4,759	100.00
66	FM-2007898	Sacramento	Juvenile Courthouse	34-C2	1	escalators	Elevators, Escalators, & Hoists - Replace wheelchair lift door latch. The latch failed due to age and not operating correctly.	\$ 2,833	\$ 2,833	100.00
67	FM-2007900	Los Angeles	East Los Angeles Courthouse	19-V1	1	plumbing	Plumbing - Sewer Line Leak - Replace 10 LF of a 3 inch cast iron pipe, (2) 2 inch couplings, and associated fittings in the 1st floor holding cell plenum space. The pipe failed due to age allowing water to leak into the holding ceiling. Environmental oversight and remediation required for category 3 water. Clean, dry and sanitize 200 SF of metal ceiling, 200 SF of concrete floor, 100 SF of cinderblock walls, and (2) light fixtures.	\$ 11,624	\$ 9,034	78
68	FM-2007902	San Bernardino	Barstow Courthouse	36-J1	1	plumbing	Plumbing - Sewer Line Leak- Replace 10 LF of 6 inch cast iron pipe and fittings and (1) 2 ft x 4 ft ceiling tile. The pipe failed due to age allowing water to leak from the 2nd floor to the 1st floor office area. Environmental testing and oversight was required. Clean and sanitize 434 SF of tile floor.	\$ 25,005	\$ 25,005	100
69	FM-2007906	Los Angeles	Norwalk Courthouse	19-AK1	1	plumbing	Plumbing - Fixture Leak - Mechanically clear 75 LF of sewer link, replace (2) ceiling tiles in 1st floor lobby and (1) 2 inch cleanout in the 2nd floor public mens restroom. A toilet blockage caused water to overflow and travel down the plenum through the ceiling onto the 1st floor main lobby. Failed clean out was identified during the clearing of the sewer line. Environmental oversight and remediation required due to category 2 water. Erect (1) 5 ft x 9 ft x 12 ft containment in the 1st floor lobby, (1) 40 x 90 inch containment in the 2nd floor mens restroom, and sanitized 541 SF of floors and walls.	\$ 17,303	\$ 14,713	85.03
70	FM-2007910	Orange	Central Justice Center	30-A1	1	vandalism	Vandalism - Plumbing - Sewer Line Leak - Mechanically clear sewer line and replace (30) 2 ft x 2 ft ceiling tiles in the 7th floor jury rooms. An unidentified in-custody blocked and continuously flushed the toilet in the 8th floor holding cell resulting in water traveling down to the jury rooms below. Blockage was found after multiple in-custodies had been in the holding cell. Environmental oversight and remediation required for category 3 water. Clean and sanitize 430 SF of holding cell concrete floor and 760 SF of ceiling and carpet on floor below.	\$ 10,639	\$ 10,639	100.00
71	FM-2007911	Los Angeles	West Covina Courthouse	19-X1	1	electrical	County Managed - Electrical - Replace 108 LED light pole heads around perimeter of the building. Lights have failed due to age creating a safety issue at night.	\$ 24,780	\$ 24,780	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
72	FM-2007913	Los Angeles	Bellflower Courthouse	19-AL1	1	lumbir	Plumbing - Domestic water line leak - Replace 10 LF of 3 inch copper pipe and associated fittings in the 1st floor AHU room and electrical room. Pipe failed due to age allowing water to leak on the floor. Work includes afterhours work due to draining the building.	\$ 10,230	\$ 7,973	77.94
73	FM-2007915	Sutter	Sutter County Superior Courthouse	51-C1	1	Protect	Fire Protection - Replace 120 fire alarm circuits. The circuits have failed due to the splice connections to the devices failing, resulting in numerous issues with the fire alarm system.	\$ 342,205	\$ 342,205	100.00
74	FM-2007916	San Bernardino	San Bernardino Justice Center	36-R1	1	HVAC	HVAC - Replace (1) VAV box and install additional (1) 24 inch x 24 inch return air grill in the 1st floor walk-up window area hard lid ceiling. VAV Box failed due to age and was unable to supply air in that area, resulting in high temperatures. Link the new VAV Box into the building automation system.	\$ 18,011	\$ 18,011	100.00
75	FM-2007920	Los Angeles	Torrance Courthouse	19-C1	1	lumbir	Plumbing - Sewer Line Leak - Replace 40 LF of 4 inch cast iron pipe, (12) 4 inch heavyweight couplings, (1) 4 inch gasket, (1) 4 inch wye adapter, (1) 4 inch x 2 inch reducer, (1) plug, (1) 4 inch 1/8 bend, and (2) 2 inch heavyweight couplings to cast iron sewer pipe. Sewer line has cracked due to age allowing water to leak from the pipe. Environmental testing and clearance to be performed. Erect (1) 4 ft x 10 ft catchall and (1) slip deterrent padding on floor to prevent injury.	\$ 29,704	\$ 25,290	85
76	FM-2007924	San Diego	North County Regional Center - North	37-F2	1	lumbir	Plumbing - Domestic Water Pipe Leak - Clear 5 LF of 1 1/4 inch condensate drain line with nitrogen in rooftop air handler unit 4 and replace 56 SF of 2 ft x 4 ft ceiling tiles. Condensate line clog on AHU allowed water to leak to 1st floor criminal office, affecting ceiling tiles and office space. Environmental oversight and remediation required for category 2 water. Erect (1) 8 ft x 14 ft x 8 ft containment, and clean, dry & sanitize 40 SF of carpet and 40 SF of hard surfaces.	\$ 22,945	\$ 22,945	100.00
77	FM-2007926	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	lumbir	Fire Protection - Replace (1) high temperature fire sprinkler head, 13,000 SF of 2 ft x 2 ft carpet tiles, 3500 SF of drywall, 800 SF of cove base, 120 SF of 2 ft x 2 ft ceiling tiles, and 60 SF of vinyl floor tiles in the 1st floor clerks office. The fire sprinkler failed due to age flooding the clerks office, affecting 63 cubicles and 20 court offices. Environmental oversight and remediation required for category 2 water. Erect 20,000 SF of containments and drying equipment.	\$ 600,120	\$ 441,148	74
78	FM-2007927	Los Angeles	Stanley Mosk Courthouse	19-K1	1	lumbir	Plumbing - Domestic Water Line Leak - Replace 2 LF of 2 inch galvanized pipe and (3) couplings. The pipe and couplings failed due to age and was discovered during rounds and readings. Work includes isolation of the steam line and drain the domestic hot water holding tank.	\$ 5,772	\$ 5,614	97.26
79	FM-2007929	Mono	Mammoth Lakes Courthouse	26-B2	1	lumbir	Plumbing - Replace (2) 1 1/2 pressure regulators. The regulators failed due to fluctuating water pressure impacting the domestic water supply to the building.	\$ 8,696	\$ 8,696	100
80	FM-2007933	El Dorado	Cameron Park	09-C1	1	HVAC	HVAC - Replace (1) 3.5 ton compressor and wiring harness, (1) 70-w crankcase heater, and (1) refrigerant liquid line filter drier. Parts failed due to age, causing the AC to shutdown, and temperature to rise in courtroom and adjacent telecommunication room.	\$ 3,805	\$ 3,805	100.00
81	FM-2007935	Contra Costa	Richard E. Arnason Justice Center	07-E3	1	HVAC	HVAC - Replace compressor 2A for air handler 5. Fan motor failed due to age requiring replacement.	\$ 3,313	\$ 3,313	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
82	FM-2007938	Sacramento	Gordon Schaber Sacramento Superior Court	34-A1	1	Plumbing	Plumbing - Domestic Water Pipe Leak - Replace 60 LF of 3 inch of drain piping, 20 LF of 2 inch drain piping, and all couplings and associated fitting. Piping failed due to age allowing water to leak into the judges parking area.	\$ 5,351	\$ 5,351	100
83	FM-2007940	San Diego	Juvenile Court	37-E1	1	HVAC	HVAC - Replace (4) SF of 2 ft x 2 ft ceiling tiles, (1) 3-way mechanical valve, and 3/4 inch fittings. The mechanical valve failed due to age allowing water to leak from the HVAC supply line onto the surfaces below. Environmental oversight and remediation is required for category 2 water. Cleaned, dried, and sanitized 50 SF of carpet, 10 LF of metal framing, (1) wood sliding door, (1) computer, (1) metal docking station, (2) glass window panels, (2) chairs, (1) wood cabinetry, and (3) pieces of clothing.	\$ 19,035	\$ 14,204	74.62
84	FM-2007943	Los Angeles	Torrance Courthouse	19-C1	1	Plumbing	Plumbing - Domestic Water Leak - Replace 6 LF of 1 1/4 inch copper piping, and (20) 12 inch x 12 inch ceiling tiles in the 3rd floor clerks office. Water supply pipe failed due to age allowing water to leak onto the tiles. Environmental oversight and remediation required for ACM. Install (1) 7 ft x 10 ft x 10 ft containment. Clean, dry, and sanitize 410 SF of carpet.	\$ 29,992	\$ 25,535	85.14
85	FM-2007946	Sacramento	Carol Miller Justice Center Court Facility	34-D1	1	and Pa	Grounds and Parking Lot - Replace (6) 10 ft sections of fencing and (7) posts. Steel fencing was damaged by concrete truck driving through them after losing control. Insurance reimbursement being sought.	\$ 13,760	\$ 13,760	100.00
86	FM-2007948	Los Angeles	Norwalk Courthouse	19-AK1	1	HVAC	HVAC - Replace (1) 2 gallon chemical feeder for the water loop system in the basement boiler room. Chemical feeder failed due to age allowing water to leak onto the floor.	\$ 2,968	\$ 2,524	85.03
87	FM-2007950	Sierra	Courthouse/ Sheriff Station-Jail	46-A1	1	Escalator	County Managed - Elevators, Escalators & Hoists - Replace elevator door on the ground level. Equipment failed due to exterior and environmental elements. Access to the elevator on the ground level is on the exterior of the building, exposed to the elements, the exterior metal shell of the door has delaminated causing the metal to scrape and grind along the framing. There was a brief entrapment caused by the door not opening.	\$ 4,076	\$ 4,076	100.00
88	FM-2007953	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	1	HVAC	HVAC - Replace the chemical controller for the cooling tower. The controller has failed due to age and will not allow new programming, resulting in the system improperly treating the water.	\$ 6,295	\$ 5,308	84
89	FM-2007960	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing	HVAC - Replace (2) variable frequency drives (VFD) and (2) fans for cooling tower 4. VFDs and fans failed due to age, causing the system to overheat and affect cooling to the building.	\$ 9,297	\$ 7,905	85.03
90	FM-2007962	Los Angeles	Compton Courthouse	19-AG1	1	Escalator	Elevators, Escalators, & Hoists - Replace (2) brake bushings on each elevator 1, 2, 6, 8, and 10. Brake bushings failed due to age, affecting the brake system and floor leveling.	\$ 38,849	\$ 25,691	66.13
91	FM-2007966	Santa Clara	Historic Courthouse	43-B2	1	HVAC	HVAC - Replace (1) burner, (1) heat exchanger, and (1) heat exchanger gasket kit on the boiler. Burner and heat failed due to age impacting building heating. Work requires isolating heating water loop and flue report for new burner.	\$ 31,949	\$ 31,949	100.00
92	FM-2007969	Imperial	El Centro Courthouse	13-A1	1	Escalator	Elevators, Escalators, & Hoist - Replace (1) cable gripper, (1) cab door control arm, and (1) bearing on public elevator 1. Components failed due to age, causing the elevator to fail intermittently. Issue was found during monthly maintenance.	\$ 7,330	\$ 7,330	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
93	FM-2007971	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	1	HVAC	HVAC - Replace 63 SF of duct insulation above the district attorneys office and (2) 2 ft x 4 ft ceiling tiles in the office. The failed insulation is resulting in condensation and water saturation of the insulation and ceiling below. Work will require the use of scaffolding.	\$ 6,192	\$ 5,221	84
94	FM-2007973	San Bernardino	Barstow Courthouse	36-J1	1	Plumbing	Plumbing - Sewer Line Leak - Replace (1) flush kit that and mechanically clear 60 LF of sewer drain line in the second floor mens restroom. Flush valve failed due to age allowing debris to block the line.	\$ 3,619	\$ 3,619	100.00
95	FM-2007975	Orange	Central Justice Center	30-A1	1	HVAC	HVAC - Replace (1) compressor on heat pump 9 that serves the jury assembly room. The compressor failed due to age impacting cooling in the space.	\$ 12,954	\$ 12,954	100.00
96	FM-2007978	Los Angeles	El Monte Courthouse	19-O1	1	Plumbing	Plumbing - Domestic water pipe leak - Replace 10 LF of 2 inch copper pipe, 50 SF of 2 x 2 inch ceramic tiles and all associated fittings. Domestic copper water line failed due to age allowing water to leak into the basement lockup restroom. Environmental and remediation protocols required due to ACM, lead, and category 2 water. Erect (1) 3x7 ft critical barrier, (1) 3 x 3 x 7 ft decontamination chamber clean, dry, and sanitized 150 SF surfaces tile flooring and walls.	\$ 40,164	\$ 23,343	58
97	FM-2007980	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	HVAC	HVAC - Replace (1) 3/4 HP condenser fan motor, (1) fan blade, and (1) capacitor on elevator control room unit. Parts failed due to age, causing high temperatures in the elevator control room. A temporary cooler was placed to provide temporary cooling to the mechanical room and restore elevator service.	\$ 4,379	\$ 3,219	74
98	FM-2007981	Los Angeles	El Monte Courthouse	19-O1	1	Escalators	Elevators, Escalators, & Hoists - Replaced (1) electronic door sensor and associated wiring for judges elevator 5. Sensor failed due to age, causing the elevator doors not to respond.	\$ 7,223	\$ 7,223	100.00
99	FM-2007983	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Sewer Line Leak - Replace (4) 1 ft x 1 ft ceiling tiles, 72 SF of carpet, and 5 inches of 2 inch cast iron pipe. The pipe failed due to age allowing water to leak from the 19th floor county space into the 18th floor secured hallway. Environmental oversight and remediation required for ACM and category 2 water. Erect (1) 9 ft x 9 ft containment and clean, dry and sanitize 72 SF of concrete floor.	\$ 30,577	\$ 21,034	69
100	FM-2007984	Los Angeles	El Monte Courthouse	19-O1	1	Interior Finishes	Interior Finishes - Replace 200 LF of cove base, 25 SF of VCT tiles at basement and 1st floor secured hallway. VCT tiles and cove base adhesive failed due to age creating a safety hazard. Environmental and remediation protocols required due to ACM. Erect (3) 3 x 7 ft critical barriers, (2) 3 ft x 7 ft x 3 ft decontamination chambers, and (1) 10 ft x 10 ft containment. Clean and sanitize 1,000 SF of surfaces, floors and walls.	\$ 40,176	\$ 23,351	58.12
101	FM-2007985	Los Angeles	Beverly Hills Courthouse	19-AQ1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 40 LF of 2 inch cast iron piping, (2) 2 inch loop hangers, and (76) 12 inch x 12 inch ceiling tiles. The Sink drain line from the 2nd floor break room cracked due to age and leaked into the plenum, down onto the ceiling tiles in 1st floor Sheriffs Office. Scaffolding required to repair the pipe. Environmental testing and oversight required for category 2 water. Erect (1) 10 ft x 7 ft x 12 ft containment, (1) 36 inch x 76 inch decontamination chamber, and (1) 14 SF catchall. Clean and sanitize 3 SF of hard surfaces.	\$ 34,302	\$ 27,277	80



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
102	FM-2007994	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) toilet assembly in the 3rd floor mens staff restroom and 32 SF of 2 ft x 4 ft ceiling tiles in the 2nd floor court storage. The toilet failed due to age allowing water to travel down to the 2nd floor court storage room. Environmental oversight and remediation required due to category 2 water. Clean, dry, and sanitize 230 SF of ceramic floor, 30 SF of vinyl floor tiles, (1) metal rack, 8 SF of light fixtures, and 40 SF of drywall.	\$ 23,213	\$ 16,247	70
103	FM-2008005	Kern	Bakersfield Juvenile Center	15-C1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) limit switch, (1) control module, and (1) relay for public elevator 2. Part failed due to age impacting the elevators operation.	\$ 8,649	\$ 5,774	66.76
104	FM-2008007	Lassen	Hall of Justice	18-C1	1	Landscaping	Grounds and Parking Lot - Repair 12 SF of walkway and curb and replace (1) tree damaged due to car accident. Public driver crashed into the landscape area in the front of the courthouse, afterhours. Insurance reimbursement is being sought.	\$ 4,141	\$ 4,141	100.00
105	FM-2008010	Shasta	Main Courthouse	45-A1	1	HVAC	HVAC - Replace bearings, shaft, fan wheels, on the cooling tower. The cooling tower shaft and bearings failed due to age.	\$ 8,214	\$ 5,726	69.71
106	FM-2008019	Butte	North Butte County Courthouse	04-F1	1	Protection	Fire Protection - Replace (1) booster panel and (1) battery for the fire detection system. The booster panel failed due to age impacting the fire detection systems operation. Rotated and recharged batteries for the panel daily, until replacement panel was installed and tested.	\$ 6,137	\$ 6,137	100.00
107	FM-2008020	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) toilet wax ring in the 1st floor womens employee restroom. Wax ring failed due to age allowing water to leak through the wall cavity onto the basement floor mechanical room. Environmental oversight and remediation required due to category 3 water. Erect (1) 3 ft x 7 ft critical barrier and sanitize 144 SF of concrete flooring and metal ducting.	\$ 7,749	\$ 7,749	100.00
108	FM-2008028	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing	Plumbing - Sewer Line Leak - Replace (1) 10 LF of 2 inch cast iron pipe, (2) 2 inch couplings, and install (1) 2 ft x 2 ft access panel. Pipe failed due to age and the leak was identified in the 3rd floor mens restroom. Environmental oversight and remediation required for category 2 water. Cleaned, dried, and sanitized 30 SF of drywall ceiling and 40 SF of 2 inch x 2 inch pink ceramic floor tile.	\$ 26,371	\$ 21,224	80.48
109	FM-2008029	San Bernardino	Historic Courthouse	36-A1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) controller drive and associated materials on elevator 2. The drive failed due to age impacting the elevators operation. The deficiency was identified during rope grip replacement.	\$ 68,229	\$ 65,643	96
110	FM-2008034	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) stop valve on the toilet in the 3rd floor mens jury room restroom and (4) 1 x 1 ft ceiling tiles in the 2nd floor DAs office. Stop valve failed due to age, allowing water to leak through the 2nd floor plenum space onto the ceiling tiles. Environmental oversight and remediation required due to ACM and category 2 water. Erect (1) 5 ft x 3 ft x 10 ft containment and sanitized 175 SF of floor tiles and walls.	\$ 12,853	\$ 12,853	100
111	FM-2008035	Los Angeles	Compton Courthouse	19-AG1	1	HVAC	HVAC - Replace (1) 30 hp motor and associated parts for condenser water pump 2 in the 13th floor chiller room. Motor failed due to age, affecting the chiller and impacting cooling to the building.	\$ 6,267	\$ 4,144	66.13



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
112	FM-2008036	Fresno	B.F. Sisk Courthouse	10-O1	1	lumbir	Plumbing - Domestic Water Pipe Leak - Replace (1) 3/4 inch ball valve, (2) electrical outlets, (1) light pack, (1) oil return pump, and (1) VFD on air handler 7,633 SF drywall and insulation, 1055 LF of cove base, (2) 120 SF galvanized metal panels. Domestic water valve failed due to age, causing flooding in multiple areas of the basement. Environmental testing costs included. Work includes 59 air scrubbers and 10 dehumidifiers.	\$ 293,517	\$ 293,517	100.00
113	FM-2008038	Los Angeles	West Covina Courthouse	19-X1	1	lumbir	County Managed - Plumbing - Replace (1) 230 volt 1/2 HP motor, pump assembly, and 10 LF of 3/4 inch copper pipe and all associated fittings. Motor and pump failed due to age impacting domestic hot water throughout the building.	\$ 9,961	\$ 9,961	100.00
114	FM-2008040	San Bernardino	San Bernardino Justice Center	36-R1	1	lumbir	Plumbing - Sewer Line Leak - Replace (1) drain seal and (4) 2 x 2 ft ceiling tiles. Seal failed due to age allowing water to leak from 1st floor plenum space into the 1st floor office space, meeting room, and the basement mens sheriff locker room. Environmental oversight and remediation required due to category 2 water. Erect (1) 2 ft x 2 ft containment, (1) 16 ft x 16 ft x 12 ft containment, (1) 40 inch x 90 inch critical barrier, extract water from 190 SF of carpet, and cleaned, dried, and sanitized 1094 SF of hard surfaces.	\$ 29,107	\$ 29,107	100.00
115	FM-2008041	Los Angeles	Norwalk Courthouse	19-AK1	1	lumbir	Plumbing - Fixture Leak - Replace (2) stop valves on the toilets from the 3rd floor womens jury restroom and (12) 1 ft x 1 ft ceiling tiles in the 2nd floor staff office. Stop valves failed due to age allowing water to leak through the 2nd floor plenum space and onto the ceiling tiles. Environmental oversight and remediation required due to ACM and category 2 water. Erect (1) 8 ft x 8 ft x 10 ft containment in the 2nd floor DAs office, (1) 5 ft x 5 ft x 10 ft containment in the 2nd floor, and clean and sanitize 609 SF of floor tiles and light fixture.	\$ 19,779	\$ 16,818	85.03
116	FM-2008044	San Diego	Kearny Mesa Court	37-C1	1	HVAC	HVAC - Replace (1) packaged terminal air conditioning (PTAC) unit located in the 1st floor walk-up payment booth. PTAC unit failed due to age causing loss of cooling.	\$ 9,467	\$ 9,467	100
117	FM-2008046	Los Angeles	Van Nuys Courthouse West	19-AX2	1	lumbir	Plumbing - Domestic Water Line Leak - Replace 4 SF of 1 ft x 1 ft ceiling tiles, 3 LF 1 1/4 inch copper pipe, (1) 1 1/4 ball valve, (2) 1 1/4 inch couplers, (1) 1 1/4 inch 90 degree elbow. The pipe failed due to age allowing water to leak from the basement plenum to the lockup office. Environmental oversight and remediation required due to category 2 water. Clean, dried and sanitize 20 SF of 1ft x 1 ft ceiling tiles.	\$ 18,855	\$ 15,175	80.48
118	FM-2008048	Los Angeles	Van Nuys Courthouse East	19-AX1	1	HVAC	HVAC - Replace (1) 15 hp motor and (1) contactor on air handler 2. The motor failed due to age impacting building conditioning.	\$ 14,663	\$ 13,158	89.74
119	FM-2008049	Los Angeles	West Covina Courthouse	19-X1	1	HVAC	County Managed - HVAC - Replace (1) 230 Volt variable frequency drive (VFD) for Air Handler 4. VFD failed due to age affecting the HVAC system throughout the building.	\$ 13,282	\$ 13,282	100.00
120	FM-2008051	San Diego	North County Regional Center - Annex	37-F3	1	lumbir	Plumbing - Domestic Water Pipe Leak - Replace 8 SF of 2 ft x 4 ft ceiling tiles, 2 LF of 3/4 inch copper piping, (2) 3/4 inch copper elbows, (2) 3/4 inch to 5/8 inch copper reducers located in 1st floor business office. Reheat coil failed due to age, allowing water leak onto the ceiling tile. Environmental oversight required for category 2 water.	\$ 4,247	\$ 4,247	100
121	FM-2008055	Los Angeles	East Los Angeles Courthouse	19-V1	1	escalator	Elevators, Escalators, & Hoists - Replace (1) control system pc board for public elevator 1. The board failed due to age causing the elevator to not stop at proper floors.	\$ 5,024	\$ 3,904	77.72



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
122	FM-2008056	Los Angeles	East Los Angeles Courthouse	19-V1	1	Escalators	Elevators, Escalators, & Hoists - Restore (1) door clutch on the judges elevator. The door clutch failed due to age causing the cab to remain on the 1st floor with the doors open. The door clutch was procured from attic stock resulting from the modernization project.	\$ 4,021	\$ 3,125	77.72
123	FM-2007022	Los Angeles	Airport Courthouse	19-AU1	1	Exterior Shell	Exterior Shell - Install (2) coats of crystalline concentrate coating on 42 SF of CMU block located in the underground secured parking area. Water penetrated the CMU wall due to the heavy rains, flooding the parking area. Work includes installing hydraulic cement to restore wall cracks.	\$ 10,442	\$ 8,058	77.17
124	FM-2007687	Los Angeles	Pomona Courthouse North	19-W2	1	HVAC	HVAC - Replace (1) 4 ft x 10 ft cooling coil for air handler 2, (2) shaft seals, (1) compressor overhaul gasket set, (2) filter cores, (1) low oil pressure cut out switch, 6 gallons of compressor oil, 300 lbs of refrigerant, 250amp 480-V breaker, and all associated fittings for HVAC compressors 1 & 2. Shaft seals and cooling coil failed due to age. Breaker is original to building and failed due to age, affecting the cooling to the entire building.	\$ 95,585	\$ 92,000	96
125	FM-2007704	Los Angeles	Downey Courthouse	19-AM1	1	HVAC	HVAC - Replace (2) motors and (2) sets of gaskets and seals for the heating hot water pumps in the 3rd floor machine room. Pumps and motor failed due to age allowing water to leak out onto the floor.	\$ 14,036	\$ 11,748	84
126	FM-2007762	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Vandalism	Vandalism - Install (1) irrigation valve cover, restore 6 SF of concrete with epoxy membrane, and replace 13 LF of cove base and 12 SF of ceiling tiles. A valve in the exterior planters area was left in the open position allowing water to flood the soil and then traveled down into the basement county office. Remediation and environmental oversight required due to category 2 water. Erect (1) water diverter and clean, dry, and sanitize 5 LF of T-Bar, 55 SF of concrete, 55 SF of carpet tiles, and 120 SF of drywall. Irrigation valve was left on by an unknown person.	\$ 22,984	\$ 16,086	70
127	FM-2007790	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Sewer Line Leak - Mechanically clear 50 LF of sewer line in 1st floor jury assembly room. Mainline stoppage caused 1st floor jury assembly mens and womens restrooms to backup allowing water to travel down to the Service level bus bay 2 concrete floor. Environmental testing and oversight required due to category 2 water loss. Erect (2) 40 inch x 90 inch critical barriers and 70 SF of floor covering. Clean, dry, and sanitize 710 SF of ceramic floor tile and concrete.	\$ 34,337	\$ 23,620	69
128	FM-2007795	San Benito	San Benito County Superior Court	35-C1	1	HVAC	HVAC - Remediate Heating Hot Water leaks at (4) Variable Air Volume (VAV) boxes, replace (2) coils and re-pipe to system, replace 65 SF of damaged drywall at floor, (18) ceiling tiles and reinstalled saved baseboard, tested all affected areas. VAV pipe connections leaked over night causing flooding at 1st and 2nd floors due to electrolysis at couplings. Work was done after hours. 90 percent of work performed on separate FM, this FM is for additional work.	\$ 8,358	\$ 8,358	100.00
129	FM-2007825	Los Angeles	Beverly Hills Courthouse	19-AQ1	1	HVAC	HVAC - Replace (2) 1/2 inch valves to inlet and outlet chiller condensing module. The valves failed due to heavy scaling, impacting condenser water flow resulting in the chillers shutting down. Work includes acid washing the chiller 1 and 2 condenser tubes.	\$ 13,209	\$ 10,504	80



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
130	FM-2007886	Los Angeles	Torrance Courthouse	19-C1	1	Plumbing	Plumbing - Domestic Water Line Leak - Replace 8 LF of 1 inch of fiber glass pipe insulation and (2) 24 inch x 24 inch ceiling tiles. The insulation failed due to age allowing condensation to build on the cold water line and leak. Environmental oversight and remediation required for category 2 water. Erect (1) 8 ft x 3 ft x 10 ft containment. Clean and sanitize 24 SF of ceiling tiles and 24 SF of vinyl flooring.	\$ 14,009	\$ 11,927	85.14
131	FM-2007888	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing	Plumbing - Sewer Line Leak - Replace (10) 1 ft x 1 ft ceiling tiles, 2 LF of cast iron pipe above the ceiling in 2nd floor DAs waiting area. Pipe failed due to age, allowing water to leak onto the ceiling and floor. Environmental oversight and remediation required due to category 3 water. Erect (1) 12 ft x 12 ft x 11 ft containment, (1) 36 in x 76 in decontamination chamber, and clean and sanitize 480 SF of floor and wall.	\$ 18,147	\$ 15,430	85.03
132	FM-2007893	Contra Costa	Richard E. Arnason Justice Center	07-E3	1	Protection	Fire Protection - Replace 72 SF of single layer drywall, 80 SF of double layer drywall, and 16 LF wall cove base and recharge the fire suppression agent holding tank. Safety ring on activation button failed, resulting in the discharge of fire suppression gas in the IT room. Clean agent fog triggered smoke detectors, which activated pre-action sprinkler system charging. Sprinkler charging and draining overflowed floor drain. Recharged the tank with 139 lbs of suppression agent. Environmental oversight required. Fans to dry the area.	\$ 50,786	\$ 50,786	100.00
133	FM-2007904	Los Angeles	Norwalk Courthouse	19-AK1	1	Security	Security - Replace (1) compressor and (1) contactor for the main computer room air conditioning unit and (1) key cylinder for the basement mens sheriffs locker room door. Compressor and contactor failed due to a power surge in the AC unit affecting the power to the card reader and not allowing the door to open. Key cylinder was replaced for the sheriffs to gain access to the locker room during repairs.	\$ 10,164	\$ 8,643	85.03
134	FM-2007921	Los Angeles	Inglewood Courthouse	19-F1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) regenerative drive on elevator 3. Regenerative drive failed due to age resulting in the elevator shutting down.	\$ 2,486	\$ 1,853	74.56
135	FM-2007930	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Sewer Line Leak - Replace (2) 2 ft x 2 ft ceiling tiles, and mechanically clear 25 LF in the 4th floor holding cell 4. Mainline branch blockage causing water to overflow in the 4th floor holding cells and travel to 3rd floor public hallway. Environmental oversight and remediation required due to ACM and category 2 water. Erect (1) 90 inch x 40 inch critical barrier and (1) 5 ft x 8 ft containment. Clean, dry, and sanitize (1) plastic light fixture, 30 SF terrazzo floor, and 16 LF of ceiling T-bar.	\$ 34,316	\$ 23,606	68.79
136	FM-2007932	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 25 SF of plaster ceiling and mechanically clear 30 LF of holding cell 6 sewer line. Blockage allowed water to overflow the holding cell toilet and travel to the P level exhibits mens restroom. Environmental oversight and remediation required for ACM and category 2 water. Clean, dry, and sanitize (1) porcelain toilet, 40 SF of ceramic tile floor, and 20 SF of concrete floor.	\$ 39,317	\$ 27,046	69
137	FM-2007949	Los Angeles	Metropolitan Courthouse	19-T1	1	Electrical	Electrical - Replaced 180 fluorescent lights, 30 ballasts, and (2) sensor control units on the 2nd floor court exclusive space. The fluorescent lights, ballasts, and controls failed due to an electrical short impacting lighting on the floor.	\$ 2,479	\$ 2,479	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
138	FM-2007959	Los Angeles	Stanley Mosk Courthouse	19-K1	1	lumbir	Plumbing - Sewer Line Leak - Replace 12 LF of 2 inch cast iron sewer line in 3rd floor plenum and (3) 1 ft x 2 ft and (3) 2 ft x 2 ft ceiling tiles on the 3rd floor. Cast iron pipe cracked due to age. Environmental oversight and remediation required for ACM and category 2 water. Erect (1) 6 ft x 6 ft, (1) 15 ft x 15 ft, and (1) 4 ft x 4 ft containments. Clean, sanitize, disinfect 50 SF of terrazzo.	\$ 40,467	\$ 39,358	97.26
139	FM-2007963	Los Angeles	Compton Courthouse	19-AG1	1	andalis	Vandalism - Replace (1) fire department connection (FDC) located in building exterior. FDC was severed by unknown individual. Work includes 24/7 fire watch until repairs are completed.	\$ 50,363	\$ 33,305	66
140	FM-2008016	Los Angeles	Inglewood Courthouse	19-F1	1	lumbir	Plumbing - Sewer Line Leak - Replace 30 LF of 4 inch cast iron pipe, 10 LF of 3 inch cast iron pipe, (3) 4 inch adapters, (2) 4 x 3 inch wye adapters, (1) 4 inch 1/8 bend, (2) 4 inch plugs, (1) 4 inch 1/16 bend, (20) 4 inch couplings, and (4) 3 inch couplings in 6th floor plenum. The pipe failed due to age allowing water to leak from the plenum into the 6th floor corridor, and two adjacent rooms. Environmental oversight and remediation required due to category 2 water. Erect (1) 4 ft x 6 ft x 10 ft, and (1) 12 ft x 12 ft x 10 ft containment. Clean and sanitize 210 SF of vinyl floor tile.	\$ 59,328	\$ 44,235	74.56
141	FM-2008023	San Bernardino	Barstow Courthouse	36-J1	1	HVAC	HVAC - Replace (1) electronic expansion valve and cable, (1) electronic expansion valve module, (1) liquid line drier cores, and (3) 100 AMP fuses for Chiller 2. The components failed due to age impacting building cooling.	\$ 12,549	\$ 12,549	100
142	FM-2008031	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	1	HVAC	HVAC - Replace (1) motor, (1) grounding rings, and (1) pulley each on exhaust fans 2, 3, and 4 and (1) switch disconnect on exhaust fan 4. The components are failing due to age. Deficiencies discovered during preventative maintenance and is impacting air circulation in the building.	\$ 9,812	\$ 8,273	84.32
143	FM-2008045	Riverside	Banning Justice Center	33-G4	1	andalis	Vandalism - Replace (2) 16 3/4 inch x 32 1/4 inch x 3/4 inch polycarbonate clad glazing of basement holding cells 2 and 12 door windows. The glazing was damaged by in-custodies. Incident reports filed and restitution to be sought.	\$ 7,305	\$ 7,305	100.00
144	FM-2008068	Sutter	Sutter County Superior Courthouse	51-C1	1	Security	Security - Repair (1) set of front door lock and assemblies. Locking mechanism has failed due to wear and tear impacting the doors operation.	\$ 4,042	\$ 4,042	100.00
145	FM-2008069	Los Angeles	East Los Angeles Courthouse	19-V1	1	and Pa	Grounds and Parking Lot - Replace 50 SF of drywall and 50 SF of sealer in the 1st floor clerks office. Water intrusion was caused by a failed abandoned sprinkler line causing water to penetrate the wall and seeped into the carpet and drywall. The irrigation line was capped and the wall cracks were resealed. Environmental oversight and remediation required for category 2 water. Clean, dry, and sanitize 20 SF of carpet.	\$ 50,835	\$ 39,509	77.72
146	FM-2008072	Sacramento	Juvenile Courthouse	34-C2	1	HVAC	HVAC - Replace (1) gasket and O-ring seal set on chiller 1. Chiller was leaking oil around the compressor, evaporator, and condenser barrel. Work includes, recovering refrigerant from chiller system, repair leaking seals, and adding 13 lbs of refrigerant.	\$ 10,033	\$ 10,033	100
147	FM-2008075	Shasta	Redding Main Courthouse	45-E1	1	rior Fin	Interior Finishes - Replace (1) 24 1/4 inch x 72 1/4 inch clear tempered glazing for a third floor window. Glazing was damaged by unknown causes.	\$ 3,591	\$ 3,591	100.00
148	FM-2008080	San Joaquin	Stockton Courthouse	39-F1	1	and Pa	Grounds and Parking lot - Remove water in judges parking lot and basement 2 mechanical rooms. Parking lot and mechanical rooms are flooding due to ingress of ground water through basement slab.	\$ 22,505	\$ 22,505	100



Judicial Council of California

Trial Court Facility Modification
Advisory Committee

Attachment A

TCFMAC-Funded Project List
Quarter 2, Fiscal Year 2024-25

Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
149	FM-2008083	Los Angeles	East Los Angeles Courthouse	19-V1	1	andalis	Vandalism - Replace (1) 24 inch x 35 inch safety tempered glass. The glass on the 1st floor public entrance door was broken.	\$ 8,036	\$ 6,245	78
150	FM-2008088	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	1	HVAC	HVAC - Replace (1) VAV unit supporting courtroom H10. The VAV has failed due to age and has an obstructed reheat coil blocking airflow and is preventing the system from properly cooling or heating the courtroom.	\$ 15,723	\$ 15,723	100.00
151	FM-2008089	Sutter	Sutter County Superior Courthouse	51-C1	1	electric	Electrical - Replace (2) power supplies, (2) two battery back up units, (1) lighting control module, (1) control relay, and install (2) grounding cables on the courtroom lighting control system. Components failed due to being improperly grounded, impacting Court Operations. Grounding cables were added to correcting grounding condition.	\$ 4,395	\$ 4,395	100
152	FM-2008092	Kern	Bakersfield Juvenile Center	15-C1	1	escalator	Elevators, Escalators, & Hoists - Replace (5) door contact block assemblies, (5) Interlock air lock hooks, and (2) gate switch contacts for public elevator 1. Parts failed due to age, causing elevator to intermittently bounce and stop between floors.	\$ 6,465	\$ 4,316	66.76
153	FM-2008093	Los Angeles	East Los Angeles Courthouse	19-V1	1	HVAC	HVAC - Replace (1) reheat coil and 15 LF of a 3/4 inch copper pipe. Install (2) 3/4 inch isolation valves, (1) strainer and associated fittings. The reheat coil and associated parts failed due to age allowing water to leak into the attorney interview room on the 4th floor. Environmental oversight and remediation required for category 2 water. Erect (1) 3 ft x 7 ft containment and clean, dry, and sanitize 300 SF of carpet.	\$ 39,902	\$ 31,012	77.72
154	FM-2008096	Los Angeles	Central Arraignment Courts	19-U1	1	HVAC	County Managed - HVAC - Replace (2) condensate pumps in mechanical room. Pumps failed due to age.	\$ 13,535	\$ 13,535	100.00
155	FM-2008098	Los Angeles	Metropolitan Courthouse	19-T1	1	escalator	Elevators, Escalators, & Hoists - Replace counterweight buffer and adjust hoist way access key switch to be self-centering for public elevator 9. Deficiencies found during regulatory compliance.	\$ 19,011	\$ 17,973	94.54
156	FM-2008100	Los Angeles	Compton Courthouse	19-AG1	1	HVAC	HVAC - Replace (1) 40hp motor and associated parts for the chilled water pump 2 in the 13th floor chiller room. Motor failed due to age, impacting cooling to the building.	\$ 7,340	\$ 4,854	66.13
157	FM-2008101	Los Angeles	Compton Courthouse	19-AG1	1	plumbing	Plumbing - Replace (1) sump pump in the public parking structure. Pump failed due to age preventing water from being pumped from pit and pooling.	\$ 3,162	\$ 2,091	66.13
158	FM-2008102	Los Angeles	Inglewood Courthouse	19-F1	1	HVAC	HVAC - Install 12 LF of insulation, and restore 5 LF of sheet metal around drain pans on air handler 1. The sheet metal failed due to age and insulation is required to address condensation build-up on AHU 1 pipe. Condensation leaked in to the gym area located in the basement. Environmental oversight and remediation required for category 2 water. Clean, dry, and sanitize 34 SF of concrete surfaces.	\$ 29,789	\$ 22,211	74.56
159	FM-2008103	Los Angeles	Torrance Courthouse	19-C1	1	plumbing	Plumbing - Domestic Water Pipe - Replace (1) 2 inch 90 degree copper fitting on domestic hot water line in the first floor plenum above cafeteria. Fitting failed due to corrosion. Environmental oversight and remediation required for category 2 water. Erect (1) 6 ft x 8 ft x 9 ft containment. Clean and sanitize 48 SF of terrazzo.	\$ 19,965	\$ 16,998	85.14



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
160	FM-2008105	Orange	Stephen K. Tamura Courthouse	30-D1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 2 LF of 6 inch overhead cast iron pipe in the basement file room. The cast iron pipe failed due to a blockage in the line age resulting in a build up of pressure leading to the pipe failing. Environmental oversight and remediation required for category 3 water. Clean and sanitize 430 SF of concrete flooring the basement file room.	\$ 7,550	\$ 7,550	100.00
161	FM-2008106	Los Angeles	Norwalk Courthouse	19-AK1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) auxiliary contact, (22) relays, (1) PRI board, and pulleys and bearings in public elevator 4. Parts failed due to the age affecting the elevators operation.	\$ 65,359	\$ 55,575	85.03
162	FM-2008114	San Diego	Central Courthouse	37-L1	1	Escalators	Elevators, Escalators, & Hoists - Shorten hoist ropes on judges elevator 1. Ropes have stretched due to use causing the counterweight to fault impacting the elevators operation.	\$ 7,439	\$ 7,439	100
163	FM-2008115	Solano	Hall of Justice	48-A1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 3 LF of 3 inch cast iron drain line from 2nd floor restroom. Pipe failed due to age and leaked to top of light fixture in office below. Environmental oversight required for category 2 water. Clean and sanitize 10 SF of area above light fixture.	\$ 5,096	\$ 5,096	100
164	FM-2008116	Los Angeles	Compton Courthouse	19-AG1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) 120V battery for emergency lighting and phone system on freight elevator 11. Battery failed due to age impacting the alarm bell and phone.	\$ 4,776	\$ 3,158	66.13
165	FM-2008120	Los Angeles	Whittier Courthouse	19-AO1	1	Vandalism	Vandalism - Replace (2) 24 inch x 36 inch mirrors in the 1st floor mens public restroom, (1) 54 inch x 36 inch mirror in the 2nd floor mens public, and (1) 54 inch x 36 inch mirror in the 3rd floor mens public restroom. Mirrors were vandalized by an unknown individual with graffiti. Work includes anti-graffiti film to be installed over the glass.	\$ 10,580	\$ 9,144	86
166	FM-2008123	Los Angeles	Airport Courthouse	19-AU1	1	Plumbing	Plumbing - Domestic Water Leak - Replace 25 SF of drywall, (5) 2 ft x 2 ft ceiling tiles, and (2) 1 inch copper fittings to the cold domestic water pipe in the 7th floor womens public restroom. The copper fitting failed due to corrosion allowing water to leak down to floors 3, 4, 5, 6, and 7. Environmental oversight and remediation required due to category 2 water. Erect multiple containments, (1) 3 ft x 8 ft x 8 ft, (1) 8 ft x 15 ft x 8 ft, (1) 5 f x 10 ft x 8 ft, and (1) 5 ft x 8 ft x 8 ft. Clean, dry, and sanitize 305 SF of carpet.	\$ 99,023	\$ 76,416	77.17
167	FM-2008125	San Diego	East County Regional Center	37-I1	1	Plumbing	Plumbing - Sewer Line Leak - Mechanically clear 50 LF of sewer line in the 8th floor probation office and restroom and replace 6 SF of drywall, 58 SF of carpet, and 7 LF of cove base. Blockage was caused by a build-up of debris in the main sewer line. Environmental and remediation required for category 3 water. Erect (2) 4 ft x 10 ft containments and clean, dry, and sanitize 61 SF of hard surfaces.	\$ 30,475	\$ 20,635	67.71
168	FM-2008127	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Security	Security - Replace (1) 15 inch touchscreen for main lockup control booth. The touchscreen failed due to age, causing controls for holding cells to be inaccessible.	\$ 4,351	\$ 4,351	100.00
169	FM-2008129	Los Angeles	East Los Angeles Courthouse	19-V1	1	HVAC	HVAC - Replace (1) 10 HP motor, (1) 6 inch pulley, (2) belts, and (1) 2 inch hot water strainer for air handler 5. The return fan motor and hot water strainer failed due to age.	\$ 9,890	\$ 7,687	77.72
170	FM-2008130	Los Angeles	Bellflower Courthouse	19-AL1	1	Escalators	Elevators, Escalators, & Hoists - Replace (3) limit switches, (3) cross rollers, (2) 3 inch plastic reel assemblies, and (1) spirator cable for wheelchair lift 4 in 3rd floor courtroom. Parts failed due to age preventing the chair lift from operating.	\$ 3,022	\$ 3,022	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
171	FM-2008138	San Joaquin	Stockton Courthouse	39-F1	1	Escalator	Elevators, Escalators, & Hoists - Replace encoder cable, drive encoder, cartop encoder, cartop communications board, and brake module for Elevator 9. Components have failed due to use resulting in the elevator not stopping at correct floors. Specialized Sr. Technicians were required to complete work and worked 4 days including a weekend to complete repairs.	\$ 45,494	\$ 45,494	100
172	FM-2008142	San Bernardino	San Bernardino Justice Center	36-R1	1	Security	Security - Replace (1) floor latch guide and associated screws and spacers on main entrance door. Floor latch guide failed due to age, affecting the operations of the door creating and security issue.	\$ 1,869	\$ 1,869	100.00
173	FM-2008153	Los Angeles	Metropolitan Courthouse	19-T1	1	Vandalism	Vandalism - Replace (1) 68 inch x 135 inch 1/4 inch thick tempered glazing and safety film on exterior window on 1st floor. Glazing was vandalized by and unidentified person after hours.	\$ 3,817	\$ 3,609	94.54
174	FM-2008157	Los Angeles	Whittier Courthouse	19-AO1	1	Escalator	Elevators, Escalators, & Hoists - Replace (1) printed circuit board and (2) tape guides in judges elevator 3. Board and tape guides failed due to age impacting elevators operation.	\$ 8,154	\$ 8,154	100
175	FM-2008158	Los Angeles	Compton Courthouse	19-AG1	1	Interior Finishes	Interior Finishes - Mechanically clear 25 LF of fire pump drain line and replace (3) 1 ft x 1 ft ceiling tiles in the 12th floor courtroom. The fire pump drain line was blocked allowing water to back-up and leak onto the ceiling tiles. Environmental oversight and remediation required due to category 2 water. Erect (1) 7 ft x 9 ft x 12 ft containment and sanitizing 447 SF of floors and walls.	\$ 18,627	\$ 12,318	66.13
176	FM-2008168	Los Angeles	Metropolitan Courthouse	19-T1	1	HVAC	HVAC - Replace (2) flow sensors for chiller 2. Sensors failed due to age causing the chiller to go into fault and impacting cooling to the building.	\$ 3,797	\$ 3,589	94.54
177	FM-2008169	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	1	Security	Security - Replace operation touch screen control panel for basement holding cell doors. Touch screen has failed due to age and use leaving the deputies without the ability to unlock holding cell doors. Manual operation required to unlock each cell affecting daily operations due to increased manpower and time to unlock each cell.	\$ 4,508	\$ 4,508	100.00
178	FM-2008170	Orange	Stephen K. Tamura Courthouse	30-D1	1	Plumbing	Plumbing - Replace (2) 7.5 hp sewage ejector pumps. The pumps failed due to foreign material blocking the pumps, allowing water to flood the basement detention and file storage areas. The new ejector pumps will have an integrated grinder to prevent this in the future. Environmental oversight and remediation required for category 3 water. Clean and sanitize 2,946 SF of concrete flooring.	\$ 125,255	\$ 125,255	100.00
179	FM-2008171	Los Angeles	Metropolitan Courthouse	19-T1	1	Escalator	Elevators, Escalators, & Hoists - Replace (2) contactors on elevator 5. Contactors failed due to age and use causing the elevator to be non-operational.	\$ 5,035	\$ 4,760	94.54
180	FM-2008173	Kern	Metropolitan Division	15-A1	1	Escalator	Elevators, Escalators, & Hoists - Replace (1) hallway station board, (2) elevator buttons, and (20) motor brushes for public elevators 1 & 2. Parts failed due to age.	\$ 6,589	\$ 4,118	62.50
181	FM-2008179	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Vandalism	Vandalism - Restore (1) steel post, and replace (4) 1/2 inch x 3 3/4 inch wedge anchor bolts. A sign by the front entrance of the building was hit by a vehicle afterhours.	\$ 5,073	\$ 3,550	69.99



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
182	FM-2008180	San Diego	East County Regional Center	37-I1	1	Plumbing	Plumbing - Domestic water pipe leak - Replace (2) 2 inch copper couplings and 2 LF of 2 inch copper pipe, (10) 2 ft x 2 ft ceiling tiles, 5 LF of 4 inch cove base, 1 SF of drywall in 5th floor office. Pipe failed due to age allowing water to leak on to ceiling tiles and the carpet. Environmental oversight and remediation required for category 2 water. Erect (1) 4 ft x 4 ft catch all container, and clean, dry, and sanitize 4 SF of drywall and 15 SF of carpet.	\$ 22,229	\$ 15,051	68
183	FM-2008185	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Escalators	Elevators, Escalators, & Hoists - Replace (4) steps, (2) handrail turnarounds, step chain, (4) upper and lower handrail guide curved tracks and rebuild motor and gear box on escalator 20. The components have failed due to age, were red-tagged and placed out of service.	\$ 270,069	\$ 262,669	97.26
184	FM-2008186	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Vandalism	Vandalism - Replace (2) 2 ft x 2 ft ceiling tiles in 13th floor public hallway. An in-custody left a 14th floor holding cell sink constantly running allowing water to travel to the 13th floor public hallway. Environmental oversight and remediation required due to category 2 water and ACM. Erect (1) 6 ft x 6 ft x 8 ft containment and (1) 60 inch x 90 inch critical door barrier. Clean, dry, and sanitize 32 SF of concrete floor and 12 SF of concrete wall.	\$ 35,721	\$ 24,572	68.79
185	FM-2008188	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC	HVAC - Replace 6 LF of 1 1/2 inch of copper hot water piping, (2) 1 1/2 inch brass fittings, and (2) 1 1/4 inch brass fittings in 8th floor mechanical room. Hot water supply line failed due to age allowing water to leak onto the floor. Environmental oversight and remediation required due to category 2 water and ACM. Erect (1) 12 inch x 12 inch containment and clean, sanitize and disinfect 80 SF of concrete floor.	\$ 43,304	\$ 29,789	68.79
186	FM-2008189	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Vandalism	Vandalism - Replace (1) 36 inch x 96 1/2 inch clear tempered glazing in the 1st floor lobby. Glazing was broken afterhours by unidentified person.	\$ 6,259	\$ 4,305	68.79
187	FM-2008191	Merced	Los Banos Division - The Robert M. Falasco Justice Center	24-G1	1	Vandalism	Vandalism - Replace (2) 60 inch x 69 inch insulated glazing for main entrance windows. Windows were smashed by a member of the public. Restitution is being sought. Costs include emergency response cleanup and temporary board up of windows.	\$ 5,473	\$ 5,473	100.00
188	FM-2008194	Tulare	South County Justice Center	54-I1	1	Interior Finishes	Interior Finishes - Replace (1) pin assembly, (2) hinges, (1) light transom patch bracket and insert for 1st floor lobby exit door. Components failed due to use, and is impacting the doors operation.	\$ 3,850	\$ 3,850	100.00
189	FM-2008195	Los Angeles	Hollywood Courthouse	19-S1	1	Vandalism	Vandalism - Replace (1) 4 ft x 6 ft window in the 1st floor waiting room. The window was broken by an unknown person afterhours. The broken glass was removed and the area was boarded up.	\$ 7,944	\$ 7,236	91.09
190	FM-2008197	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Security	Security - Replace (2) 33 inch x 34 inch tempered glazing panels with matching tint for grand entrance doors. Glazing panels were broken on the afterhours with rocks by unidentified person. Work includes board-up of the windows while glazing is procured.	\$ 4,232	\$ 4,116	97.26
191	FM-2008200	Tulare	South County Justice Center	54-I1	1	Plumbing	Plumbing - Domestic Water Pipe Leak - Replace (1) vacuum breaker, (1) wax ring and (1) O-ring in courtroom 3rd floor holding cell. Components failed due to age, allowing water to leak from the toilet.	\$ 2,802	\$ 2,802	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
192	FM-2008202	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Interior Fin	Interior Finishes - Mechanically clear 25 LF of sewer line and replace 4 ft x 5 ft of plaster ceiling in P level mens restroom. Toilet in S level mens restroom overflowed due to blockage leaking down to the P level. Environmental oversight and remediation required for category 2 water and ACM. Erect (2) 40 inch x 90 inch critical door barriers, clean, dry, and disinfect (1) metal ceiling vent, (1) porcelain toilet, and 60 SF of ceramic floor tile.	\$ 20,487	\$ 14,093	68.79
193	FM-2008203	San Diego	East County Regional Center	37-11	1	Plumbing	Plumbing - Sewer line leak - Replace (5) 2 ft x 4 ft ceiling tiles, (2) 2 ft x 2 ft ceiling tiles, 3 LF of 4 inch cove base, 6 SF of drywall, 72 SF of carpet, and mechanically clear blockage in ground floor staff office area. A toilet in the 1st floor mens public restroom was blocked allowing water to overflow into the adjacent janitor closet and down to the ground level. Environmental oversight and remediation required for category 3 water. Erect (1) 8 ft x 6 ft x 10 ft containment and clean, dry, and sanitize 18 LF of 6 in x 6 in ceramic base tile, 160 SF of 2 ft x 2 ft ceramic floor tile, (2) porcelain toilets, 20 SF of concrete, (2) metal light fixtures, and (1) metal HVAC vent.	\$ 30,463	\$ 20,626	67.71
194	FM-2008205	Los Angeles	Compton Courthouse	19-AG1	1	Interior Fin	Interior Finishes - Replace (1) 1/4 inch vinyl insert and install (1) 1/4 inch bronze glazing stop for the north side entrance door. The glazing stop was missing allowing the glazing to shift in the door.	\$ 2,407	\$ 1,592	66.13
195	FM-2008206	Imperial	El Centro Courthouse	13-A1	1	Plumbing	Plumbing - Replace (2) urinals and (2) flush valves in the mens restroom located on the 2nd floor. Urinals cracked due to age. Work is needed to prevent a possible leak in the restroom.	\$ 3,322	\$ 3,322	100.00
196	FM-2008212	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing	Plumbing - Replace (1) 2 inch gate valve, 10 LF of 2 inch copper pipe, (2) 2 inch couplings in the 7th floor womens public restroom pipe chase. The valve failed due to age allowing water to leak down to the 2nd floor ceiling and terrazzo flooring. Environmental oversight and remediation included for category 2 water. Clean, dry and sanitize 20 SF of metal ceiling and 30 SF of terrazzo flooring.	\$ 42,639	\$ 34,316	80
197	FM-2008214	San Joaquin	Stockton Courthouse	39-F1	1	Vandalism	Vandalism - Remove graffiti on the concrete around fountain, back concrete steps, doors, the front ADA ramp, and front aluminum flag poles.	\$ 9,153	\$ 9,153	100.00
198	FM-2008226	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	Interior Fin	Interior Finishes - Replace (1) 110V motor assembly, (8) top rollers, (2) bottom guides, and (2) pulleys for the main public entrance doors. Parts failed due to age causing the doors to remain unsecured after hours.	\$ 12,054	\$ 8,861	73.51
199	FM-2008236	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing	Plumbing - Fixture Leak - Replace (1) 5 5/8 inch gasket and (2) 4 inch no hub unions in the 4th floor holding cell and 8 SF of 2 ft x 2 ft ceiling tiles in 2nd floor clerks office. The toilet fitting failed due to age allowing water to travel down the pipe to the 2nd floor clerks office and pool onto a desk. Environmental oversight and remediation required for category 2 water. Clean, dry, and sanitize (1) desk and (1) cubical wall.	\$ 28,976	\$ 28,976	100
200	FM-2008239	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing	Plumbing - Replace (1) control panel, (2) 460-volt 2 HP pumps, (2) 4 inch gate valve, (2) 4 inch check valves and associated fittings for the sump pumps located in the basement. Controller failed due to age affecting the signal to the pumps to activate and causing the pumps to be grounded and locked.	\$ 39,513	\$ 26,130	66.13



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
201	FM-2008243	Los Angeles	Torrance Courthouse	19-C1	1	Plumbing	Plumbing - Domestic Water Pipe - Replace (1) braided polymer faucet hose on the hot water valve line to sink in the 2nd floor judges chambers restroom. The hose failed due to age and corrosion and affected the 2nd floor restroom down to the 1st floor admin office. Environmental oversight and remediation required for category 2 water. Erect (1) 10 ft x 4 ft x 8 ft containment. Clean and sanitize 48 SF of carpet, and 35 SF of ceramic tile.	\$ 19,839	\$ 19,839	100
202	FM-2008245	Los Angeles	Mental Health Court	19-P1	1	Handrails	Vandalism - Secure (3) doors, (5) windows with plywood, and 40 LF of fencing. A fire broke out at the vacant facility causing the Los Angeles Fire Department to cut the doors, windows, and fencing to gain access to the fire.	\$ 11,681	\$ 8,330	71.31
203	FM-2008246	Los Angeles	East Los Angeles Courthouse	19-V1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) door operator motor, (1) capacitor, and (1) board for the judges elevator. Parts failed due to age resulting in the doors getting stuck and causing entrapments.	\$ 8,456	\$ 8,456	100
204	FM-2008247	Los Angeles	East Los Angeles Courthouse	19-V1	1	HVAC	HVAC - Replace 6 SF of 1 ft x 1 ft ceiling tiles in the 4th floor secure hallway and restore (2) hot water circulating pumps in the roof boiler room. The hot water pumps failed due to age, causing water to leak down to the secure hallway. Environmental oversight and remediation required for category 2 water. Clean, dry and sanitize 20 SF of vinyl floor tile, erect (1) 3 ft x 7 ft x 8 ft containment and (1) dehumidifier.	\$ 36,579	\$ 28,429	77.72
205	FM-2008249	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	Interior Finishes	Interior Finishes - Replace (1) 25 1/2 inch x 74 1/2 inch glass window. The window was broken by an individual who kicked the panel while exiting the building. The window was boarded up using a 26 inch x 76 inch plywood panel. Restitution is being sought.	\$ 5,154	\$ 3,789	73.51
206	FM-2008250	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	Interior Finishes	Interior Finishes - Replace (1) 32 1/4 inch x 74 1/2 inch clear tempered glass for the employee entrance doors. Glass was broken due to unknown cause. The door was boarded up using a 34 inch x 76 inch plywood panel.	\$ 4,374	\$ 3,216	73.51
207	FM-2008251	Santa Barbara	Figueroa Division	42-B1	1	Protection	Fire Protection - Pneumatically cleared air handler unit 1 condensation line and replace (1) smoke detector in the holding area. Air handler unit 1s condensation line was blocked allowing water to leak on the smoke detector.	\$ 4,400	\$ 4,400	100
208	FM-2008257	Los Angeles	Compton Courthouse	19-AG1	1	HVAC	HVAC - Replace (2) pulleys and (2) bushings for AHU 1 in the basement. Pulleys failed due to age, preventing the fan from moving and impacting the airflow to the building.	\$ 3,151	\$ 2,084	66.13
209	FM-2008261	Santa Barbara	Figueroa Division	42-B1	1	HVAC	HVAC - Condensation Leak - Replace (1) condensate drain pump, 2 LF of 3/4 inch drain tubing and (10) 2 ft x 2 ft ceiling tiles in the lockup control room. Condensation pump failed due age and allowed the drain pan to overflow. Environmental oversight and remediation required due to category 2 water. Erect (1) 6 ft x 7 ft containment in the lockup control room. Clean, dry, and sanitize 125 SF of 12 inch x 12 inch vinyl floor tile, (1) wooden shelf, and (1) metal desk.	\$ 25,357	\$ 25,357	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
210	FM-2008263	Kern	Shafter/Wasco Courts Bldg.	15-E1	1	Protect	Fire Protection - Replace (4) electronic release devices and (4) 12V 4.5ah batteries for fire curtains at clerk windows and install (1) relay at the fire panel. Fire curtains failed during preventative maintenance testing and back up batteries have reached the end of their useful life. Doors to be tested and certified upon completion.	\$ 23,266	\$ 20,927	89.95
211	FM-2008264	Los Angeles	Compton Courthouse	19-AG1	1	HVAC	HVAC - Replace (1) 8 inch triple duty valve and associated parts for the condenser water pump 2 in the 13th floor chiller room. Valve failed due to age, causing a reverse siphon and not circulating water from the chiller back to the cooling tower, affecting cooling to the building.	\$ 9,737	\$ 6,439	66.13
212	FM-2008265	Fresno	Fresno County Courthouse	10-A1	1	Plumbing	Plumbing - Replace (1) combination toilet and sink in 2nd floor holding cell. Unit failed due to age and mineral buildup resulting in water flooding the cell. Environmental oversight and remediation required due to Category 2 water. Clean and sanitize 47 SF of concrete floor.	\$ 14,641	\$ 14,641	100.00
213	FM-2008270	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Plumbing	Plumbing - Sewer Leak - Replace 2 LF of 2 inch cast iron pipe, and (2) 2 ft x 2 ft ceiling tiles in 4th floor administrative office. Cast iron pipe cracked due to age. Environmental oversight and remediation required due to category 2 water. Erect (1) 14 ft x 14 ft x 10 ft containment, and clean, dry, and sanitize (1) light fixture and 10 SF of metal ceiling grid.	\$ 40,328	\$ 39,223	97.26
214	FM-2008271	Imperial	Winterhaven Court	13-D1	1	Plumbing	Plumbing - Replace (2) toilets and (2) flush valve in womens public restroom, and (1) toilet and (1) flush valve in the mens public restroom. Toilets cracked due to age. Work is needed to prevent a possible leak in the restroom.	\$ 3,260	\$ 3,260	100.00
215	FM-2008276	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 10 LF of 4 inch cast iron drain line in the 6th floor mens public restroom. Cast iron pipe cracked due to age. Environmental oversight and remediation required for category 2 water. Erect (1) critical door barrier, and clean, dry, sanitize 120 SF of plaster ceiling, and 200 SF of ceramic tile floor.	\$ 37,369	\$ 36,345	97.26
216	FM-2008277	Kern	Bakersfield Juvenile Center	15-C1	1	HVAC	HVAC - Replace (1) control board and (1) contactor for package unit 1. Parts failed due to age.	\$ 9,938	\$ 6,635	67
217	FM-2008278	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Escalators	Elevators, Escalators, & Hoists - Replace (2) demarcation strip lights for escalators 1 and 9, (13) step treads for escalators 3, 4, 5, 10, 12, 14, 15, 16, 17, 19, 21, 24, 25, and (3) comb plates for escalators 5, 9, 10. Lubricate exposed skirt panel and remove excessive oil on step treads for escalators 1, 3, 4, 5, 9, 10, 12, 14, 15, 16, 17, 19, 21, 24, and 26. Adjust step chain for 6 escalators. Work required due to preliminary orders for escalators.	\$ 52,665	\$ 51,222	97
218	FM-2008279	Los Angeles	West Covina Courthouse	19-X1	1	Electrical	County Managed - Electrical - Replace (11) emergency exit sign and battery powered combination lights and (17) emergency battery powered lights in the basement hallway. Deficiencies were identified during the annual inspection and need to be replaced due to safety hazard with emergency egress.	\$ 20,648	\$ 20,648	100.00
219	FM-2008280	Los Angeles	Torrance Courthouse	19-C1	1	Protect	Fire Protection - Replace (1) antenna extension for fire system. Antenna failed due to age impacting fire system communication.	\$ 16,483	\$ 14,033	85
220	FM-2008281	Sacramento	Juvenile Courthouse	34-C2	1	Protect	Fire Protection - Replace (1) module and program panel for communication between Fire Alarm Control Panel and releasing panel in server room. Module has failed due to age resulting in false trouble and supervisory alarm signals.	\$ 2,147	\$ 2,147	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
221	FM-2008285	Kern	Metropolitan Division	15-A1	1	and Pa	Ground and parking lots - Replace (1) concrete electrical box, (1) conduit sealant cap, and (23) 1 ft x 1 ft ceiling tiles in the basement offices. Irrigation water filled the concrete electrical box allowing water to travel through the conduit and drain above the basement ceiling. Electrical box was cracked due to age. Environmental oversight and remediation required due to category 2 water. Erect (1) 9 ft x 9 ft containment. Clean, dry, and sanitize 32 SF of vinyl floor tile, 16 SF of plaster wall, and refinished (8) SF of plaster wall.	\$ 39,184	\$ 24,490	62.50
222	FM-2008286	Los Angeles	Stanley Mosk Courthouse	19-K1	1	lectric	Electrical - Replace 100 LF of 3/4 inch EMT conduit and 100 LF of 12 gauge wiring in 3rd floor courtroom. The conduit was damaged and wiring failed due to age impacting power in the courtroom.	\$ 2,889	\$ 2,809	97.26
223	FM-2008287	Los Angeles	Burbank Courthouse	19-G1	1	HVAC	HVAC - Replace (1) condenser water pump, (1) shaft coupling, (1) 1 inch ball valve, (1) 1 inch strainer, (2) pressure gauges, 3 LF of 1 inch copper pipe, and (1) water level float assembly and associated fittings. The components failed due to age affecting the cooling to the building.	\$ 26,951	\$ 24,461	90.76
224	FM-2008289	Riverside	Riverside Hall of Justice	33-A3	1	erior S	Exterior Shell - Replace 8 1/4 ft x 7 ft 22 gauge steel slat overhead rollup loading dock door, 50k cycle barrel, guides, bottom bar, and slide locks. The door has failed due to age and use and can no longer be opened or properly secured.	\$ 8,881	\$ 8,881	100.00
225	FM-2008290	Los Angeles	Pomona Courthouse South	19-W1	1	scalate	Elevators, Escalators, & Hoists - Replace (1) main contactor and associated wiring for public elevators 1-4. The main contactor failed due to age affecting the operation to all of the public elevators.	\$ 6,780	\$ 6,179	91.14
226	FM-2008294	Los Angeles	Alhambra Courthouse	19-I1	1	ior Fin	Interior Finishes - Replace (60) 1 ft x 1 ft ceiling tiles located in courtroom 4. Ceiling tiles failed due to age creating a safety hazard in courtroom 4. Environmental oversight and remediation required due to ACM. Erect (5) 3 ft x 7 ft critical barriers, (2) 3 ft x 3 ft x 7 ft decontamination chambers, and clean and sanitize 1000 SF of wall and ceiling.	\$ 24,026	\$ 24,026	100.00
227	FM-2008297	Los Angeles	Alhambra Courthouse	19-I1	1	lumbir	Plumbing - Sewer Line Leak - Mechanically clear 60 LF of 3 inch sewer line. Sewer line was blocked affecting the 1st floor mens public restroom and leaking down to the basement file room. The debris was punched through and not recovered. Environmental oversight and remediation required due to ACM and category 3 water. Erect (1) 4 ft x 10 ft x 15 ft containment, (1) 3 ft x 7 ft critical barrier, and sanitize 850 SF surfaces.	\$ 19,358	\$ 16,648	86.00
228	FM-2008298	Los Angeles	Pomona Courthouse North	19-W2	1	HVAC	HVAC - Replace (15) 24 inch x 24 inch ceiling tiles, (1) 6 ft x 1 ft stainless steel condensate drain pan, 24 LF of duct linear insulation, 10 LF of 1 inch copper pipe, 20 SF of epoxy sealant and associated fittings for air handler unit 1. The condenser pan failed due to age affecting penthouse mechanical room and leaked down to the 2nd floor courtroom jury room. Environmental oversight and remediation required for ACM and category 2 water. Erect (1) 15 ft x 12 ft x 9 ft containment and clean, dry, and sanitized 2,150 SF of floors and walls.	\$ 38,478	\$ 37,035	96.25
229	FM-2008299	Orange	Central Justice Center	30-A1	1	lumbir	Plumbing - Fixture Leak - Restored 150 SF of carpeting and ceiling of 7th floor jury deliberation room. A blocked toilet in an 8th floor holding cell allowed water to overflow down into the deliberation room. Remediation and environmental oversight required for category 2 water.	\$ 6,333	\$ 6,333	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
230	FM-2008300	Los Angeles	Pasadena Courthouse	19-J1	1	Escalator	Elevators, Escalators, & Hoists - Replace (10) emergency batteries and (1) car access key switch for public elevators 1-7. Batteries and key switch failed due age. Deficiencies identified during DIR annual compliance inspection.	\$ 4,952	\$ 3,434	69.35
231	FM-2008301	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	HVAC	HVAC - Replace (1) computer for BAS, (1) 27 inch monitor, (1) back up battery, and restore (1) control software. The BAS computer failed due to age, affecting controls throughout the building.	\$ 19,505	\$ 14,338	73.51
232	FM-2008305	Los Angeles	Metropolitan Courthouse	19-T1	1	HVAC	HVAC - Replace (1) loop and (1) valve between hot water pumps 1 and 2 and (16) 1 ft x 1 ft ceiling tiles in the 8th floor storage room. Valve and loop failed due to age allowing water to leak from the 9th floor mechanical room down to the 8th storage room. Environmental oversight and remediation required for category 2 water. Erect (1) 8 ft x 8 ft containment and clean, disinfect, and sanitize 16 SF of ceramic floor tile, and 150 SF of concrete floor.	\$ 44,298	\$ 41,880	95
233	FM-2008306	Los Angeles	Burbank Courthouse	19-G1	1	HVAC	HVAC - Replace (2) oil filters, (1) fill float linkage, (5) gallons of synthetic refrigeration oil, and chemically clean chiller tubes for chiller 1. Oil filters and fill media failed due to age, causing the chiller to surge affecting all cooling to the north side of the building. Work includes chemically cleaning 240 CF of fill media for cooling tower 1.	\$ 50,000	\$ 45,380	90.76
234	FM-2008307	Merced	Los Banos Division - The Robert M. Falasco Justice Center	24-G1	1	Door Finish	Interior Finishes - Replace (1) door header with associated backing plate and door stop and rewire damaged retractable access controls coil cord for main public entrance door. Door became unbalanced due to use, causing component damage and inability to control locking function from access controls software.	\$ 3,155	\$ 3,155	100.00
235	FM-2008313	Sacramento	Carol Miller Justice Center Court Facility	34-D1	1	HVAC	HVAC - Replace (1) 8 inch 3-way chilled water control valve, (1) 8 inch check valve, (2) 8 inch butterfly valves, and re-install all piping insulation for Air handling unit 2. The check valve failed due to age causing air handler to not cool or operate at set temperature.	\$ 25,522	\$ 25,522	100.00
236	FM-2008314	Los Angeles	Metropolitan Courthouse	19-T1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) shower head, (1) 8 inch threaded pipe, (6) 4 inch x 4 inch ceramic wall tiles, and 1 SF of plaster in the 4th floor sheriff locker room. Shower head pipe failed due to age. Work required the removal of the tile and plaster to access the pipe. Environmental oversight and remediation required for lead in the ceramic tile. Erect (1) 4 ft x 8 ft critical barrier.	\$ 35,421	\$ 33,487	94.54
237	FM-2008315	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Vandalism	Vandalism - Fire Protection - Replace (1) fire pull station for the 6th floor public hallway. The south wing pull station was activated and broken by an unknown member of the public.	\$ 4,627	\$ 3,238	69.99
238	FM-2008317	San Diego	Juvenile Court	37-E1	1	Roof	Roof - Exterior Leak - Replace (25) 2 ft x 2 ft ceiling tiles and 8 SF of drywall in the 1st floor lobby, 2nd floor lobby, womens public restroom, and public corridor. The roof failed at the HVAC platform allowing water to leak into the building. A 20 ft scissor lift required for high ceilings. Environmental oversight and remediation required for category 2 water. Erect (43) 2 ft x 2 ft ceiling tile containments and clean, dry and sanitize 50 SF of drywall, 20 SF of carpet, (1) cubicle wall, and 8 SF of floor tile. Repairs to the platform will be handled under a separate FM.	\$ 36,352	\$ 27,126	74.62



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
239	FM-2008318	Los Angeles	Pasadena Courthouse	19-J1	1	Interior Fin	Interior Finishes - Replace (1) 90 minute fire rated door and associated hardware located at 4th floor stairwell. The door failed due to age, causing the wood to delaminate and affect the fire rating of the door. Environmental oversight and remediation required for ACM. Erect (1) 5 ft x10 ft x 9 ft containment and (1) 3 ft x 3 ft x 7 ft decontamination chamber. Clean and sanitize 100 SF of floors and walls.	\$ 26,201	\$ 18,170	69.35
240	FM-2008321	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing	Plumbing - Sewer Line Leak - Mechanically clear 50 LF of sewer line and replace (1) 2 ft x 4 ft ceiling tile. Drain line was blocked by an unknown debris allowing water to leak down into the 5th floor clerks office. Environmental oversight and remediation required due to category 2 water. Erect (1) 8 ft x 8 ft x 8 ft containment and clean, dry, and sanitize, 380 SF of hard surface.	\$ 20,726	\$ 14,258	69
241	FM-2008323	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	1	Plumbing	Plumbing - Replace 20 SF of drywall, and hydro jet and pump 1,500 gallons from the grease interceptor tanks located in the secured parking. A leak coming from the grease interceptor traveled down to the courtroom below. Environmental oversight and remediation required due to category 3 water. Erect (1) 20 ft x 10 ft containment in the basement courtroom. Clean, dry, and sanitize 24 SF of 2 ft x 4 ft metal ceiling tile, 80 SF of concrete, and 40 SF of wood panel.	\$ 45,175	\$ 33,208	74
242	FM-2008325	Los Angeles	Van Nuys Courthouse East	19-AX1	1	Plumbing	Plumbing - Domestic water pipe leak - Replace (1) 1 inch coupling, (1) 1 inch 90 degree elbow, and 10 LF of 1 inch copper pipe. The pipe failed due to age causing a leak above the sink in the 1st floor childrens waiting room. Remediation and environmental oversight required. Clean, dry, and sanitize (1) air vent and (1) office cabinet.	\$ 24,999	\$ 22,434	90
243	FM-2008327	Los Angeles	Whittier Courthouse	19-AO1	1	Interior Fin	Interior Finishes - Replace (13) 1 ft x 1 ft ceiling tiles in 3rd floor courtroom. Ceiling tiles failed due to condensation buildup from the ducting in the plenum branching off the main supply and leaking onto the ceiling, walls, and floor. Environmental oversight and remediation required for category 2 water. Erect (1) 12 ft x 14 ft x 11 ft containment, (1) 36 inch x 76 inch decontamination chamber, and clean and sanitize 390 SF of floors and walls.	\$ 19,134	\$ 19,134	100.00
244	FM-2008334	Los Angeles	Stanley Mosk Courthouse	19-K1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 3 LF or 3 inch cast iron pipe, (2) 1 ft x 2 ft ceiling tile, and (4) 2 ft x 2 ft carpet squares in the 1st floor court administrative office. Cast iron drain line cracked due to age allowing water to leak into the office below. Environmental testing and oversight required for category 2 water. Erect (1) 9 ft x 17 ft containment.	\$ 35,091	\$ 34,130	97.26
245	FM-2008335	Los Angeles	Alhambra Courthouse	19-I1	1	Holding C	Holding Cell - Replace (1) 7 3/4 inch x 11 3/4 inch glazing pane in 2nd floor holding cell. Glazing was broken by an in-custody creating a safety and security concern. Restitution is being sought.	\$ 2,378	\$ 2,378	100.00
246	FM-2008341	Los Angeles	El Monte Courthouse	19-O1	1	Plumbing	Plumbing - Sewer Line Leak - Replace 10 LF of 4 inch cast iron pipe and associated fittings in basement ceiling. The cast iron pipe failed due to age and leaked into the basement secured hallway. Environmental oversight and remediation required for ACM and category water 3. Erect (2) 3 ft x 7 ft critical barriers, (2) 6 ft x 9 ft critical barriers, and sanitize 525 SF of walls and ceilings.	\$ 26,674	\$ 15,503	58.12
247	FM-2008356	Los Angeles	Torrance Courthouse	19-C1	1	HVAC	HVAC - Replace (2) tandem belts, (2) 7.5hp fan motors, and (2) pulleys to cooling towers A and B. Motors failed due to age resulting excess noise from the units.	\$ 16,775	\$ 14,282	85



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
248	FM-2008358	Riverside	Riverside Juvenile Court	33-N1	1	andalis	Vandalism - Replace 25 ft x 8 ft mesh privacy screen for judges parking lot security gate. The screen was damaged by fire started by unidentified individual.	\$ 2,500	\$ 2,500	100
249	FM-2008365	Los Angeles	Airport Courthouse	19-AU1	1	lumbir	Plumbing - Domestic Water Pipe - Install (1) 2 ft x 2 ft access panel and replace 1 LF of 3/4 inch piping, (1) 3/4 inch 90 degree elbow, (1) 3/4 inch ball valve, (1) 3/4 inch coupling, (2) 1/2 inch ball valve, (2) 1/2 inch brass tee, (4) 1/2 inch x 2 1/2 inch brass fitting, (2) 1/2 inch threaded adapter, and (2) 1/2 inch x 1/4 inch bushings to hot water supply line within wall located in mens restroom on 4th floor. Hot water supply line failed due to age allowing water to leak onto the 4th floor mens and womens restroom. Environmental oversight and remediation required due to category 2 water. Erect (1) 2 ft x 4 ft x 7 ft containment and clean and sanitize the affected surfaces.	\$ 19,982	\$ 15,420	77
250	FM-2008369	Kern	Ridgecrest - Division B Courtroom	15-J2	1	lumbir	Plumbing - Replace (1) 2 inch domestic backflow preventer, (1) 1 inch irrigation backflow preventer, 16 LF of 2 inch piping and 16 LF of 1 inch piping from the meter to backflows. The domestic backflow preventer and underground pipe failed due to age allowing water to leaked underground creating a safety hazard. During the work the Irrigation line was identified as being in poor condition requiring replacement. Remove 2 ft x 6 ft area of concrete and excavate 2 ft deep trench to locate leak and replace piping.	\$ 10,527	\$ 10,527	100.00
251	FM-2008370	Los Angeles	East Los Angeles Courthouse	19-V1	1	lumbir	Plumbing - Domestic Water Pipe Leak - Replace 40 LF of 2 inch cast iron pipe, (30) 2 inch bands, (8) 3 inch bands, (4) 90 degree 3/4 inch copper fittings, (2) 3/4 inch couplings, (2) 3/4 inch x 45 inch bends, (1) 3/4 inch x 1/2 inch reducer, (1) 10 ft x 3/4 inch copper pipe, 5 SF of plaster ceiling, 8 SF of 2 ft x 2 ft ceiling tiles, 8 SF of 2 ft x 2 ft carpet tiles, and 60 SF of drywall with joint compound for wall cavities on the 3rd, 2nd, 1st, and the basement jury assembly room. The copper and cast iron pipes failed due to age, allowing water to leak down to the floors below.	\$ 48,004	\$ 37,309	78
252	FM-2008373	San Bernardino	Juvenile Dependency Courthouse	36-P1	1	Protect	Fire Protection - Replace (18) fire sprinklers heads, (2) chrome escutcheons, (1) post indicator valve, (1) sprinkler backflow preventer, restore (2) gate valves, and install (1) breakaway lock and chain for gate valve located on the exterior of the building. Parts failed due to age and were identified during 5 year preventive maintenance affecting the fire system throughout the building.	\$ 12,462	\$ 6,796	54.53
253	FM-2008378	Los Angeles	Compton Courthouse	19-AG1	1	ior Fin	Interior Finishes - Mechanically clear 25 LF of sewer drain line in the 4th floor mens public restroom and replace (6) 1 ft x 1 ft ceiling tiles on the 3rd floor east public hallway. A blocked toilet allowed water to overflow and travel down to the 3rd floor damaging the ceiling tiles. Blockage was not recovered. Environmental oversight and remediation required for category 2 water. Erect (1) 4 ft x 11 ft x 11 ft containment, (1) 36 inch x 76 inch decontamination chamber and clean and sanitize 360 SF of floor tiles, walls, and metal T-bar due.	\$ 14,272	\$ 9,438	66.13
254	FM-2008379	Los Angeles	Compton Courthouse	19-AG1	1	lumbir	Plumbing - Replace (15) push button valve assemblies and associated parts in the basement holding cells. Valves failed due to age allowing water to leak from the toilets when flushed.	\$ 5,545	\$ 5,545	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
255	FM-2008384	San Bernardino	Fontana Courthouse	36-C1	1	HVAC	HVAC - Condensation Leak - Pneumatically clear AC condensate drain line in court exclusive IT room. The drain line was blocked allowing water to leak onto the carpet. Environmental oversight and remediation required for category 2 water. Clean, dry, and sanitize 48 SF of carpet.	\$ 11,856	\$ 11,856	100
256	FM-2008386	Los Angeles	Airport Courthouse	19-AU1	1	HVAC	HVAC - Replace 3 LF of 3/4 inch copper pipe, and (10) 2 x 2 ft ceiling tiles and clear debris within the heating discharge line leading to VAV boxes in the 1st floor administration office area. The pipe failed due to age allowing water to leak on the ceiling tiles below. Debris in line impacting temperatures throughout the 1st floor and cafeteria.	\$ 7,945	\$ 6,131	77
257	FM-2008389	Los Angeles	Santa Monica Courthouse	19-AP1	1	Escalators	Elevators, Escalators, & Hoists - Replace (1) hydraulic pump system and restore piston seals on elevator 2. The pump failed due to age.	\$ 35,873	\$ 28,157	78.49
258	FM-2008393	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing	Plumbing - Fixture Leak - Replace (1) flush valve assembly and associated parts for toilet in 6th floor south holding cell. Valve assembly failed due to age allowing water to leak through the pipe chase and on 5th floor office floor.	\$ 3,308	\$ 3,308	100.00
259	FM-2008394	San Mateo	Northern Branch Courthouse	41-C1	1	HVAC	HVAC - Replace (1) BMS module and (1) communication line from janitors closet to module in chiller room, and recalibrate chiller 2. The module failed due to age impacting communication to multiple zones, affecting HVAC and lighting. Parts are no longer manufactured, and required secondhand replacement.	\$ 16,935	\$ 14,092	83
260	FM-2008395	Los Angeles	Van Nuys Courthouse East	19-AX1	1	Interior Finishes	Interior Finishes - Replace 30 SF of plaster ceiling in the 1st floor clerks restroom closet. The ceiling has cracks due to age. Work required to prevent the ceiling from falling. Environmental oversight and remediation required for ACM. Erect (1) 3 ft x 7 ft containment barrier and decontamination chamber.	\$ 18,689	\$ 18,689	100.00
261	FM-2008396	San Diego	Central Courthouse	37-L1	1	Vandalism	Vandalism - Replace (1) 31 3/4 inch x 38 7/8 inch clear 1/4 thick mirror in the 4th floor mens public restroom. Mirror was vandalized by an unknown person.	\$ 4,297	\$ 4,297	100
262	FM-2008401	Los Angeles	Chatsworth Courthouse	19-AY1	1	HVAC	HVAC - Replace (1) 60 hp motor, (4) belts, and (2) pulleys for air handler 3. Motor failed due to age, causing no air supply to the southeast end of the building, affecting court operations.	\$ 23,334	\$ 19,554	83.80
263	FM-2008404	Merced	Charles James Ogletree, Jr. Courthouse	24-A8	1	HVAC	HVAC - Replace (1) 30 ton compressor on package unit 2. Compressor failed due to age, impacting building conditioning. Costs include a crane pick and weekend labor.	\$ 28,593	\$ 28,593	100.00
264	FM-2008405	Merced	Charles James Ogletree, Jr. Courthouse	24-A8	1	Vandalism	Vandalism - Replace (1) 73 inch x 48 inch insulated glazing for main entrance window. Window was broken by an unknown person. Costs include emergency response cleanup and temporary board up of window.	\$ 2,527	\$ 2,527	100.00
265	FM-2008411	Merced	Charles James Ogletree, Jr. Courthouse	24-A8	1	HVAC	HVAC - Replaced (3) electrical load contactors on AHU 2 motor. Contactors failed due to age, impacting cooling capacity. Provided (4) temporary cooling units for (5) days of supplemental cooling.	\$ 6,174	\$ 6,174	100
266	FM-2008412	San Diego	Central Courthouse	37-L1	1	Escalators	Elevators, Escalators, & Hoist - Replace (1) global elevator control board on Judges elevator 2. The control board failed due to age resulting in the elevator in the elevator not operating. If not repaired, will leave only one staff elevator to serve high-rise.	\$ 8,765	\$ 8,765	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
267	FM-2008416	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Escalator	Elevators, Escalators, & Hoists - Adjust (2) chain ropes for public elevators 5 and 8. Elevators are not leveled due to a stretched chain, placing them out of service.	\$ 18,386	\$ 14,797	80.48
268	FM-2008417	Los Angeles	Inglewood Courthouse	19-F1	1	HVAC	HVAC - Replace (1) condenser water pressure transducer on chiller 1 and (1) pressure regulation module, (1) resistor, (1) liquid temperature sensor, and (1) condenser water pressure transducer on chiller 2. The components failed due to a power surge resulting in the chillers being non-responsive.	\$ 13,324	\$ 9,934	74.56
269	FM-2008420	Los Angeles	Burbank Courthouse	19-G1	1	Plumbing	Plumbing - Replace 5 LF of 2 inch copper pipe and 5 LF of 1 1/2 inch copper pipe and all associated fittings for standpipe located in basement elevator lobby. The pipe has failed due to age leaking water on to the floor.	\$ 5,979	\$ 5,427	90.76
270	FM-2008421	Los Angeles	Pomona Courthouse North	19-W2	1	Plumbing	Plumbing - Replace 1 LF of 1/2 inch copper pipe and associated fittings for domestic hot water. The copper pipe failed due to age affecting 1st floor courtroom jury room and leaked down to basement storage room. Environmental oversight and remediation required for ACM and category 2 water. Erect (1) 3 ft x 7 ft critical barriers, (1) 5 ft x 5 ft x 10 ft containment, clean, dry and sanitized 200 SF of floors and walls.	\$ 19,136	\$ 18,419	96.25
271	FM-2008097	Los Angeles	County Records Center	19-AV3	1	Security	County Managed - Security - Replace the loading dock pedestrian double doors. Doors have failed due to age and can no longer be repaired. Doors are manually closed and locked nightly to prevent intrusion.	\$ 13,950	\$ 13,950	100.00
272	FM-2008111	Los Angeles	County Records Center	19-AV3	1	Security	County Managed - Security - Replace loading dock roll up fire door. Door failed to operate during Fire Inspection initiating corrective action. Door failed due to age.	\$ 37,200	\$ 37,200	100.00
273	FM-2008324	Ventura	East County Courthouse	56-B1	1	Security and Parking	Security - Grounds and Parking Lot - Replace (1) gate operator with battery backup and (1) safety edge for judges entrance gate. Gate operator and safety edge failed due to age.	\$ 9,689	\$ 9,689	100.00
274	FM-2008340	Los Angeles	Van Nuys Courthouse East	19-AX1	1	Security	Security - Replace (2) control boards for secured parking gate. The control boards failed due to a short, causing the doors to remain open.	\$ 7,695	\$ 6,905	90
275	FM-2006801	Alameda	Wiley W. Manuel Courthouse	01-B3	2	Plumbing	Plumbing - Replace (10) flush valves on the 6th floor holding cells. In-custodies are purposely blocking and repeatedly flushing the toilets, flooding the holding cells. This issue has been recurring resulting in costly damages and loss of operational time for the courts. A programmable flush system will be installed, limiting the number of times in custodies can flush the toilets. The system includes (10) flushometer valves, (10) push buttons, (4) control modules, (4) plug in transformers to power the modules and related electrical work.	\$ 95,101	\$ 95,101	100.00
276	FM-2007356	Los Angeles	Metropolitan Courthouse	19-T1	2	Vandalism	Vandalism - Restore a total 28 SF of granite in (6) exterior areas. The granite was damaged by an unidentified person. Prepare all surfaces, fill voids, add forms to match existing stone, apply cementitious polymer, finish sand surface, and grout the joints.	\$ 20,149	\$ 19,049	94.54
277	FM-2007482	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Interior Finishes	Interior Finishes - Replace 2 in x 4 in x 7 ft wood floor joists, 20 SF of 5/8 inch plywood, and 20 SF of carpet on the 7th floor judges bench. The floor joists have failed due to age. Resulting in the sagging of the bench area and creating a trip hazard. The project includes replacing and reconstructing floor supports for the judges seating area, closing the subflooring, reinstalling carpeting, and returning the furniture to its original place. Work to be performed after hours.	\$ 15,181	\$ 12,218	80.48



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
278	FM-2007569	Los Angeles	Inglewood Courthouse	19-F1	2	Protect	Fire protection - Replace (1) fire pump module. Module failed due to age, impacting the fire pumps operation. Work will occur after hours.	\$ 4,592	\$ 3,424	74.56
279	FM-2007614	Los Angeles	Santa Monica Courthouse	19-AP1	2	Protect	Fire Protection - Replace (1) 5-inch waterflow switch, 10 LF of 5-inch grooved pipe, and (2) control valve signs. Components failed due to age. Work requires draining and refilling the fire suppression system.	\$ 7,745	\$ 6,079	78
280	FM-2007615	Los Angeles	Santa Monica Courthouse	19-AP1	2	andalis	Vandalism - Replace (1) 38 inch x 58 inch glass pane above the main entrance. Window broken by an unidentified person.	\$ 4,722	\$ 3,706	78
281	FM-2007618	Los Angeles	Santa Monica Courthouse	19-AP1	2	ior Fin	Interior Finishes - Replace (90) 12 x 12 inch vinyl floor tiles in first floor public foyer to clerks office. Tiles are damaged due to age causing a tripping hazard. Environmental oversight and remediation required for ACM.	\$ 24,864	\$ 19,516	78
282	FM-2007693	Stanislaus	Hall of Records	50-A2	2	HVAC	HVAC - Replace 3/4 HP fan motor unit on computer room air conditioner Unit 1 in main server room. Fan motor failed due to age impacting cooling to the room.	\$ 2,763	\$ 1,292	47
283	FM-2007742	Los Angeles	Santa Monica Courthouse	19-AP1	2	lumbir	Plumbing - Replace (1) drinking fountain, (1) angle stop, (1) 1/4 inch roll soft copper trap, (1) 1-1/2 inch adapter (1) 1/5 inch cast brass drinking fountain P-trap, (1) 1-1/2 inch double extension tail piece, and (1) 6 inch brass threaded coupler in the 2nd floor courtroom. Water fountain failed due to age and is non-operational.	\$ 6,363	\$ 6,363	100
284	FM-2007747	Los Angeles	Santa Monica Courthouse	19-AP1	2	lumbir	Plumbing - Install (2) gas meters, (2) 2 inch flanges, and (1) debris screen at boilers 1 and 2. The meters are a new Air Quality Management District (AQMD) requirement to monitor gas consumption.	\$ 15,991	\$ 12,552	78.49
285	FM-2007749	San Mateo	Hall of Justice	41-A1	2	lectric	Electrical - Replace 400 LF of metal wire chase, 1200 LF metal clad wiring, and 82 fluorescent light fixtures. Wiring failed due to age, resulting in a small fire in the courtroom. Install 340 LF of 3/1 metal clad wiring and 64 LED light fixtures with dimmable control.	\$ 59,297	\$ 59,297	100.00
286	FM-2007750	San Diego	North County Regional Center - South	37-F1	2	escalate	Elevators, Escalators, & Hoists - Replace (1) light key switch, (1) lock switch, (1) door restrictor, and (1) fire inspection key switch for in-custody elevator 5. Switches and restrictor failed due to age. The deficiencies were identified during annual inspection.	\$ 3,100	\$ 3,100	100.00
287	FM-2007753	Los Angeles	Eastlake Juvenile Court	19-R1	2	lectric	Electrical - Replace (6) 10 x 50 inch light lens covers, (8) T8 lamps, (4) lamp ballasts, (2) 20 AMP breakers, and 10 SF of carpet tiles in the 2nd floor courtroom, judges chambers, and interview room. Light fixture failed due to age creating an electrical short, resulting a small fire. The remaining light fixture components are being replaced as a precaution. Environmental oversight and remediation required due to smoke and soot. Clean and sanitize 2,550 SF of carpet flooring, walls, ceilings, and lighting	\$ 40,767	\$ 40,767	100
288	FM-2007756	Fresno	Fresno County Courthouse	10-A1	2	HVAC	HVAC - Replace (3) pressure sensors in the mechanical room in basement 2. The sensors have failed due to age, preventing the EMS from communicating with the economizer control and impacting courthouse cooling.	\$ 3,410	\$ 3,271	96



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
289	FM-2007758	Alameda	Wiley W. Manuel Courthouse	01-B3	2	HVAC	HVAC - Replace (1) 3/4 inch galvanized union and (6) 1 ft x 1 ft ceiling tiles in the basement lobby. The union failed due to age allowing water to leak onto the ceiling tiles and flooring. Environmental testing included, clean and sanitize 15 SF of carpet.	\$ 4,482	\$ 3,756	83.80
290	FM-2007761	Santa Clara	Hall of Justice (West)	43-A2	2	Interior Finishes	Interior Finishes - Install (1) 36 inch push bar on the 4th floor courtroom door. The push bar failed due to age impacting the doors operation.	\$ 4,224	\$ 4,224	100
291	FM-2007763	Fresno	Fresno County Courthouse	10-A1	2	Plumbing	Plumbing - Replace 10 LF of 1/2 inch copper piping and adjoining fitting on the domestic water line above holding cells 1 and 2. The pipe failed due to age allowing water to leak from the system.	\$ 2,188	\$ 2,099	96
292	FM-2007764	Alameda	Berkeley Courthouse	01-G1	2	Fire Protection	Fire Protection - Replace (1) 300 psi pressure gauge, (33) sprinkler heads, (1) 2 inch 90 degree elbows, (1) brass cover on the first floor, (1) post indicator valve sign, (1) Fire department connection identification sign, and (1) hydraulic calculation placard. The deficiencies were identified during the 5-year sprinkler certification testing.	\$ 13,209	\$ 13,209	100.00
293	FM-2007765	Humboldt	Humboldt County Courthouse (Eureka)	12-A1	2	Electrical	Electrical - Replace 19 ballasts and lamps in (19) T-8 fixtures in third floor office. Ballasts are failing due to age, impacting office lighting.	\$ 7,115	\$ 7,115	100.00
294	FM-2007769	Del Norte	Del Norte County Superior Court	08-A1	2	Electrical	Electrical - Replace (2) photocell lights and associated wall boxes on the north and west sides of the building and (1) photocell light and associated wall box at the flagpole. The lights are failing due to age.	\$ 2,769	\$ 1,697	61.27
295	FM-2007774	San Diego	Hall of Justice	37-A2	2	Interior Finishes	Security - Interior Finishes - Replace (1) motor gear box and controller on doorway between secured hallway and courtroom. The components have failed due to age preventing the door from properly closing. Work also includes resetting the closer arm to the proper operating position.	\$ 5,900	\$ 5,900	100.00
296	FM-2007775	Monterey	Salinas Courthouse-North Wing	27-A1	2	Electrical	Electrical - Replace (8) can light ballasts and LED drivers. Lights have failed due to age impacting lighting levels and security screening. Work requires lift to access fixtures.	\$ 8,303	\$ 8,303	100
297	FM-2007778	San Diego	South County Regional Center	37-H1	2	Plumbing	Plumbing - Replace (2) 1 1/2 HP chilled water pumps and (2) 3-HP heating hot water pumps located in mechanical room. Pumps are failing due to age and will impact cooling and heating to the courthouse. Work to be performed after-hours.	\$ 3,395	\$ 3,395	100
298	FM-2007781	Santa Clara	Downtown Superior Court	43-B1	2	Fire Protection	Fire Protection - Replace (1) 4 inch fire department connection check valve. The valve failed due to age, allowing water to leak from the system and impacting fire water supply pressure to the building. The deficiency was identified during the 5-year inspection. Work will be completed on the weekend to minimize court impacts.	\$ 9,365	\$ 9,365	100.00
299	FM-2007797	Orange	Betty Lou Lamoreaux Justice Center	30-B1	2	Plumbing	Plumbing - Replace (1) floor drain assembly in the 3rd floor mens public restroom. The P-trap failed due to age, allowing water to leak onto the 2nd floor ceiling. Access to drain from ceiling below through existing access panel.	\$ 3,254	\$ 2,602	79.95



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
300	FM-2007799	San Diego	Hall of Justice	37-A2	2	Interior Finishes	Security - Interior Finishes - Replace (1) motor gear box and controller and restoring the arm for 3rd floor judges courtroom access door. Gear box failed due to age resulting in the door not closing properly.	\$ 4,163	\$ 4,163	100
301	FM-2007800	Riverside	Riverside Hall of Justice	33-A3	2	Protection	Fire Protection - Replace (1) 2 inch standpipe check valve in stairwell 5. The valve failed due to age and was discovered during the 5 year fire sprinkler certification.	\$ 6,253	\$ 6,253	100.00
302	FM-2007804	San Joaquin	Stockton Courthouse	39-F1	2	Escalators	Elevators, Escalators, & Hoists - Replace Encoder on Escalator 4. The encoder failed due to age preventing the escalator from operating.	\$ 6,046	\$ 6,046	100
303	FM-2007805	Riverside	Southwest Justice Center	33-M1	2	Plumbing	Plumbing - Replace (1) check valve on the 8 inch fire service backflow preventer. The check valve failed due to age and was identified during annual testing.	\$ 7,441	\$ 5,685	76.4
304	FM-2007806	San Diego	North County Regional Center - Annex	37-F3	2	Plumbing	Plumbing - Replace (2) 1 1/2 HP chilled water pumps and (2) 3-HP heating hot water pumps located in mechanical room. Pumps are failing due to age and will impact cooling and heating to the courthouse. Work to be performed after-hours.	\$ 47,589	\$ 47,589	100
305	FM-2007809	Orange	Central Justice Center	30-A1	2	Interior Finishes	Interior Finishes - Remodel the 2nd floor restroom and shower room into (1) accessible restroom. Work includes demolition of the existing restroom and shower room, infilling the door between the conference room and restroom, and installing new finishes and fixtures. Environmental oversight and remediation is required for ACM.	\$ 53,246	\$ -	0
306	FM-2007812	Contra Costa	Wakefield Taylor Courthouse	07-A2	2	HVAC	HVAC - Restore the expansion valve terminal and oil recovery system on Chiller 1. The components failed due to age allowing refrigerant to leak from the system and was identified during preventative maintenance. Work to be completed on the weekend.	\$ 11,808	\$ 11,808	100
307	FM-2007816	Los Angeles	Norwalk Courthouse	19-AK1	2	Interior Finishes	Interior Finishes - Replace (2) 1 ft x 1 ft ceiling tiles in the 1st floor clerks office. Ceiling tiles fell due to age. Environmental oversight and remediation required due to ACM. Erect (1) 5 ft x 5 ft x 12 ft containment and sanitize 265 SF of floor and walls.	\$ 11,741	\$ 11,741	100
308	FM-2007822	Los Angeles	Inglewood Courthouse	19-F1	2	Escalators	Elevators, Escalators, & Hoists - Replace (1) regeneration drive on Elevator 3. Current drive failed due to age and the elevator is non-operational.	\$ 21,910	\$ 16,336	74.56
309	FM-2007829	Los Angeles	East Los Angeles Courthouse	19-V1	2	Interior Finishes	Interior Finishes - Replace (1) 36 inch x 84 inch 20 minute fire rated entrance double door to the 3rd floor courtroom. The door is failing due to age, impacting its fire rating and ability to latch properly. Work to be completed after-hours to not disrupt Court operations.	\$ 13,004	\$ 13,004	100.00
310	FM-2007830	San Diego	Central Courthouse	37-L1	2	Escalators	Elevators, Escalators, & Hoists- Replace (3) voice indicators on elevators 1, 5, and 7 and (4) arrival gongs on elevators 1, 4, 7, and 8. Elevators voice directional travel and arrival gong indicator failed due to age and not announcing when elevator is moving up or down on any floors	\$ 7,084	\$ 7,084	100.00
311	FM-2007835	San Bernardino	Fontana Jury Assembly Building	36-C3	2	Electrical	Electrical - Replace 100 LF of existing wiring on affected circuit that feeds the UPS in the server rack. Circuit failed due to age resulting in voltage loss to the UPS. Work is needed to prevent the UPS from faulting and or possibly damage the equipment.	\$ 5,191	\$ 5,191	100
312	FM-2007837	Riverside	Southwest Justice Center	33-M1	2	HVAC	County Managed - HVAC - Replace failing motor, bearings, shaft and fan hub of cooling tower 1. Part have failed due to age and usage. Work includes use of crane for installation and removal of the fan.	\$ 9,626	\$ 9,626	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
313	FM-2007838	San Diego	South County Regional Center	37-H1	2	lumbir	Plumbing - Replace 20 LF of 3/8 inch, 10 LF of 3/4 inch, 10 LF of 1/2 inch copper pipe, (2) faucets, (2) isolation valves, (2) check valves, (10) 3/8 inch brass fittings, (21) copper fittings, (1) mounting bracket, and (2) hammer arrestors at cafeteria dishwashing sink on 1st floor. Faucet and piping are leaking and corroded due to age. Afterhours isolation of kitchen hot and cold water required.	\$ 11,195	\$ 11,195	100
314	FM-2007840	San Diego	North County Regional Center - North	37-F2	2	and Pa	Grounds and Parking Lot - Replace 100 bricks and 170 LF of 4 inch decorative concrete at the main entrance. The bricks and concrete have failed due to soil movement caused by moisture resulting in damaged bricks and trip hazards.	\$ 18,722	\$ 18,722	100.00
315	FM-2007842	Orange	Betty Lou Lamoreaux Justice Center	30-B1	2	Protect	Fire Protection - Replace 10 LF of 6 inch sprinkler line and (6) fittings. The pipe and fittings have failed due to age, allowing water to leak from the system and were discovered during building rounds.	\$ 4,777	\$ 3,819	79.95
316	FM-2007843	Riverside	Riverside Juvenile Court	33-N1	2	HVAC	HVAC - Replace (1) chiller control panel on chillers 1 and 2. The panels failed due to age impacting cooling to the building.	\$ 57,100	\$ 28,173	49.34
317	FM-2007844	Los Angeles	Torrance Courthouse	19-C1	2	lumbir	Plumbing - Domestic Water Pipe Leak - Replace 5 LF of 6 inch copper pipe, 15 LF of 1 inch copper pipe, 10 LF of 3/4 inch copper pipe, (1) 1 inch ball valve, and (2) 3/4 inch valves in the mechanical room. Pipes failed due to age resulting in water leaking from the pipes.	\$ 18,014	\$ 15,337	85.14
318	FM-2007845	Los Angeles	Torrance Courthouse	19-C1	2	rior Fin	Interior Finishes - Replace (1) 20 inch floor door closer on 5th floor courtroom door. The door closer failed due to age allowing the door to slam shut.	\$ 6,069	\$ 5,167	85.14
319	FM-2007848	San Bernardino	Barstow Courthouse	36-J1	2	lumbir	Plumbing - Replace (1) angle stop for drinking fountain on 2nd floor public hallway. Stop failed due to age allowing water to leak onto the floor.	\$ 2,597	\$ 2,597	100.00
320	FM-2007870	San Joaquin	Stockton Courthouse	39-F1	2	escalator	Elevators, Escalators, & Hoists - Replace Controller on Escalator 1. The controller failed due to age preventing the escalator from operating.	\$ 2,486	\$ 2,486	100.00
321	FM-2007873	Riverside	Riverside Juvenile Court	33-N1	2	lumbir	Plumbing - Replace (1) 3-inch domestic backflow preventer. The backflow preventer has failed due to age impacting water flow to the building and was identified during yearly testing. New backflow preventer will be constructed of stainless steel.	\$ 8,997	\$ 4,439	49.34
322	FM-2007876	Calaveras	Calaveras Superior Court	05-C1	2	HVAC	HVAC - Replace (2) temperature sensors, (2) VAV controllers and (1) 120V - 24V transformer on chiller 1. The components failed due to age, impacting building cooling.	\$ 6,643	\$ 6,643	100
323	FM-2007878	San Francisco	Civic Center Courthouse	38-A1	2	rior Fin	Interior Finishes - Install (2) fabricated stainless steel door wrap and re-enforcements at courtroom entrance doors. Internal vertical locking rods are splitting wood door stiles on latch side due to use.	\$ 8,208	\$ 8,208	100.00
324	FM-2007879	Santa Clara	Morgan Hill Courthouse	43-N1	2	HVAC	HVAC - Replace burners and gaskets at boiler 2. The burners failed due to age and were found during Preventive Maintenance.	\$ 7,167	\$ 7,167	100
325	FM-2007880	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	2	HVAC	HVAC - Replace (2) condenser pump motors and (2) chilled water pump motors. The motors bearing have failed due to age and are vibrating, creating a lot of noise, and impacting building cooling.	\$ 20,388	\$ 17,191	84.32
326	FM-2007881	Stanislaus	Ceres Superior Court	50-C1	2	HVAC	HVAC - Replace blower fan motor and capacitor on interior AC unit. Components failed due to age impacting cooling in the courtroom and admin areas.	\$ 2,096	\$ 2,096	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
327	FM-2007882	Fresno	Fresno County Courthouse	10-A1	2	Plumbing	Plumbing - Replace (1) wall mounted drinking fountain and associated piping. The drinking fountain has failed due to age and corrosion, allowing water to leak onto the floor in basement level 2 public hallway.	\$ 4,834	\$ 4,636	95.91
328	FM-2007892	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Escalators	Elevators, Escalators, & Hoists - Replace 70 SF of rubber flooring in freight elevator 1. The flooring has failed due to use. Install new metal diamond plate flooring.	\$ 34,981	\$ 34,023	97.26
329	FM-2007896	Los Angeles	East Los Angeles Courthouse	19-V1	2	Plumbing	Plumbing - Replace (2) sewage column pump assemblies. The pumps failed due to age allowing water to flood the mechanical room. The flooding was mitigated under a separate FM.	\$ 64,334	\$ 50,001	77.72
330	FM-2007905	Santa Clara	Hall of Justice (East)	43-A1	2	Escalators	Elevators, Escalators, & Hoists - Replace 40 SF of flooring in elevators 8 and 9. Flooring has failed due to age and use. Work includes work required by the AHJ to test and certify the elevators to maintain the load permit. Environmental oversight and remediation required for ACM. FM is for labor only as the county provided the material from their attic stock.	\$ 8,358	\$ 8,358	100.00
331	FM-2007907	Napa	Criminal Court Building	28-A1	2	HVAC	HVAC - Replace (1) 2 inch tempering valve and one (1) 2 inch ball valve for boiler. Includes Components have failed due to age and were discovered during preventative maintenance. Environmental testing costs included.	\$ 12,921	\$ 12,921	100.00
332	FM-2007908	Alameda	Hayward Hall of Justice	01-D1	2	HVAC	HVAC - Replace (1) 1 inch isolation valve, (2) 1 inch unions, (1) clogged strainer, and (1) pressure regulator on the heating hot water loop. The components failed due to age, resulting in water leaking from the system. The deficiencies we discovered during rounds and readings. Work required boiler shutdown.	\$ 3,789	\$ 3,346	88
333	FM-2007912	Los Angeles	Norwalk Courthouse	19-AK1	2	HVAC	HVAC - Replace (1) 15 hp motor, (1) pulley, (1) belt, and (1) bushing for cooling tower 1. Motor and parts failed due to age, impacting cooling to the building.	\$ 10,998	\$ 9,352	85.03
334	FM-2007914	Mendocino	Ft. Bragg Justice Center	23-B1	2	and Parking	County Managed - Grounds and Parking lot - Replace (1) 16 ft chain link security gate at the judges parking. The gate is failing due to age, impacting the judges ability to enter and exit the parking lot.	\$ 13,756	\$ 13,756	100
335	FM-2007917	San Bernardino	Historic Courthouse	36-A1	2	Plumbing	Plumbing- Domestic Water Line Leak - Replaced 3 LF of 2 inch copper pipe, (2) 2 inch 90 degree elbow fittings, (1) 2 inch copper coupling, and wrap new piping with 20 MIL tape. Pipe failed due to age causing water to leak from the city meter box to the building.	\$ 5,882	\$ 5,659	96.21
336	FM-2007918	Alameda	Fremont Hall of Justice	01-H1	2	Roof	Roof - Patch 200 SF of sloped roofing and flashing at vertical building wall. Roof and flashing is leaking due to age, into 2nd floor court reporters office. Prep wall, apply waterproof coating and paint to match.	\$ 8,615	\$ 6,841	79.4
337	FM-2007934	San Diego	Central Courthouse	37-L1	2	Security	Security - Replace (1) 26 inch x 34 1/2 inch detention glass for holding cell door. Holding Cell window has been damaged by an in-custody and restitution is being sought.	\$ 14,089	\$ 14,089	100
338	FM-2007939	Riverside	Riverside Juvenile Court	33-N1	2	HVAC	HVAC - Replace (1) 1 1/2 ton split system serving the data room. The split unit is failing due to age, impacting cooling to the server room. The deficiency was discovered during the monthly preventative maintenance.	\$ 22,996	\$ 22,996	100
339	FM-2007941	San Diego	Hall of Justice	37-A2	2	HVAC	County Managed - HVAC - Replace (1) flow meter for boiler 1 on 14th floor mechanical room. Flow meter failed due to age and causing boiler to malfunction.	\$ 4,219	\$ 4,219	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
340	FM-2007944	Orange	Central Justice Center	30-A1	2	erior S	Exterior Shell - Replace (3) 12 ft x 6 inch slats, (4) endlocks, and (1) bottom rail on the sally port rollup door. The gate was damaged by a Sheriffs vehicle exiting the bus bay causing damage to the bottom section of the door, resulting in the door malfunctioning. Insurance reimbursement is being sought.	\$ 6,366	\$ 6,366	100.00
341	FM-2007945	Santa Barbara	Figueroa Division	42-B1	2	Protect	Fire Protection - Replace (3) fire sprinkler heads. The fire sprinkler heads have corroded and will not operate properly. The deficiency was discovered during annual preventative maintenance.	\$ 3,063	\$ 3,063	100
342	FM-2007951	San Diego	East County Regional Center	37-I1	2	rior Fin	Interior Finishes - Replace (2) panic bars for 1st floor double doors leading to judges chambers hallway. Panic Bars failed due to age impacting their operation.	\$ 3,244	\$ 3,244	100
343	FM-2007958	Orange	North Justice Center	30-C1	2	HVAC	HVAC - Replace (1) chilled water pump of chiller 1. The pump motor overloaded, tripped, and seized necessitating replacement. Water pump provides HVAC to 1/3 of the building.	\$ 6,143	\$ 5,548	90.31
344	FM-2007961	Los Angeles	Santa Monica Courthouse	19-AP1	2	and Pa	Grounds and Parking lot - Replace (1) guidewire on existing flagpole. Current guidewire is broken beyond repair due to age.	\$ 3,647	\$ 2,863	78.49
345	FM-2007965	Santa Clara	Morgan Hill Courthouse	43-N1	2	Protect	Fire Protection - Replace (3) sprinkler heads at first floor hallway by break room, and (1) sprinkler head at main lobby stairway. Deficiencies found during 5-year certification inspection. Stairwell sprinkler head replacement requires staged scaffolding due to high ceiling.	\$ 17,776	\$ 17,776	100.00
346	FM-2007967	San Bernardino	Victorville Courthouse	36-L1	2	Escalator	Elevators, Escalators, & Hoists - Replace (1) door lock on courtroom chair lift. Lock failed due to age and was identified during preventive maintenance.	\$ 3,194	\$ 3,194	100.00
347	FM-2007974	San Diego	South County Regional Center	37-H1	2	rior Fin	Interior Finishes - Replace four (4) sets of courtroom ID numbers at courtrooms 12, 14, 15 & 16. The numbers have broke off due to age. Fabricate new lettering and remount at entrance to courtrooms.	\$ 3,183	\$ 3,183	100
348	FM-2007976	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	olding C	Holding Cell - Restore motor for 2nd floor holding cell door. Motor is shorting out the relay causing the door to lose power and not work properly.	\$ 4,626	\$ 4,626	100.00
349	FM-2007977	Los Angeles	Airport Courthouse Parking Structure	19-AU2	2	Protect	Fire Protection - Replace (1) 10 inch check valve, and (1) 10 inch relief valve to the backflow preventer. The valves failed due to age and was unable to stop water backflow. The deficiency was identified during annual preventative maintenance testing.	\$ 3,056	\$ 2,358	77.17
350	FM-2007979	San Bernardino	San Bernardino Justice Center	36-R1	2	erior S	Exterior Shell -Restore (1) roll up door barrel and (1) spring, and replace (15) slats on Judges roll up door in the secured parking lot. Parts failed due to age impacting the doors operation. Work to be completed afterhours.	\$ 45,179	\$ 45,179	100
351	FM-2007982	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	lumbing	Plumbing - Replace (1) push button valve on water faucet in the holding cell. Part failed due to calcium buildup affecting the water pressure.	\$ 4,317	\$ 4,317	100
352	FM-2007989	Tehama	Tehama County Courthouse	52-E1	2	Escalator	Elevators, Escalators, & Hoists - Replace the packing on Elevator 1. The packing has failed due to use, impacting the elevators operation.	\$ 4,748	\$ 4,748	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
353	FM-2007990	San Diego	North County Regional Center - North	37-F2	2	Plumbing	Plumbing - Replace (1) wall-mounted drinking fountain and restore 16 SF of drywall in the public hallway. The drinking fountain failed due to age leaking water onto the floor. Environmental oversight and remediation required for category 2 water. Erect (1) 4 ft x 6 ft x 8 ft containment.	\$ 22,655	\$ 22,655	100
354	FM-2007991	Los Angeles	Metropolitan Courthouse	19-T1	2	Escalators	Elevators, Escalators, & Hoists - Replace (2) fuses on public elevator 5. The fuses failed due to use, resulting in the elevator shutting down.	\$ 2,750	\$ 2,600	94.54
355	FM-2007992	San Diego	Central Courthouse	37-L1	2	Plumbing	Plumbing - Install (12) pipe braces for 15 LF of 1-1/2 inch copper water pipe in basement exhibit room. The pipe move due to water pressure changes, which can result in premature failure.	\$ 3,816	\$ 3,816	100.00
356	FM-2007997	Los Angeles	Mental Health Court	19-P1	2	Vandalism	Vandalism - Restore 5 LF of a 6 ft x 2 inch mesh fencing and (1) 6 ft high post. The parking fencing has been vandalized by unknown individuals.	\$ 2,423	\$ 1,728	71.31
357	FM-2007998	Los Angeles	Mental Health Court	19-P1	2	Vandalism	Vandalism - Remove graffiti around the perimeter of the building. The facility has large amounts of graffiti on the exterior walls and fencing.	\$ 2,985	\$ 2,129	71.31
358	FM-2008000	Orange	Central Justice Center	30-A1	2	Fire Protection	Fire Protection - Replace (38) sprinkler heads and (1) auxiliary drain down valve in the basement holding. The sprinkler heads and drain are obsolete, and the drain failed due to rust from lack of use. All other sprinkler heads were previously replaced. Environmental testing costs are included.	\$ 12,421	\$ 12,421	100
359	FM-2008001	San Diego	North County Regional Center - North	37-F2	2	Interior Finishes	Interior Finishes - Replace (4) panic bars and associated hardware on the west doors of the 1st floor secured hallways. Panic bars and associated hardware are failing due to age causing the door to not operate properly, causing egress issues. Work to occur after hours due to location near holding area.	\$ 35,011	\$ 35,011	100.00
360	FM-2008004	San Diego	East County Regional Center	37-I1	2	HVAC	HVAC - Replace (1) hot surface ignitor and (1) wiring terminal kit on boiler 3. The ignitor and wiring kit have failed due to age, resulting in a water flow error fault causing the boiler to shut down.	\$ 4,074	\$ 2,758	67.71
361	FM-2008008	Kern	Shafter/Wasco Courts Bldg.	15-E1	2	HVAC	HVAC - Install (1) blower shaft, (2) bearings, (2) bearing brackets, and (1) pulley for package unit 9. Equipment is failing due to age impacting cooling to the building.	\$ 2,913	\$ 2,621	89.95
362	FM-2008009	Los Angeles	Bellflower Courthouse	19-AL1	2	Plumbing	Plumbing - Replace (1) 4 inch domestic backflow preventer, 10 LF of copper pipe, and associated fittings. Backflow failed due to age allowing water to leak from the system. The new backflow preventer was raised 8 inches to comply with current codes and regulations.	\$ 15,362	\$ 11,973	77.94
363	FM-2008012	Los Angeles	Whittier Courthouse	19-AO1	2	Security	Security - Replace (1) 14 ft reversing edge and (1) 2 wire take up reel for the basement lockup rollup gate. Rollup gate failed due to age, affecting the gate from opening.	\$ 4,319	\$ 4,319	100
364	FM-2008018	Los Angeles	Whittier Courthouse	19-AO1	2	HVAC	HVAC - Replace (8) actuators, (8) damper assemblies and associated parts for the outside air dampers in the penthouse. Actuators and dampers failed due to age affecting the outside airflow and impacting cooling to the building.	\$ 20,656	\$ 17,853	86.43
365	FM-2008021	Butte	Butte County Courthouse	04-A1	2	HVAC	HVAC - Replace (1) 1.5 HP pump motor assembly on boiler 6. The motor failed due to excessive vibration resulting in the motor becoming unbalanced and the motor bearings failing. The deficiency was identified due to the loud noise coming from the motor.	\$ 2,572	\$ 2,572	100



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
366	FM-2008030	Riverside	Riverside Hall of Justice	33-A3	2	Protect	Fire Protection - Restore (1) metal door frame to the jury assembly room. The frame has failed due to age, resulting in the door not operating properly. Work includes recertifying the door and frame fire rating.	\$ 6,378	\$ 6,378	100
367	FM-2008032	Orange	Harbor Justice Center-Newport Beach Facility	30-E1	2	and Pa	Grounds and Parking Lot - Remove (6) trees adjacent to Birch St and the public parking lot. The trees are leaning, causing a potential safety hazard.	\$ 10,735	\$ 9,052	84.32
368	FM-2008033	Riverside	Banning Justice Center	33-G4	2	HVAC	HVAC - Replace (1) 5 hp fan motor serving Cooling Tower 2. The fan motor failed due to age impacting cooling to the building.	\$ 17,450	\$ 17,450	100
369	FM-2008037	Los Angeles	Whittier Courthouse	19-AO1	2	HVAC	HVAC - Replace (2) spray nozzles on cooling towers 1 and 2. Spray nozzles failed due to age impacting cooling to the building. Work includes draining and refilling both cooling towers.	\$ 6,366	\$ 5,502	86.43
370	FM-2008043	San Diego	South County Regional Center	37-H1	2	HVAC	County Managed - HVAC - Replace (1) heat exchanger on boiler 1. The heat exchanger has failed due to age impacting heating to the entire building.	\$ 4,315	\$ 4,315	100.00
371	FM-2008047	Los Angeles	Norwalk Courthouse	19-AK1	2	Security	Security - Replace (2) safety sensors with power supplies for the main public entrance doors. Sensors failed due to age, impacting the doors from closing automatically.	\$ 11,136	\$ 9,469	85.03
372	FM-2008058	San Diego	Central Courthouse	37-L1	2	Interior Fin	Interior Finishes - Place (1) automatic sliding door track and (4) rollers on 3rd floor pedestrian bridge door. Components failed due to use, impacting the doors operation. Work includes removal of the door to replace components.	\$ 10,609	\$ 10,609	100.00
373	FM-2008061	San Diego	Central Courthouse	37-L1	2	Plumbing	Plumbing - Replace (1) hot water blower assembly on hot water heater 3 and hot water heater 4 located in the 23rd floor mechanical room. The blower assemblies failed due to age impacting hot water to the entire building.	\$ 9,459	\$ 9,459	100.00
374	FM-2008062	Los Angeles	Whittier Courthouse	19-AO1	2	Interior Fin	Interior Finishes - AEI - Phase I - Provide design documents for the repair of the courthouse floor.	\$ 72,500	\$ 62,662	86.43
375	FM-2008073	El Dorado	Cameron Park	09-C1	2	Interior Fin	Interior Finishes - Replace (1) door handle and push bar on courtroom main door. The handle failed due to age preventing the door from operating properly.	\$ 4,074	\$ 4,075	100
376	FM-2008227	Los Angeles	Inglewood Courthouse	19-F1	2	Plumbing	Plumbing - Replace (1) stainless steel water fountain, (1) trap, (1) 1/2 inch angle stop, and (1) 1/2 inch supply line. Drinking fountain failed due to age and not operational.	\$ 4,643	\$ 3,462	75
377	FM-2008228	San Diego	Hall of Justice	37-A2	2	Plumbing	County Managed - Plumbing - Replace (1) 7 1/2 HP domestic water booster pump in the mechanical room. The pump failed due to age impacting domestic water pressure.	\$ 9,221	\$ 9,221	100
378	FM-2008234	Sierra	Courthouse/ Sheriff Station-Jail	46-A1	2	HVAC	County Managed - HVAC - Install (2) selector switches for HVAC Control system. The current system does not have controller switches resulting in the court administration offices HVAC operating non-stop.	\$ 2,168	\$ 2,169	100.00
379	FM-2007352	Los Angeles	Santa Monica Courthouse	19-AP1	2	Plumbing	Plumbing - Replace (1) floor sink and p-trap in basement boiler room. Floor sink p-trap has collapsed due to age and attempts to mechanically clear blockage. Work will require the removal of 4 SF of concrete to remove the floor sink and p-trap. Environmental testing costs included.	\$ 12,326	\$ 9,675	78.49



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
380	FM-2007574	Los Angeles	Santa Monica Courthouse	19-AP1	2	lumbir	Plumbing - Fixture Leak - Replace 20 LF of 3/4 inch galvanized pipe, (1) 3/4 inch isolation hot water supply valve, 20 LF of 3/4 inch copper pipe, (4) 1/2 inch x 3/8 inch angle stops, (1) faucet, (44) 4 inch x 4 inch ceramic tiles, and 12 SF of plaster wall in the 1st floor mens public restroom. The pipes and faucet failed due to age allowing water to leak into the restroom. Work includes the installation of (1) 2 ft x 2 ft access panel in the wall. Environmental oversight and remediation is required for category 2 water. Erect (1) 6 ft x 10 ft x 8 ft containment, and clean and sanitize 14 SF of ceramic surface.	\$ 34,020	\$ 26,702	78.49
381	FM-2007770	Humboldt	Humboldt County Courthouse (Eureka)	12-A1	2	lectric	Electrical - Replace (4) 2 ft x 4 ft T-12 fixtures on 2nd floor office. The fixtures have failed due to wiring shorts and broken tombstones and lens frames, impacting lighting in the space.	\$ 3,124	\$ 3,124	100
382	FM-2007810	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Protect	Fire Protection - Replace firestopping in the walls and flooring for electrical rooms located in the basement, 1st, 2nd, 3rd, and 6th floors. Deficiencies were noted during the State Fire Marshals annual inspection.	\$ 61,757	\$ 43,224	69.99
383	FM-2007937	Lake	South Civic Center	17-B1	2	HVAC	HVAC - Replace (1) condenser and (1) evaporator coil on air handler unit 4. The components failed due to age impacting building cooling. Environmental oversight and remediation required for ACM. Boom lift is required to perform the work.	\$ 45,000	\$ 45,000	100
384	FM-2007957	Los Angeles	Inglewood Courthouse	19-F1	2	ior Fin	Interior Finishes - Replace (5) 12 inch x 12 inch concealed spline ceiling tiles and supporting brackets in the 3rd floor public hallway. Ceiling tiles have shifted due to age and are sagging lower than the fire sprinkler deflector. Environmental oversight and remediation required.	\$ 5,127	\$ 3,822	74.56
385	FM-2008060	San Diego	Kearny Mesa Court	37-C1	2	lumbir	Plumbing - Replace (1) drinking fountain located on 1st floor west corridor adjacent to the mens restroom. Drinking fountain failed due to age. Environmental oversight and remediation required due to ACM.	\$ 30,471	\$ 30,471	100.00
386	FM-2008063	Mono	Mammoth Lakes Courthouse	26-B2	2	and Pa	Grounds and Parking Lot - Replace (4) metal halide parking lot fixtures. The fixtures failed due to age, impacting lighting levels in the parking lot. Work includes installing LED retrofit fixtures and the use of a lift.	\$ 7,255	\$ 7,255	100.00
387	FM-2008064	Los Angeles	Airport Courthouse Parking Structure	19-AU2	2	Protect	Fire Protection - Replace (10) 100 ft fire hoses and nozzles in the parking structure. The hoses are required to be hydro-tested and replacing them is more cost effective.	\$ 3,768	\$ 2,908	77.17
388	FM-2008066	San Diego	Central Courthouse	37-L1	2	lectric	Electrical - Replace (1) UPS and battery backup in 10th floor DAS station. The UPS and battery failed due to age, resulting in the loss of power to the DAS station.	\$ 8,587	\$ 8,587	100.00
389	FM-2008070	San Diego	Kearny Mesa Court	37-C1	2	ior Fin	Interior Finishes - Replace (1) door closure at sheriffs entry door. The door closure failed due to age causing the door not to close and latch shut, creating a safety hazard.	\$ 2,124	\$ 2,124	100.00
390	FM-2008071	Mono	Mammoth Lakes Courthouse	26-B2	2	lectric	Electrical - Replace (20) 12V 20 Ah batteries on the emergency egress lighting system lighting inverter. The batteries are beyond their useful life and require replacement to ensure proper operation of the emergency lighting system.	\$ 11,074	\$ 11,074	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
391	FM-2008074	Alameda	Fremont Hall of Justice	01-H1	2	andalis	Vandalism - Replace (1) 44 inch x 77 inch x 1/4 inch tempered door glazing panel at main entrance. Glazing was broken by an unidentified person. Work includes removal of broken glass and board up prior to new glazing install.	\$ 5,763	\$ 4,576	79.40
392	FM-2008077	San Bernardino	Fontana Courthouse	36-C1	2	HVAC	HVAC - Replace (1) 3 ton heat pump package unit, (1) disconnect, and associated wiring. The unit failed due to age affecting cooling in the court exclusive clerks office.	\$ 25,450	\$ 25,450	100.00
393	FM-2008079	Mono	Mammoth Lakes Courthouse	26-B2	2	erior S	Exterior Shell - Replace (2) sensors on the front sliding exit door. The sensors failed due to use, resulting in the exit door opening after hours.	\$ 3,537	\$ 3,537	100.00
394	FM-2008084	San Diego	North County Regional Center - South	37-F1	2	lumbir	County Managed - Plumbing - Replace 10 drinking fountains in public corridors on floors 1, 3, and 4. (5) drinking fountains have failed due to age and (5) have corrosion. Fountains are 25-plus years old and past their useful life.	\$ 40,167	\$ 40,167	100.00
395	FM-2008085	Los Angeles	Chatsworth Courthouse	19-AY1	2	HVAC	HVAC - Replace (1) valve and (1) filter drier on heat pump unit 2. The valve and filter drier have failed due to age, allowing refrigerant to leak from the system and impacting building conditioning.	\$ 5,093	\$ 4,268	83.80
396	FM-2008086	Santa Clara	Family Justice Center Courthouse	43-B5	2	Protect	Fire Protection - Restore fire alarm system programming. The programming is corrupted, provides conflicting trouble signals, and does not print alarm notifications.	\$ 3,686	\$ 3,686	100.00
397	FM-2008090	Riverside	Riverside Juvenile Court	33-N1	2	lumbir	Plumbing - Replace (1) 1 inch copper tee, 1 LF of 1 inch copper pipe, (1) 1 inch ball valve and (1) 1 inch female adapter on the domestic water bypass. The pipe joint failed due to age and was noted on the daily inspection.	\$ 3,425	\$ 1,690	49.34
398	FM-2008094	Los Angeles	Van Nuys Courthouse East	19-AX1	2	securit	Security - Replace (1) antenna receiver and (60) remote control transmitters on the secured parking gate. The antenna receiver was not compatible with the new motherboard installed under a separate FM resulting in the gate not operating correctly.	\$ 5,396	\$ 4,842	89.74
399	FM-2008095	Kern	Bakersfield Juvenile Center	15-C1	2	ior Fin	Interior Finishes - Replace (1) lock for court supervisor office door. The lock failed due to age.	\$ 2,955	\$ 2,955	100.00
400	FM-2008099	Los Angeles	West Parking Structure	19-F3	2	securit	Security - Replace (2) double flanged track rollers on the parking rolling entrance gate. Rollers have failed due to use and age impacting the gates operation.	\$ 3,471	\$ 2,588	74.56
401	FM-2008110	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Protect	Fire Protection - Install firestopping for multi-purpose room and ceiling penetration and acoustical caulking in the vestibule and multi-purpose room. The deficiencies were identified during the lactation project construction.	\$ 8,868	\$ 6,207	69.99
402	FM-2008118	Solano	Law and Justice Center	48-A2	2	lectric	Electrical - Replace (1) lighting control panel and (3) muti-button light switches serving court exclusive space. Equipment has failed due to age, is obsolete, and can no longer be repaired. Environmental oversight and remediation required for ACM to replace 5 SF of brick and mortar and drywall for access to remove electrical boxes.	\$ 33,466	\$ 33,466	100.00
403	FM-2008121	San Diego	North County Regional Center - North	37-F2	2	andalis	Vandalism - Replace anti-graffiti film on (4) 2 ft x 3 ft mirrors and repaint (4) restroom stalls in the 1st floor mens public restroom. The items were vandalized by an unknown individual.	\$ 8,733	\$ 8,733	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
404	FM-2008122	San Diego	Kearny Mesa Court	37-C1	2	Plumbing	Plumbing - Replace (2) flush valve diaphragms, (2) vacuum breakers, (2) O rings located and remove scaling in (2) P-traps in the 1st floor mens employee restroom. Diaphragms, vacuum breakers and O rings have failed due to age causing low water pressure and the scaling is causing slow drainage.	\$ 3,576	\$ 3,576	100.00
405	FM-2008124	Solano	Hall of Justice	48-A1	2	HVAC	HVAC - Replace (3) heating hot water coils on 2nd floor AHU 2. One coil failed due to age and two coils are beyond their useful life. Environmental testing costs included for ACM.	\$ 94,256	\$ 68,637	72.82
406	FM-2008128	San Bernardino	Fontana Courthouse	36-C1	2	Escalators	Elevators, Escalators, & Hoists - Replace (1) position indicator sensor on secured elevator 2. Part failed due to age, causing the elevator not to respond.	\$ 3,607	\$ 3,607	100.00
407	FM-2008132	Riverside	Southwest Justice Center	33-M1	2	Interior Finishes	Interior Finishes - Replace (1) floor closer, (1) top pivot, and (1) bottom arm for lower-level public entrance glass door. Components have failed due to use impacting the doors operation. Work requires removal and reinstallation of the full-size glass door.	\$ 5,152	\$ 3,936	76.40
408	FM-2008134	San Diego	South County Regional Center	37-H1	2	HVAC	County Managed - HVAC - Replace heating hot water pump on Boiler 2. Boiler pump failed due to age causing loss of heating capacity.	\$ 5,466	\$ 5,466	100.00
409	FM-2008136	Riverside	Larson Justice Center	33-C1	2	Plumbing	Plumbing - Replace (1) 1 1/2 hp storm drain pump. The storm drain pump failed due to age and was identified during rounds and readings.	\$ 14,127	\$ 13,759	97.39
410	FM-2008137	Calaveras	Calaveras Superior Court	05-C1	2	HVAC	HVAC - Replace (1) return air duct probe sensor for VAV 316. Sensor has failed due to age impacting heating and cooling.	\$ 2,159	\$ 2,159	100.00
411	FM-2008139	San Diego	Kearny Mesa Court	37-C1	2	Exterior Shell	Exterior Shell - Replace the (4) address numbers located above the main entrance. The address numbers are failing due to age resulting in pieces of the numbers to break off can fall to the ground below. Work requires the use of a lift to replace the numbers.	\$ 3,949	\$ 3,949	100.00
412	FM-2008144	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	Interior Finishes	County Managed - Interior Finishes - Replace (71) hard wired clocks throughout the courthouse that are ran by the master clock. Clocks have failed due to age and parts are no longer available. Clocks are compatible to the existing system and power supply. Work is needed as these clocks are used by the public and court personnel for accurate timekeeping.	\$ 25,700	\$ 25,700	100.00
413	FM-2008146	San Diego	Central Courthouse	37-L1	2	Electrical	Electrical - Replace the lighting control system programming. The existing system is obsolete and is not compatible with the new windows operating system.	\$ 55,993	\$ 55,993	100.00
414	FM-2008147	Fresno	B.F. Sisk Courthouse	10-O1	2	Interior Finishes	Interior Finishes - Replace ADA door closer assembly for 1st floor main lobby exit. Closer has failed due to age and preventing public usage.	\$ 12,040	\$ 12,040	100.00
415	FM-2008148	Santa Clara	Hall of Justice (East)	43-A1	2	Plumbing	Plumbing - Replace 30 LF of 2 inch cast iron sanitary sewer waste line, couplings, and supports in the basement. The pipe failed due to age resulting in a large crack. The work will be performed after hours.	\$ 8,626	\$ 8,626	100.00
416	FM-2008149	Santa Clara	Morgan Hill Courthouse	43-N1	2	Plumbing	Plumbing - Restore sewer lift station. Lift station is impacted by debris impacting its operation. Work to occur after hours.	\$ 9,147	\$ 9,147	100.00
417	FM-2008150	Madera	Main Courthouse Parking Structure	20-F2	2	Electrical	Electrical - Replace 38 T5 bulbs and (5) ballasts on the parking structures 4th level. The lights and ballasts have failed due to age, impacting lighting levels at night.	\$ 2,237	\$ 2,237	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMS By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
418	FM-2008155	Los Angeles	Metropolitan Courthouse	19-T1	2	Escalator	Elevators, Escalators, & Hoists - Replace (2) fuses, restore wiring on contactor, and clean contact pads and drive contactors on public elevator 5. Components failed due to use impacting the elevators operation.	\$ 2,796	\$ 2,644	94.54
419	FM-2008156	San Diego	North County Regional Center - South	37-F1	2	Plumbing	Plumbing - Replace (2) drinking fountains in the secured office space on the 1st floor. The drinking fountains have failed due to age and require replacement. Environment and oversight required for lead. Erect (1) 6 ft x 6 ft x 8 ft containment.	\$ 26,874	\$ 26,874	100.00
420	FM-2008161	San Diego	Central Courthouse	37-L1	2	Vandalism	Vandalism - Replace (1) 37 1/4 inch x 22 3/4 inch heat-strengthened and polycarb combination attack glazing and (1) vandal resistant prison visitation panel telephone in the 12th floor interview room. An in-custody hit the glazing with the phone, breaking both items. Restitution is being sought.	\$ 9,614	\$ 9,614	100.00
421	FM-2008165	Los Angeles	Norwalk Courthouse	19-AK1	2	Interior Finishes	Interior Finishes - Replace (1) 24 inch x 54 inch bathroom stall door and (2) marble side panels in the 4th floor jury Womens restroom. Door and side panels failed due to age preventing the door from closing and locking.	\$ 9,197	\$ 9,197	100.00
422	FM-2008166	San Bernardino	Barstow Courthouse	36-J1	2	Security	Security - Replace (1) door alarm on 1st floor emergency exit and replace (1) door alarm on 2nd floor emergency exit. Door alarms failed due to age, creating a safety and security issue.	\$ 2,428	\$ 2,428	100.00
423	FM-2008167	Los Angeles	Beverly Hills Courthouse	19-AQ1	2	HVAC	HVAC - Replace (1) pressure and electric switch on the pneumatic valve. Switch failed due to age creating an alarm impacting the chillers operation.	\$ 2,172	\$ 1,728	79.52
424	FM-2008174	Ventura	East County Courthouse	56-B1	2	HVAC	HVAC - Replace (1) 20 hp 3-phase motor for air handler unit 1. The motor has failed due to age impacting cooling to the courthouse. The work requires the use of a crane to hoist the new motor into place and to remove the old motor from the roof.	\$ 7,764	\$ 4,794	61.75
425	FM-2008176	San Diego	Juvenile Court	37-E1	2	HVAC	HVAC - Replace (1) 2-ton split system in the main roof top. The unit has reached the end of its useful life and does not provide adequate conditioning to the IDF room. A crane rig is required to remove the old unit and lift the new unit into place.	\$ 22,886	\$ 22,886	100.00
426	FM-2008177	San Joaquin	Stockton Courthouse	39-F1	2	Vandalism	Vandalism - Replace (1) 21 3/4 inch x 35 7/8 inch piece of security glazing in basement holding cell. Glazing was damaged by an in custody. Restitution is being sought.	\$ 2,994	\$ 2,994	100.00
427	FM-2008181	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Fire Protection	Fire Protection - Replace (1) air release valve and (1) pressure reducing valve on fire pump 3. The components have failed due to age resulting in the fire pump overheating.	\$ 11,669	\$ 9,392	80.48
428	FM-2008182	San Diego	Juvenile Court	37-E1	2	HVAC	HVAC - Replace 80 LF of 2 inch, 15 LF of 1 1/2 inch, and 35 LF of 3/4 inch pipe insulation in mechanical room. The insulation has deteriorated due to age.	\$ 16,077	\$ 11,997	74.62
429	FM-2008183	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Plumbing	Plumbing - Replace (1) 8 inch backflow device. Backflow has failed due to age. The deficiency was discovered during the annual preventative maintenance.	\$ 28,592	\$ 23,011	80.48
430	FM-2008187	San Diego	North County Regional Center - South	37-F1	2	Interior Finishes	Interior Finishes - Replace (1) lock and hardware on the 2nd floor in-custody elevator area door. The lock has failed due to age, impacting the doors operation. The new lock will be a mortise lock system.	\$ 3,318	\$ 3,318	100.00
431	FM-2008196	Fresno	B.F. Sisk Courthouse	10-O1	2	HVAC	HVAC - Replace (1) 15HP motor on chiller 2. Motor failed due to age, impacting chiller operations and domestic chilled water flow throughout building.	\$ 3,781	\$ 3,781	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
432	FM-2008199	Tulare	South County Justice Center	54-I1	2	Protect	Fire Protection - Replace (1) 6 inch gate valve and (1) gate valve system sensor switch. The valve and switch have failed due to age allowing water to leak from the system.	\$ 3,847	\$ 3,847	100.00
433	FM-2008207	San Diego	Kearny Mesa Court	37-C1	2	erior S	Exterior Finishes - Replace (1) 3 ft x 7 ft exterior metal door frame located at the bottom east wing pedestrian ramp. The frame has failed due to corrosion impacting the doors operation. Environmental testing costs included.	\$ 11,618	\$ 11,618	100.00
434	FM-2008216	San Diego	North County Regional Center - North	37-F2	2	lumbir	Plumbing - Domestic Water Leak - Replace (1) 3/4 inch hose bib on the exterior wall located in the courtyard. The hose bib has failed due to age allowing water to leak into the basement. Work includes installing 10 LF of 3/4 inch copper piping, (5) 3/4 inch copper 90 elbows, (1) Vacuum breaker, (1) 3/4 inch ball valve, (5) 3/4 inch copper 45 degree elbow, (1) 3/4 inch copper coupler. Environmental testing costs included.	\$ 8,277	\$ 8,277	100.00
435	FM-2008217	San Bernardino	San Bernardino Courthouse - Annex	36-A2	2	Protect	Fire Protection - Replace (18) 1.5 inch 75 ft long fire hoses ,(18) fire hose nozzles, and (1) 1/2 inch angle fire hose valve. Deficiencies found during 5-year inspection.	\$ 9,307	\$ 8,901	95.64
436	FM-2008218	Fresno	Fresno County Courthouse	10-A1	2	ior Fin	Interior Finishes - Replace (3) locking assemblies for holding cell doors 4, 5 & 6 on floor B2. Locks have failed due to age and will not lock electronically.	\$ 5,526	\$ 5,300	95.91
437	FM-2008220	San Diego	South County Regional Center	37-H1	2	HVAC	County Managed - HVAC - Replace inducer fan assembly on boiler 2. Inducer fan assembly failed due to age causing loss of heating capacity.	\$ 9,704	\$ 9,704	100.00
438	FM-2008229	Madera	Main Courthouse - Madera	20-F1	2	lectric	Electrical - Replace (10) 12V 110 AMP UPS batteries. Batteries have failed due to age impacting the UPS operation.	\$ 7,794	\$ 7,794	100.00
439	FM-2008238	Los Angeles	Downey Courthouse	19-AM1	2	lectric	Electrical - Replace (6) 150 watt lighting fixtures in the employee parking structure. Fixtures failed due to age affecting the lighting in employee lot. Current parts are obsolete. Work requires a boom lift.	\$ 8,008	\$ 8,008	100.00
440	FM-2008240	Los Angeles	Compton Courthouse	19-AG1	2	lumbir	Plumbing - Replace (1) 1/2hp storm drain sump pump adjacent to the parking structure. Pump failed due to age affecting the ability to remove storm water.	\$ 2,218	\$ 1,467	66.13
441	FM-2008244	Orange	Central Justice Center	30-A1	2	lumbir	Plumbing - Restore (1) main potable water pump in the basement pump room. The pump failed due to age resulting in water leaking from the pump and impacting water supply to the building.	\$ 4,935	\$ 4,499	91.17
442	FM-2008248	Kern	Shafter/Wasco Courts Bldg.	15-E1	2	ior Fin	Interior Finishes - Replace (1) door closure and (1) set of pivot pins for public entrance door. Parts failed due to age.	\$ 2,069	\$ 1,861	89.95
443	FM-2008252	Los Angeles	Chatsworth Courthouse	19-AY1	2	HVAC	HVAC - Replace (1) heat pump assembly, (1) interior ceiling grill, and (1) thermostat on package unit 4. The heat pump has failed due to age impacting building conditioning.	\$ 10,797	\$ 9,048	83.80
444	FM-2008254	Los Angeles	Airport Courthouse	19-AU1	2	Protect	Fire Protection - Replace (1) fire alarm panel power supply. The supply failed due to age, impacting the panels operation.	\$ 3,391	\$ 2,617	77.17
445	FM-2008255	San Diego	North County Regional Center - North	37-F2	2	HVAC	HVAC - Install (1) thermostat for air handler unit 6 serving exhibit room and basement floor. AHU currently has no temperature controls for exhibit rooms that it serves.	\$ 3,832	\$ 3,832	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
446	FM-2008259	Los Angeles	Van Nuys Courthouse East	19-AX2	2	Interior Fin	Interior Finishes - Replace (4) public seating in the 8th floor courtroom. Chairs have failed due to use. Work includes relocating (4) chairs from the back row to the middle row. Environmental testing costs included.	\$ 18,018	\$ 18,018	100.00
447	FM-2008262	Orange	Central Justice Center	30-A1	2	HVAC	HVAC - Replace (2) 6 inch butterfly isolation valves and gasket of closed loop heat exchanger. The gasket and valves have failed due to age impacting heating to building.	\$ 14,324	\$ 13,059	91.17
448	FM-2008273	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Land Pa	Grounds and Parking lot - Replace (10) granite tile slabs. The tiles are cracked and damaged due to age.	\$ 7,702	\$ 6,199	80.48
449	FM-2008275	San Diego	Juvenile Court	37-E1	2	Land Pa	Grounds and Parking Lot - Install 8 LF of 3/4 inch gravel in roof drain outlet. Water has eroded away the sand and gravel from planters. Erosion control roll will be installed to prevent further erosion and spillway of dirt into easement and storm drains while the gravel is procured.	\$ 3,315	\$ 2,474	74.62
450	FM-2008282	Los Angeles	San Fernando Courthouse	19-AC1	2	Plumbing	Plumbing - Replace (4) sump pump pit float assemblies and (2) fuses. The floats and fuses have failed due to age, allowing the pit to overflow.	\$ 2,259	\$ 1,884	83.41
451	FM-2008283	Riverside	Southwest Juvenile Courthouse	33-M4	2	Electric	Electrical - Replace (40) 12-volt 53.8 amp power storage cells of the emergency light power inverter. The cells have reached the end of their useful life and require replacement.	\$ 13,777	\$ 13,777	100.00
452	FM-2008284	Riverside	Riverside Juvenile Court	33-N1	2	Protect	Fire Protection - Replace (1) alarm Bell and Plunger, restore (6) sprinkler heads, and install (14) sprinkler escutcheons. The bell failed due to age impacting its operation, the sprinkler escutcheons were missing, and the (6) sprinkler heads were impacted by dirt. The deficiencies were identified during the 5-year sprinkler certification.	\$ 5,575	\$ 2,751	49.34
453	FM-2008288	Los Angeles	Torrance Courthouse	19-C1	2	Interior Fin	Interior Finishes - Replace (1) keypad lock for employee restroom door located on 1st floor. The lock failed due to age allowing anyone to access the restroom. Locksmith required for installation of core & key for override use.	\$ 4,985	\$ 4,985	100.00
454	FM-2008292	Los Angeles	San Fernando Courthouse	19-AC1	2	Protect	Fire Protection - Restore (10) smoke detectors and replace (1) Fire Alarm Panel key, (1) 4 inch waterflow switch, (14) 12v 7ah batteries, (16) pull stations, and (2) breaker locks. The locks and key are missing, the smoke detectors are dislodged and need to be rehung, the switch, pull stations, and batteries have failed due to age. The deficiencies were identified during annual preventative maintenance.	\$ 10,033	\$ 8,369	83.41
455	FM-2008293	Los Angeles	Bellflower Courthouse	19-AL1	2	Protect	Fire Protection - Replace (28) sprinkler heads, (4) escutcheons, and (2) water flow switches and lower (3) sprinkler heads. Items have failed due to age and were identified during preventative maintenance.	\$ 9,828	\$ 7,660	77.94
456	FM-2008295	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Escalator	Elevators, Escalators, & Hoists - Replace (1) drive assembly for public elevator 6. The drive assembly failed due to age, causing the elevator cab to remain stuck between floors.	\$ 29,219	\$ 20,450	69.99
457	FM-2008302	Alameda	Fremont Hall of Justice	01-H1	2	HVAC	HVAC - Replace (1) slide valve piston and compressor on chiller 1. The piston and compressor failed due age causing loss of cooling capacity in the building.	\$ 9,702	\$ 7,704	79.40



Judicial Council of California

Trial Court Facility Modification
Advisory Committee

Attachment A

TCFMAC-Funded Project List
Quarter 2, Fiscal Year 2024-25

Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
458	FM-2008303	Stanislaus	Modesto Main Courthouse	50-A1	2	Interior Fin	Interior Finishes - Replace (1) door closer motor and gearbox on main entrance ADA door. Motor failed due to age leaving the ADA door non-operational.	\$ 3,441	\$ 2,677	77.82
459	FM-2008308	Los Angeles	Inglewood Courthouse	19-F1	2	HVAC	HVAC - Replace (2) flange bearings, (1) 20hp motor, (2) pulleys, and (3) belts for 1st floor AHU 1. Return fan motor and bearings are failing due to age impacting building conditioning.	\$ 16,461	\$ 12,273	74.56
460	FM-2008309	Stanislaus	Hall of Records	50-A2	2	HVAC	HVAC - Replace (1) fill valve and float ball assembly for chiller 1 cooling tower. Fill valve was sticking causing pump cavitation and low condenser flows.	\$ 4,551	\$ 3,541	77.82
461	FM-2008310	Alameda	Fremont Hall of Justice	01-H1	2	HVAC	HVAC - Replace (1) header gasket and (1) broken mounting stud on boiler heat exchanger. Parts failed due to age. Issues found during preventative maintenance.	\$ 7,531	\$ 5,979	79.40
462	FM-2008311	Alameda	Fremont Hall of Justice	01-H1	2	Security	Security - Remove (11) TV monitors and associated brackets, fasteners, conduits, and wiring from holding cells. Components have been identified as a safety issue requiring removal. Conduits and wiring will be removed back to nearest junction boxes outside of holding cells and wall penetrations will be covered and filled.	\$ 8,817	\$ 8,817	100.00
463	FM-2008316	Santa Clara	Family Justice Center Courthouse	43-B5	2	Plumbing	Plumbing - Replace (2) 4 inch cast iron risers, (2) 4 inch p-traps and connectors and install (1) 1/2 inch p-trap primer and (3) new neutralizers routed to drains in the Penthouse Boiler Room. Floor drains have corroded due to chemically treated water from Heating Hot Water and Condensing Water Heaters draining to floor drains. Work requires removing the old drain bodies, core drill new penetrations, repouring concrete and sealing around new drain bodies.	\$ 30,445	\$ 30,445	100.00
464	FM-2008319	Alameda	Fremont Hall of Justice	01-H1	2	Plumbing	Plumbing - Sewer Line Leak - Replace 1/2 LF of 4 inch cast iron pipe, (1) 45 degree elbow, and (2) 2 ft x 4 ft ceiling tiles in 1st floor staff office. Pipe failed due to age allowing water to leak onto the ceiling tiles below.	\$ 3,399	\$ 3,399	100.00
465	FM-2008322	San Diego	East County Regional Center	37-I1	2	HVAC	HVAC - Install (1) metering device on the condenser water make up water line. The device will meter how much make up water is being fed into the cooling tower/sump water loop. The system is using excess levels of treatment chemicals, and the meter will help detect if there is a leak in the system.	\$ 8,753	\$ 5,926	67.71
466	FM-2008328	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Plumbing	Plumbing - Replace (2) 4 inch gate valves and (2) 6 inch gate valves on the rooftop water tanks. The valves have failed due to age allowing water to leak from the tanks and onto the roof. Working includes draining and refilling the plumbing system.	\$ 17,800	\$ 17,312	97.26
467	FM-2008330	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	Vandalism	Vandalism - Replace (3) 9 3/4 inch x 9 3/4 inch holding cell door glazing in cells 6, 13, and 16. The glazing was damaged by unknown in-custodies.	\$ 2,369	\$ 2,369	100.00
468	FM-2008331	Los Angeles	Van Nuys Court Complex Parking Structure	19-AX6	2	Plumbing	Plumbing - Replace (2) 2 inch sump pump assemblies in the basement mechanical room. The pumps are failing due to age impacting their operation. The deficiency was identified during rounds and readings.	\$ 13,739	\$ 12,330	89.74



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
469	FM-2008332	San Bernardino	Victorville Courthouse	36-L1	2	Plumbing	Plumbing - Fixture Leak- Replace (1) toilet diaphragm valve in the 1st floor jury deliberation room. Diaphragm valve failed causing the toilet to continuously flush and in turn the toilet to overflow because toilet was blocked. Water leaked onto restroom floor and seeped into carpeted area outside of restroom. Blockage was mechanically cleared and not recovered. Environmental oversight and remediation required due to category 2 water. Erect (1) 2 ft x 8 ft x 10 ft containment, and clean, dry and sanitize 60 SF of 9 in x 9 in gray ceramic floor tile, 10 SF of carpet, 10 SF of drywall, 2 SF of 4 in brown cove base, (1) toilet, and (1) trash can.	\$ 14,252	\$ 14,252	100.00
470	FM-2008333	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Escalators	Elevators, Escalators, & Hoists - Replace 75 SF of flooring in public elevator 5. Flooring has delaminated requiring replacement. Elevator 5 is used as a secondary freight elevator and subjected to heavy usage. Work to be performed after-hours to minimize disruption of Court operations.	\$ 31,685	\$ 30,817	97.26
471	FM-2008337	Los Angeles	El Monte Courthouse	19-O1	2	Escalators	Elevators, Escalators, & Hoists - Replace (2) light fixtures with battery backup for public elevator 3. Elevator fixtures have failed due to age affecting visibility in the elevator.	\$ 3,959	\$ 2,301	58.12
472	FM-2008342	San Diego	Kearny Mesa Court	37-C1	2	HVAC	HVAC - Replace (1) 7.5 HP motor, (1) 4 3/4 inch x 1 1/8 inch sheave, (1) 5/8 inch belt, (2) 4inch rubber mounts on rooftop packed unit 17. Components have failed due to age resulting in noise in the northeast office space.	\$ 4,367	\$ 4,367	100.00
473	FM-2008344	San Diego	Central Courthouse	37-L1	2	Escalators	Elevators, Escalators, & Hoists - Install new load weighing cells on judge elevator 2. Load weighing cells are required to prevent the elevator from faulting. Deficiencies were found during normal maintenance.	\$ 10,247	\$ 10,247	100.00
474	FM-2008345	San Diego	North County Regional Center - North	37-F2	2	Interior Finishes	Interior Finishes - Replace (3) double acting pivot hinges on swinging wood doors and hinge assemblies in 1st floor courtroom. The existing hardware has failed due to age and is obsolete impacting the door operation.	\$ 3,450	\$ 3,450	100.00
475	FM-2008346	Santa Clara	Sunnyvale Courthouse	43-F1	2	Grounds and Parking Lot	Grounds and Parking Lot - Replace (1) 18-station irrigation controller, (1) 2 inch valve, (25) sprinklers heads, and 45 LF of 1/2 inch lateral line. Parts failed due to age, causing multiple leaks. Deficiency was identified by water usage tracking.	\$ 4,878	\$ 4,878	100.00
476	FM-2008348	San Joaquin	Stockton Courthouse	39-F1	2	Escalators	Elevator Systems - Replace (3) handrail guides, (1) chain, and vacuum track on Escalator 1.Components failed due to use and were identified during the annual inspection.	\$ 8,390	\$ 8,390	100.00
477	FM-2008349	San Diego	Central Courthouse	37-L1	2	Escalators	Elevator, Escalators, & Hoists - Install new load-weighing cells on elevator 11. The elevator is faulting and is unable to reset. The new cells will allow for improved precision when weighing the elevator weight.	\$ 13,234	\$ 13,234	100.00
478	FM-2008350	San Diego	North County Regional Center - Annex	37-F3	2	HVAC	HVAC - Replace (1) 10 HP variable frequency drive AHU 2 supply fan in the mechanical room. Component is damaged due to age, resulting in unbalanced air circulation throughout the floor. Work includes, programming the VFD and checking the system for proper operation.	\$ 10,994	\$ 10,994	100.00
479	FM-2008352	Alameda	George E. McDonald Hall of Justice	01-F1	2	Plumbing	Plumbing - Mechanically clear 75 LF of drain line at 2nd floor womens public restroom sink. Drain line was blocked preventing the sinks from draining. A video camera was required to guide the snake through the drain line. The blockage was not recovered.	\$ 4,144	\$ 4,144	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
480	FM-2008353	San Mateo	Central Branch	41-B1	2	HVAC	HVAC - Replace (1) hot surface ignitor, (1) flame sensor, (2) fireside gaskets, and (2) waterside gaskets at boiler Parts failed due to age. Issues found during annual preventative maintenance.	\$ 4,615	\$ 4,615	100.00
481	FM-2008357	Los Angeles	Airport Courthouse	19-AU1	2	Protect	Fire Protection - Restore (1) fire pump. Pump has failed due to age resulting in the pump smoking and leaking during preventative maintenance. Work includes installing a fire pump rebuild kit that includes new seals, gaskets, bearings, deflectors, packing rings, and lantern rings.	\$ 18,265	\$ 14,095	77.17
482	FM-2008360	Santa Barbara	Santa Barbara Jury Assembly Bldg.	42-G1	2	Plumbin	Plumbing - Replace (2) 4 inch shut off valves for domestic backflow. Valves are leaking due to age and were discovered during preventative maintenance.	\$ 12,031	\$ 12,031	100.00
483	FM-2008362	San Diego	South County Regional Center	37-H1	2	Plumbin	Plumbing - Replace (4) 1 inch flush valves and (4) 1 inch stop valves located in the 2nd floor womens staff restroom and jury deliberation room. Valves failed due to age.	\$ 5,683	\$ 5,683	100.00
484	FM-2008366	San Francisco	Civic Center Courthouse	38-A1	2	Escalato	Elevators, Escalators, & Hoists - Replace (2) auxiliary controller relays on elevator 5. Relays failed due to age resulting in an entrapment.	\$ 6,307	\$ 6,307	100.00
485	FM-2008368	Orange	North Justice Center	30-C1	2	HVAC	HVAC - Replace (1) internal oil filter, (1) external oil filter, (1) O-ring kit and 160 lbs of refrigerant on chiller 1. The components failed due to age resulting in a refrigerant leak impacting building HVAC.	\$ 17,288	\$ 15,613	90.31
486	FM-2008371	Alameda	Wiley W. Manuel Courthouse	01-B3	2	Escalato	Elevator - Replace (1) failed wire connector on motherboard at loading dock elevator. Connector failed due to age impacting the elevators operation.	\$ 9,952	\$ 8,340	83.80
487	FM-2008372	Kings	Kings Superior Court	16-A5	2	Electric	Electrical - Replace (80) 82AH 336W UPS batteries. Batteries have failed due to age and were identified during annual preventative maintenance. UPS serves emergency egress lighting.	\$ 45,208	\$ 45,208	100.00
488	FM-2008374	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	HVAC	HVAC - Replace (1) pressure manifold, (1) relief flange, (10) gallons of oil, and (1) oil filter for chiller 2. Parts failed due to age causing the chiller to go on alarm and trip. The system will be recharged with refrigerant.	\$ 24,545	\$ 18,043	73.51
489	FM-2008375	San Joaquin	Stockton Courthouse	39-F1	2	Protect	Fire Protection - Replace (36) 8AH batteries that are part of the fire detection system. The batteries have reached the end of their useful life and are beginning to fail. The deficiency was identified during the annual fire alarm inspection.	\$ 2,678	\$ 2,678	100.00
490	FM-2008376	San Bernardino	Historic Courthouse	36-A1	2	Plumbin	Plumbing - Replace (1) 3 inch backflow preventer and associated hardware. Backflow preventer failed during annual preventive maintenance and inspection.	\$ 10,776	\$ 10,368	96.21
491	FM-2008377	San Joaquin	Stockton Courthouse	39-F1	2	Escalato	Elevator Systems - Replace (3) handrail guides, (1) chain, and vacuum track on Escalator 3.Components failed due to use and were identified during the annual inspection.	\$ 3,061	\$ 3,061	100.00
492	FM-2008380	San Joaquin	Stockton Courthouse	39-F1	2	Escalato	Elevator Systems - Replace (3) handrail guides, (1) chain, and vacuum track on Escalator 4.Components failed due to use and were identified during the annual inspection.	\$ 3,061	\$ 3,061	100.00
493	FM-2008381	San Joaquin	Stockton Courthouse	39-F1	2	Escalato	Elevator Systems - Replace (3) handrail guides, (1) chain, and vacuum track on Escalator 2.Components failed due to use and were identified during the annual inspection.	\$ 2,995	\$ 2,995	100.00
494	FM-2008383	San Diego	North County Regional Center - South	37-F1	2	Interior Fin	Interior Finishes - Replace (2) mortise locksets on sheriffs office door on the 2nd floor. Lockset failed due to age and use resulting in the sheriffs unable to exit the room.	\$ 3,549	\$ 3,549	100.00



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
495	FM-2008385	San Joaquin	Stockton Courthouse	39-F1	2	andalis	Vandalism - Replace (1) 21 3/4 inch x 35 7/8 inch piece of security glazing in basement holding cell. Glazing was damaged by in-custody. Restitution is being sought.	\$ 2,994	\$ 2,994	100.00
496	FM-2008387	Santa Clara	Santa Clara Courthouse	43-G1	2	escalator	Elevator - Replace (2) door edges and restore the edge sensor circuit. Door edges failed due to age and were discovered during the DIR preliminary inspection. The edge sensor issue was discovered while working on the door edges.	\$ 4,026	\$ 4,026	100.00
497	FM-2008398	San Joaquin	Stockton Courthouse	39-F1	2	HVAC	HVAC - Restore Chiller 1. Chiller was not operating due to a partial obstruction in the chiller tubes and was in alarm. Work includes cleaning and brushing the chiller tubes to clear debris from the tubes.	\$ 2,719	\$ 2,719	100.00
498	FM-2008399	San Joaquin	Stockton Courthouse	39-F1	2	HVAC	HVAC - Restore Chiller 2. Chiller was not operating due to a partial obstruction in the chiller tubes and was in alarm. Work includes cleaning and brushing the chiller tubes to clear debris from the tubes.	\$ 2,925	\$ 2,925	100.00
499	FM-2008400	Los Angeles	Inglewood Courthouse	19-F1	2	escalator	Elevators, Escalators, & Hoists - Replace (1) elevator control valve, (2) shut off valves, (1) hydraulic oil line shut off valve, and 220 gallons of oil for public elevator 7. Component have reached the end of their useful life, requiring replacement.	\$ 32,621	\$ 24,322	74.56
500	FM-2008408	Orange	Stephen K. Tamura Courthouse	30-D1	2	plumbing	Plumbing - Replace (1) 5 ft drinking fountain flex supply line on 2nd floor. Flex line failed resulting in water leaking into neighboring janitorial closet and down onto ceiling and wall of first floor womens public restroom below. Environmental oversight and remediation required for category 2 water. Erect (1) 5 ft x 5 ft containment and provide (1) dehumidifier, and (1) fan to for 8 days.	\$ 4,110	\$ 3,727	90.68
501	FM-2008409	Alameda	Wiley W. Manuel Courthouse	01-B3	2	escalator	Elevators, Escalators, and Hoists - Replace (2) call button sensors on elevator 2. Buttons failed due to age and are obsolete resulting in the elevator being out of service for an extended period of time.	\$ 4,345	\$ 3,641	83.80
502	FM-2008410	Alameda	East County Hall of Justice	01-J1	2	Protection	Fire Protection - Replace (7) sprinkler heads, (3) 1 1/2 inch elbows, (1) 1 1/2 inch close nipple, (1) 1 1/2 inch x 4 inch nipple, (1) 1 1/2 inch coupling, (1) 1 inch elbow, (1) 4 LF of 1 1/2 inch black iron pipe, (2) 1 1/4 inch swing check valves, (1) 1 1/4 inch coupling and (4) 2 1/2 inch hose valves at locations throughout the building. Items were identified during the 5 year sprinkler certification inspection.	\$ 14,779	\$ 14,779	100.00
503	FM-2008414	Los Angeles	Santa Monica Courthouse	19-AP1	2	plumbing	Plumbing - Replace 15 LF of 1 inch copper pipe, (1) 1 inch strainer, (1) 1 inch check valve, (2) 1 1/4 inch pump flanges, (1) mechanical temperature controller, and (4) 1 inch isolation valves on domestic recirculating pump 1. The components failed due to age and were discovered during rounds and readings. Work also includes restoring and repainting pump.	\$ 13,281	\$ 10,424	78.49
504	FM-2008418	Los Angeles	Beverly Hills Courthouse	19-AQ1	2	HVAC	HVAC - Replace (1) actuator to the hot and cold deck. Actuator failed due to age impacting conditioning to the 4th floor receptionist area.	\$ 2,230	\$ 1,773	79.52
505	FM-2008419	Los Angeles	Whittier Courthouse	19-AO1	2	HVAC	HVAC - Replace (1) controller for boiler 4 in the basement. Controller failed due to age impacting the boilers ability to ignite and affecting heating throughout the building.	\$ 4,622	\$ 3,994	86.43



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMs By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
506	FM-2008423	Los Angeles	Inglewood Courthouse	19-F1	2	Plumbing	Plumbing - Replace (1) gauge on the fuel system above ground storage tank (AST) and restore the AST supply and return lines and spill bucket. The components have failed due to age and was discovered during preventative maintenance testing.	\$ 5,809	\$ 4,331	74.56
507	FM-2008429	Los Angeles	Beverly Hills Courthouse	19-AQ1	2	HVAC	HVAC - Replace (1) 1 HP motor within the blower assembly unit for Boiler 2. Motor failed due to age due to motor producing current surges, tripping the circuit breaker.	\$ 5,888	\$ 4,682	79.52
508	FM-2008496	San Diego	Central Courthouse	37-L1	2	Security	Security - Replace (1) 26 inch x 34 1/2 inch detention glazing pane in the basement holding cell door. Glazing was damaged by an in-custody. Restitution is being sought.	\$ 14,089	\$ 14,089	100.00
509	FM-2008078	Butte	Butte County Courthouse	04-A1	2	and Pa	Security - Grounds and Parking Lot - Replace (3) loop sensors on the judges and staff entrance gate. The sensors have failed due to use, resulting in the entrance gate not operating properly.	\$ 20,552	\$ 20,552	100.00
510	FM-2008407	San Diego	Central Courthouse	37-L1	2	Security	Security - Replace (1) fire-rated electric strike on main entrance doors to building. The electric strike on doors failed due to age and heavy use not allowing for doors to remain closed.	\$ 4,202	\$ 4,202	100.00
511	FM-2008430	San Diego	East County Regional Center	37-I1	2	Security	Security - Replace (1) 17 ft x 16 ft rolling aluminum grille gate, curtain, and guides at the ground level sally port. The gate has failed due to age resulting in the gate not completely closing.	\$ 13,437	\$ 13,437	100.00
512	FM-2008320	Los Angeles	Compton Courthouse	19-AG1	2	Plumbing	Plumbing - GCI - Replace the plumbing fixtures in court exclusive areas throughout the courthouse. The fixtures have reached the end of their useful life and require replacement. The failure of the fixtures and the leaks from the connections has caused major priority 1 projects in the past.	\$ 1,733,400	\$ 1,733,400	100.00
513	FM-2008209	Los Angeles	Compton Courthouse	19-AG1	2	Plumbing	Plumbing - GCI - Replace the plumbing fixtures in common areas throughout the courthouse. The fixtures have reached the end of their useful life and require replacement. The failure of the fixtures and the leaks from the connections has caused major priority 1 projects in the past.	\$ 1,290,000	\$ 853,077	66.13
514	FM-2008213	Los Angeles	Compton Courthouse	19-AG1	2	Plumbing	Plumbing - GCI - Replace the plumbing fixtures in county exclusive areas throughout the courthouse. The fixtures have reached the end of their useful life and require replacement. The failure of the fixtures and the leaks from the connections has caused major priority 1 projects in the past.	\$ 457,100	\$ -	0.00
515	FM-2008143	San Diego	East County Regional Center	37-I1	2	Interior Fin	Interior Finishes - GCI - Replace 88 spectator seats in (2) courtrooms on 1st & 3rd floors. Seating is not usable due to age and use. Environmental testing costs included. Salvageable parts will be retained for repairs throughout the courthouse.	\$ 111,706	\$ 111,706	100.00
516	FM-2007782	Orange	Central Justice Center	30-A1	2	Plumbing	Plumbing - GCI - Replace domestic water piping, hydronic piping, and valves. The systems are failing to age resulting in several leaks throughout the facility. The hidden conditions were found during the Fire Life Safety Modernization Project.	\$ 1,721,206	\$ 1,578,346	91.70
517	FM-2008024	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Vandalism	Vandalism - Restore the finish on (26) courtroom doors. Doors have been vandalized with graffiti. Work includes removing the doors to refinish them. Work to occur on multiple weekends.	\$ 123,485	\$ 99,381	80.48



Item Number	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	FMS By PROJECT TYPE	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
518	FM-2007720	San Diego	Trailer - Family Support	37-F7	2	and Pa	Grounds and Parking Lot - AEI - Install new stormwater drainage system to collect at divert water away from four modular buildings. Standing rainwater is softening the soil resulting in 1 modular building sinking. Work includes reinforcing building 37-F7s footings, connecting downspouts to the stormwater system, and sealing or covering the decks to prevent water intrusion below.	\$ 146,100	\$ 146,100	100.00
519	FM-2008017	Los Angeles	Stanley Mosk Courthouse	19-K1	2	Escalator	Elevators, Escalators, & Hoists - Replace (3) direct drive gears and (1) step chain on escalator 2 and (3) handrails, (4) direct drive gears, (4) step chains, frequency reversing device, (4) curved handrail guides on escalators 3, 5, 6, 25, 26. The components have failed and were identified for replacement during an engineering study.	\$ 2,237,595	\$ 2,176,285	97.26
520	FM-2008059	San Diego	Central Courthouse	37-L1	2	Plumbing	Plumbing - Install (1) domestic water filtration system. The city provided water is highly corrosive, which reduces the lifespan of the buildings plumbing components, resulting in costly replacements.	\$ 141,584	\$ 141,584	100.00
521	FM-2008215	San Diego	Central Courthouse	37-L1	2	Security	Security - Replace (1) 24 ft x 15 ft vehicle steel-gauge panel roll-up gate, (1) safety edge, (8) track roller wheels, (16) hinge assemblies, and (2) infrared loop detectors. The vehicle access gate is failing due to use, resulting in vehicles not being able to enter or exit the parking area without manually operating the gate.	\$ 105,755	\$ 105,755	100.00
522	FM-2008304	Los Angeles	Metropolitan Courthouse	19-T1	2	Plumbing	Plumbing- Domestic Water Booster Pumps- Replace and install (3) domestic water booster pumps (3) skid plates, (3) VFD controls with pressure transducers to control system pressure, approx. 8 ft. of 6" manifold piping, (3) check valves, and (6) cut off valves. Due to domestic water booster pumps (1-3) not working properly.	\$ 112,499	\$ 106,357	94.54
523	FM-2007506	San Joaquin	Stockton Courthouse	39-F1	2	Exterior S	Exterior Shell - Install 6000 SF of 2 in exclusion netting and (1) 4 ft x 7ft netting access door on two rooftop areas, 20 LF of ledge spikes on two roof ledges, and 5,566 SF of 2 in exclusion netting on the front and back of the building. The netting is required to prevent birds roosting in the rooftop mechanical enclosures, roof ledges, and window ledges and mitigate animal droppings from accumulating near air handling equipment and on the window ledges. Work includes removal of bird droppings from the roof area.	\$ 152,410	\$ 152,410	100.00
524	FM-2007777	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Security	Security - Update jail controls, intercom, and door controls with a new touchscreen-based operator Interface. The existing controls are failing. Work is required due to the current system being obsolete and causing interruption to lockup operations when there is a power surge.	\$ 1,046,986	\$ 1,046,986	100.00
Total:								\$ 19,101,955	\$ 16,613,958	



Judicial Council of California

Trial Court Facility Modification
Advisory Committee

Attachment B

Court-Funded Facilities Requests (CFRs)
Quarter 2, Fiscal Year 2024-25

Item Number	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	TOTAL APPROVED
1	01-CFR017	Alameda	01-B3	Wiley W. Manuel Courthouse	Facility Modification	This is a CFR request for Alameda court for the costs of environmental testing for the two (2) interview rooms in the CARE Act Court at Wiley Manuel.	N/A	TCTF	\$ 4,005
2	05-CFR010	Calaveras	05-C1	Calaveras Superior Court	Facility Modification	Funds to cover the cost to have two safes mounted to two separate stands and the stands bolted to the floor for security.	1 Year	TCTF	\$ 1,363
3	07-CFR024	Contra Costa	07-A2	Wakefield Taylor Courthouse	Small Project	Annual Budget	N/A	TCTF	\$ 20,000
4	07-CFR025	Contra Costa	07-A2	Wakefield Taylor Courthouse	Facility Modification	Cost for lead paint on walls, possible abatement, and mounting of wall kiosks at the Wakefield Taylor 1st floor lobby, Bray lobby, and Walnut Creek lobby. This CFR will also fund installation of standard 120v electrical outlets and wiring, if needed, for standing kiosks in the Wakefield Taylor 2nd floor lobby, Spinetta lobby, Pittsburg lobby, and Richmond lobby. Each kiosk has 1 plug for the touch screen and 1 plug for the compact PC. The kiosks are funded by the Signage and Technology Grant. Work must be completed by the 6/30/2025 grant funding deadline.	1 Year	TCTF	\$ 8,000
5	09-CFR007	El Dorado	09-A1	Main St. Courthouse	Small Project	Annual Budget	5 Year	TCTF	\$ 250,000
6	16-CFR016	Kings	16-A5	Kings Superior Court	Facility Modification	The Court's proposed funding contribution [FHOB] cover the concurrent architectural and construction activities related to the completion of Department 12's Courtroom and associated operational and Court staff workspaces. This project will be completed in conjunction with the Judicial Council Facilities group. The planning and project completion will take at least three years and we are unable to encumber money with the Judicial Council. The Court will use the Court Funded Request (CFR) with Judicial Council Facilities each year to keep the project moving forward. TCTF Funds Held on Behalf for the time period covered by the request, including contribution and expenditure: 3 Years FY23/24 through FY25/26, \$1,166,786.	3 years	TCTF	\$ 1,166,786
7	28-CFR008	Napa	28-00	Multiple	Small Project	Annual Budget CFR.	1 Year	TCTF	\$ 20,000
8	30-CFR044	Orange	30-A1	Central Justice Center	Facility Modification	This is a CFR from Orange for modification of the C31 bench so that it is closed off from the witness side for security purposes. This will provide an added layer of protection for the Judicial Officer and is in response to an attack on a Judicial Officer in a Las Vegas courthouse.	N/A	TCTF	\$ 7,660
9	31-CFR027	Placer	31-00	Multiple	Small Project	The court is requesting a successor IBA with the Judicial Council to allow for multiple small projects. These can include hanging signage, furniture moves, minor electrical outlet moves, and other court initiated small projects.	N/A	TCTF	\$ 175,000
10	34-CFR029	Sacramento	34-A1	Gordon Schaber Sacramento Superior Court	Small Project	Annual Budget CFR.	N/A	TCTF	\$ 50,000
11	37-CFR046	San Diego	37-00	Multiple	Small Project	Annual budget for rule 10.810 and non-rule 10.810 allowable small projects.	N/A	TCTF	\$ 300,000
12	45-CFR003	Shasta	45-E1	New Redding Courthouse	Small Project	The proposed funding would be used to complete small projects under \$50,000 each that may or may not be Rule 10.810 allowable.	N/A	TCTF	\$ 50,000
13	45-CFR004	Shasta	45-E1	New Redding Courthouse	Facility Modification	This is a CFR from Shasta to remove a fence in a parking lot recently acquired by Judicial Council and to resurface and restripe the same parking area for court employees, jurors and court visitors.	N/A	TCTF	\$ 50,000
14	50-CFR035	Stanislaus	50-00	Multiple	Small Project	Annual Budget CFR.	N/A	TCTF	\$ 60,000



Item Number	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	TOTAL APPROVED
15	50-CFR036	Stanislaus	50-A1	Modesto Main Courthouse	Facility Modification	Funds for the removal of old solar film and to replace with ASWF Illusion reflective solar film at Modesto Main Courthouse on the upper first floor main entry windows.	N/A	TCTF	\$ 16,829
16	52-CFR009	Tehama	52-E1	Tehama County Courthouse	Small Project	Annual budget for small projects to be completed during fiscal year as needs arise.	N/A	TCTF	\$ 15,000
17	57-CFR008	Yolo	57-A10	Yolo Superior Court	Small Project	Annual Budget CFR.	1 Year	TCTF	\$ 30,000
18	19-CFR158	Los Angeles	19-00	Multiple	Facility Modification	This is a CFR from Los Angeles court for design and infrastructure at multiple locations.	N/A	TCTF	\$ -
19	19-CFR159	Los Angeles	19-00	Multiple	Facility Modification	This is a CFR for Los Angeles for project administration for applying for applying for grants related to the EV charging program for all LA courts except for Catalina Courthouse.	N/A	TCTF	\$ -
20	19-CFR160	Los Angeles	19-00	Multiple	Facility Modification	Project Management Services to support on-going Los Angeles Superior Court projects including, but not limited to Courtroom Modernization, Digital Signage, Landscaping, Lighting, CARE PODS, and Foltz Civil Appeals. For services from November 1, 2024 through September 1, 2025	10 Months	TCTF	\$ 860,000
21	39-CFR026	San Joaquin	39-F1	Stockton Courthouse	Facility Modification	Cost for the install of two (2) new gun safes that will not require engineering approvals. The is the second phase of gun locker updates; Phase 2. The Court will buy the gun safes separate from this CFR. This CFR is for installation-only related fees for the replacement of gun lockers in the men and women's locker rooms in the law enforcement office of the Court, on the first floor. Pride will install the lockers.	1 Year	TCTF	\$ 3,344
22	41-CFR011	San Mateo	41-A1	Hall of Justice	Facility Modification	This is a CFR from San Mateo for the MOU between the County of San Mateo, the Judicial Council of California, and the Superior Court of California, County of San Mateo. The MOU is expected to be executed some time on or after Oct 22, 2024. The court is in need of 2 additional up-to-date court rooms, chambers, and a conference room in the HOJ.	N/A	TCTF	\$ 4,200,000
Total:									\$ 7,287,987