

JUDICIAL COUNCIL OF CALIFORNIA

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on February 25-26, 2016

Title

Court Facilities: Trial Court Facility Modification Quarterly Activity Report for Quarter 2 of Fiscal Year 2015–2016

Submitted by

Trial Court Facility Modification Advisory
Committee
Hon. Donald Cole Byrd, Chair

Agenda Item Type

Information Only

Date of Report January 4, 2016

Contact

Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

Executive Summary

The Trial Court Facility Modification Advisory Committee (TCFMAC) has completed its facility modification funding for the second quarter of fiscal year 2015–2016. In compliance with the *Trial Court Facility Modifications Policy*, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 2, Fiscal Year 2015–2016* as information for the council. This report summarizes the activities of the TCFMAC from October 1, 2015, to December 31, 2015.

Previous Council Action

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*, ¹ adopted by the Judicial Council in 2005 and revised on December 12, 2014. The working group's primary oversight responsibilities included reviewing statewide facility modification (FM) requests and approving FM funding.

The working group's charge was formalized by the Judicial Council on December 14, 2012, and the working group was assigned additional oversight responsibility for the operations and

¹ As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See www.courts.ca.gov/documents/jc-20120727-itemG.pdf.

maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability. On April 25, 2013, the working group's status was elevated to that of advisory committee.

An updated Court-Funded Facilities Request (CFR) approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all CFRs to be reviewed and approved by the TCFMAC. These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at www.courts.ca.gov/2567.htm under Research and Reports: Conditions in Our Courts.

Methodology and Process

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, but Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, but Serviceable; and Priority 6–Hazardous Materials, Managed but Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC predominantly approves FM projects at the Priority 1 and Priority 2 levels. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

Policy and Cost Implications

During the second quarter of fiscal year (FY) 2015–2016, the TCFMAC reviewed and approved a total of 362 facility modifications for a total projected cost of \$21,492,723. The Facility Modification budget is responsible for \$18,123,570 with the respective counties throughout the state being responsible for the remainder. These approved projects were limited to Priority 1 emergency projects and Priority 2 urgent projects. Among other urgently needed projects, the committee approved 12 roof replacement projects in addition to the regular roof maintenance and repair projects. The committee also ratified emergency projects, including a significant number of HVAC and electrical repairs. See Attachment A for a detailed list of all approved projects during the second quarter of FY 2015–2016.

During this quarter, 11 projects required additional funds in excess of \$50,000 from their original estimates. The Facility Modification budget responsibility of these cost increases totaled \$2,487,473. Projects that required excess costs of this magnitude were largely projects for which project managers encountered unforeseen site or equipment conditions.

Also during this quarter, 12 CFRs were reviewed and approved by the TCFMAC, including leases for the Superior Courts of San Diego, Santa Clara, and Tulare Counties and small-project CFRs for the Superior Courts of Alameda, Fresno, Humboldt, Los Angeles, Orange, San Bernardino, and San Francisco Counties. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the second quarter of FY 2015–2016.

Implementation Efforts

The TCFMAC saw a change in leadership this quarter with the Chief Justice's appointment of existing member Judge Donald Cole Byrd to the role of committee chair after the retirement of previous chair Judge David Power. The committee also welcomed new member Judge Jennifer K. Rockwell of the Superior Court of Sacramento County this quarter. Before her appointment as judge in the traffic division, Judge Rockwell was Chief Counsel for the California Department of Finance.

Meeting activities

Under the new chair, the committee conducted two meetings—one in person in Sacramento on October 23, 2015, and one via teleconference on December 7, 2015—to review FM funding requests and to discuss the topics below:

- The committee conducted its regular review of facility modification projects lists: A (Emergency and Priority 1); B (FMs Under \$50K); C (Cost Increases Over \$50K); D (FMs Over \$50K Eligible for Funding); E (Court-Funded Facilities Requests); and F (Funded FMs on Hold).
- The committee received an update on water conservation efforts in support of the Judicial Council's *Water Conservation Policy*, adopted in 2015. These efforts include usage audits and regular meetings with courts on conservation practices.
- The committee prepared and submitted its FY 2014–2015 annual report to the Judicial Council. The report provides an overview and details on the committee's activities and budget expenditures over the course of the year.
- The committee reviewed and approved the *Trial Court Facility Modification Quarterly Activity Report: Quarter 1 of Fiscal Year 2015–2016.*
- The committee received an informational overview and update on the Facilities Policies Working Group's charge and activities.

Completed courthouse project spotlights

The examples below are of facility modifications projects that have been completed during this quarter. These examples illustrate the varied problems that California courthouses regularly face, from emergency repairs and mitigation to projects identified during preventive maintenance rounds and readings. Under any circumstance, it is the committee's goal, with Judicial Council facility management staff, to provide dedicated service and resolution to court users and employees throughout the state.

Priority 2 Project—Elevator renovations at Santa Clara County Hall of Justice West—FM-0022152. The elevators at the Hall of Justice West in Santa Clara County were in poor running condition, and the court staff, public, and sheriff's staff while transporting persons-in-custody were suffering from multiple elevator entrapments. A facility modification project was awarded to Enovity to refurbish the elevators. The project included the replacement of pulleys, belts, motors, and other major components. The replacement of the obsolete, worn-out 30-year-old gear wheels to gearless and the addition of smoke guards to the cabs, per the State Fire Marshal's inspection, were also included in this project. Because of the complexity of their being only one in-custody and one public/staff elevator over the four-month duration of the project, tremendous coordination and teamwork with the Judicial Council Facilities Management unit, court management staff, and the sheriff's office were necessary to schedule the in-work rotation of the elevators. Weekly meetings took place through completion of this project to ensure that the court and the transportation of persons-in-custody were not affected. Final project cost was \$679,541.





Before:

Photo of the mechanical room while removing the old, obsolete gear wheels (far left).

After: New gearless wheels (near left).

Priority 2 Project—Construction of new courtroom in existing space at Betty Lamoreaux Justice Center, Orange County—FM-0050564. With the closure of the Harbor Justice Center – Laguna Hills Facility, the Superior Court of Orange County lost four courtrooms in July 2013. The Betty Lou Lamoreaux Justice Center was not able to absorb the additional Family Law hearings with its given courtroom space and needed an additional courtroom. Existing Domestic Violence Assistance Program (DVAP) work space was converted into a new courtroom, and the DVAP was relocated to an alternate location. With the addition of this new courtroom, the Judicial Council was able to terminate a state-funded lease to encompass court activities. Final project cost was \$828,251.





Before: Court-exclusive work space (left). After: New courtroom (right).

Next Steps

The *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2015–2016* will be submitted to the Judicial Council in June 2016.

Attachments

- 1. Attachment A: TCFMAC-Funded Project List: Quarter 2, Fiscal Year 2015–2016
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 2, Fiscal Year 2015–2016

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----|--------------|----------------------------|---|-----------------|----------|--|----------|----------------------|---|---|
| | | | | | | Security - Replace the existing and antiquated Identification card access control system to a DSX access control system. The buildings' Identification card system is no longer manufactured or supported. The current servers | | | | |
| 1 | FM-0009593 | Butte | Butte County Courthouse | 04-A1 | 2 | and operating systems are outdated and will not support an updated access control system. System failures have had adverse effect on Court operations. | \$ | 74,672 | \$74,672 | 100 |
| | EN 4 0047EE7 | Los Annales | Consulton Consulton | 10 461 | 2 | Plumbing - Replace failed Pressure Relief Valves on 2nd, 4th, 6th & 8th floors; valves are inoperable and require | ۲ ا | 200.000 | Ć257.04 <i>4</i> | 66.42 |
| | FM-0017557 | Los Angeles | Compton Courthouse | 19-AG1 | | replacement. Replace failed Domestic Water Booster Pump package. Electrical - Replace two (2) 3.15M BTU Boilers and one (1) 750Kw Generator. Replacement is required in order | Ş | 389,860 | \$257,814 | 66.13 |
| 3 | FM-0019392 | Los Angeles | Downey Courthouse | 19-AM1 | 2 | to comply with current AQMD standards. | \$ | 796,699 | \$ 666,837 | 83.70 |
| | | | | | | COUNTY MANAGED - Audience Seating, Dept 22 Ceremonial Courtroom - Remove and replace 102 audience | | | | |
| | | | | | | seats (all) in this Courtroom. Damage includes torn fabric, exposed framework and 18 seats damaged beyond | ١. | | | |
| 4 | FM-0025652 | Ventura | Hall of Justice | 56-A1 | 2 | repair. | \$ | 70,000 | \$70,000 | 100 |
| | | | | | | Interior Finishes - Refurbish a 65+ year old Terrazzo lobby floor that is approximately 2,000 square feet. Floor | | | | |
| 5 | FM-0037757 | Merced | Old Court | 24-A1 | 2 | has numerous cracks where many are more pronounced than others. Floor presents a higher risk to high heeled shoes then flatware shoes. | \$ | 101,008 | \$101,008 | 100 |
| | 1101 0037737 | IVICICCU | Edmund D. Edelman | 24 7.1 | | Shoes then hatware shoes. | 7 | 101,000 | 7101,000 | 100 |
| 6 | FM-0041057 | Los Angeles | Children's Court | 19-Q1 | 2 | HVAC - Replace metal front filters - System failure imminent | \$ | 11,522 | \$ 11,522 | 100 |
| | 1101 0041037 | Los / trigeres | Alhambra | 13 Q1 | | Electrical - Replace one (1) 250Kw Generator. ACM abatement required. Replacement is required in order to | 7 | 11,322 | γ 11,322 | 100 |
| 7 | FM-0041137 | Los Angeles | Courthouse | 19-I1 | 2 | comply with current AQMD standards. | \$ | 448,388 | \$385,614 | 86 |
| | | | Santa Barbara | | | | | | | |
| 8 | FM-0050594 | Santa Barbara | Figueroa Division | 42-B1 | 2 | Security - Add handcuff portals to 8 cell doors - Security Risk/High | \$ | 3,096 | \$ 3,096 | 100 |
| | | | Santa Barbara | | | Interior Finishes - Reinstall electronic high volume record filing system. System was removed as part of a P1 | | | | |
| 9 | FM-0051229 | Santa Barbara | Figueroa Division | 42-B1 | 2 | effort re-installation is required to return court to fully operational status. | \$ | 50,000 | \$50,000 | 100 |
| | | | | | | Roof - Remove and replace existing one story section of roof with new and overlay 5 story section of roof with | | | 4 | |
| 10 | FM-0052970 | Los Angeles | Whittier Courthouse | 19-AO1 | 2 | torch applied system. Renovation required due to age and water penetration. | \$ | 742,000 | \$641,311 | 86.43 |
| 11 | FM-0052981 | Los Angolos | East Los Angeles Courthouse | 19-V1 | 2 | Roof - Remove and replace existing failing roof system with new PVC roof system (30,625). | ځ | 715,093 | \$555,770 | 77.72 |
| 11 | FIVI-0032981 | Los Angeles | Courtilouse | 19-71 | | Roof - Remove and replace existing failing roofing systems on main deck, 2nd and 3rd floor Northeast decks as | ٦ | 713,093 | Ş333,770 | 77.72 |
| | | | San Fernando | | | well as machine room roofs at the main roof (approximately 38,000) with a SBS roof System. Roof metal will be | | | | |
| 12 | FM-0052988 | Los Angeles | Courthouse | 19-AC1 | 2 | replaced as needed. | \$ | 807,176 | \$673,266 | 83.41 |
| | | J | | | | Roof - Remove and replace existing roof system at eleven different areas (20,000 SF). Due to the poor condition | <u> </u> | <u> </u> | , , | |
| | | | Monrovia Training | | | of these areas, recommended removal and replacement of existing and building metal will bring entire building | | | | |
| 13 | FM-0053002 | Los Angeles | Center | 19-N1 | 2 | roof to good condition. | \$ | 450,000 | \$316,305 | 70.29 |
| | | | | | | | | | | |
| | ENA 0053033 | 1 0 1 | | 10.14 | | | | COO 004 | 6004.045 | |
| 14 | FIVI-0053003 | Los Angeles | Courtnouse | 19-11 | 2 | | > | 699,821 | \$601,846 | 86 |
| | | | Van Nuws Courthouse | | | | | | | |
| 15 | FM-0053004 | Los Angeles | • | | 2 | | 1 . | 585.070 | \$470.864 | 80.48 |
| | FM-0053003 | Los Angeles Los Angeles | Alhambra Courthouse Van Nuys Courthouse West | 19-I1 19-AX2 | 2 | Roof - Remove and replace existing roof with new SBS roof system - Remove and replace approximately 31,800sf of failing built up roof system. Work will include new building metal, vents and walk pads as needed. Roof - Remove and replace existing failing roof with new SBS roof system - Work to include replacing approximately 25,000sf of failing built up roof, two roof drains, re-coat the Heli-Stop and replace building metal as needed. | \$ | 699,821 585,070 | \$601,846 \$470,864 | 80 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----|---------------|------------------|---------------------------------------|----------------|----------|--|----|----------------------|---|---|
| | | | | | | Roof - Remove and replace existing roof with new SBS roof system - Work to include replacing approximately 34,000sf of failing built up roof, restore roof drains, install tapered insulation as needed and replace building | | | | |
| 16 | FM-0053030 | Los Angeles | Glendale Courthouse | 19-H1 | 2 | metal if not re-usable. | \$ | 757,338 | \$685,694 | 90.54 |
| 17 | FM-0053394 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | Roof - Remove and replace 40,000 square feet of the existing main deck and lower deck sections with new SBS roof system / Due to roof decks currently failing and leaking. Work to include new building metal, vent jacks and equipment curbs as needed | \$ | 845,633 | \$719,972 | 85.14 |
| | | | | | | Roof - Remove and replace 43,000 sf of existing roof with new SBS roof system, currently the existing roof is in | | | | |
| | | | Edmund D. Edelman | | | poor to fair condition at best, work will replace the roof at three building sections at various levels. New | | | | |
| 18 | FM-0053460 | Los Angeles | Children's Court | 19-Q1 | 2 | building metal and curbs will be replaced as needed. (No work to be done on the Heli - Stop). | \$ | 946,000 | \$662,105 | 69.99 |
| 19 | FM-0053549 | Los Angeles | Downey Courthouse | 19-AM1 | 2 | Roof - Remove and replace existing main deck, lower east deck and lower west deck (approximately 34,000 sf) with a SBS type roof system - Due to main and lower decks are past due and beginning to leak during rainy weather. | \$ | 753,487 | \$630,669 | 83.7 |
| | | 3 3 3 | | | | | | | , , , , , , , , | |
| 20 | FM-0053554 | Los Angeles | Pomona Courthouse South | 19-W1 | 2 | Roof - Remove and replace existing roof with new SBS roof system at main deck (23,220 sq. ft.), lower north deck (2,838 sq. ft.), and lower south deck (2,838 sq. ft.). Roofing metal will be replaced as needed. | \$ | 682,895 | \$622,391 | 91.14 |
| 21 | FM-0053561 | Los Angeles | Metropolitan Courthouse | 19-T1 | 2 | Electrical - Failed Exterior Lighting - Replace a total of 98 exterior Mercury Vapor, High Pressure Sodium, and Fluorescent Light fixtures with high efficient LED fixtures. Remove and replace the failed lights and ballasts in 16 soffit areas (Each approximately 8'x8'). Building exterior lighting fixtures/poles have broken lenses, sockets, bulbs and ballasts making the area dark at night, safety issue. Parts are no longer available due to fixtures being outdated. | | 176,525 | \$166,887 | 94.54 |
| | 1111 0033301 | 203711180103 | Courtinouse | 13 .1 | | Roof - Remove and replace 53,000 sf of existing roof with new SBS roof system, currently the existing roof is in | | 170,323 | Ψ100,007 | 33 . |
| | | | Santa Monica | | | poor to fair condition at best, work will replace the roof at three building sections at various levels. New | | | | |
| 22 | FM-0054101 | Los Angeles | Courthouse | 19-AP1 | 2 | building metal and curbs will be replaced as needed. | \$ | 1,114,341 | \$874,646 | 78.49 |
| 23 | FM-0054644 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Grounds and Parking Lot - Replace waterproof membrane, sprinklers, and landscaping in planter on the exterior of the Courthouse near County Council Chambers. Due to years of deterioration the waterproofing membrane in the planter leaks through when there is excessive water present. This was the cause of a serious leak into the County Council Chambers in January 2014. | | 30,000 | \$ 20,997 | 69.99 |
| | | 3 | | | | Vandalism - Glass on elevators #1-4, glass panes on flrs 3 & 8 and men's public restrooms mirrors (all floors) have been vandalized by graffiti being etched into them. Need to remove etching to help prevent future vandalism/safety hazards. Resurface 24 windows and 33 mirrors with multistage polishing to remove graffiti, approximately 2 hrs per window. Remove 3 windows on 3rd flr due to deep etching and install (3) 105" x 65" x | | • | | |
| 24 | FM-0054783 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | 1/2" laminated clear green Solex windows. | \$ | 72,260 | \$55,763 | 77.17 |
| - | | Solano Solano | Hall of Justice Hall of Justice | 48-A1 48-A1 | 2 2 | Interior finishes - Atrium Doors - Replace worn-out and failing atrium door hardware on eight doors to include closers and pull handles and locks and pivot hinges and stops -Doors don't close causing a security issue. Roof - Replace roof. Phase II of existing/funded Phase I FM#50740 | \$ | 41,011 1,341,198 | \$ 29,864 \$ 976,660 | 72.82 72.82 |
| 20 | . 141 0054500 | 30.4110 | 1.4 01 3436166 | 1.0 / 1.1 | | Exterior Shell - South Side Rotary Exit Door - Door Mechanism Failed/Non-Op - Repairs not possible due to age | | ±,5 1±,±50 | 370,000 | , 2.02 |
| 27 | FM-0055052 | Ventura | Hall of Justice | 56-A1 | 2 | and condition. Replacement is required. | \$ | 93,813 | \$93,813 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----|---------------|----------------|----------------------------------|-------------|----------|--|----------------|----------------------|---|---|
| 28 | FM-0056596 | Lassen | New Susanville Courthouse | 18-C1 | 2 | Security - Supply and install new Daikin mini split FTX24LVJU to monitoring office including all Electrical, line set and roof jack - The existing security is required to maintain site monitoring 24/7. Building design does not provide 24x7 support to this area. High weekend temps will cause the equipment premature equipment failure. | | 24,494 | \$ 24,494 | 100 |
| 20 | 1101 0030330 | Lasseri | Courtifouse | 10 01 | | Elevator - Custody elevator #4 - Replace defective parts (1) earthquake plate, (4) cover plate kits, (4) elsco seismic retainers, (8) stud support washers, (24) hex nuts, (4) roller glides and (1) can of LPS cutting fluid. | 7 | 24,434 | 24,434 | 100 |
| 29 | FM-0056653 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | Elevator had cracked roller guide and durng the replacement other critical renovations were identified. Plumbing - Water leak - Remediate wet interior finishes to include approximately 300 square feet of carpet and | \$ | 10,050 | \$10,050 | 100 |
| 30 | FM-0056654 | Alameda | Juvenile Justice Center | 01-C3 | 1 | lower parts of adjacent sheetrock walls with dehumidifiers and fans - Work was performed on off hours and a Sunday. | \$ | 4,538 | \$4,538 | 100 |
| | | | | | | COUNTY MANAGED - HVAC Controls Upgrade - The pneumatic controls that operated the HVAC system at the Jail/Justice Center are leaking and obsolete. This project replaces the original control system with Johnson | | 25.000 | 407.000 | 100 |
| 31 | FM-0056655 | Shasta | Justice Center Metropolitan | 45-A2 | 2 | digital controls. Interior Finish - Remove furniture and stretch carpets in 4 Depts. The carpets are lifting and creating ridges | \$ | 25,000 | \$25,000 | 100 |
| 32 | FM-0056657 | Los Angeles | Courthouse | 19-T1 | 2 | causing a tripping hazard. | \$ | 7,720 | \$7,720 | 100 |
| 32 | 1101 0030037 | 2037 (1186163 | Santa Clara | 13 11 | | Plumbing - Water heater has failed - Replace 1 each 74 gal. domestic hot water heater - Hot water is | Υ | 7,720 | 77,720 | 100 |
| 33 | FM-0056659 | Santa Clara | Courthouse | 43-G1 | 2 | intermittent. | Ś | 4,896 | \$4,896 | 100 |
| | | | | | - | Electrical - Replace (40) Defective 175W HID bulbs with 32W CFL bulbs by modifying existing wiring & conduit directly to bulb sockets and bypassing the defective ballasts on a total of 6 different floors in (14) court | | | | |
| 34 | FM-0056660 | Los Angeles | Compton Courthouse | 19-AG1 | | exclusive depts. Security - Secure parking gate was hit by a sheriff's bus and bus damaged the sensor. Gates were inoperable | \$ | 3,956 | \$3,956 | 100 |
| 35 | FM-0056661 | San Bernardino | New San Bernardino Courthouse | 36-R1 | 2 | due to failed photo eye. and the gate door was stuck open. Replaced two failed photo eyes on the rolling gates to the secured parking lot. ABM manually secured and opened gates daily until delivery of the replacement photo eye sensors. | \$ | 2,671 | \$2,671 | 100 |
| 26 | EN4 00E6662 | Los Angolos | Pomona Courthouse | 10 141 | 2 | Plumbing -Install (1) new Acorn stainless steel sink, (1) new Acorn stainless steel toilet; modify existing drain & water lines to accommodate new fixtures. The current porcelain sink & toilet in lock up cell #1 on the first floor | ٤ | | | 01 14 |
| 30 | FM-0056662 | Los Angeles | South | 19-W1 | | are broken and need to be replaced by stainless steel. HVAC - Replace (2) deteriorated canvas flex connectors for Supply Fan #1 & Exhaust Fan #2. The canvas flex | Ş | 9,603 | \$8,752 | 91.14 |
| 37 | FM-0056664 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | connector are breaking & the connectors have no more flex in them; this condition allows air to escape which can cause damage to ducting & can also cause motor strain. | Ś | 3,273 | \$2,164 | 66.13 |
| | | <u> </u> | , 553 | | | HVAC - The Indoor evaporator fan motor is deteriorated. Replace one existing 3 ton evaporator fan coil and | | -, | 7 -/ 1 | 22.20 |
| | | | Kearny Mesa Traffic | | | install one new required R-22 Thermostatic Expansion Valve (TXV). Need to replace the fan coil to prevent | | | | |
| 38 | FM-0056666 | San Diego | Court | 37-C1 | 2 | future downtime. | \$ | 5,556 | \$5,556 | 100 |
| 30 | FM-0056667 | San Diego | Kearny Mesa Traffic Court | 37-C1 | 2 | Plumbing - Leaking Water Heater - Remove and replace one, 100 Gallon Water Heater, and extract water from the public hallway. | ¢ | 3,208 | \$3,208 | 100 |
| 33 | 1 141 0030007 | Jan Diego | Court | J, C1 | | Plumbing - Provide remediation for flood on the second and third floors caused by a malfunctioning toilet; | , , | 3,200 | 73,208 | 100 |
| | | | | | | Provide two laborers for 6 hours to dry out the second and third floor jury rooms and hallways; Provide 2 | | | | |
| | | | | | | dehumidifiers, 12 fans for three days - Toilet malfunctioned and flooded the hallways and jury rooms on two | | | | |
| 40 | FM-0056668 | Contra Costa | Bray Courts | 07-A3 | 2 | floors. | \$ | 6,485 | \$6,485 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----|--------------|--------------|-----------------------------------|-------------|----------|---|----|----------------------|---|---|
| | | | | | | Electrical - Install (2) new 20amp 120v electrical outlets in marked out spots on the wall in the old pay phone | | | | |
| | | | Inglewood Juvenile | | | area; run approx. 20LF of conduit & wiring inside wall, over top, and down to new dedicated 20amp breakers installed on existing breaker box located inside nearby IT closet. Currently two vending machines are poorly | | | | |
| 11 | FM-0056671 | Los Angeles | Court | 19-E1 |) | located in 2 separate areas on the first floor and the location is away from departments & public waiting areas. | خ | 4,438 | \$3,585 | 80.78 |
| 41 | FIVI-0030071 | LOS Aligeles | North County | 19-L1 | | Electrical - Exit signs are dim and may not be visible in case of an emergency. Need to replace the exit signs as | γ | 4,430 | 33,363 | 80.78 |
| | | | Regional Center - | | | this a potential safety issue. Isolate electrical circuit and replace 50 exit signs. Install 50 exit signs with battery | | | | |
| 42 | FM-0056672 | San Diego | Vista Center | 37-F2 | 2 | backup. | \$ | 4,775 | \$4,775 | 100 |
| 72 | 1101 0030072 | San Diego | Vista Ceriter | 37 12 | | buckup. | 7 | 7,773 | үч, 773 | 100 |
| | | | North County Regional Center - | | | Interior Finishes - Smoke Restoration - Replacement of 30 sq ft drywall, 260 pieces of 12x12 ceiling tiles, primer all painted walls with Kilz and apply final coat of paint, install 240 sq ft new carpet, replacement of 6 light fixture lens and thermostat. Short in personal fan unit creted a fire impacting Attorney / Client Mediation | | | | |
| 43 | FM-0056676 | San Diego | Vista Center | 37-F2 | 1 | Room between Dept. 15 and 17. Room is unavailable and restoration is needed to restore room to use. | \$ | 55,463 | \$55,463 | 100 |
| | | | Bellflower | | | HVAC - Condenser pump has failed and bearings seized, causing Chiller #2 to trip due to high pressure. Need to | | | | |
| 44 | FM-0056682 | Los Angeles | Courthouse | 19-AL1 | 1 | replace condenser pump and motor. | \$ | 20,443 | \$15,933 | 77.94 |
| 45 | FM-0056683 | Contra Costa | Arnason Justice Center | 07-E3 | 2 | Grounds and Parking Lot - Cut down and remove (13) 25 ft trees that have grown to where they are blocking the views of the security cameras; Grind the stumps and remove the debris; Plant 13 small, drought tolerant shrubs in place of the trees. The trees are blocking camera views of the entry to the Judges parking lot, the sally port entrance, the employee parking lot, and two public entrances to the Courthouse. This work is recommended by JCC Security Operations. | | 5,843 | \$5,843 | 100 |
| | | | Metropolitan | | | Plumbing - Drain Line Leak - Remove and replace 50' of 3" cracked Cast iron pipe and extract approximately 10 gallons of water. Drain restriction in the 1st floor snack bar creating water to leak down to the Level A Sheriff's Women's Locker Room affecting 9'x7' hard lid ceiling. 9'x7'x9.5' ACM containment erected in locker room and 3 | | | | |
| 46 | FM-0056684 | Los Angeles | Courthouse | 19-T1 | 1 | a stage wipe down on 12'x10' area on the 1st floor was required. | \$ | 15,000 | \$14,181 | 94.54 |
| 47 | FM-0056685 | Lake | South Civic Center | 17-B1 | 2 | Interior Finishes - Install a baby changing station in both men's and women's restrooms. | \$ | 1,268 | \$938 | 74 |
| | | | Metropolitan | | | Plumbing - Rebuild booster pump #3 that is leaking. Currently the pump is leaking water and if it is not rebuilt, the pump could fail effecting water pressure to the upper floors which include all the bathrooms, cooling | | | | |
| 48 | FM-0056687 | Los Angeles | Courthouse | 19-T1 | 2 | towers and boilers. | \$ | 4,992 | \$4,719 | 94.54 |
| 49 | FM-0056688 | Orange | West Justice Center | 30-D1 | 2 | Electrical - Uninterrupted Power Source (UPS) - Replace the Syncron AC Power Board, DC Power Board and Inverter Control Board for Emergency Egress Lighting UPS 4. The emergency lights in Courtrooms W10 and W12 have failed. This was very disruptive to the Courtrooms. | \$ | 4,802 | \$4,354 | 90.68 |
| | | | Clara Shortridge Foltz | | | Plumbing - Toilet and Urinal Angle shut off valves replacement. Replace approx. 30 failed and damaged 1.5" | | | | |
| 50 | FM-0056689 | Los Angeles | Criminal Justice Center | 19-L1 | 2 | angle shut off on urinals and 3.5" angle shut off valves on toilets in various restrooms from P-Level up to the 15th floor. | \$ | 4,978 | \$3,424 | 68.79 |
| | | | Alhambra | | _ | HVAC - The motor on AHU #4 has bad bearings & is ready to fail; if AHU#4 goes down the entire 4th floor will be without air flow for heating/cooling. Replace (1) 25HP motor on Air Handler Unit #4 inside roof top mechanical | | | 4 | |
| 51 | FM-0056690 | Los Angeles | Courthouse | 19-I1 | 2 | room using special rigging; re-use existing guards, belts, pulley, & commission motor to operate. | \$ | 4,539 | \$3,904 | 86 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----|----------------|----------------|--|----------------|----------|--|--|----------------------|---|---|
| 52 | FM-0056691 | San Diego | East County Regional Center | 37-l1 | 2 | Plumbing - Piping above the T-bar ceiling grid in the 5th floor D.A. office area was cracked and needed replacing. Replaced 10' section of 2" piping and fittings. | ς . | 2,454 | \$1,662 | 67.71 |
| 32 | 1101 0030031 | San Diego | Center | 37 11 | | HVAC - Boiler #2 motor and pump have failed. Re-build one (1) pump and replace one (1) motor; install re-built | 7 | 2,434 | 71,002 | 07.71 |
| 53 | FM-0056692 | San Diego | Juvenile Court | 37-E1 | 2 | pump. | \$ | 4,524 | \$3,376 | 74.62 |
| | | | | | | Fire Protection - Replace Fire Pump #1 heat exchanger core, install new gaskets & seals, thermostats and | | , | | |
| | | | | | | alternator belts. Fire Pump #1 heat exchanger has a water leak. Heat exchanger is meant to keep diesel engine | | | | |
| _ | | Los Angeles | Compton Courthouse | | 2 | at an allowable temperature while running. | \$ | , | · | 66.13 |
| 55 | FM-0056695 | Solano | Hall of Justice | 48-A1 | 2 | Elevators -Remove protruding wires from concrete wall inside hoist way based on DIR notice. | \$ | 3,432 | \$2,499 | 72.82 |
| | | | | | | HVAC - AHU-3 is not operating properly - AHU-3 solenoid valve must be replaced and strainer must be | | | | |
| | EN 4 005 660 6 | | D | 40 4844 | 4 | unclogged. The failed system is affecting the cooling of the elevator - mechanical room. Excessive heat in the | _ ا | C 445 | ĆE 442 | 02.7 |
| 56 | FM-0056696 | Los Angeles | Downey Courthouse | 19-AM1 | 1 | elevator room can affect the performance of the elevator equipment. | \$ | 6,145 | \$5,143 | 83.7 |
| 57 | FM-0056697 | Los Angeles | Bellflower Courthouse | 19-AL1 | 1 | HVAC - Replace failed VFD & Motor. AHU #3 Return fan 5HP VFD is not operating and 5 HP Motor has shorted out. Currently the third floor has inadequate cooling due to the air handler not functioning properly. | \$ | 9,435 | \$7,354 | 77.94 |
| 58 | FM-0056698 | Riverside | Larson Justice Center | 33-C1 | 1 | Fire Protection- Remove and replace failed 10" fire service DCDS backflow assembly device (N. side of building) with new 10" backflow and relocate above ground per CA plumbing code. Current backflow is located in below ground vault and is leaking. Vault will be back-filled and compacted prior to new installation. Fire Protection - Remediate non-code compliant conduit penetrations - Install fire stopping at several areas in the basement ceiling/floor concrete at conduit penetrations. The concrete spawled when drilled exposing rebar | \$ | 35,236 | \$28,474 | 80.81 |
| | | | | | | in areas and fire stopping was never installed. Spawled areas to be patched with a cementious material. Work | | | | |
| 59 | FM-0056699 | Los Angeles | Glendale Courthouse | 19-H1 | 2 | was identifide by the State Fire Marshal. | \$ | 4,298 | \$3,891 | 90.54 |
| 60 | FM-0056700 | San Bernardino | Needles Courthouse- Dept. N-1 | 36-K2 | 2 | COUNTY MANAGED- Roof- Replace / reseal roof as needed in an approx. 7,200SF area, replace and counter flash ducting and mechanical roof penetrations as needed to make 100% weather tight. Work is necessary to prevent water intrusion in the rainy season. | \$ | 10,249 | \$10,249 | 100 |
| 61 | FM-0056701 | Los Angeles | Bellflower Courthouse | 19-AL1 | 1 | Elevators, Escalators, & Hoists - Remove damaged and broken Elevator car doors; install new 42"x93" Stainless steel elevator doors. Elevator #2 has cracked welds and damaged doors that are beyond repair and non-operational. This leaves the Court public elevators down to 50% operable and elevator lobbies overcrowded. | ς . | 8,344 | \$6,503 | 77.94 |
| 51 | 141 0030/01 | LOS MIGEIES | Arnason Justice | 12 75 | | Exterior Shell - Vandalism - Replace damaged ADA powered door opener/closer. An angry member of the public | | 0,344 | دىد,ىد | 77.34 |
| 62 | FM-0056702 | Contra Costa | Center | 07-E3 | 2 | slammed the door open, damaging the exit door. | Ś | 9,006 | \$9,006 | 100 |
| | | San Mateo | Municipal Court Building - Northern Branch | 41-C1 | 2 | HVAC - Expansion Tank - Replace failed existing expansion tank w/new bladder tank - Existing expansion tank has failed forcing blow off valve to vent hot water. | \$ | 6,191 | \$5,152 | 83.21 |
| | | | Alhambra | | | Vandalism - Prime and paint (16) 10' tall aluminum columns - (8) on the 2nd floor, (8) on the 3rd floor. The | | | | |
| | | Los Angeles | Pomona Courthouse | 19-I1 19-W1 | 2 | aluminum columns have been vandalized with offensive & obscene words & pictures. Elevators, Escalators, & Hoists - Elevator will not power up. Swing panel boards and power supply for elevator #3 have failed. Replace faulty swing panel boards and power supply for elevator #3 and return elevator to | \$ | 3,756 | \$3,230 | 91 14 |
| 05 | FM-0056706 | Iros Hilagies | South | T2-AAT | | service. | ۲ | 10,495 | \$9,565 | 91.14 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------|--------------|--|-------------|----------|---|------------|----------------------|---|---|
| 66 | FM-0056708 | Los Angeles | Downey Courthouse | 19-AM1 | 2 | Elevators, Escalators, & Hoist - Elevator Failure - Remove and replace 1 emergency light and 1 alarm board in the elevator, validate proper operation of seismic derailment wire in the elevator hoist way. | \$ | 3,331 | \$2,788 | 83.7 |
| | | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | Holding Cell - The inner door inside Lock Up holding cell B in the basement is not closing properly due to a very old & defective automatic door closer that has worn out internal gears; this affects the Sheriff's safety. Fabricate failed hardware and rebuild the automatic door closer. Original unit is no longer manufactured. | \$ | 10,453 | \$7,249 | 69.35 |
| 68 | FM-0056710 | San Diego | North County Regional Center - Department 34 Trailer | 37-F4 | 2 | HVAC - Compressor has failed- Install compressor heat pump, reversing valve, compressor contactor, and replacement filter drier. Area becomes warm due to lack of air conditioning. | \$ | 2,865 | \$2,865 | 100 |
| | | | South County Justice | | | HVAC - Glycol Leak - Isolate leak and replace failed parts. Thermal Energy Storage Tank #2 is leaking 30% glycol | | | | |
| 69 | FM-0056712 | Tulare | South County Justice Center | 54-I1 | 1 | mixture into the tank. Tank #2 is not operational due to the leak and the ice system is not providing necessary cooling to the building. | Ġ | 30,000 | \$30,000 | 100 |
| 05 | 1101 0030712 | Tulare | Center | 34 11 | | | 7 | 30,000 | 730,000 | 100 |
| 70 | FM-0056713 | Santa Clara | Old Courthouse | 43-B2 | 2 | HVAC- Boiler has failed- Replace (2) pressure gauges, (1) liquid fill gauges, (1) PRV, Re-wire 1 controller and Reprogram for proper operation Required to maintain the required heating capability | \$ | 5,103 | \$5,103 | 100 |
| | | | Downtown Superior | | | HVAC - Replace (4) failed& leaking heating hot water isolation valves and (1) Bearing assembly -Insufficient | | | | |
| 71 | FM-0056714 | Santa Clara | Court | 43-B1 | 2 | heating capacity | \$ | 4,889 | \$4,889 | 100 |
| 72 | FM-0056715 | Los Angeles | Van Nuys Courthouse East | 19-AX1 | 2 | Exterior Shell - Broken glass in the secured clerk's area. Removed broken glass and temporarily boarded up affected area with (2) sheets of 3/4 inch plywood. Install (1) 1/4" grey safety laminated glass in customers gasket storefront system approx. 48" x 30". | \$ | 5,000 | \$4,487 | 89.74 |
| 73 | FM-0056716 | Los Angeles | Clara Shortridge Foltz Criminal Justice Center | 19-L1 | 1 | Plumbing - Replace cracked water pipes inside of the wall in the Law Library Conference Room #602-8. Remove and renovate 4ft x 3ft damaged area and a new cut-off valve to minimize future damage. ACM work required. Leak was caused by water the pipes "hammering" inside the wall. Approximately 80 gallons of water leaked into affected areas. Water leaked down to the 5th floor Clerks area. | \$ | 65,665 | \$45,171 | 68.79 |
| 7.4 | ENA 00E 6747 | | A: | 40 4114 | 2 | Plumbing - Failing Backflow Preventer – Remove and replace one failing backflow preventer in the 10th floor | 4 | 2 400 | ¢4.020 | 77.47 |
| /4 | FM-0056717 | Los Angeles | Airport Courthouse Metropolitan | 19-AU1 | 2 | chiller room. Code required. HVAC - Replace failed motor to Cooling tower #2. Motor has grounded out and non-operational. Currently cooling tower #1 is in operation but to maintain the comfort cooling in the building, the Cooling Tower #2 | \$ | 2,488 | \$1,920 | 77.17 |
| 75 | FM-0056718 | Los Angeles | Courthouse | 19-T1 | 2 | motor must be replaced. | \$ | 9,972 | \$9,428 | 94.54 |
| 76 | FM-0056720 | Los Angeles | Chatsworth Courthouse | 19-AY1 | 2 | Electrical - The inverter board & power supply for the Uninterruptible Power System (UPS) are not working and need to be replaced; the UPS backs up power to multiple areas of the courthouse including the emergency lights which are critical. Replace (1) inverter board & power supply for 7KW DSPM Inc. power panel for the UPS. | \$ | 10,806 | \$9,055 | 83.8 |
| 77 | FM-0056721 | I os Angeles | Bellflower Courthouse | 19-AL1 | 2 | Elevators, Escalators, & Hoists: Renovate Generator Motors- The Generator and Motors on Elevators 1, 2, 3, & 4 have accumulated a large amount of carbon dust build up over time which can cause the generators / motors to fail to ground. The failure of these elevators may result in passenger entrapments. | | 20,954 | \$ 16,332 | 77.94 |
| | | 02.30 | | | | 1 2 | <u>. '</u> | - / | , | . , |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----|--------------|--------------|--|-------------|----------|--|---------|----------------------|---|---|
| | | | Parking Structure Lot 94 Airport | | | Electrical Pemove and replace 40 LIDS batteries to the emergency circuit backup invertor system for the | | | | |
| 78 | FM-0056722 | l os Angeles | Courthouse | 19-AU2 | 2 | Electrical - Remove and replace 40- UPS batteries to the emergency circuit backup inverter system for the parking structure. They no longer accept a charge. | 5 | 26,779 | \$20,665 | 77.17 |
| 78 | 1101 0030722 | Los Angeles | Courtilouse | 15 AU2 | | Plumbing - Rebuild deteriorated/failing Hot water pumps 1 & 2. Hot water pump isolation valves have failed necessitating draining the buildings hot water loops to replace the pumps. Demo insulation and (4) 4in gate valves, replace with new 4in lug type butterfly isolation valves. Remove and rebuild (2) existing hot water | 7 | 20,773 | ¥20,003 | 77.17 |
| 79 | FM-0056723 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | pumps and re-install pumps. | \$ | 40,224 | \$26,600 | 66.13 |
| | | | East County Regional | | | Plumbing - Boiler #3 has failed due to flue gas condensing in system as a result of boiler not reaching 110 degree inlet temperature within 2-4 minutes of start-up. Demo existing failed boiler and install (1) new Raypak MVB 2003 1,999,000 BTU boiler. Install (1) Raypak Z12 Condensate Neutralizer Kit, (1) Raypak Cold Water Starter Kit (to eliminate flue gas condensing), 10LF of 2-1/2" copper pipe, 10LF of 1-5/8 " x 1-5/8" channel | | | | |
| 80 | FM-0056725 | San Diego | Center | 37-I1 | 2 | framing and (6) copper elbows. | \$ | 77,329 | \$52,359 | 67.71 |
| | | | Pasadena | | | Plumbing - Replace leaking sink and drain pipe. 6th Floor Janitor's Closet sink drain pipe leaked and water has | | | | |
| 81 | FM-0056726 | Los Angeles | Courthouse | 19-J1 | 1 | leaked down into the 5th Floor Judges Lounge. | \$ | 5,000 | \$3,468 | 69.35 |
| 82 | FM-0056727 | Los Angeles | Edmund D. Edelman Children's Court Edmund D. Edelman | 19-Q1 | 2 | HVAC - Chiller #2 will not operate properly due to high motor bearing temperature due to a blockage in the motor cooling line. Remove and replace failed economizer. HVAC - Restore chiller#1 with a Rydlyme treatment and tube brushing on Chiller #1. Scale and calcium buildup inside of the condenser tubes which is causing poor beat transfer at condenser barrel. Building system not | \$ | 5,540 | \$3,877 | 69.99 |
| 83 | FM-0056728 | Los Angeles | Children's Court | 19-Q1 | 1 | inside of the condenser tubes which is causing poor heat transfer at condenser barrel. Building system not cooling the facility. Court is impacted. | ر | 15,254 | \$10,676 | 69.99 |
| 03 | 1101 0030728 | LOS Aligeies | Arvin/ Lamont | 13 Q1 | | Plumbing - Replace failed 3" 90 degree pipe in the main domestic water. Line is located in the lawn area on the | - | 13,234 | \$10,070 | 05.55 |
| 84 | FM-0056729 | Kern | Branch | 15-H1 | 2 | north side. Install new 90, pipe and fittings. | Ś | 3,783 | \$2,304 | 60.91 |
| | | | Criminal Court | | | HVAC - Failed Condenser Fan on Condenser 2 of Mammoth AC1; replace bearings, shaft, blade, pulley, belts and | T | 3,133 | + =/ | |
| 85 | FM-0056730 | Napa | Building | 28-A1 | 2 | motor sheave. Bearing and sheaves failed, damaging condenser fan. | \$ | 8,494 | \$8,494 | 100 |
| 86 | FM-0056731 | Los Angeles | El Monte Courthouse | 19-01 | 2 | Electrical - The diesel transfer pump is currently leaking during operation and has a bad motor. Replace existing pump and motor with skid mounted 4GPM diesel pump and 1/3HP 120V AC motor; includes new filter & assembly. | \$ | 5,714 | \$3,321 | 58.12 |
| | | | Arnason Justice | | | Elevator - Install three (3) Expanding doorway flood barriers and cove base for wall barrier - Remove the sound proofing approximately 12" off the floor; Seal electrical penetrations in the three (3) elevator mechanical rooms; Label the annular sensor in the generator belly tank's secondary containment - Work is required by | | | | |
| 87 | FM-0056732 | Contra Costa | Center | 07-E3 | 2 | code. | \$ | 14,410 | \$14,410 | 100 |
| 88 | FM-0056733 | Kern | Bakersfield Superior Court | 15-A1 | 2 | HVAC - Restore AHU 21 to full functionality, bearings and shaft were damaged/worn on AHU 21 rendering Public Defender's offices and Jury Services lobby with minimal cooling. Installed a new shaft, (2) new bearings and removed existing long shaft from blower wheel. | \$ | 11,030 | \$6,909 | 62.64 |
| | ENA 0056706 | | Fremont Hall of | 04 114 | | Plumbing - HVAC - Replace two (2) each failed and leaking isolation valves and one (1) each failed pneumatic | , | 4 000 | 63.064 | 70.4 |
| | | Alameda | Justice County Courthouse | 01-H1 | 2 | Interior Finishes - Sound deadening material - install sound deadening material in vestibule between courtrooms A & B on 1st floor, and landing, approx 480 Sq ft. currently this vestibule is producing noise that is | \ \dots | 4,992 | \$3,964 | 79.4 |
| 90 | FM-0056737 | Mendocino | County Courthouse | 23-A1 | | disrupting court proceedings. | ۱۶ | 2,354 | \$1,592 | 67.62 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|----------|----------------|-------------------------|---------------------|-------------|----------|--|----------|----------------------|---|---|
| | | | North County | | | | | | | |
| | | | Regional Center - | | | HVAC - Package Units #1 & #2 supply HVAC to interior spaces and were non-operational causing uncomfortable | | | | |
| 04 | EN 4 00E 6720 | C Di | Department 34 | 27.54 | _ | conditions and potential health issues. Removed and replaced compressors and fan motors in Package Units #1 | | F (42) | Ć4 245 | 77.40 |
| 91 | FM-0056738 | San Diego | Trailer | 37-F4 | 2 | and #2. | \$ | 5,612 | \$4,345 | 77.42 |
| | | | Dol Norto County | | | HVAC - Replace damaged Vent/Louver - Remove the existing rusted and failing outside air intake vent/Louver | | | | |
| 0.2 | FM-0056739 | Del Norte | Del Norte Court | 00 41 | ٠, | and replace with a new stainless steel version to matchthe the existing unit. Stainless steel required due to the | ۲ | 2 900 | ¢1 716 | 61.27 |
| 92 | FIVI-0050759 | Del Norte | Superior Court | 08-A1 | | location of the building next to the ocean. Elevators, Escalators, & Hoists - Power supply to Elevator #4 is not working and needs to be replaced. Replace | Ş | 2,800 | \$1,716 | 61.27 |
| 03 | FM-0056740 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | non-working Power Supply on Elevator #4. | خ | 4,121 | \$3,180 | 77.17 |
| 93 | 1101-0030740 | LOS Aligeles | Airport Courtilouse | 13-A01 | | Plumbing - A sewer line above the ceiling failed - Remove and replace 10 ft. section of 4 inch cast iron sewer | ٦ | 4,121 | 73,180 | //.1/ |
| | | | | | | line. Extract black water resulting from the failed sewer line, disinfect all horizontal and vertical surfaces, office | | | | |
| | | | | | | equipment and carpet in Room 3005. Remove and replace all ceiling tiles in room 3005. Work is per ACM | | | | |
| 94 | FM-0056741 | San Diego | County Courthouse | 37-A1 | 1 | protocols. | Ś | 11,658 | \$11,658 | 100 |
| <u> </u> | 55507.12 | 24.1.2.1080 | North County | 07712 | | | Υ | 11,000 | Ψ11,000 | |
| | | | Regional Center - | | | Plumbing - Septic sump pumps have failed, this will cause backup in the supported trailers plumbing system. | | | | |
| 95 | FM-0056743 | San Diego | Traffic Annex | 37-F3 | 2 | Replace (2) existing 100V, 1/2HP sump pumps including new check valves, and 4ft of 2 inch ABS piping. | \$ | 4,994 | \$4,994 | 100 |
| | | | | | | Plumbing - Domestic water line was leaking on the 6th floor. Replace 6 feet of defective 1/2" copper water | <u>'</u> | , | , , | |
| | | | Inglewood | | | supply line above the ceiling inside Room 603. Enclosed barrier 6' x 6'x 10' for AVCM. Replaced 4 - damaged | | | | |
| 96 | FM-0056745 | Los Angeles | Courthouse | 19-F1 | 1 | ceiling tiles. | \$ | 30,055 | \$22,409 | 74.56 |
| | | | Stanley Mosk | | | Plumbing - Replace failed domestic water handle and remediate water damage in Room 105E break room. | | | | |
| 97 | FM-0056746 | Los Angeles | Courthouse | 19-K1 | 1 | Water saturated 300 sq feet. | \$ | 12,102 | \$11,770 | 97.26 |
| | | | Hayward Hall of | | | HVAC - Replace failed HV cable splices on chiller line power in control panel, includes (3) 760 amp terminal | | | | |
| 98 | FM-0056747 | Alameda | Justice | 01-D1 | 2 | blocks in starter cabinet, and (6) copper feeders. | \$ | 5,433 | \$5,433 | 100 |
| | | | | | | Plumbing - Failing Sewage Ejector Pumps #1 & #2 - Restore Ejector Pump #1 and replace cracked leaking piping | | | | |
| | | | Metropolitan | | | for Ejector Pump #2. Sewage Ejector Pump #1 motor is not working and Sewage Ejector Pump #2 has a cracked | | | | |
| 99 | FM-0056748 | Los Angeles | Courthouse | 19-T1 | 1 | discharge line. | \$ | 20,067 | \$18,971 | 94.54 |
| | | | | | | Grounds and Parking Lot - Judges' secure exit gate will not open. The overhead wheels that support the door | | | | |
| | | | North County | | | are seized. The main control circuit board and control relay have failed. In the event of an emergency situation, | | | | |
| | | | Regional Center - | | | egress could be inhibited. Damage to vehicles could occur using the entry gate as an exit. Replace (1) main | | | | |
| 100 | FM-0056749 | San Diego | South | 37-F1 | 2 | circuit board, (1) control relay and (4) truck rollers. | \$ | 6,088 | \$4,094 | 67.24 |
| 401 | EN 4 005 055 1 | C D !! | San Bernardino | 26.44 | | Plumbing - Abandoned 8" cast iron drain line is leaking into court space. Cleanly cut 8" break and concrete filled | _ ا | 40.474 | 440.04 | 05.64 |
| 101 | FM-0056751 | San Bernardino | Courthouse | 36-A1 | 2 | waste line. Install permanent cap. | \$ | 10,471 | \$10,014 | 95.64 |
| 103 | ENA 005 6753 | Volo | Troffic Count | [T A 2 | 4 | Utilities - Replace failed hardware on exterior sprinkler system. Remediate water damage in courtroom office | ۲ | C 207 | ¢c 207 | 100 |
| 102 | FM-0056753 | Yolo | Traffic Court | 57-A3 | 1 | area within ACM protocals. | \ | 6,287 | \$6,287 | 100 |
| | | | | | | COUNTY MANAGED- Parking Lot- Demo approx. 205,938SF 3 inch depth of asphalt and resurface with approx. | | | | |
| | | | Victorville | | | 205,938SF 3 inch thick asphalt & re-stripe. Demo concrete sidewalks and pour new ADA sidewalks and parking | | | | |
| | | | Courthouse-Dept. N- | | | approx. 1,750SF, install truncated domes, and signage to bring up to code. Slurry seal new asphalt. Currently parking is not up to ADA code in some areas and the asphalt in the parking lot has numerous cracks, pot holes, | | | | |
| 102 | EM_0056755 | San Bernardino | 1 | 36-L1 | 2 | and uneven areas that pose a tripping hazard. | ر | 342,744 | \$342,744 | 100 |
| 103 | נכ/טכטט־ואו ון | ביוומוטוווט ביוומיטוווט | <u> </u> | 120-FT | | jana aneven areas mat pose a mpping nazara. | ا ک | J44,/44 | ې۵4۷,/44 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------|--------------|---------------------|-------------|----------|--|----------|----------------------|---|---|
| | | | | | | Fire Protection - State Fire Marshal inspection deficiencies - Throughout courthouse, Seal (120) 6" penetrations with intumescent fire caulking, install 120 glow-in-the-dark one sided exit signs; replace 25 damaged labels on | | | | |
| | | | Edmund D. Edelman | | | fire doors. Kitchen area replace damaged fire door with 90 minute fire rated door and a 6' door coordinator. | | | | |
| 104 | FM-0056756 | I os Angeles | Children's Court | 19-Q1 | 2 | Loading dock replace (1) pair of double doors with mortis locks, 2 closers and door vision glass. | Ś | 49,959 | \$34,966 | 69.99 |
| 101 | 1101 0030730 | 20371166163 | Cimaren s Court | 15 Q1 | | Interior Finishes - Stairwell #3 stair risers/nosing have deteriorate over time with many breaking off. Broken | 7 | 13,333 | γ3 1,300 | 03.33 |
| | | | | | | risers/nosing present a tripping/safety hazard in stairwell and need to be replaced with ADA/OSHA compliant | | | | |
| | | | | | | tread. Demo existing tread/riser covers and addition 6" of tile/linoleum per step. Drill 1/4" holes in concrete for | | | | |
| | | | Edmund D. Edelman | | | countersunk masonry screws, 4 screws per stair (628 fasteners). Install (157) 4.5' W Flexmaster black/yellow | | | | |
| 105 | FM-0056757 | Los Angeles | Children's Court | 19-Q1 | 2 | safety renovation treads. | \$ | 71,602 | \$50,114 | 69.99 |
| 100 | | | Santa Clarita | | | County Managed - HVAC - Remove and Replace failing boiler #2 at the Santa Clarita Civic Center Power Plant. | 7 | , = = | φοσ,==: | |
| 106 | FM-0056758 | Los Angeles | Courthouse | 19-AD1 | 2 | Remove and replace expansion tank. Install new burners and controls. | Ś | 40,720 | \$ 40,720 | 100 |
| | | | | | _ | HVAC - Remove and replace failed ABB-VFD for HVAC unit #13 (OM00015825) with a new Nema 1 ABB-VFD | 7 | . 5), 25 | Ψ, | |
| | | | Central Justice | | | (with bypass), current damaged VFD is in by-pass mode and is requiring immediate replacement to avoid | | | | |
| 107 | FM-0056762 | Orange | Center | 30-A1 | 2 | system failure. | \$ | 5,109 | \$4,658 | 91.17 |
| | | | | | | Grounds and Parking Lot -Sally Port Roll up motor failed. Installed (1) new SGH motor operator, a new loop | <u>'</u> | , | , , | |
| 108 | FM-0056763 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | detector, photo eye, and coil cord. | \$ | 4,858 | \$3,749 | 77.17 |
| | | | · | | | Elevators, Escalators, & Hoists - Elevator #9 car equipment replacement. Elevator floor level buttons are | | , | | |
| | | | South County | | | malfunctioning and need to be replaced. Install 3 failing handrails using a bolt-through fastening system. Install | | | | |
| 109 | FM-0056764 | San Diego | Regional Center | 37-H1 | 2 | 2 car Level Indicator Buttons. Work is code required. | \$ | 9,087 | \$9,087 | 100 |
| | | | | | | Grounds and Parking Lot -Damaged underground conduit causing light out above parking space #6 at Secured | | | | |
| | | | | | | Judges parking. Underground conduit has been crushed/broken at several spots and the wiring is damaged. | | | | |
| | | | | | | Install 45' new underground conduit and wiring to restore power to the affected parking lot pole. Hand dig | | | | |
| 110 | FM-0056766 | San Diego | Juvenile Court | 37-E1 | 2 | required to protect irrigationand control wiring. | \$ | 7,951 | \$7,951 | 100 |
| | | | | | | Exterior Shell - Sheriff's custody bus hit the sallyport gate and damaged the guiderails making the gate | | | | |
| 111 | FM-0056768 | Los Angeles | Torrance Courthouse | 19-C1 | 1 | nonfunctional causing a safety/security situation for the court. Replaced 2- damaged guiderails. | \$ | 12,677 | \$10,793 | 85.14 |
| | | | | | | Plumbing - Water leak in Room 323 Judge's Lounge; Approx. 2 sq ft of carpet affected and 4 ceiling tiles. 4th | | | | |
| | | | Stanley Mosk | | | floor Mechanical Room had water leak due to backed up floor drain. Replace 4 damaged ceiling tiles, remove | | | | |
| 112 | FM-0056773 | Los Angeles | Courthouse | 19-K1 | 1 | and replace 60 ft. of insulation under ACM conditions. | \$ | 15,195 | \$14,779 | 97.26 |
| | | | | | | | | | | |
| | | | Santa Monica | | | HVAC - Chilled water pump #3 motor is burned out and the impeller is locked causing the pump to not operate, | | | | |
| 113 | FM-0056774 | Los Angeles | Courthouse | 19-AP1 | 1 | affecting the HVAC system to the building. Replace chill water pump and motor for proper operation. | \$ | 17,565 | \$13,787 | 78.49 |
| | | | | | | | | | | |
| | | | | | | HVAC - AHU #6 is very loud and disrupting court proceedings due to bad motor bearings. Replace 40 hp supply | l . | | , | |
| 114 | FM-0056775 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | fan motor, pulley and belts before the motor fails and causes further damage to the air handler. | \$ | 9,384 | \$6,206 | 66.13 |
| = | | | Stanley Mosk | 10 | _ | Interior Finishes - Remove and replace third floor corridorfire doors. Units are cracked, missing proper | _ | | 1 | |
| 115 | FM-0056776 | Los Angeles | Courthouse | 19-K1 | 2 | hardware, and is non-repairable. Replacement is code required. | \$ | 6,640 | \$6,458 | 97.26 |
| | | | | | | HVAC - Return fan #3 has bad bearings and a worn out shaft, replacement will prevent down time and costly | | | | |
| | | | | | _ | damage to additional components in the future. Replace (2) bad bearings & (1) custom built shaft, re-assemble | _ ا | | | |
| 116 | FM-0056777 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | pulleys & belts, and return to proper operation. | \$ | 9,029 | \$7,687 | 85.14 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|------|---------------|-------------|--|-------------|----------|---|--------|----------------------|---|---|
| 1,,- | 7 584 0056770 | | Pasadena | 10.11 | 2 | Elevators, Escalators, & Hoists - Replace (3) hoistway limit switches on passenger elevators #1, #2, & #3. Current | _ ا | 0.262 | ć5 7 00 | 60.25 |
| | 7 FM-0056779 | Los Angeles | Courthouse | 19-J1 | 2 | limit switches are not functioning properly and need to be replaced. Grounds and Parking Lot - Vandals/homeless continually break into the irrigation and gas meter cage leaving waste, creating health hazards and unplugging Irrigation timers. Need to demo existing fence and install heavy duty fence with security screen. Demo 57 LF existing chain link fence and posts. Install 57 LF of 14'H wrought iron fence with 1"x 1" pickets and (1) 14'H x 4'L matching gate. After installation of wrought iron fence weld on | \$ | 8,362 | \$5,799 | 69.35 |
| 118 | 3 FM-0056782 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | 7'H x 57'L 1/2" expanded steel security mesh. | \$ | 52,772 | \$34,898 | 66.13 |
| 119 | FM-0056783 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | Fire Protection - Sprinkler and Pipe Deficiencies Replace 10 LF of corroded 6" standpipe in 14th floor mechanical room. Replace PRVs on flrs 1 - 7. Install 100 Marc Star Model E sprinkler heads throughout building. Replace water flow switches on flrs 2, 6, and 7 and water flow detectors on flrs 4, 6, 11, and 12. Work found during Level IV PM. | \$ | 56,884 | \$37,617 | 66.13 |
| 120 | FM-0056784 | Yuba | Yuba County Courthouse | 58-A1 | 2 | COUNTY MANAGED - ADA Compliance: Replace 5 sets of double outer doors, remove 5 pairs of inner Courtroom doors, install automatic openers/closers on new doors. Door frame modifications will require working within an ACM environment. An ADA accessibility complaint was received which has initiated this project. Interior Finishes - ACM Abatement - Abatement on fireproofing material on ceiling, 1-beam, and work down | | 100,000 | \$100,000 | 100 |
| | | | Pomona Courthouse | | | walls toward floor. Re-spray fireproofing. Debris to be disposed of in accordance with regulations. Abatement | | | | |
| 123 | FM-0056785 | Los Angeles | South | 19-W1 | 2 | to address Fire Safety Correction notice from State Fire Marshal. | \$ | 239,919 | \$218,662 | 91.14 |
| 122 | 2 FM-0056786 | San Diego | East County Regional Center | 37-l1 | 2 | Interior Finishes - Replace deteriorated spline ceiling tile with 760-sq. feet of 2 x 4 fire rated ceiling tiles and aluminum concealed spine T-bar grid system, replace current recess mercury vapor bulbs with eighteen (18) 36-Watt LED bulbs and 8-Inch recess light fixtures. Scope of work includes scaffolding set up and removal to access 40-foot ceilings, relocating fire sprinklers & smoke detectors below grid to remain compliance, and dispose of hazardous waste. Currently, 66% of antiquated mercury vapor bulbs are burned out, product is no longer available, and debris from deteriorated spline ceiling is falling and posing as a safety hazard. | | 56,874 | \$ 56,874 | 100.00 |
| 123 | B FM-0056787 | Los Angeles | Glendale Courthouse | 19-H1 | 1 | HVAC - Replace 2 defective compressors, replace defective TXV unit and install Electronic Expansion Value. Set- up temporary cooling(1-120 ton Chiller Unit, 2-Air Handlers, 1-222kva generator, 1-300kva generator). In addition, create a design for a new HVAC system. The following HVAC units failed and not able to provide cooling to the building. | Ś | 333,347 | \$301,812 | 90.54 |
| | | | | | 2 | HVAC- Replace two (2) defective coils in AHU#2 and two (2) expansion valves. Provide and install new sheaves | , , | | | |
| | FM-0056787 | Los Angeles | Van Nuys Courthouse | | | for AHU #1 & #3. County installed coil units are incorrectly sized and have caused chiller pump failures. HVAC - 2nd floor DA (East) Wing, the entire wing has no HVAC circulation, office temperatures are too warm. Replace faulty damper, faulty damper actuator, blown damper access door and trunk line. Environmental | \$ | 65,000 | | 90.54 |
| 125 | 5 FM-0056788 | Los Angeles | East | 19-AX1 | 1 | testing, set up containment at HVAC access point and restore cooling to entire East Wing. | \$ | 20,110 | \$18,047 | 89.74 |
| 126 | 5 FM-0056789 | Los Angeles | Whittier Courthouse Bakersfield Superior | 19-AO1 | 1 | Elevator, Escalators, & Hoists - Remove and replace door hoist way gibs and door edge. Public Elevators 1 & 2 are not operating and are stuck on the first floor. HVAC - Restore FAN Unit 6 to full functionality for Chilled Water Cooler, failed heat strip rendered FAN Unit 6 | \$ | 15,691 | \$13,562 | 86.43 |
| 127 | FM-0056791 | Kern | Court | 15-A1 | 2 | offline and prevented cooling to IT Server Room. Replace defective heater and faulty PSI switch. | \$ | 2,383 | \$1,493 | 62.64 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|------------|----------------|--|-------------|----------|--|----|----------------------|---|---|
| 128 | FM-0056792 | San Francisco | Civic Center Courthouse | 38-A1 | 2 | Security - Replace failed one (1) operator, one (1) Motor gear box, one (1) controller, one (1) 80' bronze header and multiple relays on ADA door located in courtroom 613 on 6th floor. | Ś | 6,775 | \$6,775 | 100 |
| | | San Diego | East County Regional Center Stanley Mosk | | 2 | Plumbing - Replace 30' of 2" Cast Iron pipe and 20' of 3" Cast Iron roof drain pipe and install (3) 2" Cast Iron fittings and bands and replace damaged ceiling tiles above meeting room. Second floor Family Law Office meeting room has cracked piping and fittings above the T-bar ceiling that leak and need to be replaced. Electrical - Install (3) new 20AMP electrical outlets in room 258, Administrator's office on the 2nd floor; remove (1) existing outlet currently mounted on the floor. Currently there is one electrical outlet mounted to the floor which is a tripping hazard as well as a potential fire hazard due to multiple extension cords & power bars all | \$ | 5,766 | \$3,904 | 67.71 |
| 130 | FM-0056794 | Los Angeles | Courthouse | 19-K1 | 2 | running through a single outlet. | Ś | 7,617 | \$7,408 | 97.26 |
| 131 | FM-0056795 | San Diego | North County Regional Center - Vista Center Stanley Mosk | 37-F2 | 2 | Holding Cell - Remove existing non-working lock and install a new #12 deadlock with two new keys for access panel. Plumbing chase access panel is locked and there is no key to open it. Access is required in an emergency. Elevators, Escalators, & Hoists - Escalator 5 to 4 Hill Street side - Replace burnt coil and brake pads and returned | | 5,749 | \$5,749 | 100 |
| 132 | FM-0056796 | Los Angeles | Courthouse | 19-K1 | 1 | escalator to service. Escalator 5 to 4 Hill Street side had a burnt coil causing the brake to pick and burn the pads. | | 5,737 | \$5,580 | 97.26 |
| | FM-0056797 | Los Angeles | Hall of Records | 19-AV1 | 2 | COUNTY MANAGED - Roof - Install new roof base over the elevator shaft. | \$ | 17,200 | | 100 |
| | FM-0056798 | Monterey | Monterey Courthouse | 27-C1 | 2 | COUNTY MANAGED - Energy Management System (EMS) - Replace building EMS (server and operating system) to include: demo replace 2 plant controllers, 8 space temp sensors, 4 duct temp sensors, 4 strap on temp sensors, a current sensor relay, a mixed IO modular, 1 analog input module and relay, installation of set points, graphics, and training EMS currently inoperable. Plumbing - Holding Cells 1-5 - Replace leaking (5) Prison Toilet/Sink combination units to include; (4) new units, (1) new ADA unit, install pneumatic flushing mechanism (all units), new waste line for 3 units, core drilling, rebar installation where needed, remove current remote flush option, install master water shutoff at control board - Units are aged and failing regularly, parts are obsolete, ACM testing required, impact to court operations due to volume of in custodies is a constant threat, due to part availability units can be down weeks | \$ | 27,200 | | 100 |
| 135 | FM-0056799 | Santa Cruz | Main Courthouse | 44-A1 | 2 | at a time even during P1 events. | Ś | 172,897 | \$172,897 | 100 |
| | | | Pasadena | | | HVAC - Failing AHU 10 and AHU 11 - Remove and replace 1 cold water coil, 1 hot water coil, 4'x12 stainless steel drain pan, 4 gate valves, 2 balancing valves, 2 pressure gauges and 2 thermometers on each AHU #10 & #11. Air handler coils are leaking and the drain pans have deteriorated. ACM testing and containment required prior to | , | | | |
| 136 | FM-0056800 | Los Angeles | Courthouse | 19-J1 | 2 | work. | \$ | 169,122 | \$117,286 | 69.35 |
| 137 | FM-0056802 | San Bernardino | Barstow Courthouse | 36-J1 | 2 | Interior Finishes - Room 110 Self-help office expansion- Remove (96SF) wall between Rm 109 and 110. Manage with ACM contaminant requirements (10SF.patch carpet, touch up paint, and rewire light switch). Expansion needed since there will soon be significant additional traffic due to upcoming re-opening of the branch and reallocation of Court resources. | \$ | 18,532 | \$18,532 | 100 |
| 138 | FM-0056803 | Los Angeles | San Fernando Courthouse | 19-AC1 | 2 | Interior Finishes - Remove and replace audience, jury, and witness seating in Dept. H, J, and N. Dept H, N, and J (63) audience seating, (14) jury box seating, and (1) witness chair. Totaling (189) Audience seating, (42) jury box seating, and (3) witness chairs. Existing seating is old and constantly breaking, parts are not available for repairs. Safety hazard with seating failing with public use. | \$ | 114,000 | \$114,000 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|------|------------------|----------------|------------------------|-------------|----------|--|-----------|----------------------|---|---|
| | | | | | | HVAC - Install (1) 2-ton 24,000 BTU Mitsubishi ductless split system with remote, condensate pump and drain | | | | |
| | | | | | | line. Install 150' of power wiring, 300' of 3/4" conduit, 30 AMP breaker, 30 AMP disconnect and (2) 30 AMP | | | | |
| | | | | | | fuses. Observation/control booth for Lockup was not in original HVAC design. Current use with full time staff | | | | |
| 139 | FM-0056806 | Los Angeles | Burbank Courthouse | 19-G1 | 2 | and increased electrical load than the original design makes area excessively hot. | \$ | 23,895 | \$ 21,687 | 90.76 |
| | | | | | | Exterior Shell - Windows were vandalized by graffiti/etching. A safety concern, the windows need to be | | | | |
| | | | | | | replaced and install anti-graffiti film to prevent future graffiti. East 1st Flr: Replace 3 windows, Install film on 20 | | | | |
| | | | Clara Shortridge Foltz | | | windows (734SF). North 1st Flr: Replace 4 windows, Install film on 49 windows (1550SF). West 1st Flr: Install film | | | | |
| | | | Criminal Justice | | | on 8 windows (284SF). South 1st Flr: Replace 12 windows, Install film on 31 windows (971SF). South 2nd Flr: | | | | |
| 140 | FM-0056807 | Los Angeles | Center | 19-L1 | 2 | Replace 6 windows, Install film on 20 windows (640SF). | \$ | 162,815 | \$112,000 | 68.79 |
| | | | | | | COUNTY MANAGED - HVAC- Install a new 1.5 ton mini-split system unit to provide appropriate levels of cooling | | | | |
| | | | | | | and air flow to the Judge's Chambers. Relocate existing T-Stat & ducting in the chambers to supply 3 offices | | | | |
| | | | Victorville | | | alone. Courthouse is in a desert area, reaching extreme hot temperatures in the summer months, making it | | | | |
| | | | Courthouse-Dept. N- | | | uncomfortable for staff. County has made several attempts to have the existing unit adequately supply all 4 | | | 4 | |
| 141 | FM-0056809 | San Bernardino | 1 | 36-L1 | 2 | rooms all to which has not had success. | \$ | 4,500 | \$4,500 | 100 |
| | | | | | | Interior Finishes - Floor tiles 108 sq.ft. of tile are coming unglued from the floor, the adhesive used to secure the | | | | |
| 1,42 | EN 4 00 5 60 4 4 | | | 40 454 | | tiles to the floor contain ACM. Remove and replace along with 42 ft of cove base. Continuing degrading | _ | 0.002 | ¢0.002 | 400 |
| 142 | FM-0056811 | Los Angeles | Sylmar Juvenile Court | 19-AF1 | 2 | condition is becoming hazardous. | \$ | 8,992 | \$8,992 | 100 |
| 142 | FN4 00F6913 | Can languin | Manteca Branch | 20.61 | , | Vandalism Cafaty, Danlage broken skylight window above public space. Lift required to replace glass | ۲ | 2 500 | ¢2 F09 | 100 |
| 143 | FM-0056813 | San Joaquin | Court | 39-C1 | | Vandalism - Safety - Replace broken skylight window above public space. Lift required to replace glass | \$ | 3,508 | \$3,508 | 100 |
| | | | | | | Exterior Shell - The In-Floor door closers for the cafeteria (leading to the parking meters) are worn out and do | | | | |
| | | | | | | not function properly. The doors do not close automatically and need new door closers/closing arms to be | | | | |
| 144 | FM-0056814 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | installed. Replace In-Floor door closers with (4) Rixson free swing arms and (4) surface mount closers. | Ś | 4,385 | \$3,384 | 77.17 |
| 177 | 1101 0030014 | LOS / trigeres | Parking Structure Lot | | | instance. Replace in Floor door closers with (4) Mixson free swing arms and (4) sarrace mount closers. | 7 | 7,303 | 73,304 | 77.17 |
| | | | 94 Airport | | | Plumbing - 10" Backflow failed and it is unrepairable. Remove existing backflow device and install a new | | | | |
| 145 | FM-0056815 | Los Angeles | Courthouse | 19-AU2 | 2 | backflow unit. | Ś | 10,333 | \$7,974 | 77.17 |
| | | 0- 3- | | | - | HVAC - Cooling tower is running at very high temperatures due to a bad breaker that is tripping & pitted | <u> </u> | -,,,, | , , , , , , | |
| 146 | FM-0056816 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | contactors that need to be replaced. Remove and Replace (3) bad contactors & (1) bad breaker. | \$ | 4,707 | \$4,008 | 85.14 |
| | | 1 | Turlock Superior | | | • | | · | . , | |
| 147 | FM-0056818 | Stanislaus | - | 50-D1 | 2 | Interior Finishes - Stretch failing carpet. Anchor audience seating to concrete in the courtroom. | \$ | 6,345 | \$6,345 | 100 |
| | | | | 40.000 | | Fire Protection - Replace Speaker near room 697 that does not sound upon activation of alarm. Adjust Tamper switch on Bypass Upstream Valve and Tamper switch on Main Pump Discharge Valve in the Fire Pump Room. Restore stairwell doors that do not unlatch upon activation of alarm in Stairwell #5 - Floors 9, 7, 3; Stairwell #4 - | | 2.22 | 40 - 0 - | |
| 148 | FM-0056819 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Floors 9, 4, 2; Stairwell #3 - Floors 3 & 10; Stairwell #2 - 10th Floor; Stairwell #1 - 9. Work is code required. | Ş | 3,364 | \$2,596 | 77.17 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|------|--------------|----------------|--|-------------|----------|---|-------------|---------------------------------------|---|---|
| | | | | | | Fire Protection - Existing Simplex 2000 fire panel is ground faulting and reading false trouble calls that could | | | | |
| 149 | FM-0056820 | Los Angeles | Bellflower Courthouse | 19-AL1 | 2 | lead to false alarms and subsequent court evacuations. Need to upgrade existing panel to a modern 4100ES with capability of supporting future upgrades. Demo existing system & install new Simplex 4100ES, (1) addressable smoke detector above fire alarm control panel (FACP), (1) horn strobe above FACP and (1) LCD enunciator. | Ś | 48,064 | \$ 37,461 | 77.94 |
| 1.5 | 1111 0030020 | Los / ingeres | Courtifouse | 13 / (21 | | HVAC - Replace (6) corroded and failed return air dampers, (5) corroded and failed outside air dampers and | | 10,001 | 37,101 | ,,,,,, |
| 150 | FM-0056821 | Humboldt | Humboldt County Courthouse (Eureka) | 12-A1 | 2 | linkages on AHU-5,6,7,8 and 9. Replace (12) pneumatic damper actuators. Currently dampers are severely corroded and linkages are broken. | \$ | 77,551 | \$77,551 | 100 |
| | | | Da usa su a Cassuntha assas | | | Doef Dain water an actuated the worf Dain water leaded into the 5th and 4th flagrand the 2nd flagrand Court | | | | |
| 151 | LM 00E6930 | Los Angolos | Pomona Courthouse | 10 \\/1 | 1 | Roof - Rain water penetrated the roof. Rain water leaked into the 5th and 4th floors and the 3rd floor Dept. C, | ۲ | 20.150 | ¢10.265 | 01 14 |
| 151 | FM-0056829 | Los Angeles | South | 19-W1 | 1 | Room 302. ACM remediation & containment, dry leak affected areas and replace wet and damaged ceiling tiles. HVAC - Chiller #2 - Remove and replace failed purge pump. The failed pump has rendered the chiller inoperable | + | 20,150 | \$18,365 | 91.14 |
| 152 | FM-0056830 | Riverside | Hall of Justice | 33-A3 | 1 | and leaving the building insufficiently cooled. | Ś | 7,255 | \$7,255 | 100 |
| | | | | | | Roof - Rain Water penetrating the roof of the 1st Floor Sheriff Vehicle Inspection Station. Replace | T | ., | 7.7-55 | |
| | | | Metropolitan | | | approximately 350 sq ft of ceiling tiles have been affected by the leak/rain water. 450sf ACM containment and | | | | |
| 153 | FM-0056831 | Los Angeles | Courthouse | 19-T1 | 1 | remediation. | \$ | 25,100 | \$25,100 | 100 |
| | | | | | | COUNTY MANAGED - Replace exhaust pipe on emergency generator at Central Plant, this generator supports | | | | |
| | | | South County | | _ | emergency power to South County Regional Center, current system has failed and is out of compliance with | ١. | | 4 | |
| 154 | FM-0056832 | San Diego | Regional Center | 37-H1 | 2 | local authorities. | \$ | 3,242 | \$3,242 | 100 |
| 155 | EN4 00E (022 | l os Amaroles | Pomona Courthouse | 10 \\\ | 1 | Roof - Rain water penetrating roof and leaking into the 6th floor Public Hallway Dept. P & Dept. R. Leak has | ۲ | 15.050 | ¢12.717 | 01.14 |
| 155 | FM-0056833 | Los Angeles | South Monrovia Training | 19-W1 | 1 | been contained to the 6th floor.CM remediation & containment, dry leak affected areas. | \$ | 15,050 | \$13,717 | 91.14 |
| 156 | FM-0056834 | Los Angeles | Center | 19-N1 | 1 | Roof - Rain water is penetrating and leaking into the 1st floor Large Lock-up Cell. CM remediation & containment, dry leak affected areas. Remediate damaged roofing penetrations and fan unit cowling. | ¢ | 15,102 | \$10,615 | 70.29 |
| 130 | 1101 0030034 | LOS Aligeies | Center | IJ IVI | | Roof - Water is leaking into the 1st floor Lock-up Control Room. Rain water is leaking at the sergeants desk area; | 7 | 13,102 | 710,013 | 70.23 |
| 157 | FM-0056835 | Los Angeles | Mental Health Court | 19-P1 | 1 | affecting an 8ft x 8ft area & 10x10ft ACM areas. Replaced failed drain hardware. | \$ | 15,075 | \$10,750 | 71.31 |
| | | | Van Nuys Courthouse | | | Roofing - Renovate failed roofing seams and mitigate water damage to 7th floor Women's public restroom | | · · · · · · · · · · · · · · · · · · · | . , | |
| 158 | FM-0056836 | Los Angeles | East | 19-AX1 | 1 | creating a slip hazard and safety situation. Secure and clean up under ACM requirements. | \$ | 16,585 | \$14,883 | 89.74 |
| | | | Harbor Justice Center | - | | | | | | |
| | | | Newport Beach | | | Electrical - Replace three severely rusted light poles in the parking lot. Two poles were in immediate danger of | | | | |
| 159 | FM-0056838 | Orange | Facility | 30-E1 | 2 | falling and have been removed. All parking lot lighting is necessary, so the poles must be replaced. | \$ | 7,730 | \$6,518 | 84.32 |
| 1.00 | ENA 00E (020 | Carata Clara | | 42.44 | _ | HVAC - Replace (1) each failed blower assembly - Boiler is currently out of service - Reduced heating capacity to | ۲, | 2.645 | ¢2.645 | 100 |
| 100 | FM-0056839 | Santa Clara | Hall of Justice (East) | 43-A1 | 2 | the court - Boiler #04 has failed. HVAC - Replace failed compressor, worn condenser motor and fan blade, filter drier, starter caps, and | > | 3,615 | \$3,615 | 100 |
| | | | | | | contactor. Split system serving the 1st floor data room is down due a filed compressor. Replacement required | | | | |
| | | | San Bernardino | | | to ensure adequate cooling of the data room to prevent possible heat related damage to critical court network | | | | |
| 161 | FM-0056840 | San Bernardino | Courthouse - Annex | 36-A2 | 2 | equipment. | \$ | 3,755 | \$3,589 | 95.58 |
| | | | George D. Carroll | | | Interior finishes - Vandalism Grind, sand, and buff out profanity and drawings etched into (10) steel beams | <u> </u> | -,3 | 72,230 | |
| 162 | FM-0056841 | Contra Costa | Courthouse | 07-F1 | 2 | Graffiti carved into the beams and window frames outside of the Jury Assembly Room. | \$ | 2,140 | \$2,140 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|------|----------------------|----------------|------------------------------------|-------------|--------------|---|--|----------------------|---|---|
| | | | | | | Interior Finishes - Dept. S-53 Chambers the paint on plaster wall is bubbled due to condensate leak. Need to dry | | | | |
| | | | | | | wall and repaint, this work is necessary in order to restore the Courtroom to its original condition. Utilize an air | | | | |
| | | | San Bernardino | | | injection system and dehumidifier to dry approximately 50SF of plaster wall that was dampened by a | | | | |
| 163 | FM-0056842 | San Bernardino | Courthouse | 36-A1 | 2 | condensate leak. Encapsulate lead blistered paint areas and repaint wall. | \$ | 5,098 | \$5,098 | 100 |
| | | | Criminal Court | | _ | HVAC - Remove existing EOL Drift Mist Eliminators and reinstall (7) mist eliminators on top and (14) each mist | ١. | | 4 | |
| 164 | FM-0056844 | Napa | Building | 28-A1 | 2 | eliminators on side of the Mammoth Package Air Handler - Several (8) eliminators failed. | \$ | 3,519 | \$3,519 | 100 |
| | | | | | | | | | | |
| 4.65 | 5.4 005 60 45 | | Humboldt County | 42.44 | | COUNTY MANAGED - Fire System - Expand system - Install expansion pack for fire panel (Notifier NFS2-640), to | ۱, | 4 704 | 64.724 | 100 |
| 165 | FM-0056845 | Humboldt | Courthouse (Eureka) | 12-A1 | 2 | allow existing AHU duct detectors (8) to be attached to Fire system. | \$ | 4,721 | \$4,721 | 100 |
| 166 | ENA 00E6946 | Can Matao | I lall of lustice | 11 11 | , | COUNTY MANAGED - Electrical - Connect court UPS equipment to the emergency power supply per estimate | ے ا | г ос1 | ¢F 061 | 100 |
| 100 | FM-0056846 | Sali Mateu | Hall of Justice | 41-A1 | | 150232 Rev 2. This is a County responsibility. Elevators, Escalators, & Hoists - Renovate Judge's Elevator #5 leaking Worm Gear and Bad Shaft. Work required | γ | 5,061 | \$5,061 | 100 |
| 167 | FM-0056847 | Los Angeles | Downey Courthouse | 10-11 | 1 | to preclude system failure. | | \$28,031 | \$23,462 | 83.7 |
| 107 | 1101-0030847 | LOS Aligeles | Downey Courtilouse | 13-AIVII | | HVAC - Replace leaking, rusted 40 year old 75 ton Cooling Tower and 110 ton Chiller, Piping and VFD included. | | 720,031 | 723,402 | 85.7 |
| | | | | | | Existing equipment has continual leaks and failed component replacements. Increased number of hot calls is | | | | |
| 168 | FM-0056848 | Santa Clara | Old Courthouse | 43-B2 | 2 | affecting operations. | Ś | 590,244 | \$590,244 | 100 |
| 100 | 00000 10 | Janta Gara | 0.000.0.000 | 1.5 52 | | Interior Finishes - Abate 825 SF of ACM linoleum flooring and ACM mastic between linoleum and floor. Install | ļ - | 330)= : : | φ333,2 | |
| | | | | | | new linoleum tile. Remove and later replace 16 rows of 7 seats (112 seats). Dept. 11 Room 246 VCT flooring | | | | |
| | | | Stanley Mosk | | | contains ACM and due to prior floods is delaminated and buckling. Flooring is a tripping hazard to public/court | | | | |
| 169 | FM-0056849 | Los Angeles | Courthouse | 19-K1 | 2 | staff and a liability to the court. | \$ | 48,739 | \$48,739 | 100 |
| | | | | | | HVAC - Cooling Tower #1 VFD and 15 HP motor are not functioning creating Cooling Tower #2 to run at 60 | | | | |
| | | | East Los Angeles | | | degree chill water temp which is not sufficient for comfort cooling to support the building. Replace VFD and | | | | |
| 170 | FM-0056854 | Los Angeles | Courthouse | 19-V1 | 1 | motor for Cooling Tower #1. | \$ | 20,758 | \$16,133 | 77.72 |
| | | | | | | | | | | |
| | | | Monrovia Training | | | HVAC - The DX system is leaking refrigerant which is causing the compressor to shut down on high head | ١. | | | |
| 171 | FM-0056855 | Los Angeles | Center | 19-N1 | 1 | temperature. Not able to cool the building. Replace defective King Valve and restore system to operation. | \$ | 15,509 | \$10,901 | 70.29 |
| 172 | | Manaad | New Downtown | 24.40 | ١ , | Doof Donland foiled VED. VED stamped working | _ ا | 10.400 | ¢10.460 | 100 |
| 1/2 | FM-0056856 | Merced | Merced Courthouse Turlock Superior | 24-A8 | | Roof - Replace failed VFD - VFD stopped working. HVAC: Replace Existing 5-Ton Package Unit. Unit is failed beyond repair (Compressor). Unit replacement | Ş | 10,469 | \$10,469 | 100 |
| 172 | FM-0056857 | Stanislaus | Court | 50-D1 |) | required - Age 30+ years. | ا د | 11,083 | \$11,083 | 100 |
| 1/3 | 1101-0030837 | Stariisiaus | Court | 30-01 | | required - Age 30+ years. | ٦ | 11,003 | \$11,065 | 100 |
| | | | | | | Interior Finishes - Remove failed existing floor closers, and furnish and install (4) new Rixson 27 90 degree floor | | | | |
| | | | | | | closers with new offset arms and make adjustments for proper operation and locking. The glass doors leading | | | | |
| 174 | FM-0056859 | Shasta | Main Courthouse | 45-A1 | 2 | into the admin floor lobby slam shut, this is a safety hazard as the glass may break. | Ś | 6,402 | \$4,463 | 69.71 |
| | | | | - · · · - | - | Plumbing - Vandalism Holding cell #5, Remove previously fabricated and installed block off plate, Install new | | -, | ÷ ., | |
| | | | | | | sink components and modify to fit existing combi unit. Sink compartment of unit is currently out of service, sink | | | | |
| 175 | FM-0056860 | Santa Cruz | Main Courthouse | 44-A1 | 2 | in not usable due to damage from vandalism. | \$ | 3,377 | \$3,377 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|---------------------|-----------------|-----------------------------------|-------------|----------|--|--------------|----------------------|---|---|
| | | | | | | HVAC - Replace existing rooftop AHU to include integral VFD, install VAV controller and sensors for VAV | | | | |
| | | | | | | conversion, install VAV boxes in zones and integrate existing reheat coil, replace chilled water valve and roof piping insulation, integrate controls with new BAS, tie in new actuator and sensors into local controller - Existing | | | | |
| | | | | | | unit is constant volume zone reheat chiller water AHU, it is exhausted and at end of life, inefficient, ineffective. | | | | |
| 176 | FM-0056862 | Santa Cruz | Main Courthouse | 44-A1 | 2 | Replacement will enhance monitoring and control. | Ś | 68,425 | \$67,816 | 99.11 |
| | | | East County Regional | 1 | | Interior Finishes - Dept. 1 Gallery seating is deteriorated posing public safety and health risk. Replace seating | † <i>'</i> | , | 12,22 | |
| 177 | FM-0056866 | San Diego | Center | 37-I1 | 2 | components and upholstery on 75 spectator seats, backs, and other miscellaneous hardware. | \$ | 11,458 | \$ 11,458 | 100 |
| | | | Van Nuys Courthouse | | | HVAC - 5th floor Supply motor for HVAC #5 has failed causing temperatures to rise. Replace bad supply motor | | | | |
| 178 | FM-0056867 | Los Angeles | East | 19-AX1 | 1 | and restore cooling to 5th floor. | \$ | 7,500 | \$6,731 | 89.74 |
| | | | | | | Plumbing - 1st floor Room 111A, Remove and replace a 20' section of 4" inch cast iron sewage pipe and fittings. | | | | |
| 170 | 5. 4 005 000 | | Stanley Mosk | 40.1/4 | | Pipe is cracked and leaking through the ceiling. Install (4) new 24"x24" ceiling tiles and restore the carpet. ACM | | 45.075 | 644.662 | 07.26 |
| 1/9 | FM-0056868 | Los Angeles | Courthouse | 19-K1 | 1 | Work required. | \$ | 15,075 | \$14,662 | 97.26 |
| 190 | FM-0056869 | Los Angeles | Burbank Courthouse | 10 61 | 1 | HVAC - Chiller #1 is failing - Fabricate shaft and 3 fan wheels to match existing cooling tower model. Chiller #1 is failing and not providing cooling. Dept. 1G, Clerk's area and Civil area is too warm. | ے ا | 12,050 | \$10,937 | 90.76 |
| 100 | FIVI-0030809 | LOS Aligeles | Burbank Courthouse | 19-01 | - | Plumbing- Replaced pipes that were leaking. 3 section of ¾ inch copper pipe, (1) ¾ union, & (1) ¾ inch ball | ٦ | 12,030 | \$10,937 | 90.70 |
| | | | | | | valve,30x40 affected area (Men's public restroom, women's restroom, hallway to 272F, Dep. 5, Dep. F, traffic, | | | | |
| | | | | | | jury room, and hallway to public jury room), Prep ACM work in 10x10 area of plaster ceiling and (7) 7x7 critical | | | | |
| 181 | FM-0056870 | Los Angeles | Glendale Courthouse | 19-H1 | 1 | barriers, exctract 100 gallons of contaminated water. | \$ | 15,100 | \$13,672 | 90.54 |
| | | | | | | Plumbing - Replace failed roof drain with new No-Hub 3" roof drain, drain ring. Replace 2-3 feet of failed drain | | | | |
| | | | Pomona Courthouse | | | pipe under the roof deck, reseal roof deck around drain unit. Work required in ceiling area above Sheriff's | | | | |
| 182 | FM-0056871 | Los Angeles | South | 19-W1 | 2 | office. | \$ | 5,281 | \$ 4,813 | 91.14 |
| | | | | | | Plumbing - Replace failed and leaking water supply hardware and install new 2 1/2 three piece ball valve in | | | | |
| 102 | ENA 00E6973 | l os Angolos | Chatsworth | 10 471 | , | public men's restroom and 1 1/2 ball valve in the women's restroom. Work impacts Public Men's Restroom and | ے ا | F 266 | 6 4 412 | ၈၁ ၈ |
| 183 | FM-0056872 | Los Angeles | Courthouse Clara Shortridge Foltz | 19-AY1 | | 2nd floor Women's Restroom inside Dept. 2700. |) | 5,266 | \$ 4,413 | 83.8 |
| | | | Criminal Justice | | | Fire Protection - Fire sprinkler located in Elevator Shaft is not to code and must be removed per SFM | | | | |
| 184 | FM-0056873 | Los Angeles | Center | 19-L1 | 2 | notification. Permit will not be released until work is complete. | Ś | 2,902 | \$ 2,902 | 100 |
| | | | | | | · · | <u> </u> | , | , | |
| | | | Edmund D. Edelman | | | Fire Protection - Replace (52) Sprinkler Heads and Escutcheons and Replace (20) outdated pressure gauges | | | | |
| 185 | FM-0056874 | Los Angeles | Children's Court | 19-Q1 | 2 | throughout building. Also Fire Pump Room, Riser #2 replaced failed coupling. | \$ | 12,416 | \$ 8,690 | 69.99 |
| | | | | | | Vandalism - Vandalism in the public restrooms on floors #5-8 is creating a safety issue to staff and public. | | | | |
| | | | | | | Etching on sinks, bathroom partition walls, toilet seats and mirrors. Install graffiti mirror film on 16 mirrors, | | | | |
| 100 | | 100 000 | Metropolitan | 10. T1 | | remove and replace 28 toilet seats, paint and epoxy sinks, and sand/paint the restroom walls and partition | | 40 222 | 6 0.572 | 04.54 |
| 186 | FM-0056875 | Los Angeles | Courthouse | 19-T1 | 2 | doors. Electrical - Replace Failed 20 Amp circuit breakers on panels #E1 and #V1; Breakers were found to be failing | > | 10,232 | \$ 9,673 | 94.54 |
| 197 | FM-0056876 | Contra Costa | Wakefield Taylor Courthouse | 07-A2 | 2 | during IR scans. | ر | 4,344 | \$ 4,344 | 100 |
| 107 | 1141 0030070 | Contra Costa | Courtilouse | 0, 72 | | Elevators, Escalators, & Hoists - Elevator cab interior panels are badly damaged and deteriorated. Current | ر | 7,344 | 7 4,344 | 100 |
| | | | | | | system delaminating including failure of metal fixtures creating potential safety issues. Install 7 new laminate | | | | |
| 188 | FM-0056877 | San Diego | Juvenile Court | 37-E1 | 2 | material on cab panels. | \$ | 7,848 | \$ 5,856 | 74.62 |
| | | | | | • | | | | | |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|---------------|-------------|----------------------------|-------------|----------|---|-----|----------------------|---|---|
| | | | | | | Elevators - Replace failed elevator components (2) communication boards, one (1) car operating panel interface board, seventeen (17) Floor push buttons, six (6) key switches, one (1) ADA phone, one (1) Emergency | | | | |
| | | | Downtown Superior | | | light board, two (2) PI boards, three (3) emergency light batteries, one (1) fire service cabinet fixture, and two (2) seismic/fire button jewels (seismic, fire) Elevator #4 has failed due to water intrusion damaging controls | | | | |
| 190 | FM-0056878 | Santa Clara | Court | 43-B1 | 1 | and is non operational at this time. | | \$39,371 | \$39,371 | 100.00 |
| 109 | FIVI-0030878 | Santa Ciara | Court | 43-01 | 1 | Electrical - Existing 2000A Westinghouse ATS has failed. Replacement parts are no longer available. Demo | | γ 55,571 | 759,571 | 100.00 |
| | | | | | | existing and install 1 new 2000A ATS with microprocessor controls and NEMA 1 cabinet. Install five 50 LF (250 | | | | |
| | | | Edmund D. Edelman | | | LF) runs of 500 MCM cable for low side and 120 LF of 500 MCM cable for high side. Install 9 500 MCM lugs. | | | | |
| 190 | FM-0056879 | Los Angeles | Children's Court | 19-Q1 | 2 | Building power will be shut off for 12 hours while ATS is replaced. | Ś | 108,896 | \$ 76,216 | 69.99 |
| | | | | | | Security - Correct failed Andover Access Control System - Current system software, operating system, | 7 | | 7 7 9,220 | 33.33 |
| | | | Criminal Court | | | input/output and control modules are not operational, causing perimeter, holding cell, in-custody transport, | | | | |
| 191 | FM-0056882 | Napa | Building | 28-A1 | 2 | secure space and Courtroom security/safety issues. | \$ | 133,300 | \$ 133,300 | 100 |
| 192 | FM-0056883 | Los Angeles | Pomona Courthouse South | 19-W1 | 2 | HVAC - Due to age/corrosion Cold & Hot Water Coils for 3rd, 6th and 7th flr Air Handler Units are leaking and need to be replaced. Leaking coils have caused deterioration of condensation pans and floor drains; both will be replaced. Spring Isolators on AHU-5 require replacement. Perform environmental testing, set up containments. Install 10 new 680lb Fail Safe Spring isolators. Replace 2 cold water coils, 1 hot water coils with custom made coils. Replace condensate drain pans with custom units. | \$ | 379,957 | \$ 346,293 | 91.14 |
| | | | | | | | T | , | 7 213,255 | |
| 193 | FM-0056884 | San Diego | County Courthouse | 37-A1 | 2 | Interior Finishes - Ceiling tiles in the Press Room are deformed, stained and have become weak and brittle due to past leaks. The potential for ceiling tiles to fall is present with resulting ACM contamination. Remove, dispose and replace approximately 1,050 sq. ft. of ceiling tiles per ACM protocols. | \$ | 17,411 | \$ 17,411 | 100 |
| | | | New Mammoth | | | HVAC - Redesign and install new components for the snow melt system. Modification are required in order to | | | 4.5 | |
| 194 | FM-0056886 | Mono | Lakes Courthouse | 26-B2 | 1 | allow safe ingress and egress to the building during the winter months. | | \$35,247 | \$35,247 | 100.00 |
| 105 | EN4 00EC000 | None | Historical Countbours | 20 D1 | _ | HVAC - Replace failed Package AC compressor (1 of 2), replace return air fan belts, bearings, shaft and sheaves - | ے ا | 20.640 | ¢ 20.640 | 100 |
| | FM-0056889 | Napa | Historical Courthouse | | 2 | Unit is not operationally effective causing room temps of 78-85 degrees. Plumbing - Replace 9 valves, 12 flanges. Rebuild (2) 15HP pumps and (1) 7.5 HP pump. Replace (1) 15 HP ODP motor and (1) motor mounting. Domestic water pumps are deteriorated and require replacement. 60% of | Ş | 30,649 | | 100 |
| 196 | FM-0056890 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | system has failed. Loss of the last pump will result in the courthouse losing water supply. | \$ | 41,416 | \$ 31,961 | 77.17 |
| 107 | ENA 0056901 | Mandacina | County Courthouse | 22 41 | 2 | Interior Finishes - Modification - Family Law In-custody Courtroom 'F' judicial officer, clerk and parties at high security risk due to small size and configuration of old Muni courtroom also with poor acoustics. Bench and witness stand modification to reconfigure and reorient for safe proceedings and accurate court reporter | ė | 10 207 | ¢ 10.207 | 100 |
| 19/ | FM-0056891 | Mendocino | County Courthouse | 23-A1 | | operations. Electrical - Relocate existing electrical outlets from the floor to the wall. Currently there are electrical outlets | ٦ | 19,207 | \$ 19,207 | 100 |
| | | | Stanley Mosk | | | located on the floor in multiple workstations in room 102; chords and plugs in the floor outlets are being kicked | | | | 1 |
| 198 | FM-0056892 | Los Angeles | Courthouse | 19-K1 | 2 | and damaged causing major safety hazards. | \$ | 7,069 | \$ 6,875 | 97.26 |
| 133 | 223332 | | Morgan Hill | | | HVAC - Replace (1) thermal expansion valve, system oil charge, filter dryer and (1) new isolation valve evacuate | T | .,555 | , 3,3.3 | 37.20 |
| 199 | FM-0056893 | Santa Clara | Courthouse | 43-N1 | 2 | system. dedicated cooling system for IT equipment has failed components and is not operational at this time. | s | 6,779 | \$ 6,779 | 100 |
| 199 | 1 141 0020032 | Janta Ciara | Courtifouse | ITO INI | | bystem, acadeated cooming system for it equipment has failed components and is not operational at this time. | ۲ | 0,113 | ا با ا | 100 |

| B.F. Sisk Federal HVAC - Replace failed heat exchange on boiler 83. Materials covered under warranty, Replacement labor is not. Courthouse 10-01 2 replacement required to provide sufficient building pleat. Significant placement labor is not. Significant placement labor is not. Significant placement required to provide sufficient building pleat. Significant placement labor is not. Significant labor labor. Significant labor. Signific | 100 PROGRAM SHARE % OF COST COST |
|--|----------------------------------|
| 200 FM-0056894 Fresno Courthouse 10-01 2 replacement required to provide sufficient building heat. \$ 11,117 \$ 1 | 77.17 77.17 |
| 201 FM-0056898 Los Angeles Airport Courthouse 19-AU1 2 Elevator - Replace failed Amp traps and lower sheave switch on Elevator #4. Unit is inoperable at this time. \$ 2,290 \$ 1,767 Plumbing - Replace failed Amp traps and lower sheave switch on Elevator #4. Unit is inoperable at this time. \$ 2,290 \$ 1,767 Plumbing - Replace failed Airtrol valve on heater water expansion tank (boiler) #2. Unit has failed and not allowing water to pass through. 8.F. Sisk Federal Electrical - Replace the bad underground wiring from the O Street pedestrian gate call box to inside the building Electrical - Replace the bad underground wiring from the O Street pedestrian gate call box to inside the building Electrical - Replace the bad underground wiring from the O Street pedestrian gate call box to inside the building Electrical - Replace the favour of the county of t | 77.17 77.17 |
| 202 FM-0056899 Los Angeles Airport Courthouse 19-AU1 2 Plumbing - Replace failed Airtrol valve on heater water expansion tank (boiler) #2. Unit has failed and not \$ 2,814 \$ 2,172 \$ 1,000 \$ 2,000 \$ 1 | 77.17 |
| 202 FM-0056990 Los Angeles Airport Courthouse 19-AU1 2 allowing water to pass through. 5 2,172 | |
| B.F. Sisk Federal Courthouse 10-O1 2 Electrical - Replace the bad underground wiring from the O Street pedestrian gate call box to inside the building with direct or Call box is not functioning due to damaged wiring. S 2,825 \$ 2, | |
| 203 FM-0056900 Fresno Courthouse 10-01 2 with direct burial Cat 6 wire - Call box is not functioning due to damaged wiring. \$ 2,825 \$ | 100 |
| Electrical - Run new conduit and install new UL rated exit signs with emergency lighting combo and replace power efficient exit signs with e-lighting where needed. Currently there are no UL rated Exit signs in the 1st & 2nd secured hallways (1953 side of building). The City of Burbank Fire Marshall has requested the installation of exit signs with emergency lighting. 5 2,750 \$ 2,496 Exterior Shell - Install Roof Access Ladder and walk off mat, to allow access to the Penthouse mechanical room from the exterior of the building - Currently access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays contractor access. 5 11,494 \$ 11,494 Plumbing - Replace sink faucet broken by unknown vandal - Replace approximately 10 square feet of water damaged wallboard & six ceiling tiles. Water damage in the 3rd floor jury assembly men's restroom and second floor women's staff restroom. 5 4,397 \$ 4,397 Electrical - Replace 25% (approx. 50 bulbs) of the light bulbs/ballast in D-16 courtroom, and re-lamp D-33 by replacing approx 200 bulbs. Above ceiling work to occur per ACM protocols. Dept. 16 & 33 has poor lighting replacing approx 200 bulbs. Above ceiling work to occur per ACM protocols. Dept. 16 & 33 has poor lighting conditions due to burned out bulbs, ballast and a black substance/residue on the diffuser lenses. 5 16,845 \$ 16,845 Exterior Shell - Remove and replace existing roof gutter system with new acrylic coated gal volume sheet steel rain gutter system at 5 locations. Install new downspouts and channel water away from building. Rain gutters that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building creating potential water intrusion and interior flooding. | 100 |
| power efficient exit signs with e-lighting where needed. Currently there are no UL rated Exit signs in the 1st & 2nd secured hallways (1953 side of building). The City of Burbank Fire Marshall has requested the installation of exit signs with emergency lighting. Exterior Shell - Install Roof Access Ladder and walk off mat, to allow access to the Penthouse mechanical room from the exterior of the building - Currently access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays contractor access. \$ 11,494 | |
| 204 FM-0056901 Los Angeles Burbank Courthouse Exterior Shell - Install Roof Access Ladder and walk off mat, to allow access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires essenting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires essenting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires essenting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires essenting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires essenting from the County Sheriff which disrupts the operation of the Jail and delays owned Jai | |
| Exterior Shell - Install Roof Access Ladder and walk off mat, to allow access to the Penthouse mechanical room from the exterior of the building - Currently access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays of the Jail and delays owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays of the Jail and delays of the Jail and Jai | |
| Exterior Shell - Install Roof Access Ladder and walk off mat, to allow access to the Penthouse mechanical room from the exterior of the building - Currently access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays contractor access. \$ 11,494 \$ 1 | 00.76 |
| from the exterior of the building - Currently access to the Penthouse mechanical room is through the county owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays contractor access. \$ 11,494 \$ 11,4 | 90.76 |
| owned Jail, this requires escorting from the County Sheriff which disrupts the operation of the Jail and delays 11,494 5 11,494 5 11,494 5 11,494 | |
| 205 FM-0056902 El Dorado Johnson Bldg. O9-E1 2 Contractor access. \$ 11,494 | |
| Plumbing - Replace sink faucet broken by unknown vandal - Replace approximately 10 square feet of water damaged wallboard & six ceiling tiles Water damage in the 3rd floor jury assembly men's restroom and second Justice 01-D1 2 floor women's staff restroom. \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ 5 4,397 \$ 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | 100 |
| Hayward Hall of Justice 01-D1 2 floor women's staff restroom. \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 4,397 \$ 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | |
| 206 FM-0056903 Alameda Justice 01-D1 2 floor women's staff restroom. \$ 4,397 \$ 4,397 \$ 4,397 \$ 4,397 \$ | |
| Electrical - Replace 25% (approx. 50 bulbs) of the light bulbs/ballast in D-16 courtroom, and re-lamp D-33 by replacing approx. 200 bulbs. Above ceiling work to occur per ACM protocols. Dept. 16 & 33 has poor lighting conditions due to burned out bulbs, ballast and a black substance/residue on the diffuser lenses. \$ 16,845 \$ | 100 |
| replacing approx. 200 bulbs. Above ceiling work to occur per ACM protocols. Dept. 16 & 33 has poor lighting San Diego County Courthouse 37-A1 County Courthouse 37-A1 County Courthouse County Courthouse 37-A1 County Co | |
| 207 FM-0056905 San Diego County Courthouse 37-A1 2 conditions due to burned out bulbs, ballast and a black substance/residue on the diffuser lenses. \$ 16,845 \$ 16,84 | |
| Exterior Shell - Remove and replace existing roof gutter system with new acrylic coated gal volume sheet steel rain gutter system at 5 locations. Install new downspouts and channel water away from building. Rain gutters that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building San Diego County Courthouse 37-A1 2 creating potential water intrusion and interior flooding. | |
| rain gutter system at 5 locations. Install new downspouts and channel water away from building. Rain gutters that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building County Courthouse 37-A1 2 creating potential water intrusion and interior flooding. | 100 |
| that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building County Courthouse 37-A1 that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building County Courthouse 37-A1 that serve the penthouse roofs are failing, loose and are no longer diverting water away from the building \$4,250\$ | |
| 208 FM-0056907 San Diego County Courthouse 37-A1 2 creating potential water intrusion and interior flooding. \$ 4,250 \$ 4,250 | |
| | |
| Exterior Shell - Expansion joints have deteriorated allowing water to penetrate into the interior of the building | 100 |
| | |
| flooding hallways and damaging ceilings during rainstorms. Set up (1) swing stage, grind out, clean, and acid | |
| Pomona Courthouse etch 1450 SF of and around expansion joints. Install 5800 LF of polyurethane backer rod and caulk 5800 LF of | 04.44 |
| 209 FM-0056908 Los Angeles South 19-W1 2 joints with single component polyurethane joint sealant. \$ 185,188 \$ 168,780 | 91.14 |
| Fire Protection - Replace 2 EA sets, 4 total, (12 x 30 each) of won doors at second and third floor elevator lobby. Replace existing track with new curved track system. Existing doors are literally falling apart. They do not close | |
| Replace existing track with new curved track system. Existing doors are literally falling apart. They do not close 210 FM-0056909 Contra Costa Bray Courts 07-A3 2 all the way. These are fire doors and this is a safety issue. \$ 264,961 \$ 226,595 | 85.52 |
| 210 W 0030303 Contra Costa Diay Courts 07-75 2 an the way. These are the doors and this is a safety issue. | 03.32 |
| HVAC -Corrections needed for Chiller #1 & 2 due to deficiencies found during Level VIII PM 2462651 & 2462638. | |
| Overhaul recommended to prevent downtime, damage and loss of comfort cooling to the courthouse. Purge all | |
| refrigerant and lube oil piping. Replace compressor journal bearings and high and low speed thrust bearings. | |
| San Fernando Replace compressor shaft seal, PRV control shaft seals and motor bearings. Install refrigerant cleanup kit. | |
| 211 FM-0056911 Los Angeles Courthouse 19-AC1 2 Replace (2) condenser water rubber vibration eliminator joints. \$ 223,294 \$ 186,250 | |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------|---------------|---------------------------------------|-------------|----------|--|--------|----------------------|---|---|
| 212 | FM-0056912 | El Dorado | Juvenile Hall | 09-G1 | 2 | Roof - Install a new TPO 80 MIL Single Ply overlay (Approximately 2400 sf) over the existing membrane - The existing roof is leaking and needs to be repaired before any damage occurs | Ś | 49,000 | \$ 49,000 | 100 |
| | | Los Angeles | Inglewood Courthouse | 19-F1 | 1 | HVAC - Replace 25hp supply side drive motor, front and rear bearings, sheaves, and bushings on the supply drive shaft. Replacement of 15 & 25hp VFDs, that were defective. AHU#2 was not operational and a section of the building was hot. Plumbing - Remediate flood water damage in 2nd floor Clerk's Area, Window #7 under ACM protocols. In- | , | \$40,000 | | 100.00 |
| | | | Van Nuys Courthouse | | | custody in the 4th floor Lock-up jammed a drinking fountain and stopped drain, causing water to run down pipe | | | | |
| 214 | FM-0056916 | Los Angeles | West | 19-AX2 | 1 | chase and leak into the 2nd floor. | | \$15,080 | \$12,136 | 80.48 |
| 215 | FM-0056917 | Los Angeles | San Fernando Courthouse | 19-AC1 | 1 | Plumbing - Remediate water damage from failed plumbing inside wall between the Men's and Woman's restroom in the public defender's office on the second floor under ACM protocols. Replace damaged 30' x 30' area of failed ceiling tiles. | | \$67,234 | \$67,234 | 100.00 |
| 213 | 1101 0030317 | LOS / MIGCICS | Courtiflouse | 13 7.01 | | HVAC - Replace failed Y Strainer on chill water pump#2. Leak impacted the Jury Assembly room affecting a 5' x | | Ψ07,23 + | ψ01,23 ⁻¹ | 100.00 |
| 216 | FM-0056919 | Los Angeles | Mental Health Court | 19-P1 | 1 | 20' area of carpet. Remediate water damage per ACM protocols. | | \$30,213 | \$21,545 | 71.31 |
| | | 9 | Santa Clarita | | | County Managed - HVAC - Replace cooling tower pump. Install new gasket and mounting plate. Cooling tower | | | | |
| 217 | FM-0056920 | Los Angeles | Courthouse | 19-AD1 | 1 | pump failed causing high temps in all the civic center buildings. | | \$1,909 | \$1,909 | 100.00 |
| | | | Santa Clarita | | | County Managed - HVAC - Replace 5 leaking bundles to boiler and restore to normal operation. Boiler failed due | | | | |
| 218 | FM-0056921 | Los Angeles | Courthouse | 19-AD1 | 1 | to the leaks. | | \$2,545 | \$2,545 | 100.00 |
| 219 | FM-0056922 | Los Angeles | Edmund D. Edelman Children's Court | 19-Q1 | 2 | Interior Finishes -Replace failed 1 electrify panic exit device on the East Front Exit Door and 1 rim panic exit device on the West Front Exit Door. During after hours when the court personnel are leaving, the doors are not locking leaving the exit doors unlock and open. | \$ | 3,715 | \$ 2,600 | 69.99 |
| | | | Santa Barbara | | | HVAC - Replace failing Cooling Tower sheaves and bushings for fan motor and blower shaft. Replacement | | | | |
| 220 | FM-0056923 | Santa Barbara | + - | 42-B1 | 2 | required to prevent further damage to Cooling Tower. | \$ | 2,287 | \$ 2,287 | 100 |
| 221 | FM-0056924 | Los Angeles | San Fernando Courthouse | 19-AC1 | 2 | HVAC - Remove and renovate leaking Condenser water pump motor. Water pump is leaking from the shaft seal causing excessive loss of water and chemical. | ر خ | 7 090 | ¢ 6.556 | 83.41 |
| 221 | FIVI-0030924 | LOS Aligeles | Pomona Courthouse | 13-AC1 | | HVAC - Replace (1) failed cut-out water probe sensor. Current status will not allow unit to pass AQMD code | Ą | 7,980 | \$ 6,656 | 65.41 |
| 222 | FM-0056925 | Los Angeles | North | 19-W2 | 2 | requirements. | Ś | 2,396 | \$ 2,306 | 96.25 |
| | | | | | | Elevators, Escalators, & Hoists - Replaced failed shaft seal on elevator #9. Remove and dispose of oil within | т | _, | , | |
| 223 | FM-0056926 | San Diego | County Courthouse | 37-A1 | 2 | elevator pit per HAZMAT protocols. | \$ | 4,147 | \$ 4,147 | 100 |
| 224 | FM-0056927 | Solano | Old Solano Courthouse | 48-A3 | 2 | Electrical -Replace failed speed governing components on emergency generator. Work to include magnetic pick- up & speed switch and engine governor-actuator and main control circuit board. Generator trips out on over- speed and shuts down when needed during electrical power outages | \$ | 6,889 | \$ 6,889 | 100 |
| | | | San Fernando | | | HVAC - Replace (1) Shaft, (2) Bearings, (1) driver in Cooling Tower #1. Bearings and shaft have excessive rust build-up and are failing due to high temperatures. Resulting failure to condenser water cooling within this | | | | |
| 225 | FM-0056928 | Los Angeles | Courthouse | 19-AC1 | 2 | chillers creates warm HVAC supply temps. | Ś | 11,042 | \$ 9,210 | 83.41 |
| | 0030320 | 200711160100 | Pomona Courthouse | 15 / (01 | | HVAC - Replace failed flame sensor and install new plugs on leaking water tubes. Continued delay in repair | 7 | ±±,0-72 | 7 3,210 | 55.71 |
| 226 | FM-0056929 | Los Angeles | South | 19-W1 | 2 | could flood mechanical room and take system off-line. | \$ | 4,532 | \$ 4,130 | 91.14 |
| | | | Kearny Mesa Traffic | | | Fire Protection - Install a new KOSO automatic natural gas shut off valve and pipe back into main. Work is | | , | , | |
| 227 | FM-0056932 | San Diego | Court | 37-C1 | 2 | required by code. | \$ | 3,877 | \$ 3,877 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|----------------------|---------------|--|-------------|----------|--|----------|----------------------|---|---|
| | | | | | | HVAC - Replace failed digital thermometers in the evaporator and condenser liquid "dry wells", Chilled water | | | | |
| | | | Alhambra | | | supply sensor and defective feedback potentiometer on Chiller #2. Court operation would have been impacted | ١. | | | |
| 228 | FM-0056933 | Los Angeles | Courthouse | 19-I1 | 2 | if Chiller #2 was not restored. | \$ | 3,900 | \$ 3,354 | 86 |
| 220 | 5. 4. 005.004 | 6 5: | | 27.44 | | HVAC - Replace failed leaking pump on the DFT Boiler Feed Water Pump for Boiler #1. Replacement required to | | 2.674 | | 77.40 |
| 229 | FM-0056934 | San Diego | County Courthouse | 37-A1 | 2 | restore system back to full operation. | \$ | 3,671 | \$ 2,842 | 77.42 |
| | | | Bakersfield Juvenile | | | Security - Secured Sally Port West Entrance Rolling Steel Door, the motor for the 12' x 12' door is no longer | | | | |
| 220 | FM-0056935 | Vorn | | 1E C1 | 2 | functioning and is preventing access to the secured Holding Garage. Replace burnt out Chain Hoist Motor | خ | E 0E2 | ¢ 5.052 | 100 |
| 230 | FIVI-0030933 | Kern | Center | 15-C1 | 2 | Operator and mount with heavy duty brackets. Vandalism - Remediate vandalism damage 2- restroom ceilings, entry doors (100 sqft) and (94 chairs) to | Ş | 5,052 | \$ 5,052 | 100 |
| | | | | | | remove graffiti. The etching/scribing must be removed due to the contents may be gang related which could | | | | |
| 231 | FM-0056936 | Ι ος Δησείες | Torrance Courthouse | 19-C1 | 2 | cause a safety situation to the courthouse | ¢ | 4,283 | \$ 3,647 | 85.14 |
| 231 | 1101-0030330 | LOS Aligeles | Tottance Courtilouse | 19-01 | | cause a safety situation to the courthouse | ٦ | 4,203 | 3,047 | 65.14 |
| | | | North County Regional Center - | | | COUNTY MANAGED - Grounds and Parking lot - Remove and replace 6 existing trees from the slope in the Judges secure parking lot and Replace with drought resistant, low-maintenance trees. Building occupants have | | | | 100 |
| 232 | FM-0056937 | San Diego | South | 37-F1 | 2 | expressed their concern numerous times stating that sap from existing trees is causing vehicle damage. | \$ | 19,422 | \$ 19,422 | 100 |
| 222 | EN 4 00E CO 40 | | El Marata Carretta acces | 10.01 | _ | Elevators, Escalators, & Hoists - Rebuild failing electrical generators on Elevators #1, #2, #3, and #4. Unit failure | ۸ ـ | 20.275 | 6 47.654 | 50.43 |
| 233 | FM-0056940 | Los Angeles | El Monte Courthouse | 19-01 | 2 | could create entrapments and negative impact to court operations. | \$ | 30,375 | \$ 17,654 | 58.12 |
| 234 | FM-0056942 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | HVAC - Courtrooms are too hot. Dampers actuators for AHU#3 & 4 found to be faulty and 30 VAV boxes were not connected. Replace (3) damper actuators and (2) valve actuators for AHU 3 & 4. Reconnect wiring for 30 VAV boxes and recommission. Upgrade obsolete BAS software from Siemens Apogee Insight software from v3.10 to v3.13, install Remote Email Notification, install BAS Uninterrupted Power Supply, back up data for (9) Siemens controllers and replace (6) batteries for Siemens FLNC controller. | \$ | 58,347 | \$ 45,026 | 77.17 |
| | 56565.1 | 2007geres | 7 in port dour thouse | 13 / (0 1 | _ | Electrical - Remove and cover obsolete/disconnected Duress Call devices (12) at all In-Custody elevator landings | <u> </u> | 30,3 .7 | .3,020 | ,,,, |
| 235 | FM-0056943 | San Francisco | Hall of Justice | 38-B1 | 2 | - To prevent mistaking non-working devices for working devices | \$ | 2,000 | \$ 2,000 | 100 |
| | | | San Fernando | | | Plumbing - Water is leaking from the ceiling into the 2nd Floor, Men's Public Restroom affecting a 4' x 4' area of | | • | | |
| 236 | FM-0056945 | Los Angeles | Courthouse | 19-AC1 | 1 | ceiling tiles. Remediate under ACM conditions. | | \$13,565 | \$11,315 | 83.41 |
| 237 | FM-0056946 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 2 | Interior Finishes - Install door in judge's room In Depart 22 - Cut and frame a new opening, install (1) custom aluminum frame, (1) custom laminated door, (1) mortise lock, (1) Norton closer and (3) 4.5" knuckle hinges. The Judge currently enters through the double entry courtroom doors near the public seating area. County Judicial Agency has concerns for Judge's safety and is requesting a separate door for entry/exit. | \$ | 9,914 | \$ 9,914 | 100 |
| | | | Education d D. E. L. | | | Interior Cinishes Deplete failed describes an above of the control | | | | |
| 222 | EN 4 005 00 47 | 1 4 1 | Edmund D. Edelman | 10.01 | _ | Interior Finishes - Replace failed door closers on three cafeteria glass doors leading to the outside dining area. | , | 4.24.0 | 6 2054 | 60.00 |
| 238 | FM-0056947 | Los Angeles | Children's Court | 19-Q1 | 2 | Doors are slamming. Work is required by ADA code and to mitigate risk to the public. | \ | 4,216 | \$ 2,951 | 69.99 |
| | | | Motropolitar | | | HVAC - Replace the non-functioning VFD and (1) 25HP US-Motor, pulley, bushing & belt to allow the air flow to | | | | |
| 220 | ENA COFCOAS | Los Angolos | Metropolitan | 10 T1 | 2 | be regulated throughout the 8th floor. The VFD is working on bypass and running full speed which could cause | ۲ | 0.042 | 6 0.200 | 04.54 |
| 239 | FM-0056948 | LOS Affgeles | Courthouse | 19-T1 | | too much air to flow and over pressurize the ducting system causing damage. | Þ | 9,942 | \$ 9,399 | 94.54 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------------------|-------------------------|--------------------------|-----------------|----------|--|----------|----------------------|---|---|
| | | | | | | Plumbing - Water leaked from the 4th flr deputies shower through ACM fireproofing into the 3rd flr court reporters office requiring a procedure 5. Replace 10SF of LCM ceramic tile & gypsum backing board, re-grout | | | | |
| | | | | | | 50SF of tile, replace (2) shower valves & mixers, demo 6'x6' section of water damaged wall, install mold and | | | | |
| | | | Metropolitan | | | mildew resistant drywall, install (1) 24"x24" access panel, paint and patch, replace 132 SF of ACM contaminated | | | _ | |
| 240 | FM-0056949 | Los Angeles | Courthouse | 19-T1 | 1 | carpet, and replace (26) 12"x12" ceiling tiles. | | \$44,650 | \$42,212 | 94.54 |
| 241 | ENA 005 6050 | A la va a ala | Wiley W. Manuel | 04 D2 | _ | Vandalism - Replace (1) 7"X32 3/4" X 1/2 security glass view window on fifth floor cell 110-2 door. Window | _ ا | 4 707 | ć 4.727 | 100 |
| 241 | FM-0056950 | Alameda | Courthouse | 01-B3 | 2 | broken by an inmate. Plumbing - Redesign and modify strainer box from basement sewer discharge to lift station. Original design of | \$ | 1,737 | \$ 1,737 | 100 |
| | | | Modesto Main | | | strainer box is inconsistent with current jail operation and is creating obstruction to sewer discharge from | | | | |
| 242 | FM-0056952 | Stanislaus | Courthouse | 50-A1 | 2 | building to lift station. | S | 2,279 | \$ 2,279 | 100 |
| | 0030302 | Starmera as | ecur in cuse | 30712 | _ | Fire Protection - Replace a 4 - 6 ft section of 6" fire sprinkler, one 8" x 6" grooved coupling and one 6" grooved | <u> </u> | _,_, | Ψ =,=73 | |
| | | | | | | coupling and two 6" OS&Y control valves (fire pump suction & discharge). Fire Pump Room has a section of 6" | | | | |
| | | | East County Regional | | | Main Fire Pump Pipe rusting out and the 2 Main Shut off Valves are leaking and cannot properly secure the | | | | |
| 243 | FM-0056953 | San Diego | Center | 37-I1 | 2 | water. | \$ | 6,060 | \$ 4,103 | 67.71 |
| | | | | | | HVAC - Replace failed canvas flex connectors in AHU01, AHU02, AHU04, AHU17, and AHU14. Canvas flex | | | | |
| 244 | FM-0056954 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | connectors on these AHU are broken/deteriorated and need to be replaced. | \$ | 9,224 | \$ 6,100 | 66.13 |
| | | | South County | | | COUNTY MANAGED - Replace faulty gearboxes and fan motors for Cooling Tower at Central Plant, this | | | | |
| 245 | FM-0056955 | San Diego | Regional Center | 37-H1 | 2 | corrective measure is needed restore to normal efficiency. | \$ | 6,211 | \$ 6,211 | 100 |
| 246 | | Cooronoonto | lunionilo Counthouse | 24.62 | , | HVAC - Upgrade existing BAS software system - Replacement of existing server requires higher level software in | ے ا | 14 002 | ć 14.002 | 100 |
| 246 | FM-0056956 | Sacramento | Juvenile Courthouse | 34-C2 | | order to operate within new IOS. Electrical - Replace failed courtroom lighting (50%) within ACM ceiling plenum in Dept. #11. Courtroom lighting | Ş | 14,893 | \$ 14,893 | 100 |
| 247 | FM-0056957 | San Diego | County Courthouse | 37-A1 | 2 | has failed to the point of impacting court operations. | \$ | 8,293 | \$ 8,293 | 100 |
| 247 | 1101 0030337 | San Diego | County Courtinouse | 37 711 | | has railed to the point of impacting court operations. | 7 | 0,233 | ψ 0,233 | 100 |
| | | | | | | Plumbing - Replace faulty and leaking basin faucet. During building water outage install new "in-line" ball valves | | | | |
| | | | Van Nuys Courthouse | | | for this faucet and 4 other faucets/toilets 7th Floor secure hall. Janitor's wash basin has a leaking basin faucet, | | | | |
| 248 | FM-0056958 | Los Angeles | East | 19-AX1 | 2 | there is no shut off for hot & cold supply lines, there is a risk of flooding if basin sink plugs up or if faucets fail. | \$ | 2,972 | \$ 2,667 | 89.74 |
| | | | | | | HVAC - Replace failed purge unit and inline refrigerant filters on Chiller #1. Hardware failure is causing Chiller #1 | | | | |
| 249 | FM-0056959 | Los Angeles | Torrance Courthouse | 19-C1 | 2 | to run at a high temperature. | \$ | 8,738 | \$ 7,440 | 85.14 |
| | | | | | | Interior Finishes - Replace 6 defective courtroom gallery seats in 2nd Floor Dept. 241 within ACM environment. | | | | |
| | | | | | | The attachment points on the metal frame for seat #1, #2 and #3 are broken and cannot be repair. This is a | | | | |
| 250 | LN4 00E6060 | Los Angolos | Inglewood Juvenile | 10 51 | , | safety hazard and the seats must be replaced. This row of seats is not modular and entire row of six seats must | ے | 0 700 | ¢ 7,000 | 90.79 |
| | FM-0056960 FM-0056961 | Los Angeles Los Angeles | Court Airport Courthouse | 19-E1 19-AU1 | 2 | be replaced. HVAC - Replace failed Refrigeration Leak Detection Monitor. Replacement required by code. | ۶ ¢ | 8,788 9,339 | | 80.78 77.17 |
| 231 | 1 141 0030301 | LOS Aligeles | Air port Courtilouse | 12 701 | | HVAC - Remove and replace one (1) 4 bolt flanged bearing on Air Handler Unit #3. Air Handler Unit #3's supply | ۲ | 2,333 | γ /,20/ | //.1/ |
| | | | Pomona Courthouse | | | fan bearing is very noisy and has excessive amounts of vibration when running. Failure will result in system | | | | |
| 252 | FM-0056962 | Los Angeles | South | 19-W1 | 2 | down time and emergency repairs. | \$ | 2,087 | \$ 1,902 | 91.14 |
| | | | | | | HVAC - Replace failed two way heating valve and two (2) thermostat controls The heat exchanger will only | | | , | |
| | | | Pomona Courthouse | | | provide domestic hot water at 100 degrees due to the two way heating valve is stuck in mid position and not | | | | |
| 253 | FM-0056963 | Los Angeles | South | 19-W1 | 2 | opening causing low water temperatures throughout the higher floors. | \$ | 7,546 | \$ 6,877 | 91.14 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|------------|--------------|--|-------------|----------|---|----|----------------------|---|---|
| | | | Monterey | | | County Managed - Electrical - install replacement generator - Current equipment has failed. A temp rental has | | | | |
| 254 | FM-0056965 | Monterey | Courthouse | 27-C1 | 2 | been deployed during replacement. | \$ | 36,750 | \$ 36,750 | 100 |
| 255 | FM-0056966 | Los Angeles | Pomona Courthouse South | 19-W1 | 2 | Roof - Build-up roof area (400 sq. ft) around cooling towers, replace roofing material and install 1 new roof drain and divert all the water into new drain system. Rain water sits on the roof, under and around the cooling towers after each rain. The rain water leaks into the building and causes damage. | \$ | 16,688 | \$ 15,209 | 91.14 |
| 256 | FM-0056968 | Orange | Central Justice Center | 30-A1 | 2 | Interior Finishes - Elevator rooms 7 through 15 lack secondary containments required to complete CUPA permitting. Remove 1163 SF of epoxy paint, prep and epoxy fill 125 LF of cracks, construct 55 LF of new containment berms in rooms 7-15, acid wash and degrease 1163 SF of concrete, apply 825 SF of Petra Xtra-Kote TC to horizontal surfaces, and apply 338 SF of Petra Xtra-Kote TC to vertical surfaces. | \$ | 54,674 | \$ 49,840 | 5 91.17 |
| 257 | FM-0056969 | Los Angeles | Michael D. Antonovich Antelope Valley Courthouse | 19-AZ1 | 2 | HVAC - Install (1) York Optiview board, (1) service trigger kit, (1) time clocks, and (1) Eprom on Chiller #2. Chiller is non operational due to failed circuit boards and microprocessors. Electrical - Replace main breaker handle, Kirk Keys, broken indicator lights on 4160 transformer. Main breaker | \$ | 26,875 | \$ 19,750 | 5 73.51 |
| | | | Central Justice | | | handle and kirk keys are missing and 8 indicator lights are out creating operational risk of building not being | | | | |
| 258 | FM-0056970 | Orange | Center | 30-A1 | 2 | able to restore power in the event of the transformer tripping. | \$ | 27,755 | \$ 25,304 | 91.17 |
| 259 | FM-0056972 | Los Angeles | Metropolitan Courthouse | 19-T1 | 2 | Interior Finishes - Dept. 70 Cashier's Public stadium seating; 14% of seats are completely broken & missing seat bottoms. Approx. 80% have broken or missing springs/bearings and replacement parts are obsolete. Seats need to be replaced as this is a safety issue for the public when trying to sit. Demo 101 existing damaged chairs, fill mounting holes and install 101 new American Seating Model 408 fiberglass seats and secure with epoxy. Perform environmental testing and set up 30'W x 32' L x 8' H containment. | ς. | 78,669 | \$ 74,374 | 1 94.54 |
| | | | Metropolitan | | | Exterior Shell - Windows have been vandalized and are severely etched. Etching is deep and requires glass replacement and addition of anti-graffiti (A/G) film. East 1st Flr: Replace (12) 33-1/4"x33" tinted tempered glass panes; Install A/G film on 17 windows. North 1st Flr: Replace (3) 24"x78" tinted tempered glass panes; install A/G film on 4 windows. West 1st Flr: Install A/G film on 3 windows. Flrs 2 - 8 replace 174 tinted tempered glass | | | | |
| 260 | FM-0056973 | Los Angeles | Courthouse | 19-T1 | 2 | panes (19"x90") and install A/G film on 199 windows. | \$ | 197,385 | \$ 186,608 | 94.54 |
| 261 | FM-0056976 | Contra Costa | Bray Courts | 07-A3 | 2 | HVAC - Replace six (6) failed 5/8 diameter x 4 long capillary tubes, install 1 filter dryer. Leaks causing unit to not provide sufficient cooling. | \$ | 8,766 | \$ 7,49 | 85.52 |
| 262 | FM-0056977 | Fresno | Firebaugh Court | 10-K1 | 2 | HVAC - Remove old leaking condenser water pump and replace with a new Gould 1 1/2 HP pump and motor. | \$ | 3,755 | \$ 2,179 | 58.02 |
| 263 | FM-0056978 | Orange | West Justice Center Pomona Courthouse | 30-D1 | 2 | Plumbing - Storm Drain Lines are cracked and damaged - Line two (2) 3" storm drain lines, approximately 40' per line. Drain lines are leaking into the detention tunnel creating a slip/fall safety issue. Plumbing - Replace 30ft of 4 cast iron pipe. Replace 2 cracked pipe coming from 7th floor janitorial mop sink and 30ft of sewer line on the 6th floor courtroom. A section of the building's water waste piping system has | \$ | 8,480 | \$ 7,690 | 90.68 |
| 264 | FM-0056980 | Los Angeles | South | 19-W1 | 2 | deteriorated, this is causing leaks into the court room. | \$ | 9,656 | \$ 8,800 | 91.14 |
| 265 | FM-0056981 | Kern | Delano/North Kern Court | 15-D1 | 2 | HVAC - Install (1) new evaporator coil, filter drier, txv (expansion valve). Current evaporator coil for PKU#10 is failed and no longer providing cooling to the main lobby and District Attorney's offices. | \$ | 11,629 | \$ 9,378 | 80.64 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|-------------|---------------|--|--------------------|----------|---|-------|----------------------|---|---|
| 266 | ENA 00E6093 | Canta Darbara | Santa Barbara | 42 D1 | 2 | HVAC - Replace (2) inline centrifugal pumps, replace (2) pressure gauges, replace (2) copper flanges and (2) | _ ا | 26 212 | ć 26.212 | 100 |
| 200 | FM-0056982 | Santa Barbara | Figueroa Division Stanley Mosk | 42-B1 | Z | copper 90s. Hot water pumps #1 and #2 and the pump flanges are badly corroded and leaking. Elevators, Escalators, & Hoists - Replace failed electrical generator on Elevator #2, Unit is stuck on the 2nd floor |) | 26,313 | \$ 26,313 | 100 |
| 267 | FM-0056983 | l os Angeles | Courthouse | 19-K1 | 1 | and not responding. Bearing failure caused grounding of the unit. | | \$65,100 | \$63,316 | 97.26 |
| | | | | | 2 | HVAC - Replace (2) custom chilled water coils, (2) 2-1/2" butterfly valves and (2) 2-1/2" pneumatic control valves, perform hydrostatic test and re-insulate 60 LF of 2-1/2" pipe. Chilled water coil needs to be replaced as it is not cooling the area. The coil shows signs of severe blockage and condensate is carrying over onto the AHU | 6 | | | |
| 268 | FM-0056985 | San Diego | County Courthouse | 37-A1 | 2 | floor creating a slip hazard. | \$ | 37,139 | \$ 37,139 | 100 |
| 260 | FM-0056986 | Los Angeles | Torrance Courthouse | 10 ₋ C1 | 2 | Elevators, Escalators, & Hoists - Rebuild elevator electrical generator. Generator #2 has begun to fail resulting in the car not leveling properly creating a trip hazard for passengers. | ا د | 33,372 | \$ 28,413 | 85.14 |
| | | Los Angeles | Airport Courthouse | 19-AU1 | 2 | HVAC - Replace 75HP VFD and combination starter bypass and program VFD into court house BAS system and update graphics. AHU #2's VFD shorted out after an over current. AHU #2 is currently operated exclusively in bypass mode. | \$ | 36,152 | | 77.17 |
| | | | Downtown Superior | | | Exterior Shell - Vandalism - Replace (1 each) 76 X 88 broken front window - Currently compromising the courts | | | | |
| 271 | FM-0056988 | Santa Clara | Court | 43-B1 | 1 | security access | | \$5,117 | \$5,117 | 100.00 |
| 272 | FM-0056989 | Santa Clara | Santa Clara Courthouse Fremont Hall of | 43-G1 | 2 | Plumbing - Replace (1) failed underground plumbing connection to sewer line, install (1) two way cleanout. Currently impacting the Courts storm sewer ability to drain and will cause flooding. Grounds and Parking - Remove (4) dead plum trees including stump grinding. Safety issue. Branches and dead trees have a huge potential to fall on people causing injury during the stormy weather. Limbs have fallen in the | \$ | 5,185 | \$ 5,185 | 100 |
| 273 | FM-0056990 | Alameda | Justice | 01-H1 | 2 | past | Ś | 3,502 | \$ 2,781 | 79.4 |
| | | Alameda | Wiley W. Manuel Courthouse | 01-B3 | 2 | Grounds and Parking Remove (3) dead olive trees and stump. Trees having visible structural hazards and liabilities in stormy weather. Safety Issue. Branches have fallen in the past during rainy, windy storms. HVAC - Install cooling unit in first floor AV closet - Install (1) 120V/20A dedicated circuit for cooling unit - install | \$ | 5,991 | | 83.8 |
| 275 | FM-0056992 | Santa Clara | Hall of Justice (West) | /3-A2 | 2 | 20' of 6" flexible ductwork for condenser exhaust - fire caulk all penetrations. Lack of cooling in the space is causing Court AV equipment to shutdown | اد | 4,030 | \$ 4,030 | 100 |
| | | Santa Clara | Hall of Justice (East) | 43-A1 | 2 | HVAC - Install cooling unit in first floor AV closet - Install (1) 120V/20A dedicated circuit for cooling unit - install 20' of 6" flexible ductwork for condenser exhaust - fire caulk all penetrations - Lack of cooling in the space is causing Court AV equipment to shutdown | \$ | 5,923 | | 100 |
| | | | Michael D. Antonovich Antelope | | | Interior Finishes – Replace 45 sq. ft. of epoxy paint flooring and 14 linear ft. of epoxy paint for the base. Courtroom holding cell flooring is starting to fail and it is easy to be broken off into pieces which creates a | | | | |
| 277 | FM-0056994 | Los Angeles | Valley Courthouse | 19-AZ1 | 2 | safety hazard due to in custody visitors creating cutting/stabbing type of weapons. | \$ | 6,026 | \$ 4,430 | 73.51 |
| 278 | FM-0056995 | Los Angeles | Airport Courthouse | 19-AU1 | 2 | Elevators, Escalators, & Hoists - Replace the failing generator brushes for Elevators 1, 2, 3 and 4. Replacement required to maintain operations. | \$ | 4,027 | \$ 3,108 | 77.17 |
| 279 | FM-0056997 | San Diego | County Courthouse | 37-A1 | 2 | HVAC - Exhaust Fan #38 bearing and shaft repair - Remove the existing (2) pillow-block bearings and replace with factory supplied pillow-block bearings type BB Size 330 1 15/16 for Exhaust Fan #38. The South Tower is without exhaust air in the restrooms due to bad bearing and shaft. Operational fan units are required by code. | \$ | 12,905 | \$ 9,991 | 77.42 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|------------|--------------|---------------------------------|-------------|----------|--|----|----------------------|---|---|
| 280 | FM-0056998 | I os Angeles | Glendale Courthouse | 19-H1 | 2 | Electrical - Replace and rewire 1 defective light fixture under ACM protocols. Main lighting over the bench has failed and requires replacement. | ١ | 4,689 | \$ 4,245 | 90.54 |
| | FM-0056999 | | County Courthouse | 37-A1 | 2 | Elevators, Escalators, & Hoists - Replace failed emergency reset and amplifier circuit cards for Elevator 8. Install one new drive contactor and for (4) new amp traps. The staff pedestrian traffic is delayed due to elevator being non-operational. | \$ | 7,474 | | 77.42 |
| 282 | FM-0057000 | Los Angeles | Airport Courthouse | 19-AU1 | 1 | HVAC - Replace failed 75 HP motor for Air Handler 1, and integrate into the Building Energy Management System. Air Handler Unit 1 main motor is not functioning. | | \$17,762 | \$13,707 | 77.17 |
| | | Santa Clara | Santa Clara Courthouse | 43-G1 | 2 | Grounds and Parking - Remove (5) hollowed out beetle infested dying pine trees with exposed roots. Trees are heavily leaning sideways into the parking lot. Remove (1) dead redwood tree near the gas meter and main. Safety issue when the storms begin. Dead and dry cracked limbs have already fallen during heavy winds. Electrical - Replace 40 failed lobby lights. 60% of lights have failed. ACM containment and disposal required. No | \$ | 8,373 | | 100 |
| 284 | FM-0057002 | Los Angeles | Pasadena Courthouse | 19-J1 | 1 | lights are on in front lobby, this creates a safety and security hazard for early morning at end of day weapon screening processing. HVAC - Replace (1) failed condenser float valve and damaged components for the Cooling Tower that flooded | | \$33,818 | \$23,453 | 69.35 |
| 285 | FM-0057003 | Santa Clara | Downtown Superior Court | 43-B1 | 1 | two Courtrooms. Extracted approx. 330 gallons of clean water from approx. 1000 sq ft of court space. Remediated and replaced 224 square feet of damaged VCT tile including ACM abatement | | \$36,901 | \$36,901 | 100.00 |
| 286 | FM-0057004 | Los Angeles | Pomona Courthouse South | 19-W1 | 1 | HVAC - Replace failed drain line for Chiller #2. Remediate flooding water throughout the mechanical room and basement under ACM procedures. | | \$10,198 | \$9,294 | 91.14 |
| 287 | FM-0057005 | El Dorado | Cameron Park | 09-C1 | 2 | Exterior - Renovate and waterproof approximately 825 sf of crack and molded stucco on the north exterior wall. Work required to prevent water intrusion and potential interior flooding. | \$ | 4,550 | \$ 4,550 | 100 |
| 288 | FM-0057007 | Contra Costa | Arnason Justice Center | 07-E3 | 2 | HVAC - Replace one Failed Burner Controller Board on Boiler #2. Board has failed and the boiler will not operate. | \$ | 4,312 | \$ 4,312 | 100 |
| 289 | FM-0057008 | Solano | Hall of Justice | 48-A1 | 2 | Pest Control - Building exterior - Using a 40' boom truck Remove and remediate damage caused by a 3' x 4' beehive on the exterior eves of the west side of the building. The beehive creates an unsafe environment for court staff and visitors. | \$ | 5,461 | \$ 3,977 | 72.82 |
| 290 | FM-0057009 | El Dorado | Main St. Courthouse | 09-A1 | 2 | HVAC - Replace the defective High Pressure Sensor Cut-Out device and the Discharge Temperature Sensor. Chiller compressor is not cycling and is causing the compressor to overheat. | \$ | 4,079 | \$ 4,079 | 100 |
| 291 | FM-0057010 | Stanislaus | Turlock Superior Court | 50-D1 | 2 | Grounds and Parking Lot - Install 80 skate stops at 3ft intervals on assigned planter beds on front and back public entry to the courthouse. Closure and removal of City Skate Park in adjacent lot has had negative impact and recent change in skaters using court property. Skaters are creating a potential public hazard during court operational hours. | \$ | 3,583 | \$ 3,583 | 100 |
| | | Contra Costa | George D. Carroll Courthouse | 07-F1 | 2 | Fire Protection - Replace (10) Damaged Sprinkler Heads, (4) missing escutcheons, and (12) Hoses that are out of compliance. | Ś | 8,089 | | 74.99 |
| | | Alameda | Hayward Hall of Justice | 01-D1 | 2 | HVAC - Replace Building Automation System (BAS) with new and current technology. Provide and install one (1) panel mounted BAS workstation configured with Windows 7 Pro and one (1) Automation Server. Upgrade installation to StruxureWare and migrate existing system configuration, sequence and graphics. Current system has failed components that are discontinued and no longer available or supported by the manufacture. | \$ | 18,229 | | 88.3 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------------|---------------|-----------------------|-------------|----------|---|----------|----------------------|---|---|
| | | | | | | HVAC - Replace Building Automation System (BAS) with new and current technology. Provide and install one (1) | | | | |
| | | | | | | panel mounted BAS workstation configured with Windows 7 Pro and one (1) Automation Server. Upgrade | | | | |
| | | | | | | installation to StruxureWare and migrate existing system configuration, sequence and graphics. Current system | | | | |
| 294 | FM-0057014 | Alameda | Berkeley Courthouse | 01-G1 | 2 | has failed components that are discontinued and no longer available or supported by the manufacture. | \$ | 18,229 | \$ 18,229 | 100 |
| 205 | EN 4 0057046 | | Bellflower | 40 414 | 4 | Plumbing - Remove and renovate failed sump pump #1 and #2. Remediate black water overflow in the Lock-up | | ¢60.605 | Ć5.4.24.2 | 77.04 |
| 295 | FM-0057016 | Los Angeles | Courthouse | 19-AL1 | 1 | areas on 1st, 2nd, 3rd & 4th flrs affecting 6,939sf. Inmate vandalism caused pumps to fail. | | \$69,685 | \$54,312 | 77.94 |
| | | | | | | Dlumbing Paplace 2.20 ft section of 4" cast iron drain pine under ACM protocols. North Side Exterior of | | | | |
| 206 | FM-0057017 | Los Angeles | Compton Courthouse | 10 461 | 1 | Plumbing - Replace a 20 ft section of 4" cast iron drain pipe under ACM protocols. North Side Exterior of | | ¢n 202 | ¢6.205 | 66.13 |
| 290 | FIVI-0037017 | LOS Aligeles | Compton Courthouse | 19-AG1 | 1 | Building a 4" Cast Iron Drain Pipe is cracked and leaking into the employee lounge and maintenance office. | | \$9,383 | \$6,205 | 00.13 |
| | | | Del Norte County | | | Exterior Grating - Replace rusted grates (2) - replace rusted grating at 2 locations, 1- approx. 240 sq ft with | | | | |
| 297 | FM-0057018 | Del Norte | Superior Court | 08-A1 | 2 | fiberglass grating due to location near ocean, 1- approx. 13 sq ft with frame and fiberglass grating with lock. | Ġ | 11,513 | \$ 7,054 | 61.27 |
| 237 | 1101 0037018 | Derivorte | Superior Court | 00 AI | | HVAC - Replace shorted compressor and malfunctioning thermostat control for ACU #1 that serves the | 7 | 11,515 | 7,054 | 01.27 |
| | | | | | | courtroom exclusively Compressor is not working due to winding wires being shorted and thermostat is not | | | | |
| 298 | FM-0057020 | Kings | Avenal Court | 16-C1 | 2 | functioning properly. | Ś | 3,122 | \$ 3,122 | 100 |
| 230 | 1111 0037020 | 183 | B.F. Sisk Federal | 10 01 | _ | Elevators - Enhance elevator #3 programming to ensure that elevator will not allow public access to the secured | · · | 3,122 | у 3,122 | 100 |
| 299 | FM-0057021 | Fresno | Courthouse | 10-01 | 2 | area. Current operation allows intermittent access. | Ś | 4,956 | \$ 4,956 | 100 |
| | | | | | | HVAC - Replace failed condensate pan. Pan failure caused condensate to run off through the elevator | <u> </u> | , | , , | |
| | | | | | | penthouse to the 7th floor mediation room #701 dripping through the ceiling tiles replace (6) 24"x24" ceiling | | | | |
| 300 | FM-0057022 | Los Angeles | Norwalk Courthouse | 19-AK1 | 1 | tiles and remediate water from approximately 6'x6' of carpet per ACM protocols. | | \$15,320 | \$13,027 | 85.03 |
| | | | | | | HVAC - Replace failed 40 HP VFD. Currently 40 HP motor is running at a 100% which is causing air noise in | | | | |
| 301 | FM-0057024 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | courtrooms and it may over pressurize and damage ducting. | | \$10,015 | \$6,623 | 66.13 |
| | | | Pasadena | | | Elevators, Escalators, & Hoists - Replace relay on the main power supply to all elevators. All elevators are down, | | | | |
| 302 | FM-0057025 | Los Angeles | Courthouse | 19-J1 | 1 | there is no power going to the elevators. | | \$10,100 | \$7,004 | 69.35 |
| | | | | | | Grounds and Parking Lot - Judges secured parking gate - Remove and replace the failed gate openers (left and | | | | |
| 303 | FM-0057026 | Riverside | Larson Justice Center | 33-C1 | 2 | right) with two new Liftmaster #SL585. Current units are obsolete and cannot be repaired. | \$ | 8,860 | \$ 8,860 | 100 |
| | | | Inglewood | | | HVAC - Remove and replace transducers to allow sensors. Chiller #1 & Chiller #2 has tripped off-line due to low | | | | |
| 304 | FM-0057027 | Los Angeles | Courthouse | 19-F1 | 1 | water flow which is leaving no cooling to the building. | | \$8,652 | \$6,451 | 74.56 |
| | | | | | | Roof - Restore Roof: Seal roof area with polyurethane chemlock to mitigate future rust, apply asphalt emulsion | | | | |
| | | | | | | and elastomeric coating. The roof has several penetrations throughout the surface that are allowing leaks to | | | | |
| 205 | 5.4 0057020 | | Santa Barbara | 40.04 | | develop inside the building during storms/rain. Some areas of the roof are rusting. Remove all penetrations to | _ | 4.420 | â 2.66 7 | |
| 305 | FM-0057029 | Santa Barbara | Juvenile Court | 42-C1 | 2 | restore roof, making the roof fully sustainable against leaks and damage. | \ | 4,120 | \$ 3,667 | 89 |
| | | | Hayward Hall of | | | Plumbing - Replaced failed hardware on toilet fixture. Remediate 600 sq ft wet floor dried & 200 sq ft sheetrock | | | | |
| 206 | FM-0057030 | Alamoda | Hayward Hall of | 01 D1 | 1 | dried & 200 sq ft of ceiling tile replaced & 100 sq ft sheetrock ceiling opened and lacerated &, 20 ft of baseboard replaced under ACM protocols. | | ¢E 726 | ¢E 726 | 100.00 |
| 300 | 1111-005/030 | Alameda | Justice | 01-D1 | 1 | Vandalism - Replace (1) broken window at holding cell 101A interview room with like for like replacement glass | - | \$5,726 | \$5,726 | 100.00 |
| | | | Wiley W. Manuel | | | 32"x62" 1/2 thick clad poly. Work is to be coordinated with Marshall's office for access during normal court | | | | |
| 207 | FM-0057031 | Alameda | • | 01-B3 | 2 | hours. | Ś | 4,252 | \$ 4,252 | 100 |
| 307 | 1 141-002/021 | Mailleua | Cour allouse | 101-D2 | | liouis. | ۲ | 4,434 | 4,۷۵۷ ب | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------|----------------|-----------------------------------|-------------|----------|--|----------|---|---|---|
| | | | | | | HVAC - Judges chambers room 312 and 313 lack independent zone control and are excessively hot during the summer. Install (2) VAV boxes, (2) steam reheat coils, 40LF of 8" spiral duct, 80 LF of 10" spiral duct, (2) spiral | | | | |
| 200 | EN4 00E7022 | Can Barnardina | San Bernardino | 26 11 | 2 | reducers, (6) 10" sheet metal elbows, 50 LF of fiberglass round duct, 50 LF of 1-1/2" black pipe, 50 LF of 1" black pipe, (2) steam traps, (2) 1-1/2" basket strainers, (2) thermometers, (2) pressure gauges, (2) independent | ے | 72 252 | ¢ 72.252 | 100.00 |
| 308 | FIVI-0057032 | San Bernardino | Courthouse | 36-A1 | 2 | thermostats, integrate with county owned Siemens BAS. Interior Finishes - Install (17) 10" x 10" x 9/16" forced entry resistant laminated glass and (32) 12" x 16" x 1" | \$ | 73,252 | \$ 73,252 | 100.00 |
| | | | Clara Shortridge Foltz | | | forced entry resistant laminated glass. Lock up cell viewing windows for cells #1-9 on each the 1st, 4th, 8th, | | | | |
| | | | Criminal Justice | | | 10th, and 14th floors have are damaged, crack, or heavily etched obscuring vision into the cells and presenting | | | | |
| 309 | FM-0057033 | Los Angeles | Center | 19-L1 | 2 | a safety issue for deputies conducting checks. | \$ | 35,294 | \$ 35,294 | 100 |
| 210 | ENA 00E7024 | L a a America | Inglewood | 10.51 | _ | HVAC - Replaced a defective 5 amp fuse in the MCC control panel. The MCC control panels for AHU 2, 3, 4, & 5 | | ¢0.220 | ¢C 040 | 74.56 |
| 310 | FM-0057034 | Los Angeles | Courthouse Hayward Hall of | 19-F1 | 1 | are not allowing the VFD's to operate which is making the temperature in the building rise. Vandalism - Window - Single pane exterior door side-light approximately (1.5' x 7') - Replace window glass | | \$9,320 | \$6,949 | 74.56 |
| 311 | FM-0057035 | Alameda | Justice | 01-D1 | 1 | broken out by thrown rock. | | \$3,500 | \$3,091 | 88.30 |
| 311 | 1101 0037033 | riameda | Justice | 01 01 | | Exterior Shell - Vandalism - Broken exterior glass window. Replace (1) 34 /12 X 52 X 1/4 thick window next to | | 73,300 | γ3,031 | 00.30 |
| 312 | FM-0057036 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | the main entrance of the building. Add graffiti film and tinting on new window. | | \$7,562 | \$5,001 | 66.13 |
| 313 | FM-0057037 | Los Angeles | Pomona Courthouse South | 19-W1 | 1 | Plumbing - Cold water valve to sink in lock up has failed and water is leaking into the 2nd floor DA's woman's restroom. Remediate damage The affected areas is approximately 7'X5' of plaster ceiling and the east wall approximately 7'X 8', 2x2 area re-plastering required. This work was conducted in a ACM environment. HVAC - Chiller #2 has leaks on the Solenoid valve and liquid valve. Install one (1) new liquid line solenoid valve | | \$10,205 | \$9,301 | 91.14 |
| | | | Santa Barbara | | | with coil to replace leaking valve. Replace liquid line drier core and sight glass. Replace old time delay in control | | | | |
| 314 | FM-0057038 | Santa Barbara | | 42-B1 | 2 | panel with a new solid state timer and replace oil pressure safety control. | \$ | 7,157 | \$ 7,157 | 100 |
| | | _ | Metropolitan | | | Fire Protection - Replace (7) 75' failed Fire Hoses. Replace (5) defective sprinkler heads in parking structure to | ١. | | | |
| 315 | FM-0057039 | Los Angeles | Courthouse | 19-T1 | 2 | maintain compliance. Extract and replace (2) leaking nipples on the South FDC Manifold. | Ş | 7,382 | \$ 6,979 | 94.54 |
| | | | Van Nuys Courthouse | | | Exterior Shell - Removed damaged window glass and installed one (1) insulated 45in x 80in window glass into the existing aluminum frame. Ground Level, West Side Main Entrance a person threw a rock at the building | | | | |
| 316 | FM-0057041 | Los Angeles | West | 19-AX2 | 2 | causing a corner window to break/crack. | ς . | 3,943 | \$ 3,173 | 80.48 |
| 310 | 1101 0037041 | Los / tilgeres | Inglewood Juvenile | 13 7 7 7 7 | | Roof - Remove and replace approximately 11,600 SF of failing built up roof. New roof to be a SBS multi-ply roof, | 7 | 3,343 | 3,173 | 00.40 |
| 317 | FM-0057043 | Los Angeles | Court | 19-E1 | 2 | to include new building metal, and install new roof drain caps. | \$ | 280,307 | \$ 226,432 | 80.78 |
| | | | San Fernando | | | Interior Finishes - Replace (6) panes of 71" x 52-1/4" x 1-1/8" thick laminated bronze tinted glass. Judges | <u> </u> | , | , | |
| 318 | FM-0057044 | Los Angeles | Courthouse | 19-AC1 | 2 | Chambers for Dept. D, G, J, L, N, and I have been broken or damaged window glass. | \$ | 30,832 | \$ 25,717 | 83.41 |
| | | | Michael D. Antonovich Antelope | | | HVAC - Cooling towers #1 and #2 media has significant calcium build up causing water to escape and puddle at the towers base. Floats do not provide adequate make up water causing pump surge. Replace (72) counter flow eliminators, (8) 63-1/4 W x 35-1/2 H louvers, (16)44-5/8 W x 35-1/2 H louvers, (4) 8" butterfly valves, (2) gear operated 3" butterfly drain valves, 101"Wx252"L Cooling tower media, (2) EZ Float Kits, (2) 4B154 power band | | | | |
| 319 | FM-0057045 | Los Angeles | Valley Courthouse | 19-AZ1 | 2 | belts, and (2) grease line kits. | \$ | 82,230 | \$ 58,745 | 71.44 |
| | | | Chatsworth | | | HVAC - Replace failing liquid filter, oil filter, and install 5/8" isolation valves, replace suction elbow gaskets on | <u> </u> | <u>, , , , , , , , , , , , , , , , , , , </u> | , | |
| 320 | FM-0057046 | Los Angeles | Courthouse | 19-AY1 | 2 | Chiller #2. Unit showing high levels of moisture which will cause premature system failure. | \$ | 29,580 | \$ 26,723 | 90.34 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|----------------------|----------------|-----------------------------------|--------------|----------|--|-------------|----------------------|---|---|
| | | | | | | Interior Finishes - Remove and replace failing lathe & plaster ceiling system (18' x 28' = 504 SF). The plaster and | | | | |
| | | | | | _ | lath ceiling in the main communications room has begun to collapse in several areas. Falling debris could result | _ | | | |
| 321 | FM-0057047 | Los Angeles | Norwalk Courthouse | 19-AK1 | 2 | in serious damage to employees and electronics. | \$ | 25,417 | \$ 21,612 | 85.03 |
| | | | Clara tan una untila | | | Plumbing -Replace two Nibco LD-200 4" butterfly main domestic water isolation valves, replace four 4" flange | | | | |
| 222 | ENA 00E7049 | Los Angolos | Chatsworth | 10 4 1 | 2 | gaskets, four 4" and four 6" coupling gaskets, four 4" gasket isolators and bolts. Main Isolation valves in the | ۲ | 4 2 4 1 | ¢ 2.554 | 02.0 |
| 322 | FM-0057048 | LOS Angeles | Courthouse | 19-AY1 | | basement are not closing completely and will not isolate the water if a leak were to occur. **COUNTY MANAGED** Security Intrusion Alarmy Bonlass Onboard Battony Metion Sensors & check | > | 4,241 | \$ 3,554 | 83.8 |
| | | | Control Arraignment | | | **COUNTY MANAGED** Security - Intrusion Alarm; Replace Onboard Battery, Motion Sensors & check | | | | |
| 222 | ENA 00E7040 | Los Angolos | Central Arraignment | 10 111 | 2 | programming of Alarm Panel for Clerk's office, Back staff corridor, Judges Entry Doors, Elevator Lobby, Training | ۲ | 2 205 | ¢ 2.20F | 100 |
| 323 | FM-0057049 | Los Angeles | Court | 19-U1 | | room & Elevator/Stairwell. | > | 3,305 | \$ 3,305 | 100 |
| | | | Pancha Cucamanga | | | Elevators Escalators & Hoists Donlars failing hoist machine worm shaft soals on Secure Elevator to provent | | | | |
| 224 | FM-0057050 | San Bernardino | Rancho Cucamonga Courthouse | 36-F1 | 2 | Elevators, Escalators, & Hoists - Replace failing hoist machine worm shaft seals on Secure Elevator to prevent | ۲ | 4.404 | ¢ 2.419 | 76.05 |
| 324 | FIVI-0037030 | San Bernarumo | Morgan Hill | 20-L1 | | future failure and stop leaking. Work prevents damage to the hoist machine gear box by addressing it promptly. HVAC - Replace (1 each) failed 350 amp main breaker to building chiller. Main breaker to chiller failed and is | Ş | 4,494 | \$ 3,418 | 70.03 |
| 225 | FM-0057052 | Santa Clara | Courthouse | 43-N1 | 2 | affecting the courts cooling capacity | ċ | 4,665 | \$ 4,665 | 100 |
| 323 | 1101-0037032 | Santa Ciara | North County | 43-111 | | arrecting the courts cooling capacity | 7 | 4,003 | ۷ 4,005 | 100 |
| | | | Regional Center - | | | Fire Protection - Fire Alarm Panel is showing ground fault, six Horns/Strobes have failed. Replace (6) Horns / | | | | |
| 326 | FM-0057053 | San Diego | Vista Center | 37-F2 | 2 | Strobes. Locate source of fault on panel as panel must be free of deficiencies. | Ś | 4,010 | \$ 4,010 | 100 |
| 320 | 1101 0037033 | Jan Diego | Van Nuys Courthouse | + | | Vandalism - The holding cell door's window was broken by in-custody creating a safety hazard. Replace (1) 30 | 7 | 7,010 | γ -,010 | 100 |
| 327 | FM-0057054 | Los Angeles | West | 19-AX2 | 2 | 1/4" X 49 1/2" 1" safety laminated glass in customers steel frame with security screws. | Ś | 4,403 | \$ 4,403 | 100 |
| 327 | | 2007ge.es | 11.650 | 13 / 13 / 13 | _ | Elevators - Rewire the oil heaters for the elevator #3 and #4 oil tanks to code. Wire to step-down transformer | · · | ., | γ 1,100 | |
| | | | Criminal Court | | | from the 480v disconnect so when the disconnect is turned off power to the heaters turns off as well Existing | | | | |
| 328 | FM-0057056 | Napa | Building | 28-A1 | 2 | oil heaters wiring does not conform to code | \$ | 7,092 | \$ 7,092 | 100 |
| | | ' | | | | | , | , | , | |
| | | | Pasadena | | | Electrical - Replace 25 burnt out lights/ballasts in sally port bay and lock-up ramp with LED lighting, replace light | | 4 | 4 | |
| 329 | FM-0057057 | Los Angeles | Courthouse | 19-J1 | 1 | covers that are deteriorated and can be used as a weapon by an inmate creating a safety situation. | | \$17,265 | \$11,973 | 69.35 |
| | | | | | | Plumbing - Replace (4) non-mercury float switches, (2) 4" epoxy coated resilient disc check valves, and (2) 5HP | | | | |
| | | | D 11(1 | | | 4" discharge sewage pumps with Tsurumi 5 HP cutter type sewage pumps. Existing 5 HP sewage ejector pumps | | | | |
| 220 | 5. 4. 0057050 | | Bellflower | 40 414 | _ | are damaged due to inmate generated debris in the sewage systems resulting in flooding sewage back into the | _ | 44.005 | d 22.402 | 77.04 |
| 330 | FM-0057059 | Los Angeles | Courthouse | 19-AL1 | 2 | building. | \ | 41,305 | \$ 32,193 | 77.94 |
| | | | Control luction | | | HVAC - 3rd Floor Ceiling - Remove 100 lf of broken and separated fiberglass duct work in the 3rd floor public | | | | |
| 224 | ENA 0057060 | Oranga | Central Justice | 20.41 | 2 | hallway and court reporter/interpreter services space and replace with new sheet metal ducting and insulation | ۲ | 25 500 | ć 22.240 | 04.47 |
| 331 | FM-0057060 | Orange | Center | 30-A1 | | per ACM protocols. The duct work currently is noisy and inefficiently distributing air. | > | 25,500 | \$ 23,248 | 91.17 |
| | | | North County Regional Center - | | | COLINITY MANIAGED. Dlumbing Poplace one Hot Water Holding Tank and two Expansion tanks that have failed | | | | |
| 227 | FM-0057068 | San Diego | South | 37-F1 | 2 | COUNTY MANAGED - Plumbing. Replace one Hot Water Holding Tank and two Expansion tanks that have failed due to leaks that are beyond repair | ڔ | 3,920 | \$ 2020 | 100 |
| 332 | 1 101-003/008 | Jan Diego | Journ | 3/-LT | ۷ | due to leaks that are beyond repair | ٦ | 3,320 | \$ 3,920 | 100 |
| | | | Chatsworth | | | HVAC - Remove failing i2920 controller for AHU # 4 and install new i2920 controller for AHU #4 controller. | | | | |
| 222 | FM-0057069 | Los Angeles | Courthouse | 19-AY1 | 2 | Controller is failing, this will effect cooling for the entire section of building at the North East side. | ¢ | 5,071 | \$ 4,249 | 83.8 |
| 333 | . 141 0037003 | 2007,11180100 | - Sourcifousc | 15 / 111 | | controller is raining, and will effect cooling for the charte section of building at the North East side. | | 3,071 | 7 7,273 | 33.0 |
| 334 | FM-0057070 | San Francisco | Polk St. Annex | 38-A2 | 2 | Vandalism - Graffiti - Apply blackout film over existing at street level windows (20) - Glass etched with graffiti | \$ | 3,901 | \$ 3,901 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|----------------------|---------------|----------------------------|-------------|----------|--|----------|----------------------|---|---|
| | | | | | | Plumbing - Install new copper piping between gate valves at the regulator station and 5 of the regulators. Replace 2" gate valves with ball valves in 12 locations. Install 12 gauges with quarter turn ball valves before & | | | | |
| | | | | | | after regulators. Install a new copper union on the vertical. South basement Pressure Regulating Valves at | | | | |
| 225 | FM-0057071 | San Diego | County Courthouse | 37-A1 | 2 | Manifold are leaking onto the floor and not properly reducing the city water pressure. Over pressurization creates risk of piping failures. | ć | 13,821 | \$ 10,700 | 77.42 |
| 333 | 1101-0037071 | San Diego | County Courtilouse | 37-A1 | | creates risk of piping failures. | ٦ | 13,821 | 3 10,700 | 77.42 |
| | | | | | | Elevators, Escalators, & Hoists - Faulty drive was removed and replaced on public elevator 4B. Replace | | | | |
| 336 | FM-0057072 | San Diego | County Courthouse | 37-A1 | 1 | additional failed hardware including one (1) new CPU board and one (1) new Miprom 21 Relay Pilot board. | | \$34,963 | \$27,068 | 77.42 |
| | | | | | | Interior Finished - Replace Courtroom Door and hardware - Replace door in courtroom H damaged by in | | | | |
| 337 | FM-0057073 | Mendocino | County Courthouse | 23-A1 | 2 | custody, new door to be finished to match existing and add hardware, auto flush bolt, closure. | \$ | 4,652 | \$ 4,652 | 100 |
| | | | | | | HVAC - Install (2) 3/4" Black Steel coupon racks, 60LF 3/4" copper pipe assembly, (8) 3/4" ball valves, (2) 3/4" PVC coupon racks, install 60LF 3/4" PV. Installation is required in order to monitor system acid content in the | | | | |
| 338 | FM-0057074 | Los Angeles | Compton Courthouse | 19-AG1 | 2 | HVAC water system. | Ś | 21,893 | \$ 14,478 | 66.13 |
| 330 | 666767 | 2007ge.co | | 13 / (01 | _ | Parking Lot - Remove 275 sf of curb, gutter, and side walk to replace with a commercial driveway. Apply one | <u> </u> | | Ψ 1,1,7,5 | 00.13 |
| | | | | | | coat of OverKote asphalt sealer to approximately 4600 sf of asphalt concrete. Restripe parking lot to original | | | | |
| | | | Traffic Court - | | | layout with one ADA stall and ADA signage. Install 14 concrete wheel work required in order to comply with | | | | |
| 339 | FM-0057075 | Yolo | Modular | 57-A8 | 2 | turn-back conditions of the lease. | \$ | 47,123 | \$ 47,123 | 100 |
| | | | | | | Dlumbing Poplace 20' of 4" 8, 20' of 2" failed black east iron drain nining and fittings, 25' scaffolding required | | | | |
| | | | | | | Plumbing - Replace 30' of 4" & 20' of 2" failed black cast iron drain piping and fittings. 25' scaffolding required to address work location. Remediation of 5,76SF ACM water damage. Impacted area includes 2nd Flr Cafeteria | | | | |
| 340 | FM-0057076 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | to Public Lobby, RM-100 Traffic Court Clerks, RM-101 Small Office, Basement Employee Hallway & B-8 file rm. | | \$50,650 | \$33,495 | 66.13 |
| | | | , | | | HVAC - Replace failed 40HP Supply Fan motor. AHU #12 Supply Fan has seized effecting air supply to the 12th | | . , | , | |
| 341 | FM-0057082 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | floor. | | \$10,116 | \$6,690 | 66.13 |
| | | | | | | | | | | |
| 242 | ENA 0057002 | Cara Marta a | Hall of looking | 44 44 | _ | Security - Install door closer at Courtroom 2M door to secure hallway - Original door closer was removed prior | ۸ ا | 1 000 | ć 1.000 | 100 |
| 342 | FM-0057083 | San Mateo | Hall of Justice | 41-A1 | 2 | to transfer allowing Courtroom occupants access to secure areas; identified by SO security assessment. | \$ | 1,000 | \$ 1,000 | 100 |
| | | | | | | Plumbing - Replace failed flush assembly in holding area which is concealed behind wall. Remediation required | | | | |
| 343 | FM-0057084 | Los Angeles | Norwalk Courthouse | 19-AK1 | 1 | in 3rd flr Room 309. ACM and remediation include 8'x8' section of carpet and (6) 12"x12" ceiling tiles. | | \$12,280 | \$10,442 | 85.03 |
| | | | Hayward Hall of | | | | | | | |
| 344 | FM-0057085 | Alameda | Justice | 01-D1 | 2 | Vandalism - Phones - Replace six holding cell interview phones damaged by inmates | \$ | 2,457 | \$ 2,457 | 100 |
| | | | North County | | | | | | | |
| 215 | FM-0057086 | San Diego | Regional Center - South | 37-F1 | 2 | COUNTY MANAGED - plumbing. Replace 6" water pressure reducing valve. Site is experiencing water pressure spikes due to existing valve being inoperable. | ć | 5,232 | \$ 5,232 | 100 |
| 343 | 1 141-003/000 | Jan Diego | Gordon Schaber | 3/-1 I | | spines due to existing vaive being inoperable. | ٦ | ع,دعد | ا ۵٫۷۵۷ | 100 |
| | | | Sacramento Superior | | | Vandalism - East Front entrance glass door is broken due to vandalism. Replace (1) 46 3/8 x 106 9/16 - 3/8" clear | | | | |
| 346 | FM-0057088 | Sacramento | Court | 34-A1 | 2 | tempered glass with flat polish and add tinting to glass and repair broken door handle. | \$ | 2,560 | \$ 2,560 | 100 |
| | | | | | | HVAC - Daikin Heat Pump - Remove and replace failed PCB inverter circuit board (1) and condenser fan | | | | |
| | FN 4 00== 000 | | Youth Guidance | 20.01 | | blades(2) and motors(2). Unit servers Department 3, Judges Chambers and reporters office. There is currently | | 2 22- | A | |
| 347 | FM-0057089 | San Francisco | Center | 38-C1 | 2 | no cooling in these areas and supply air temps are at 77 in the afternoons. | Ş | 8,888 | \$ 8,888 | 100 |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|--------------------------|--------------------|--|----------------|----------|--|----------|----------------------|---|---|
| | | | New San Bernardino | | | | | | | |
| 348 | FM-0057090 | San Bernardino | Courthouse | 36-R1 | 1 | HVAC - Replace 2 failed refrigerant monitoring probes. Work is code required. | | \$9,830 | \$9,830 | 100.00 |
| | | | New Hollister | | | Vandalism - Exterior shell - Replace 1 each Broken Bullet resistant glass pane in room 269 utilizing a boom lift - | | | | |
| 349 | FM-0057093 | San Benito | Courthouse | 35-C1 | 2 | Bullet resistant glass is compromised and requires replacement. | \$ | 9,854 | \$ 9,854 | 100 |
| 350 | FM-0057101 | Los Angeles | Compton Courthouse | 19-AG1 | 1 | Interior Finishes - Replace existing 30YD, 30yr old and failed Trash compactor. New system to include Hopper Open w/side modification flare, 42"x72" Safety Railing w/mounted dock, Guide island w/stops; Work is required to maintain current garbage removal process. No alternate location available for change to current process and workflow. | | \$42,465 | \$28,082 | 66.13 |
| | | | | | | | | | | |
| | | | Central Arraignment | | | COUNTY MANAGED - Fire Protection - Replace defective board on main Fire Alarm Panel, program the device | | | | |
| 351 | FM-0057102 | Los Angeles | Court | 19-U1 | 1 | points into the new panel, change power supplies & EOL resisters. Replace two failed Enunciators. | | \$14,744 | \$14,744 | 100.00 |
| | | | Rancho Cucamonga | | | Elevators, Escalators, & Hoists - Replace failed rope gripper pads on Elevator #5. Elevator is currently locked out | | | | |
| 352 | FM-0057103 | San Bernardino | Courthouse | 36-F1 | 2 | due excessively worn rope gripper pads. | \$ | 14,606 | \$ 14,606 | 100 |
| 353 | FM-0057104 | San Bernardino | San Bernardino Courthouse Gordon Schaber | 36-A1 | 2 | Security - The gate barrier arm operator for the entrance/exit to the Judges' secured parking lot has failed. Replace failed 1/2 HP gate barrier arm operator with (1) new 1/2 HP gate barrier arm operator with 12' arm and (1) loop detectors. This work is required in order to ensure that the Judges' parking lot remains secure. | \$ | 3,106 | \$ 3,106 | 100 |
| | | | Sacramento Superior | | | HVAC - Replace 2 failed HVAC control valves at Basement South. (1) 5" cold water valve, and (1) 3" hot water | | | | |
| 354 | FM-0057105 | Sacramento | Court | 34-A1 | 2 | valve. | \$ | 6,721 | \$ 6,721 | 100 |
| 355 | FM-0057106 | San Diego | Juvenile Court | 37-E1 | 2 | Interior Finishes - Replace 8 ft 6in x 7ft 6in size sheet vinyl flooring and 4 in base material in 2 restrooms. The linoleum flooring is damaged and needs to be replaced. Flooring is cracked and pieces of linoleum are coming off, creating possible trip hazards. | \$ | 3,368 | \$ 2,513 | 74.62 |
| | | | | | | Grounds - Perform corrosion control on the flag pole, replace the upper/lower pulleys, cable, and padlock. The | | | | |
| | | | Inglewood Juvenile | | _ | flag pole in the front of the courthouse is rusted and has flaking paint. The rope pulleys are rusted and the cable | | | | |
| 356 | FM-0057108 | Los Angeles | Court | 19-E1 | 2 | to raise the flag is worn down due to age. | Ş | 4,250 | \$ 3,433 | 80.78 |
| 357 | FM-0057109 | Contra Costa | George D. Carroll Courthouse | 07-F1 | 2 | Electrical - Replace one (1) failing 15 Amp breaker and install an upgraded 20 Amp breaker to replace 2nd failing 15 Amp breaker. Install 200 feet of wire and 40 feet of conduit. Existing electrical service is not sufficient and system trips when both pumps kick in. Exterior Shell – Remediate water intrusion by removing soil from adjacent planters and back fill with drain rock | \$ | 4,106 | \$ 3,079 | 74.99 |
| 250 | ENA 0057440 | Lagger | New Susanville | 10.64 | 2 | and install weather sealing on four faulty windows. Water Intrusion into the structure, presenting in the Sierra | _ ا | F 000 | c 5000 | 100 |
| | FM-0057110 FM-0057111 | Lassen Humboldt | Courthouse Humboldt County Courthouse (Eureka) | 18-C1 12-A1 | 2 | HVAC - Remove and replace motors on AHU 1 & 2 supply fan units. The motor bearings in AHU 2 are worn out and failure is imminent, causing a disruption to court. The supply fan motor on AHU 1 should also be replaced as it is the same age and it is anticipated that the unit will start to fail in the same way. | \$ | 5,000 4,556 | | 100 |
| | | | | | | 1 | 7 | .,555 | , ., | |

| # | FM NUMBER | LOCATION | FACILITY NAME | BUILDING ID | PRIORITY | SHORT TITLE | PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE | FACILITY MODIFICATION PROGRAM SHARE % OF COST |
|-----|------------|-----------|----------------------|-------------|----------|---|----------------------|---|---|
| | | | | | | Interior finishes - Install One (1) new 1/2 HP 115V Gear Head Motor Operator with three (3) button control | | | |
| | | | East County Regional | | | station, using heavy duty brackets. Run wire and conduit up to 5' electrical connection to the existing dedicated | | | |
| 360 | FM-0057112 | San Diego | Center | 37-I1 | 2 | power supply. Loading Dock Gate # 4 the motor is inoperable and needs to be replaced. | \$ 3,659 | \$ 3,659 | 100 |
| | | | | | | HVAC - Remove and replace return fan, bearings, and shaft to HVAC system. The return fan is damaged and is | | | |
| | | | Butte County | | | out of balance. If continued operation without repairs, return fan will vibrate apart and cause collateral damage | | | |
| 361 | FM-0057113 | Butte | Courthouse | 04-A1 | 2 | to interior of HVAC system. | \$ 5,337 | \$ 5,337 | 100 |
| | | | | | | Plumbing - Replace 3" & 1" corroded high pressure Gate Valves and Fittings that serve the domestic cold water | | | |
| | | | | | | in the South Tower. The deteriorated valves are leaking water and currently at risk of failing while under high | | | |
| 362 | FM-0057114 | San Diego | County Courthouse | 37-A1 | 2 | pressure. Repairs are needed to avoid potential risk of flooding. | \$ 3,178 | \$ 2,460 | 77.42 |
| | | | | | | | \$ 21,492,723 | \$ 18,123,570 | |

| ITEM # | CFR NUMBER | COUNTY | BUILDING ID | FACILITY NAME | LEASE, LICENSE, OR FM | CFR DESCRIPTION | CFR TERM | FUND SOURCE | ESTIMATED CURRENT YEAR COSTS | (Includes existing costs prior to CFR term) | ESTIMATED BUDGET YEAR COSTS | | TOTAL ESTIMATED CFR COMMITMENT (CFR Term) | REVIEW NOTES - OREFM, JBCPO, & FSO |
|--------|------------|-------------|--------------|------------------|--------------------------|---|------------|-------------|------------------------------|---|-----------------------------|----------------|---|------------------------------------|
| | | | | | | Minor renovations to convert first floor courtroom into Self-Help Center and | | | | | | | | |
| | | | | Hayward Hall of | Eacility | secure non-public space from the new public space. Currently, the Self-Help | | | | | | | | No |
| 1 | 01-CFR007 | Alameda | 01-D1 | , | Facility Modification | space is located in the lobby of this building impacting court flow and function, and making privacy for Self-Help users difficult. | One-Tim | ATCTE | خ | 20,000 | \$ - | Ś | 20 000 | Concerns |
| | OI CINOU | Alameda | 01 01 | Justice | Ivioameation | Modify one trial courtroom to handle Dependency cases, which requires more | One min | | 7 | 20,000 | 7 | 7 | 20,000 | Concerns |
| | | | | Fresno County | Facility | space for court participants in the well, the removal of the jury box, and | | | | | | | | No |
| 2 | 10-CFR013 | Fresno | | Courthouse | Modification | 1 ' ' ' ' | One-Tim | e TCTF | \$ | 22,686 | \$ - | \$ | 22,686 | Concerns |
| | | | | | | Transfer of County Law Library to Court with tenant improvements for use as a | | | | · | | | · | |
| | | | | | | courtroom to hold cases requiring security. This will require an amendment to the | | | | | | | | |
| | | | | Humboldt County | Facility | JOA to begin January 1, 2016 as well as an additional fee for the Court's facilities | | | | | | | | |
| 3 | 12-CFR001 | Humboldt | 12-A1 | Courthouse | Modification | service provider to maintain the space. | One Yea | r TCTF | \$ | 4,709 | \$ - | \$ | 24,460 | Pending |
| | | | | | | FM for interior improvements to the existing snack bar to meet and be in | | | | | | | | |
| | | | | | | compliance with Dept. of Public Health Inspection Report requirements. Until | | | | | | | | |
| | | | | | | facilities are in compliance the vendor is not allowed to be in full operation, | | | | | | | | |
| | | | 40.54 | Inglewood | Facility | thereby creating an urgent need to be able to provide food/beverage services to | | | | 47.007 | 4 4 - 0 | | 4- 00- | |
| 4 | 19-CFR032 | Los Angeles | 19-F1 | Courthouse | Modification | | One Tim | e TCTF | Ş | 17,827 | \$ 17,8 | 27 Ş | 17,827 | Pending |
| | | | | | | FM to install exterior power outlets (and related electrical work/dedicated circuit) to accommodate the installation of Automated Bill Payment kiosks. The kiosks | | | | | | | | |
| | | | | | | will reduce congestion as well as provide easier access by allowing traffic citations | | | | | | | | |
| | | | 19-T1 & | Metropolitan & | Facility | and criminal payments to be paid outside of the courthouses. These will also | | | | | | | | |
| 5 | 19-CFR033 | Los Angeles | | - | Modification | | One Tim | e TCTF | Ś | 60,000 | \$ 60,0 | 00 \$ | 60.000 | Pending |
| | | | | | | FM for interior improvements to the existing cafeteria to meet and be in | | | 1 | | 7 55,5 | - · | | |
| | | | | | | compliance with Dept. of Public Health Inspection Report requirements. Until | | | | | | | | |
| | | | | | | facilities are in compliance the vendor is not allowed to be in full operation, | | | | | | | | |
| | | | | Torrance | Facility | thereby creating an urgent need to be able to provide food/beverage services to | | | | | | | | |
| 6 | 19-CFR034 | Los Angeles | 19-C1 | Courthouse | Modification | | One Tim | e TCTF | \$ | 25,000 | \$ 25,0 | 00 \$ | 25,000 | Pending |
| | | | | | | Comprehensive retrocommissioning assessment on the HVAC system. This FM is | | | | | | | | |
| | | | | Central Justice | Facility | an effort to identify and address issues prior to them becoming P1 events that | | | 1 | | | | | |
| 7 | 30-CFR023 | Orange | 30-A1 | Center | Modification | · | | e Non-TCTF | \$ | 80,694 | \$ - | \$ | 80,694 | Pending |
| | | | | | | Phase 1: Design - Modifications to the building's main entry to accommodate new | | | | | | | | |
| | | Con | | Joshua Trass | Facility | turnstile security equipment and refresh the appearance of the lobby. | | | | | | | | No. |
| | | San | 36-E1 | Joshua Tree | Facility Modification | The detailed execution scope of work will be developed by the JCC and approved by the court upon completion of final design | | e Non-TCTF | خ | 10 200 | ر خ | خ | 10 200 | No |
| 0 | 30-CI NU32 | Bernardino | JU-LI | Courthouse | ivioanication | by the court upon completion of final design. Renew parking lease for 175 overflow parking spaces (March 1, 2016 through | 0116-11111 | I INUITICIF | ۲ | 19,300 | - | } | 13,300 | Concerns |
| | | | | | | February 28, 2019). There is a current shortfall of parking at the courthouse and | | | | | | | | |
| | | | | East County | | the lease renewal with MDA El Cajon One, LLC would allow court users and jurors | | | | | | | | |
| | | | | Regional Center | Lease | to park at the adjacent shopping center, thereby reducing delays in court | Three | | | | | | | |
| l a ' | 37-CFR021 | San Diego | 37-16 | Overflow Parking | | | Years | TCTF | \$ | 84.982 | \$ 87,9 | 62 \$ | 270.092 | Pending |

| ITEM # | CFR NUMBER | COUNTY | BUILDING ID | FACILITY NAME | LEASE, LICENSE, OR FM | CFR DESCRIPTION | CFR TERM | FUND SOURCE | TED CURRENT YEAR CO | (includes existing costs prior to CFR term) | ESTIMATED BUDGET YEAR COSTS | TOTAL ESTIMATED CFR | COMMITMENT (CFR Term) | REVIEW NOTES - OREFM, JBCPO, & FSO |
|--------|------------|-------------|-------------|--------------------|-----------------------|---|----------|-------------|---------------------|--|-----------------------------|---------------------|--------------------------|------------------------------------|
| | | | | Civic Center | | Convert the current rule 10.810 MOU into a rule 10.810/Small Project MOU and | | | | | | | | |
| | | San | 38-A1 & | Courthouse & Hall | | designate an annual budget of \$120,000 for small projects for the Civic Center | | | | | | | | No |
| 10 | 38-CFR005 | Francisco | 38-B1 | of Justice | Annual Budget | Courthouse and Hall of Justice. | Ongoing | TCTF | \$ | - | \$ - | \$ | 120,000 | Concerns |
| | | | | 64 N. Market | | | | | | | | | | |
| | | | | Street (LAZ | Lease | Two-year lease extension to provide parking privileges for Superior Court | Two | | | | | | | |
| 11 | 43-CFR008 | Santa Clara | 43-B6 | Parking) | Extension | employees and jurors (approx. 1,300 SF of spaces). (1/1/16 - 12/31/17) | Years | TCTF | \$ | 50,884 | \$ 50,884 | \$ | 101,768 | Pending |
| | | | | Visalia Convention | | Two-year lease for rental of a conference room at the Visalia Convention Center | Two | | | | | | | |
| 12 | 54-CFR011 | Tulare | 54-J1 | Center | New Lease | to hold Small Claims Court on Mondays. (1/4/16 - 12/18/17) | Years | TCTF | \$ | 4,526 | \$ 4,526 | \$ | 18,105 | Pending |