

JUDICIAL COUNCIL OF CALIFORNIA

455 Golden Gate Avenue · San Francisco, California 94102-3688 www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on: March 24, 2017

Title

Court Facilities: Trial Court Facility Modification Quarterly Activity Report for Quarter 2 of Fiscal Year 2016–2017

Submitted by

Trial Court Facility Modification Advisory Committee Hon. Donald Cole Byrd, Chair Agenda Item Type

Information Only

Date of Report March 3, 2017

Contact

Jagan Singh, 415-865-7755 jagandeep.singh@jud.ca.gov

Executive Summary

The Trial Court Facility Modification Advisory Committee (TCFMAC) has completed its facility modification funding for the second quarter of fiscal year 2016–2017. In compliance with the *Trial Court Facility Modifications Policy*, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 2, Fiscal Year 2016–2017* as information for the council. This report summarizes the activities of the TCFMAC from October 1, 2016, to December 31, 2016.

Previous Council Action

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*, adopted by the Judicial Council in 2005, the latest revision of which was on December 12, 2014. The working group's primary oversight responsibilities included reviewing statewide facility modification (FM) requests and approving FM funding.

On April 25, 2013, the working group's status was elevated to that of advisory committee. The committee operates in accordance with rule 10.65 of the California Rules of Court, which was

¹ As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See www.courts.ca.gov/documents/jc-20120727-itemG.pdf.

approved on January 1, 2015. The committee was assigned additional oversight responsibility for the operations and maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability.

On August 26, 2016, the Judicial Council approved an update to the Court-Funded Facilities Request (CFR) process, permitting approval authority delegation from the TCFMAC to the director of Real Estate and Facilities Management (REFM). CFR submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at www.courts.ca.gov/2567.htm under Research and Reports: Conditions in Our Courts.

Methodology and Process

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, but Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, but Serviceable; and Priority 6–Hazardous Materials, Managed but Not Abated. These categories are based on methods commonly used by private-sector facility management firms.

Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC predominantly approves FM projects at the Priority 1 and Priority 2 levels. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

Policy and Cost Implications

During the second quarter of fiscal year (FY) 2016–2017, the TCFMAC reviewed and approved a total of 372 facility modifications for a total projected cost of \$12,283,200. The FM budget is responsible for \$11,168,851, with the respective counties throughout the state being responsible for the remainder. These approved projects were primarily Priority 1 (P1) emergency projects (90 total) and Priority 2 (P2) urgent projects (277 total). There were, however, five Priority 3 (P3) energy efficiency projects also approved. Elevator, HVAC, and plumbing repairs or replacements comprised the bulk of emergency P1 and urgent P2 projects this quarter. See

Attachment A for a detailed list of all approved projects during the second quarter of FY 2016–2017.

During this quarter, seven (7) projects required additional funds in excess of \$50,000 from their original estimates. The FM budget responsibility of these cost increases totaled \$1,384,323. Projects that required excess costs of this magnitude were largely projects for which project managers encountered unforeseen site or equipment conditions.

Also during this quarter, seven CFRs were approved by the REFM director and reviewed by the TCFMAC: lease extensions for the Superior Courts of Merced, San Luis Obispo, and Stanislaus Counties; annual budgets for small projects for the Superior Courts of Los Angeles and Merced Counties; and Facility Modification projects for the Superior Courts of Sacramento and San Bernardino Counties. Attachment B provides a detailed list of CFRs approved by the REFM director during the second quarter of FY 2016–2017.

Implementation Efforts

The committee conducted an in-person meeting in San Bernardino at the San Bernardino Justice Center on October 14, 2016, and a telephonic meeting on December 5, 2016, to review FM funding requests and to discuss the topics below. The committee thanks the Superior Court of San Bernardino County, especially Presiding Judge Raymond L. Haight and interim Court Executive Officer Nancy Eberhardt, for the opportunity to visit three courthouses as well as for the use of facilities for the meeting.

- The committee conducted its regular review of facility modification projects lists: A (Emergency and Priority 1); B (FMs Under \$100K); C (Cost Increases Over \$50K); D (FMs Over \$100K Eligible for Funding); E (Court-Funded Facilities Requests); and F (Funded FMs on Hold).
- The committee toured the public and nonpublic areas of the Rancho Cucamonga Courthouse, San Bernardino Justice Center, and the San Bernardino Historic Courthouse.
- The committee prepared and submitted its FY 2015–2016 annual report to the Judicial Council. The report provides an overview and details on the committee's activities and budget expenditures over the course of the year.
- The committee reviewed and approved the *Trial Court Facility Modification Quarterly Activity Report: Quarter 1 of Fiscal Year 2016–2017.*
- The committee approved revisions to the Court-Funded Facilities Request form to align with the updated policy approved by the Judicial Council in August 2016. The form was circulated among court leadership for comment.

Completed courthouse project spotlights

The examples below are of facility modification projects that have been completed during this quarter. These examples illustrate the varied problems that California courthouses regularly face, from emergency repairs and mitigation to projects identified during preventive maintenance rounds and readings. It is the committee's goal, with Judicial Council facility management staff, to improve court facilities to assure equal access to justice throughout the state.

Priority 2 Project—Replace Failing Emergency Generator, Metropolitan Courthouse, Los Angeles County—FM-0054821

The existing emergency generator was 43 years old, consistently failing, and out of compliance with local air quality regulations (South Coast Air Quality Management District, SCAQMD). The replacement also included installation of two automatic transfer switches, a 50-gallon day tank, and replacement of the existing inline fuel pump motor. A crane was used to remove the old unit and place the new unit, which required a city permit to close the street to traffic for six hours on a Saturday morning in downtown Los Angeles, where the courthouse is located. The unit was replaced and operational in five days.

The final project cost was \$535,000.





Before: Removal of the old generator. The unit weighed over 21,000 lbs., approximately twice as much as the new generator (*above left*).

After: The new generator being delivered. It provides the same power distribution as the old unit, but is lighter, more economical, and SCAQMD compliant (*above right*).

Priority 2 Project—Air Handling Unit Improvements, Pomona South Courthouse, Los Angeles County—FM-0056883

Due to age and corrosion, the cold and hot water coils for the 3rd, 6th, and 7th floor air handler units were leaking and needed to be replaced. Leaking coils have caused deterioration of condensation pans and floor drains (both were replaced). The work included environmental testing, abatement, and reapplication of fire-proofing.

Below: Old, leaking unit.

Right: New coils ready to be installed.





The final project cost was \$380,897.

Next Steps

The *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2016–2017* will be submitted to the Judicial Council in May 2017.

Attachments

- 1. Attachment A: TCFMAC-Funded Project List: Quarter 2, Fiscal Year 2016–2017
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 2, Fiscal Year 2016–2017

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			West Covina			County Managed - Roof - Due to consistent leaks, LAISD is recommending to remove and replace 87,00 square feet of roofing material consisting of rock roof material, and 2 layers of 1" insulation. Further details of LAISD scope of					
_ 1	FM-0020990	Los Angeles	Courthouse	19-X1	2	work attached in notes and docs. Security - Remove and replace 8 cell doors to include handcuff portals to improve security and mitigate risk to	\$	2,065,289	\$ 2,0	55,289	100
2	FM-0050594	Santa Barbara	Figueroa Division	42-B1	2	Sherriff Dept. employees - Security Risk/High	\$	123,204	\$ 1	23,204	100
3	FM-0052830	Ventura	Hall of Justice	56-A1	2	COUNTY MANAGED - Electrical - 4160 Volt Breaker Upgrade. Replace 36yr old breakers to improve reliability of esystem.	\$	88,250	\$	88,250	100
						Interior Finishes - 28% of Dept. L, 31% of Dept. R, and 35% of Dept. P have damaged public seating, un-repairable & a safety hazard to public attempting to use. Replacement parts are no longer available. Demo 211 existing damaged chairs and replace with a similar style to existing. Floor mastic is known to have ACM. All work will be done in an					
4	FM-0058194	Los Angeles	Pasadena Courthouse	19-J1	2	ACM environment.	\$	142,670	\$ 14	12,670	100
5	FM-0058195	Los Angeles	West Covina Courthouse	19-X1	2	Interior Finishes - 33% of Dept.1, 36% of Dept.4, and 28% of Dept. 10 have damaged public seating, un-repairable & a safety hazard to public attempting to use. Replace 254 audience, 42 jury, and 3 witness seats with a similar style to existing. Floor mastic is known to have ACM. All work will be done in an ACM environment.	\$	150,600	\$ 1	50,600	100
6	FM-0058697	Santa Cruz	Main Courthouse	44-A1	2	HVAC - Replace failing court exclusive Air Handling Unit with Variable Air Volume system and integrate into existing building hot water register. Add BAS controls and replace corroded water control valves. Existing unit is not sufficient to support current occupancy requirements and is not currently controlled by the BAS system.	\$	121,500	\$ 1:	21,500	100
7	FM-0058711	Fresno	Fresno County Courthouse	10-A1	2	Fire Protection - Safety - Correct unsafe emergency exit conditions at the East exit door to the "moat" on the B-1 level. Install magnetic lock, exit card reader, and intercom door station and integrate into the fire alarm system. This will correct current safety and security deficiencies whereby the public exits through the door without alarm or detection, directly into the path of inmate transport in the moat area, and whereby the public can let accomplices into the building without detection. Submittal drawings and Fresno Fire permit included.	Ś	13,592	Ś	.3,036	95.91
			Siskiyou County			COUNTY MANAGED - Roof - Refurbish existing roof. Work to include sealing 11,700 square feet with Bio-guard membrane and application of Acrylic coating over high density spray-on foam. Roof is leaking throughout the		·		·	
8	FM-0058881	Siskiyou	Courthouse	47-A1	2	winter.	\$	48,920	\$	6,452	33.63
9	FM-0058906	Orange	Central Justice Center	30-A1	2	Electrical - Replace two existing 4.99 kW Generator engine block electric heaters with heat pump to support the necessary NFPA required maximum start time and even heat distribution.	\$	22,000	\$	20,057	91.17
		El Dorado	Juvenile Hall	09-G1	2	Interior Finishes - Set up containments, Remediate affected ceiling in the men's restroom where growth was found. Clean and treat the affected area/s. Replace the ceiling sheet rock tape and paint areas that were replaced Water heater failed in the facility above and leaked into the men's restroom and causing water damage and mold growth. This area is going to be remediated and restored to normal function.	\$	13,639		13,639	100
11	FM-0058943	Los Angeles	Chatsworth Courthouse	19-AY1	2	Exterior Finishes - Install 1,050 sq. feet of window tinting to the main lobby front entrance windows to block out sun light and provide safety to the windows that overlook the weapons screening for security issues.	\$	10,982	\$	9,203	83.80

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Lakeport Court			HVAC - Replace failed chiller coil- Replace chiller coil 1 failed - 42" tall x 96" long 6" thick, replace 1 chiller coil same				
12	FM-0059105	Lake	Facility	17-A3	2	size due to imminent failure, install 2 coil dryers with isolation valves, including crane lift and refrigerant.	\$	34,292	\$ 34,	292 100
13	FM-0059155	San Mateo	Hall of Justice	41-A1	2	County Managed - Roof - Remove 3,600 sq. ft. of failed roofing; permanently remove 160 ft. of existing 18' high chain-link fence enclosure (requires jack-hammer); install two layers of new roofing to insulate and provide adequate run-off; project requires crane. Failed roofing at non used, roof top exercise yard causing leaks at 3rd and 4th floors.	\$	182,538	\$ 182,	538 100
			Metropolitan			HVAC - Replace the non-functioning VFD, (1) Supply Air 15HP US-Motor & (1) Return Air 5HP US-Motor to allow the				
14	FM-0059164	Los Angeles	Courthouse	19-T1	2	air flow to be regulated throughout the 1st floor.	\$	10,783	\$ 10,	194 94.54
15	FM-0059222	Los Angeles	Pasadena Courthouse	19-J1	2	Exterior Shell - Remove old expansion joints and apply new sealer for the joints. The exterior expansion joints on the side of the building have deteriorated due to old age exposing gaps to the interior of the building. As a result water can intrude to the Interior during rainstorms resulting in cleanup and drying equipment rentals which could be prevented.	\$	25,738	\$ 17,	349 69.35
						Elevators, Escalators, & Hoists - Generator has failed and is non-operative on elevator #5. Rebuild generator, strip				
			San Fernando			and rewind armatures, dip and bake, replace Babbitt bearings, replace brushes, clean brush holders and riggings,				
16	FM-0059230	Los Angeles	Courthouse	19-AC1	2	steam clean, dip and bake exciter assembly.	\$	31,916	\$ 26,	83.41
					_	Fire Protection - Replace failed fire panel charging system card Receiving trouble alarm from panel, failure to				
17	FM-0059241	Contra Costa	Bray Courts	07-A3	2	replace failing card will prevent the backup batteries from charging.	\$	3,488	\$ 2,	983 85.52
10	FM-0059242	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	1	Security - Electrical - Install automatic doors openers on Main entrance (2) and employee entrance (1). The static pressure in the building would not allow the doors to close, causing a safety concern after business hours. The building is currently undergoing a HVAC building project. That will address the static pressure, and other HVAC issues in the building.	ć	67,000	\$ 46,	393 69.99
10	1101-0033242	LO3 Angeles	Ciliaren 3 Court	13-Q1	1	Interior Finishes - Replace cracked window (133"x 52") on the 4th floor public area. Boom lift will be necessary to	٦	07,000	7 40,	353 05.55
19	FM-0059243	Los Angeles	Torrance Courthouse	19-C1	2	replace the window. Safety concern at this time.	\$	3,533	\$ 3,	008 85.14
						Plumbing- Replace defective chilled water pump motor that is over heating due to the bearing failing. Water pump				
20	FM-0059244	Los Angeles	Pasadena Courthouse	19-J1	2	is currently not working.	\$	5,200	\$ 3,	606 69.35
21	FM-0059245	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Replace (1) 2" Cast Iron P-trap, (2) 2" No-Hub Couplings & (4) 1'x1' acoustic ceiling tiles. Remediation due to category 3, black water contamination. 7th Floor Women's Public Restroom floor drain leaked down to the 6th Floor Clerk's Office Room 604A.	\$	24,275	\$ 16,	053 66.13
22	FM-0059246	Los Angeles	East Los Angeles Courthouse	19-V1	1	Plumbing - Replace failed Hot Water Valve. Water leaked from an AC vent from a 3/4" hot water pipe above the ceiling, wetting a 3'x3' section of VCT flooring. Work conducted in known ACM environment.	Ġ	24,835	\$ 19,	302 77.72
	FM-0059247	Los Angeles	Downey Courthouse	19-V1 19-AM1	2	Grounds and Parking Lot- Remove and replace thirty-six (36) light fixtures in the parking lot with LED light fixtures. The existing lights are burned out, creating a safety issue. The LED lights will create a savings in power consumption and will last longer than current lighting. Currently a safety issue. 50% of the lights are currently not working.	\$	28,568		
24	FM-0059248	Sacramento	Gordon Schaber Sacramento Superior Court	34-A1	2	Security - Repair damaged door and track at the south sally port roll up door. The door jumped the track and is damaged - Door is a high security issue.	\$	3,618	\$ 3,	518 100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Elevators, Escalators, & Hoists - Install emergency lights in the Judges' Elevator #5 and Custody Elevator #4 per DIR requirements and preliminary work orders SWO#2490083 and SWO#2490084. Includes; provide and install				
						emergency light and bell units, mount and wire to the existing alarm system and test operation and return to				
25	FM-0059249	Los Angeles	Torrance Courthouse	19-C1	2	normal service. These Preliminaries are due on 8/15/2016.	\$	12,276	\$ 10,452	85.14
		J	San Fernando					· · · · · · · · · · · · · · · · · · ·	,	
26	FM-0059250	Los Angeles	Courthouse	19-AC1	2	Fire Protection - Replace (10) faulty smoke detectors for the Halon fire alarm panel.	\$	2,861	\$ 2,386	83.41
						Plumbing - Replace countertops with new Corian tops with a 6" back splash; replace (4) new angle stops and (2)				
						commercial p-traps in each restroom. Women's and men's employee restrooms have damaged Formica counter				
27	FM-0059251	San Diego	Juvenile Court	37-E1	2	tops and deteriorating p-traps and angle stops.	\$	9,915	\$ 9,915	100
						Interior Finishes - Replacing 270 sq. yards of old carpet with new in lobby, copy room, finance office, hallway &				
28	FM-0059253	Colusa	Courthouse Annex	06-A2	2	main office area Old carpet is coming up and causing it to be a tripping hazard.	\$	24,812	\$ 24,812	100
						Security - Correct failed 1200lb main entrance doors (2) - Remove LH door; re-secure dropped lock set, replace				
			Civic Center			pivot, replace failed opener motor: Remove RH door, reattach cladding, relocate bottom pivot: Requires lift to				
29	FM-0059254	San Francisco	Courthouse	38-A1	2	remove/install doors - Front doors not operating, locked w/cable lock.	\$	23,339	\$ 23,339	100
						Plumbing - Public drinking fountains have failed - Remove and replace 6 each failed fountains (2 on 1st floor and 4				
			Fremont Hall of		_	on 2nd floor) - Replace with like fixtures of SS construction - Replace failed piping in wall at all locations - Court	_		4 40 0=0	
30	FM-0059255	Alameda	Justice	01-H1	2	impact, no public drinking fountains.	\$	54,625	\$ 43,372	79.4
31	FM-0059256		Old Solano Courthouse	48-A3	2	Grounds and Parking Lot - Replace 75' of 6" storm drain piping found failed during previous excavation. Saw cut 75'L x 2'W asphalt and excavate to 2'D. Remove all excavated soil and failed pipe from site. Install base gravel and compact. Install 75' new 6" drain pipe and route to existing drain boxes. Backfill trench and compact. Re-pave and restripe parking stalls. Existing storm pipe is crushed, causing flooding in the parking lot during rains.	\$	26,854	\$ 26,854	100
							†	,	-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
32	FM-0059257		Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	HVAC - Replace deteriorated shaft seal and solid state coolant pump. Chiller leaking excessive amount of oil due wear and tear of the equipment.	\$	42,130	\$ 30,970	73.51
1						Electrical - Generator and fire pump batteries and battery cables are beyond their life expectancy and require				
						replacement. Secondary containment boxes are needed around the generator and fire pump batteries per code.				
						Install new battery cables for both the generator and fire pump. Install new GRP8HD batteries (2 each) for both the				
1			East County Regional		_	generator and fire pump. Install new battery boxes for secondary containment for the generator and the fire pump	l			
33	FM-0059258	San Diego	Center	37-l1	2	batteries.	\$	5,700	\$ 3,859	67.71
						Interior Finishes - Remove and reupholster with a 60k abrasion fabric on (16) sixteen affixed Jury seating and thirty-				
			S 11 S 1			one (31) ganged Spectator seats inside Dept. #16. Currently, the 30+ year fabric and padding on seat pans, backs,				
	ENA 0050350		South County	27.116	_	sides and chair arms are torn, ripped and worn beyond repair. This courtroom is high volume as it serves as the	,	0.000	¢ 0.000	400
34	FM-0059259	San Diego	Regional Center	37-H1	2	supervising presiding judge courtroom.	>	9,663	\$ 9,663	100

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Plumbing - Isolate domestic water supply to 2nd floor; Drain and cut out copper to failed faucets; Install (12) new isolation valves and re-pipe to new faucets; Install (8) new faucets and (16) new pushbuttons; Install proper pipe supports and reinsulate; Replace all failed internal components, seals and gaskets to (8) holding cell toilet				
			Law And Justice			flushometers. Flush air and debris Valves and faucets have failed requiring water to be shut off from the holding				
35	FM-0059260	Solano	Center	48-A2	2	cells.	\$	46,189	\$ 46,189	100
						COUNTY MANAGED - Plumbing- Replace water main service zone and associated valves due to leaks, wear and age		•	·	
		San	Rancho Cucamonga			of the water lines. Work to include replacement of pressure regulators, gate valves, pressure gauges and copper				
36	FM-0059261	Bernardino	Courthouse	36-F1	2	piping.	\$	24,859	\$ 18,905	76.05
			New Hollister			Exterior Shell - Canopy Glass - Replace (1) shattered custom glass panel glass (60"x60") in overhead canopy. Safety				
37	FM-0059262	San Benito	Courthouse	35-C1	2	Hazard.	\$	26,049	\$ 26,049	100
			N			Plumbing - Replace a defective 2 inch 3/4 sump pump, containment, and remediation. Sewer water was seeping	_			27.00
38	FM-0059264	Los Angeles	Norwalk Courthouse	19-AK1	1	from the main waste line ground cover onto the floor in the employee break room.	\$	23,457	\$ 19,945	85.03
						Exterior Shell - Approximate 12 ft. window on 6th floor of north face of building is cracked, offset, and splitting. If the crack continues to expand, the glass has the potential of falling in pieces and injuring pedestrians below. High				
20	FM-0059265	Los Angeles	Pasadena Courthouse	10 11	1	reach equipment required to perform work.	ċ	9,414	\$ 6,529	69.35
33	FIVI-0039203	LOS Aligeles	rasaueria Courtilouse	13-11		HVAC - Replace evaporator coil and install a new filter drier and expansion valve. PKU 2 evaporator coil is	ې	3,414	\$ 0,329	09.33
			Delano/North Kern			inoperable, several leaks were found in evaporator coil. PKU 2 is no longer providing cooling to secured Clerk's				
40	FM-0059266	Kern	Court	15-D1	2	area.	Ś	9,234	\$ 7,446	80.64
	0033200			15 51	_		Υ	3,23 .	7,1.0	00.01
						Fire Protection - Replace failed fuel injection pump, failed water pump and all associated hoses for the fire pump				
						diesel engine. The fuel and water pumps are leaking and continue to get worse when we run the engine on the				
			Betty Lou Lamoreaux			required weekly fire pump run. The replacement of the pumps is necessary to avoid damaging the equipment, for				
41	FM-0059267	Orange	Justice Center	30-B1	2	the equipment to run properly without failure and compromise the facility.	\$	8,433	\$ 6,742	79.95
			South County Justice			Plumbing - Replace leaking section of pipe and perform mold abatement as there is visible mold in the walls and ceiling in the plenum area. Remove and replace approximately 25 sq. ft. of affected drywall and paint as needed. Mold testing and clearance provided by FACS. A leak in the 2 1/2" copper main water line above the staff restroom				100
42	FM-0059268	Tulare	Center	54-I1	1	on first floor south has caused flooding in the restroom and into adjacent hallway.	\$	6,500	\$ 6,500	100
						Electrical - Replace 1 ballast and 2 fluorescent lights, set up 4ft X 4ft x 12ft containment and environmental testing.				
43	ENA 0050360	San Dicas	County Counth assa	27.44	_	Dept. 9 overhead fluorescent light ballast burnt out and produced a low voltage electric arc. Dept. 9 was without	ے ا	C 272	6 6 272	100
43	FM-0059269	San Diego	County Courthouse San Fernando	37-A1	1	lighting and courtroom was relocated.	>	6,272	\$ 6,272	100
11	FM-0059270	Los Angeles	Courthouse	19-AC1	2	Electrical - Replace (20) egress lights and (100) exit signs that failed the Level IV PM.	Ġ	9,214	\$ 7,685	83.41
44	1 191-0039270	San	San Bernardino	13-ACI		Elevators, Escalators, & Hoists - Replace failed rope gripper on Public Elevator #1. Elevator is currently off line and	٧	5,414	ر ر ر	05.41
45	FM-0059272	Bernardino	Courthouse	36-A1	2	cannot be returned to service until the rope gripper has been replaced.	Ś	16,821	\$ 16,088	95.64
		San Bernardino	San Bernardino Justice Center	36-R1	2	Vandalism - A court customer (public) broke the Clerk's transaction window. Window needs to be replaced so members of the public cannot reach through the talk through cut-outs, potentially endangering Court staff. Install new window pane approximately 77" X 80" to match existing pane with appropriate speak through cut-outs.		12,288		
40	FIVI-0039273	DELLIGITUITO	Justice Ceriter	7U-05		The will down balle approximately // A our to match existing pane with appropriate speak through cut-outs.	Įγ	12,288	12,288	100

*	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACIUTY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
47	FM-0059274	Los Angeles	Norwalk Courthouse	19-AK1	2	Plumbing - Remove leaking toilet that is not working properly and replace with a new toilet that will be retrofitted to the original space. Work will be completed in an environmental area.	\$	14,921	\$ 12,687	
		Orange	Betty Lou Lamoreaux Justice Center	30-B1		Plumbing - Replace 3/4" hot water pipe that is leaking above the ceiling in C523 and install a shut off valve. The replacement of the hot water pipe requires full building drain down and re-charge.	\$	3,340	\$ 2,670	
			Edmund D. Edelman			Plumbing - Replace 8 feet of 2inch defective Cast Iron Pipe. Containment and remediation. Water was leaking from				
49	FM-0059276	Los Angeles	Children's Court	19-Q1	1	the metal mesh ceiling of the 1st floor lock-up.	\$	22,565	\$ 15,793	69.99
50	FM-0059277	Los Angeles	Pasadena Courthouse	10 11	1	Elevators, Escalators and Hoists - Replace non-functioning governor, governor cable, and governor tail sheave. Elevator #1 is not operational.	Ś	53,975	\$ 37,432	69.35
30	FIVI-0039277	LOS Aligeles	rasaueria Courtilouse	13-11		Elevators, Escalators, & Hoists - Lighting -Replace failed lighting controller, ceiling mount, and power supply. 75% of	٦	33,373	3 37,432	. 09.33
51	FM-0059278	Riverside	Larson Justice Center	33-C1	2	the lighting have failed and is a safety hazard to employees, jurors, and public	\$	11,730	\$ 9,479	80.81
						HVAC - Remove and replace failing 7.5 VFD for the 9th floor HVAC system. This VFD produces a smoky smell and	T	,:	7 5,	
						shows signs of heat damage on the inside components. Immediate need for replacement is needed due to this				
52	FM-0059280	Orange	Central Justice Center	30-A1	2	type of VFD blowing up in the past.	\$	5,789	\$ 5,278	91.17
			West Covina			COUNTY MANAGED - Interior Finishes - Replace two (2) defective panic bars. The doors currently can't lock, causing				
53	FM-0059282	Los Angeles	Courthouse	19-X1	2	a safety concern.	\$	4,000	\$ 4,000	100
54	FM-0059283	San Diego	Hall of Justice	37-A2	1	COUNTY MANAGED - Plumbing - Priority 1 Water damage caused by an overflow commode on 5th floor Jury Deliberation Room flooded 5th, 4th and 3rd floors of Chambers Corridors, Jury Delib. Rm, Staff Restroom and section of D69 Courtroom. County of San Diego responded, extracted water, removed vinyl flooring in restrooms, and 136 LF (101 LF 5th, 23 LF 4th, 12 LF 3rd floor) of affected drywall and cove base, wire brushed metal studs, applied antimicrobial, cleaned carpets . Performed moisture testing and environmental report.	\$	18,644	\$ 18,644	100
55	FM-0059285	Los Angeles	Glendale Courthouse	19-H1	1	Plumbing - Replace two (2) 1-inch angle stops on both unisex staff restrooms and cracked toilet carrier due to water leaking between the wall affecting 2nd floor annex (2) unisex staff restrooms in the secured hallway, and 2nd floor annex Dept. F which has a 10x5 carpet area affected. A 4-foot square area has been cut in the unisex staff restroom where leak originated for plumber to access and make repairs.	\$	34,915	\$ 31,612	90.54
						Plumbing - Replace 20' cast iron pipe & install (2) ball valves. 2" domestic water line leaked affecting 5th flr public				
56	FM-0059286	Los Angeles	Compton Courthouse	19-AG1	1	RR & 4th Dept. 3 Judge's Chamber. Work performed in ACM known environment.	\$	28,735	\$ 19,002	66.13
57	FM-0059287	Los Angeles	Pasadena Courthouse North County Regional Center -	19-J1	2	Plumbing - Replace 10 feet 2 inch & 10 feet 1-1/4 inch copper piping, (1) 1-1/4 inch ball valve, (1) 1-1/4 inch coupling, (2) 2 x 1-1/4 copper tee, (1) 1-1/2 inch Cap. Domestic Water line is leaking from ceiling above the Chilled Water Pump and in mid floor area above the Domestic Water Pump and Boilers. Plumbing - Rebuild push button and air bladder assemblies. Replace failed hot and cold water, air actuated valves. Holding cell combination drinking fountain/faucet failed both hot and cold water inoperable. In-custody cannot get	\$	4,593	\$ 3,185	69.35
58	FM-0059288	San Diego	South	37-F1	2	water to drink or wash their hands.	\$	2,534	\$ 1,704	67.24
			Fremont Hall of							
59	FM-0059289	Alameda	Justice	01-H1	2	Elevators, Escalators, and Hoists - Replace failed door control circuit board on this non-functioning public elevator.	\$	4,082	\$ 3,241	. 79.4

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Plumbing - basement storm drain water sump pump - Remove and replace four failed storm water sump pump				
60 504	0050300	0	Cantural Investigat Countries	20.44		floats and the control panel. The existing panel is outdated and will not accommodate the new components.	<u>,</u>	7.500	ć (03)	04.47
60 FIVI-C	-0059290	Orange	Central Justice Center	30-A1		Failure to replace will result in basement flooding. Elevators, Escalators, & Hoists - Replace (2) relays and mechanical edge sensors to keep Elevator #1 doors from	\$	7,500	\$ 6,838	91.17
C1 FN4 (I-0059291	Los Angolos	Pasadena Courthouse	10 11		closing on passengers.	ė	5,833	\$ 4,04!	69.35
01 FIVI-C	1-0059291	Los Angeles	Pasaueria Courtilouse	19-11		Elevators, Escalators, & Hoists - Replace (18) deteriorated brake solenoid core bushings for elevator 1, 2, 4, 5, 6, 7,	Ş	3,633	\$ 4,043	09.55
62 514 (0050202	Los Angeles	Compton Courthouse	10 461		8, 9, 10 & recalibrate; (2) brake solenoid core bushings per elevator.	ė	62 649	\$ 42,090	66.13
02 FIVI-C	1-0059292	LOS Aligeles	Clara Shortridge Foltz	19-AG1		6, 5, 10 & Tecambrate, (2) brake solenou core businings per elevator.	Ş	63,648	\$ 42,090	00.13
			Criminal Justice			Interior Finishes - Remove hazardous waste chemicals found around the courthouse by court staff and dispose of				
63 EM-(1-0059293	Los Angeles	Center	19-L1		properly.	¢	9,563	\$ 6,578	68.79
US FIVI-C	1-0033233	LOS Aligeles	Center	15-L1		Interior Finishes - Replace broken window & patch/paint damaged wall. Window glass pane and wall were	Ą	3,303	٥,576	08.79
64 EM-(1-0059297	Los Angeles	Compton Courthouse	19-AG1		damaged by a stray bullet.	ć	4,683	\$ 3,09	66.13
04 1101-0	1-0033237	LO3 Aligeles	Compton Courtilouse	13-A01		Elevators, Escalators, & Hoists - Rebuild elevator generator on elevator#1. Elevator #1 has failed and is currently	Ą	4,003	Ş 3,03	00.13
65 EM (1-0059298	Los Angeles	El Monte Courthouse	19-01		not operational.	Ś	34,009	\$ 19,766	58.12
03 1101-0	1-0039298	LOS Aligeres	Li Wonte Courthouse	15-01		not operational.	Ą	34,003	7 13,700	36.12
			Edmund D. Edelman			Plumbing - Replace damaged 4" cast iron drain line. Ground Floor Kitchen dishwasher area, a 4"cast iron drain line				
66 FM-(1-0059300	Los Angeles	Children's Court	19-Q1		is leaking; affecting (5) 2ft x 2ft ceiling tiles and a 10ft x 5ft area of floor tile.	Ś	32,971	\$ 23,076	69.99
67 EM /		Los Angeles	Van Nuys Courthouse West	19-AX2		Plumbing - Plumbing leak in wall on 10th floor Public Hallway next to room 1024 with a 4' x 9' area initially affected. In a known hot environment, open walls in Rm. 1024 & 1020 to locate leak; remove section of 1/2" galvanized drinking fountain water supply line; replace water line with copper piping and 1/2" ball valve. Two containments 14x7x11 hallway, 6x8x9 Rm. 1024, extract 160 gal. Water elevator pit; 1 negative air mach.; 1 dehumidifier.	ė	35,115		
07 FIVI-C	1-0059501	LOS Aligeles	Clara Shortridge Foltz	19-AAZ	1	1447/X11 Hallway, 0x0x9 Kill: 1024, extract 100 gai. Water elevator pit, 1 negative all mach., 1 denumumer.	Ş	33,113	\$ 20,20.	00.46
1			Criminal Justice							
68 EV4 (1-0059302	Los Angeles	Center	19-L1	2	Grounds and Parking Lot - Replace four (4) damaged cables to flag poles in front of building.	خ	3,448	\$ 2,372	68.79
00 1111-0	1-0033302	LOS Aligeles	Santa Monica	13-FT		Plumbing - Remove cracked/leaking 2.5" copper pipe & fittings, Install new 2.5" x 2.5" x 1¼" tee pipe & couplings.	ې	3,440	2,377	06.79
69 EV/-(-0059303	Los Angeles	Courthouse	19-AP1		Cut-out a 10' section wall to access pipe & restore wall.	Ś	4,143	\$ 3,252	78.49
US FIVI-C	0033303	EO3 MISCIES	County Records	13-WLT		COUNTY MANAGED – Electrical – Remove and Replace sensors, test diesel fuel tank to conform to regulatory	٧	4,143	3,25،	70.49
70 EM-(1-0059304	Los Angeles	Center	19-AV3		agency requirements to certify and obtain permit to operate.	Ś	6,000	\$ 6,000	100
7.0 11111-0	3033304	FO3 VIIBEIE3	CCITICI	12 742		Page 104 requirements to certify and obtain permit to operate.	7	0,000	7 0,000	, 100
			East Los Angeles			 Elevator, Escalator, & Hoist - Replace failed door safety edge for Public Elevator #1. Safety edge stopped working				
71 FM-(1-0059305	Los Angeles	Courthouse	19-V1		and does not detect passengers entering/exiting Elevator cab & creating a safety hazard.	Ś	2,596	\$ 2,018	3 77.72
/ 1 I I I			- Coartifoasc	1.7 V.I		and about not active publicing circumg circumg circumg circumg a dictumg a surety matara.	7	2,330	2,010	, ,,,,,,
1						Grounds and Parking Lot - Rebuild failed assembly barrel & shaft to the Secured/Main Parking Roll Up Gate. The				
1						shaft to the barrel/drum has cracked/sheared-off the drum assembly. Parts are obsolete and must be special				
72 FM-(1-0059306	Los Angeles	Compton Courthouse	19-AG1		ordered. High lift equipment required to remove and reinstall barrel assembly & shaft.	Ś	32,450	\$ 21,459	66.13
1-1-1-1-1			zzpto courtilouse			Elevators, Escalators, & Hoists - Restored Public Elevator S-3. Elevator had become stuck on 3rd floor due to faulty	7	3=,-130		00.13
73 FM-(1-0059307	San Diego	County Courthouse	37-A1		travel cable wires and drive fault. Restored travel cable wires and reset drive.	Ś	2,600	\$ 2.013	77.42

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
74	FM-0059308	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Remove/replace 10' of 4" cracked Cast Iron Pipe & fittings. Replace (4) 1'x1' saturated ceiling tiles & replace 5'x10' Carpet. Remediate Category 3, Black Water contamination. Water leaked from the 6th flr Men's Jury RR drain pipe affecting the 5th flr Alternate Public Defenders office.	\$ 3	2,520	\$ 32,520	100
	FM-0059309 FM-0059310	San Diego Los Angeles	Juvenile Court Stanley Mosk Courthouse	37-E1 19-K1	2	Electrical- Install 8 new emergency LED light fixtures (Lithonia E1500, T-8 E-ballast for the child holding cells and PL E-ballast for adult holding cells) using existing conduit and electrical wiring that is needed in the adult / children's holding cell area. The lights are currently not on emergency power and were brought up in a recent safety walk. Fire Protections - Remove and replace 5 feet of 5 inch, obsolete, cast iron riser pipe. Fire Sprinkler Riser Pipe#2 leaked into room 105B. Environmental containment and water remediation required.		5,312 8,750		
77	FM-0059311	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing – Replace 3ft. section of 4 in. drain line that cracked and (2) toilet wax rings in the 5th floor lockup. Removed 120 sq. ft. of carpet and 44 linear feet of cove base, replaced (4) 1x1 ceiling tiles. A Critical barrier (36x84) was set up with drying equipment. Area tested and FACS approved area re-occupancy.	\$ 3	4,250	\$ 34,250	100
78	FM-0059313	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Fire Protection - Fire Life Safety - Replace failed manual pull station on 3rd and 8th floors. Replace failed valve supervisory switches on 7th, 8th, & 10th floors and repair stairwell doors per annual PM test.	\$	5,133	\$ 4,131	80.48
79	FM-0059314	San Diego	North County Regional Center - North	37-F2	2	Holding Cell - Replace holding cell door locks. Court Holding Male Ad-Seg Cell 4B the lock is sticking and not working as designed and the door is hard to close, making this a security issue.		3,721	\$ 3,721	100
80	FM-0059315	Del Norte	Del Norte County Superior Court	08-A1	2	Security - Clear and illuminate courtyard - Install 1 new LED lighting fixture on the east side of the generator shed that is on the south end of the building to illuminate courtyard. Remove and dispose of one (1) 40ft tree in the courtyard. The tree and lack of lighting are causing a safety and security issue in that they can provide a hiding/camping place for individuals.	\$	2,003	\$ 1,227	61.27
81	FM-0059317	Los Angeles	Airport Courthouse	19-AU1	1	Plumbing - Replace 5' of 1" Copper pipe & fittings. Replace (4) saturated 2.x2' ceiling tiles. Remediate 3'x6' section of water damaged carpet and water affected areas. A 1" copper supply line leaked affecting the 7th floor secured hallway, employee's restroom & 6th flr secured hallway.	\$ 2	9,150	\$ 22,495	77.17
82	FM-0059318	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Replace isolation valves; (2) 4" Butterfly Valves & (1) 1.5" Ball Valve. Replace 4' pipe insulation. The 4" chill water return pipe has a failed 3/8" test fitting nipple & leaked onto the 10th flr AHU rm. Electrical - Tri signal will supply one FS-250 User Interface and CPU one hour of Labor for programming user	\$ 2	8,650	\$ 18,946	66.13
83	FM-0059319	Merced	Old Court	24-A1	2	interface Siemens Tech will spot test devices on Fire Alarm System to verify function - LED lights on panel are no longer working cause us to fail our annual fire panel test.	\$	4,326	\$ 4,326	100
84	FM-0059320	Orange	Central Justice Center	30-A1	2	Interior Finishes - Replace bloating/broken front door in Department C38 Courtroom. This door has deteriorated beyond repair and is often found un-secured creating a safety concern.	\$	4,353	\$ 3,969	91.17
85	FM-0059321	Mendocino	County Courthouse	23-A1	2	HVAC - Boiler repairs - Remove and replace failed low pressure switch (1) on Boiler #1. Remove and replace failed relief valve (1) and associated 3" x 3" x 1.5" tee on Boiler #1. Remove and replace failed relief valve (1) and associated 3" x 3" x 1.5" tee on Boiler 2.	\$	6,915	\$ 4,676	67.62

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Betty Lou Lamoreaux			Plumbing - Replace failed bearings, seal sleeves and gaskets, steam clean, treat and balance the boiler hot water				
86	FM-0059322	Orange	Justice Center	30-B1	2	recirculation pump #7. It is currently leaking.	Ś	5,000	\$ 3,998	79.95
	FM-0059323	Orange	North Justice Center	30-C1		Interior Finishes - N14 Courtroom Remove and replace 143 sq. ft. of carpet damaged during flooding from nearby urinal. Scope of work also includes replacement of 143 ln. ft. of wall base and 192 ln. ft. of visual safety nosing removed as part of remediation.	-	2,000		100
- 07	1101 0033323	Grange	North Justice Center	30 C1		Elevators - Preform Preliminary Orders on In-custody transfer elevators (4) #'s 9, 10, 11 & 12; All work will be	γ <u>1</u> .	2,000	7 12,000	100
88	FM-0059324	San Francisco	Hall of Justice	38-B1	2	completed after-hours or Court closure - Required corrections from DIR Inspector.	Š 1:	2,228	\$ 12,228	100
	FM-0059326		Hall of Justice	38-B1	2	Interior Finishes - Replace 10 viewing window countertops - Remove 10 window protective glass and remove 10 existing failed mdf countertops - install 10 new non-porous countertops and re-install 10 viewing windows.		5,567	\$ 5,567	100
90	FM-0059327	San Bernardino	Fontana Courthouse	36-C1	2	Vandalism - 1st and 2nd floors have (6) window panes that have been graffiti etched by vandals. Replace six (6) window panes (approximately 20 1/4" X 55 1/4") and apply graffiti film to prevent future vandalism. This work is necessary to remove gang related graffiti from public view. HVAC - Boiler #2 tubes are leaking and need to be replaced. If tubes break the basement could flood and impact	\$!	5,371	\$ 4,413	82.17
91	FM-0059328	Los Angeles	Pomona Courthouse South	19-W1	2	power to the building. Remove six leaking boiler tubes and install six 2" dia. x 99 ½ long 13 gauge ASTM steel tubes and new head plate gaskets.	\$:	3,456	\$ 3,150	91.14
92	FM-0059329	Los Angeles	West Covina Courthouse	19-X1	2	Interior Finishes - Basement Room B-6 fire doors are cracked / damaged and cannot be repaired. Fire doors are rated for 60 minutes, fire proofing is exposed and doors no longer function as designed. Install (1) pair of new white oak 60 min fire doors with custom staining, (6) New NRP 4.5" x 4.5" Hinges, new Schlage mortis lock, S-88 smoke seal and (2) Surface mount LCN door closers.	\$!	5,579	\$ 4,631	83.01
						Elevators, Escalators, & Hoists - Replace worn out and broken rollers for Elevator 5. Currently a safety issue because				
93	FM-0059332	Los Angeles	El Monte Courthouse	19-01	2	it's causing excess vibration.	\$	5,529	\$ 3,213	58.12
94	FM-0059333	San Bernardino	Victorville Courthouse Dept. N-1	36-L1	2	Elevators, Escalators, & Hoists - Service Elevator counterweight buffer was tested in accordance with a current preliminary order and dampened the counterweigh load, buffer failed as it remained in the compressed position and could not be decompressed. Replace failed spring loaded counterweight buffer on the service elevator. This work is necessary as the elevator cannot be returned to service until the counterweight buffer is replaced.	\$	7,546	\$ 7,546	100
95	FM-0059334	San Bernardino	Juvenile Dependency Courthouse	36-P1	2	HVAC - Electrical room contains a large transformer and currently has no active ventilation or cooling with the room temperature routinely approaching 100 degrees during summer months. Install 1000CFM exhaust fan in UPS / electrical room, (1) dedicated 120V circuit, exhaust plenum and grill, and control thermostat.	\$	7,744	\$ 4,223	54.53
96	FM-0059335	San Bernardino	San Bernardino Courthouse	36-A1	2	Elevators, Escalators, & Hoists - In-Custody Elevator is not leveling properly and car stops 4 -inches short of the floor; elevator is currently locked out to prevent possible trip and falls. Replace failed contactor and relay associated with the retiring cam.	\$	7,161	\$ 6,849	95.64
07	EN4 00E0226	l as America	Dawn au Carrette	10 4544	_	Elevators, Escalators, & Hoists -Replace failed motion board on elevator#4. Custody Elevator #4 was stuck on an	<u>.</u>	C 174	ć F465	02.7
9/	FM-0059336	Los Angeles	Downey Courthouse East County Regional	19-AM1	2	unknown level with the doors closed and not responding. Elevators, Escalators, & Hoists - Public Elevator #3 motor-generator has failed and elevator placed out of service.	\$	6,171	\$ 5,165	83.7
98	FM-0059337	San Diego	Center	37-I1	2	Rebuild motor generator and install new bearings and carbon brushes.	\$ 13	2,268	\$ 12,268	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
00	FM-0059339	Los Angeles	Pasadena Courthouse	10 11	2	Plumbing - Replace a cracked 2 cast iron drain pipe in the janitorial mop sink, on the 5th floor. Water leaked down to the 4th and 3rd floor. Replace (5) 2 x 2 acoustic ceiling tiles.	ċ	28,750	\$ 19,938	69.35
99	FIVI-0033333	LOS Aligeles	rasaueria courtilouse	13-11	2	Plumbing - Water Heater - Remove and replace failing 80 gallon commercial water heater. The current water heater is leaking; water is being diverted to a nearby drain on the roof of the building. This is the only unit supporting the building and needs immediate replacement to ensure proper operating conditions within. Additional scope includes replacement of necessary pipe connections and repair to copper line. Court staff to remove and recycle	7	26,750	3 19,950	09.55
100	FM-0059340	Riverside	Family Law Court	33-A1	2	old unit.	\$	7,127	\$ 7,127	100
101	FM-0059341	Riverside	Southwest Justice Center	33-M1	2	Plumbing - Water Pumps - Remove and replace failing seal kits and impellers on 3 Paco Pumps and 1 Taco pump. All pumps are currently leaking and have been taken out of service. The building currently does not have a backup. Work to be completed during regular business hours.	Ś	19,240	\$ 14,699	76.4
101	FIVI-0059541	riverside	Center	33-IVI1	2	Fire Protection - AQMD Procedure 5 cleanup was performed on 6000 square feet of ceiling fireproofing in the Basement Mechanical Room. Containment was setup and remediation was performed. Fireproofing was	7	19,240	\$ 14,099	76.4
102	FM-0059342	Los Angeles	Norwalk Courthouse	19-AK1	1	delaminating and falling onto mechanical equipment and onto the floor creating a hazardous ACM environment.	\$	60,000	\$ 51,018	85.03
103	FM-0059344	Los Angeles	Compton Courthouse	19-AG1	1	Grounds and Parking Lot - Remove/replace (1) Bottom Safety Edge Sensor Rail, (3) Door Slats & (1) Take-up Reel. Custody bus rear ended the Basement Sally Port Roll-up gate damaging bottom slats & caused gate to be out of alignment. Roll-up gate cannot be closed & creating a safety hazard.	\$	7,657	\$ 7,657	100
104	FM-0059345	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	HVAC - Replace VFD motor control for Return fan #1 and VFD motor control for Condenser Pump #2. They were damaged beyond repair by power outage due to Edison equipment failure.	\$	17,028	\$ 11,918	69.99
105	FM-0059346	Los Angeles	Airport Courthouse	19-AU1	2	Vandalism - Replace damaged mirror graffiti film (Mirror Shield 6-Mil AG) on 2 mirrors. Replace (2) broken 4"x4" porcelain tiles, restore damaged adjacent wall and re-anchor divider wall to new tiles. 1st floor men's public lobby restroom 2 mirrors have been damaged by graffiti and the urinal divider broken by a Court visitor.	\$	2,864	\$ 2,210	77.17
106	FM-0059347	Fresno	B.F. Sisk Courthouse	10-01	2	HVAC - Replace cracked and leaking heat exchanger in Boiler #2. Construct 1 x 6 x 10 wooden platform in well area outside of boiler room to be able to crane out failed heat exchanger and crane in the new one. Failed heat exchanger was determined in the field to have a manufacturer's defect and should be under materials only warranty. Cost of project however includes a \$21,875 purchase order materials deposit per manufacturer's requirement.	\$	35,973	\$ 35,973	100
107	FM-0059348	Los Angeles	Parking Structure-El Monte Courthouse-	19-02	2	Vandalism - Replace 6 damaged light fixtures and paint over 9,000 Square Feet of graffiti.	\$	6,715	\$ 6,715	100
108	FM-0059350	Orange	Betty Lou Lamoreaux Justice Center	30-B1	2	Interior Finishes - Replace 75 LF of damaged drywall 6" high and finish to match existing, replace 75 SF of damaged insulation, replace 80 LF of damaged rubber base in C404. Replace 48 SF of damaged drywall and finish to match existing, replace 16 LF of damaged rubber base in C304. Replacement is necessary due to flood under SWO 1454888.	\$	5,201	\$ 5,201	100
109	FM-0059351	San Diego	South County Regional Center	37-H1	2	Interior finishes - Floor 3 Corridor - Replace ADA 8000 Door Operator. The ADA door slams shut and cannot be adjusted any further. This is a safety issue since the door closes very quickly.	\$	4,820	\$ 4,820	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			51 10 511			Electrical - Replace 21 burned out lobby ceiling lights with LED bulbs. Located on the 1st and 2nd floor lobby.					
110	FM-0059352	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Multiple lights are out and poor lighting is a safety concern. Special equipment (man lift) will be needed to perform the FM.	ċ	32,554	ć	22,785	69.99
	FM-0059353	Los Angeles	Pomona Courthouse South	19-W1	2	Exterior Shell - Remove and replace sealant in north and south expansion joints. During completion of sealant (3,800 linear feet) replacement on east side, north and south were inspected and found to be deteriorating due to age. As a result, water can enter the building from rain.	\$	177,352		161,639	91.14
112	FM-0059354	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing – Floor drain clogged at 1st floor kitchen. Water backed up impacting 8,000 SF in the 1st floor kitchen, cafeteria, adjoining restrooms, and 900 SF on the service level loading dock. Containment and remediation conducted on category 3 water. Drain line was manually cleared and camera showed the line clear.	Ś	55,000	\$	37,835	68.79
	FM-0059355	Los Angeles	Downey Courthouse	19-AM1	2	Elevators, Escalators, & Hoists - Replace defective worm seal on public elevator#1. Worm seal on public elevator #1 motor is constantly leaking out oil.	\$	7,991		6,688	83.7
114	FM-0059356	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Plumbing - Replaced 12 foot section of 4 inch cast iron drain line, and 12 feet of 2 inch cast iron drain line that were cracked. Environmental and water remediation for leak, 17th floor room 410. 12 X 12 foot area and ceiling impacted.	\$	23,350	\$	16,062	68.79
115	FM-0059357	Riverside	Larson Justice Center	33-C1	1	Elevators, Escalators, & Hoists - Lighting - Replace failed lighting controller, ceiling mount, and power supply for Elevator #1. 90% of the lighting have failed and is a safety hazard to employees, jurors, and public.	\$	14,513	\$	11,728	80.81
446	514 0050350		Stanley Mosk	40.144		Plumbing – Replaced 15 feet of 2 inch Cast Iron Pipe, Six 2 inch No-Hub Couplings, One 2 inch 90 degree Long Bend, and one, 2 inch Combi. Water remediation and testing required for 3x3 area in spectator seating and 4x5 area in chambers. Water originated from a cracked 2 inch cast iron floor drain at the 9th floor kitchen.		25.774		24 704	07.25
116	FM-0059358	Los Angeles	Courthouse Chatsworth	19-K1	1	Exterior Finishes - Install window tint (gty. 660 sg. ft.) in 5 offices on the 1st floor. Window tint will reduce the heat	\$	35,774	\$	34,794	97.26
117	FM-0059359	Los Angeles	Courthouse	19-AY1	2	load in the 5 offices, HVAC can't keep up during extreme temperatures.	Ś	8,614	Ś	7,219	83.8
110	FM 0050360	_	Clara Shortridge Foltz Criminal Justice	10 11	1	Plumbing – drained 19th & 18th floors hot water to stop leak. Replaced a copper 1¼ to ¾ line adapter and added a new ¾ ball valve. 18th floor room 606. Containment, remediation and build-back includes 40 replaced 1x1 ceiling	ė	-		16 570	69.70
	FM-0059360	Los Angeles	Center Clara Shortridge Foltz Criminal Justice	19-L1	1	tiles, and patching all holes required during work. HVAC - Shaft and pulley snapped - Remove and replace the failed shaft and pulley in air handler supply #24. Shaft	2	24,100	·	16,578	68.79
	FM-0059361 FM-0059362	Los Angeles Los Angeles	Compton Courthouse	19-L1 19-AG1	1	and pulley snapped from the unit and shut off the equipment, effecting 9th and 10th floors. Plumbing - Replace 3'x3' acoustic ceiling tiles, extract approx. 50-80 gallons of grey water. A Court visitor clogged a sink on the 9th flr women's RR flooding 15'x15' section inside Rm 801A Public Defender's office & affecting ceiling tiles, floor & fabric sofa. Remediation required due to category 2, grey water contamination.	\$	38,875 20,925		26,742 13,838	68.79
121	FM-0059363	Napa	Napa Juvenile Court	28-C1	2	Electrical - Install load testing equipment on panel L1. Capture load information for 72 hours. Remove equipment and provide a written report stating how many 20 amps circuits can be added to the existing panel.	\$	1,752	\$	1,752	100
122	FM-0059364	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Fire Protection - Repair deficiencies identified during the recent Level VIII PM that 6 sprinkler heads were either painted or corroded, 5 escutcheons were missing or broken.	\$	3,284	\$	2,643	80.48

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Exterior shell - Provide and install raised metal address numbers "550-600" to building above South Wing entry; Provide and install new signage, new spotlight, 120 of conduit and wire; Provide and install 1 new photocell;				
						Provide and install vinyl address numbers to 4 exterior doors New signage, to indicate street address, to be added				
123	FM-0059366	Solano	Hall of Justice	48-A1	2	to meet city fire code as dictated by the Fairfield Fire Marshal.	\$	12,054	\$ 8,778	3 72.82
124	ENA 00E0267		FI Manada Canada anna	10.01	,	HVAC - Replace defective float for the East Cooling Tower. Water blow down and replenishment is affected with	ċ	C 120	ć 2.55	50.43
124	FM-0059367	Los Angeles	El Monte Courthouse Van Nuys Courthouse	19-01	2	only one float working. Elevators, Escalators, & Hoists - Replaced fuse holder 65 assembly and adjusted door operator. Elevator #2 will not	\$	6,120	\$ 3,557	7 58.12
125	FM-0059368	Los Angolos	East	19-AX1	2	stop at the 2nd, 5th, 6th or 7th floors.	ċ	3,482	\$ 3,125	89.74
123	FIVI-0039308	Los Angeles	Last	13-471		HVAC - Chiller #2 - Remediate leaks found on York Chiller #2 at the discharge of the compressor, slide valve cover,	ې	3,462	3,12.	69.74
			Harbor Justice Center-			the bottom of the condenser plug, and 4-way valve. Additional scope includes replacement of reclaim filters,				
			Newport Beach			recovering of existing refrigerant, and verification of operation upon completion. Leaks detected are below				
126	FM-0059370	Orange	Facility	30-E1	2	reportable amounts.	Ś	10,488	\$ 8,843	84.32
			,							
127	FM-0059372	San Bernardino	San Bernardino Justice Center	36-R1	2	Grounds and Parking Lot - In front of the South Main Entrance there is approximately 347SF of loose pavers. The pavers acrylic grout and sand/mortar bed have been compromised due to high traffic creating a potential safety / liability concerns. This work is needed to address an existing trip hazard/safety issue. Remove and reinstall approximately 347SF of loose pavers, utilizing a VBM mortar blend for superior adhesion and water resistance.	\$	9,537	\$ 9,537	7 100
			Chatsworth			HVAC - Replace non-functioning VAV controllers that are causing no air or too much air in designated areas. The				
128	FM-0059374	Los Angeles	Courthouse	19-AY1	2	VAV controllers are needed to control CFM and the temperature from the BAS.	\$	4,648	\$ 3,895	83.8
129	FM-0059375	Tulare	Tulare Division	54-B1	2	Exterior Shell - Seal $3' \times 1/2''$ crack at joint on outside concrete wall at ramp to basement to prevent further asset deterioration. Remove loose debris from crack and fill in area with liquid epoxy and sack outside wall area with non-shrink grout - For asset preservation to stop the progressive widening of the crack and to prevent water from penetrating into the building.	\$	2,720	\$ 1,904	1 70
		Con	Can Damardina			Grounds and Parking Lot - Trash dumpster storage enclosure gates are broken, drag on the ground, and cannot be		·		
120	EN4 00E027C	San	San Bernardino	26 42	٦	properly secured. Replace (2) 10ft x 6ft swinging doors and install new hinges on the trash dumpster storage	۲	4.152	¢ 2.077	05.64
130	FM-0059376	Bernardino	Courthouse - Annex Metropolitan	36-A2	2	enclosure. Grounds and Parking Lot - Replace (1) damaged 3"x20' door slat and straightened (6) damaged 3"x20' door slats, restore bottom safety edges, adjusted the barrel tension & limit switch. Custody bus backed into Sally Port Roll-up	Ş	4,153	\$ 3,972	95.64
131	FM-0059377	Los Angeles	Courthouse	19-T1	1	gate causing damage to 7 door slats.	Ś	9,850	\$ 9,850	100
-51	0033377	_557 (ligeles	Stanley Mosk	-5 11		HVAC - AHU S-34 condensate pan is leaking water onto the 9th floor mechanical room leaking 50-80 gallons down	7	2,030	5,650	100
132	FM-0059379	Los Angeles	Courthouse	19-K1		to stairwell #4.	\$	23,495	\$ 22,851	97.26
133	FM-0059380	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	HVAC - Chilled Water Coils in Air Handler S12 have failed impacting Court Operations Room 336, 422 A,E,F,G,K,L 426A, 428A,B,D,F,G,H,K,L, 436A, 438A Court Administrator and Staff Offices, Known hot environment for TSA piping insulation requires containment to remove, replace failed CW coils, and drain pan, sheet metal plenum as needed, isolation valves and other regulating valves and gauges as needed.	\$	75,000	\$ 75,000) 100
134	FM-0059381	Los Angeles	Pomona Courthouse North	19-W2	1	Plumbing - Replaced 5 damaged ceiling tiles. Containment set-up and remediation was performed. A inmate clogged the toilet in lock-up and water leaked from the 5th level, into the 4th floor, room 410 department 281.	\$	23,314	\$ 23,314	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Bellflower			Plumbing - Replace defective drain line for the 2nd floor drinking fountain. Work will take place in a ACM condition.				
135	FM-0059382	Los Angeles	Courthouse	19-AL1	2	Drinking fountain is currently non-operational and employees have no source of drinking water.	\$	14,650	\$ 11,418	77.94
						HVAC - Replace 30 HP motor for the main chilled water pump #4. The motor has failed and is in need of immediate		•		
			Betty Lou Lamoreaux			replacement. We are operating on pump #5 only. Loss of pump #5 would result in loss of cooling to the facility.				
136	FM-0059383	Orange	Justice Center	30-B1	2	Investigative work was performed under JO SWO 1456942.	\$	8,467	\$ 6,769	79.95
						Plumbing – Remove/replace 15' of 4" Cast iron pipe & fittings. Remediate due to Category 3/Black Water				
40-		l				Contamination. Waste water leaked from 3rd flr attic into 2nd flr rm 202, Main jury assembly rm, affecting 10 'x10'				100
137	FM-0059384	Los Angeles	Compton Courthouse	19-AG1	1	area of celling and floor.	\$	36,575	\$ 36,575	100
						HVAC - Replaced 12 feet of old and delaminating insulation from ¾ HVAC condensation pipe. Containment was set-				
120	FM-0059385	Los Angeles	Alhambra Courthouse	10_11	1	up and remediation was performed. Water was leaking from 1st Floor Deputy's Office #117.	¢	17,355	\$ 14,925	86
130	1101 0033303	LOS Aligeres	Amamora courtilouse	13 11		ap and remediation was performed. Water was reaking from 15t 1001 Deputy 3 Office #117.	7	17,333	ÿ 14,323	- 00
						Roof - Install one 30" x 36" safety railing system for roof hatch, with chain barrier and safety post - Roof access is				
139	FM-0059386	Kings	Avenal Court	16-C1	2	unsafe and does not have proper fall protection. Noted on FPE building inspection report.	Ś	2,817	\$ 1,634	58.01
						Electrical - Install (3) 120V 20amp circuits with (2) single duplex plugs and (1) quad plug in the café. This work is			,	
		San	San Bernardino			necessary as multiple extension cords are currently be utilized to support the café appliances creating a trip hazard				
140	FM-0059388	Bernardino	Justice Center	36-R1	2	and potential Court liability.	\$	6,371	\$ 6,371	100
141	FM-0059389	Santa Cruz	County Administration Bldg.	44-A2	2	COUNTY MANAGED - HVAC - Install Pony Boiler, pumps and startup commissioning - Existing boiler inefficient and failing.	\$	98,921	\$ 98,921	100
142	FM-0059390	Los Angeles	Pasadena Courthouse	19-J1	2	Elevators, Escalators, & Hoists - Passenger Elevator #7 did not pass the yearly load test, needs a new power unit, new feed line with OSV and Shut off valve, re-pipe low pressure galvanized lines and, reconnect new necessary wiring. Test and return elevator back to service, and provide inspections documents.	\$	32,307	\$ 22,405	69.35
143	FM-0059391	Los Angeles	Pomona Courthouse South	19-W1	1	Plumbing - Replaced defective angle stop and 12 ceiling tiles that were damaged. Containment was set-up and remediation was performed. 5th Dept. J Room 502 C Judge's Chambers restroom angle stop leaked water onto the tile floor (4'x7' area) which leaked through the ceiling wetting a 3'x3' section of fire proofing above the ceiling of the 4th floor Dept. J Room 418C Judge's restroom and on to the tile flooring.	\$	24,755	\$ 24,755	100
		0	Pomona Courthouse			Plumbing - Replaced (1) defective toilet wax ring and replaced 12 ceiling tiles. Set-up containment, and	,	,	,,,,,,,	
144	FM-0059392	Los Angeles	South	19-W1	1	remediation. Water leaked from the 2nd Floor Room C toilet, down to the first floor.	\$	22,875	\$ 22,875	100
						HVAC - BAS Server power supply has failed and the BAS cannot be accessed, set-points throughout the building			·	
						unable to be adjusted. One of the chillers was not responding and court rooms were getting hot. Replace failed				
		San	San Bernardino			power supply in BAS server. Validate the database is still intact and that all points in the system are responsive with				
145	FM-0059394	Bernardino	Justice Center	36-R1	2	all graphics in place.	\$	3,221	\$ 3,221	100
146	FM-0059395	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Electrical- Replace (1) check valve on day tank for emergency generator. The current check value on the day tank is not operational.	\$	4,743	\$ 3,320	69.99

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
1/17	FM-0059396	Los Angeles	Santa Monica Courthouse	19-AP1	2	Elevators, escalators, & hoists - Remove and replace the controller starter for Public Elevator #3. The existing controller starter is malfunctioning, causing breakdown.	خ	6,030	ċ	4,733	78.49
	FM-0059397	Los Angeles	Santa Clarita Courthouse	19-AD1		COUNTY MANAGED - LA County ISD- Plumbing-Replace 1000 feet of 3" & 4" insulated underground pipe supplying heating water loop and four (4) isolation valves. Pipe must be replaced to provide heating for all Civic Center Building.	\$	120,124		120,124	100
						Interior Finishes - Replaced thirty (30) Emergency Evacuation signage missing on all floors in main halls to direct					
149	FM-0059398	Los Angeles	Pasadena Courthouse	19-J1	2	path to egress to safely exit, in the event of an emergency. Cited by the Fire Inspector.	\$	7,423	\$	5,148	69.35
150	FM-0059399	Contra Costa	George D. Carroll Courthouse	07-F1	2	Grounds and Parking Lot - Energy Project - Replace Qty. 10 High Energy Consuming Mercury Vapor Fixtures with Energy Efficient LED Fixtures. Existing fixture's electrical components are beginning to corrode, become brittle and failing. Four of the ten are not working at all. This is a security issue and a concern of Court Security. HVAC - Plumbing - Remove and replace one failed 3 way pneumatic heat valve and remove approx. 30lbs of	\$	15,997	\$	15,997	100
151	FM-0059400	Orange	Central Justice Center	30-A1	2	asbestos containing insulation around plumbing elbows supplying hot water for the heating system in the Civil Department. The asbestos needs to be removed to access valve and with winter coming, immediate remediation of the leak is required to avoid further leaks and damage.	\$	4,075	\$	4,075	100
			Van Nuys Courthouse			Elevators, escalators, & hoists - Replace broken leveling ring switches. Elevator selector malfunctioned causing the					
	FM-0059401	Los Angeles	East Metropolitan	19-AX1		elevator to fail. Plumbing - Replace 10' of 3/4" domestic hot water supply line leaking between walls of the Men's employee restroom and Room 601 Judge's chamber restroom wall which leaked down to the 5th floor (Next to Room 500)	\$	3,225		2,894	89.74
153	FM-0059402	Los Angeles	Courthouse	19-T1	1	City Attorney Storage room, wetting the hard lid ceiling and tile floor.	\$	34,675	\$	34,675	100
154	FM-0059403	Los Angeles	Stanley Mosk Courthouse Stanley Mosk	19-K1	1	Plumbing – Replace seal around floor drain in 2nd floor snack bar. Remediate leaked water at 1st floor sheriff office room 125. 1 cubicle. (4) 1'x1' acoustic ceiling tiles wet, (1) cubicle partition fabric wet, 3' x 3' section of carpet wet. Plumbing - Water is leaking from the ceiling of the 8th floor, Dept. 88 Court Reporter's Office, Room 831R	\$	23,819	\$	23,819	100
155	FM-0059404	Los Angeles	Clara Shortridge Foltz Criminal Justice	19-K1	1	saturating (2) 2'x4' ceiling tiles that have fallen and leaving a 4'x5' section of the tile floor wet. Plumbing - Remove and replace two (2) gate valves that are not working: 1. 3" main water supply valve is not closing 2. 1 1/2" hot water valve is not closing. Due construction in the 1st floor jury room, the pipes need to be relocated to finish the construction, both valves are located above "Bus bay #4", ACM test has to be done, and	\$	43,475	\$	43,475	100
156	FM-0059405	Los Angeles San	Center San Bernardino	19-L1	2	remediation for positive test. HVAC - Replace failed line reactor on AHU PH2. The line reactor supports 3 of the 6 supply fan motors, work is needed as one of the 2 primary AHU's for the tower is currently running at 50% capacity and may not be able to	\$	27,268	\$	18,758	68.79
157	FM-0059406	Bernardino	Justice Center	36-R1	2	hold building temps should triple digit temps occur.	\$	3,853	\$	3,853	100
158	FM-0059407	Santa Clara	Palo Alto Courthouse	43-D1	2	HVAC - Cooling tower - Replace (1) failed VFD - Start up and test operation.	\$	4,578	\$	3,023	66.04
159	FM-0059408	Solano	Hall of Justice	48-A1	2	Grounds and Parking Lot - Install 700 Lf of temporary barrier wall around building entrances -install drainage hoses and 2 pumps to extract water trapped within the prevention area; Remove and restore all entrance for Court and Public use on Monday through Friday; Provide sandbags, sand and plastic. Preparation for flooding at the HOJ.	\$	19,627	\$	14,292	72.82

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
160	FM-0059412	San Joaquin	Lodi Branch- Dept. 2	39-D2	2	HVAC - Replace Failed Variable Frequency Drive for 7.5-HP Supply fan motor on AHU-03.	Ś	4,725	\$ 4,725	100
		San Joaquin	Manteca Branch Court	39-C1	2	HVAC - Replace failed aluminum condenser coil on the PKU04 - Replacing the condenser coil is now the only method to repair the package unit.	Ś	6,403		
101	0003 120		Mammoth Lakes	55 61		Plumbing - Rebuild check valves to backflow which failed annual testing - One of the Check valves in backflow is not	Υ	0, .00	φ 0,103	100
162	FM-0059414	Mono	Courthouse	26-B2	2	closing tight and water bleeds.	\$	4,815	\$ 4,815	100
163	FM-0059417	San Joaquin	Manteca Branch Court	39-C1	2	Exterior Shell - Replace shattered window in clerestory approx. 4ft x 5ft.	\$	3,226	\$ 3,226	100
164	FM-0059418	San Francisco	Hall of Justice	38-B1	2	COUNTY MANAGED - Exterior Shell - Install new exterior doors (10) at Front Entrance, Rear Entrance and Freight Entrance; install new interior door (2) at Rear Entrance foyer; correct failed roll-up garage door.	\$	27,064	\$ 27,064	100
165	FM-0059419		New Amador County Courthouse Stanley Mosk	03-C1	2	Grounds and Parking Lot - Remove and dispose of 2 dead oak trees - The oak trees are dead and have the potential of causing damage to vehicles, pedestrians and pavement due to falling branches or the trees themselves. Remove and Dispose of 1 Tree at edge of parking lot on East Side it is interfering with ability to park 3 vehicles due to overhanging branches (Trimming back is not feasible as would remain ongoing maintenance issue). Plumbing - Backflow devise failed PM. Needs to be replace, backflow is leaking and domestic water can get	\$	7,508	\$ 7,508	100
166	FM-0059420		Courthouse	19-K1	2	contaminated.	Ś	9,412	\$ 9,412	100
			Hayward Hall of Justice	01-D1	2	Elevators, Escalators, & Hoists - Elevators - Regulatory Compliance Preliminary Orders - DIR - Compliance Date 10/10/2016 - Brake and Earthquake Testing - The operation of the elevator under earthquake or other emergency conditions shall be checked for proper operation Subsection 3041(d) - The elevator brake shall be adjusted to hold the car at rest with its rated load while on car top inspection and hoistway inspect car drifts "up" after the key switch is turned off Subsection 3038 (h).	\$	16,206	, ,	
168	FM-0059422	San Diego	North County Regional Center - North	37-F2	2	HVAC - Replace failing return fan motor on AHU #4.	\$	2,553	\$ 2,553	100
169	FM-0059423	Los Angeles	Alhambra Courthouse	19-I1	2	Elevators, Escalators, & Hoists - Replace defective contactor on Elevator #5. Elevator is not responding.	\$	5,865	\$ 5,044	86
170	FM-0059425	Kern	Taft Courts Bldg.	15-F1	2	HVAC - Replace failed PKU 6 compressor. Unit is not operational.	\$	4,853	\$ 4,853	100
171	FM-0059427	San Diego	750 B Street - 4 DCA 1	64-A1	2	Plumbing - Remove and replace failed domestic hot water circulation pump on Boiler 1.	\$	4,068	\$ 2,754	67.71
172	FM-0059428		Edmund D. Edelman Children's Court	19-Q1	2	HVAC- Remove and replace damaged media fills on cooling towers 1 & 2(4). Damaged media fills do not allow the system to work at maximum efficiency. In addition, the damaged media fills are deflecting water away from the cooling towers and onto the roof. Water is accumulating on the roof and could potentially leak into building.	\$	25,164	\$ 17,612	69.99
173	FM-0059429	San Francisco	Hall of Justice	38-B1	2	COUNTY MANAGED - HVAC - Install new Boiler room feeder pump; new I-beam supports; condenser waterline piping; hangers & fittings - Original equipment is failing/leaking causing loss of heating.	\$	13,875	\$ 13,875	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Clara Shortridge Foltz			Plumbing – Replaced defective Sloan valve assembly with a new pneumatic unit, installed add a valve to secure				
l			Criminal Justice			water supply at angle stop in lockup 13th floor. 12' by 30' area affected ceiling tiles damaged. Containment and	_			60 -0
174	FM-0059430	Los Angeles	Center	19-L1	1	remediation required for category 2 water intrusion.	\$	30,850	\$ 21,222	68.79
			Hayward Hall of	04 D4	_			25.664	å 24.400	
175	FM-0059433	Alameda	Justice	01-D1	2	HVAC - Replace failed control air compressor system to include compressed air storage tank and air dryer.	\$	35,661	\$ 31,489	88.3
						Interior Finishes - Replace damaged locks from (3) interview rooms and replace (3) new Stainless Steel wraps on (3)				
476	FN 4 0050434	l		40.444	_	doors complete with (3) Schlage L9482 Prison function Mortise Locks. The door handles were damaged by inmates		40.467	0.545	05.00
1/6	FM-0059434	Los Angeles	Norwalk Courthouse	19-AK1	2	and need to be replaced for the safety for the sheriffs.	\$	10,167	\$ 8,645	85.03
177	FM-0059435	Los Angeles	Norwalk Courthouse	19-AK1	2	HVAC - Replace a defective AC unit. Compressor is not working and temperature in MCR data room is extremely hot. High temperature is a health hazard to employees and potentially harmful to computer equipment. Elevators, escalators, & hoists - Remove and replace worn motor shaft, gear, and brakes for Judge's elevator #9.	\$	18,020	\$ 18,020	100
			Edmund D. Edelman			Worn shaft and gear are causing excessive vibration. Worn shaft and gear can cause elevator to fail, resulting in				
170	ENA 00E0427	Los Angolos		10.01	2		۲.	4F 171	ć 21.61E	60.00
1/8	FM-0059437	Los Angeles	Children's Court	19-Q1	2	entrapments.	\$	45,171	\$ 31,615	69.99
470	FN 4 00F0 430	C F	Hall of booking	20.04	_	COUNTY MANAGED - Elevators, Escalators, & Hoists - Install new motor generator at elevator #8 - Elevator not		7.602	å 7.600	100
1/9	FM-0059439	San Francisco	Hall of Justice	38-B1	2	leveling at floors due to failed equipment.	\$	7,692	\$ 7,692	100
400	EN 4 00E0440		T Cth	40.04		HVAC - Replace failed magnetic starter, contactor, and overload relay for Air handler #6 which controls air flow to		46 200	42.050	05.44
180	FM-0059440	Los Angeles	Torrance Courthouse	19-C1	1	the entire 5th floor.	\$	16,290	\$ 13,869	85.14
404	EN 4 0050444	C F	Hall of booking	20.04	_	COUNTY MANAGED - Electrical - Install insulation wrapping at Emergency Generator Fuel Lines and hangers - SFMA		6 624	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	100
181	FM-0059441	San Francisco	Hall of Justice	38-B1	2	code compliance request for equipment.	\$	6,634	\$ 6,634	100
			601 W. Santa Ana				_	=		
182	FM-0059442	Orange	Blvd - 4 DCA 3	64-E1	2	Electrical - Install (14) CAT6 cable drops throughout the building to support the Courts installation of a Wi-Fi system.	\$	7,348	\$ 7,348	100
400	EN 4 0050440	Cht-	Maria Carratharra	45 44	_	Fire Protection - Replacement and retest of (2) 55ah batteries (2) 18ah batteries (1) wall mount horn/strobe and (1)		2.022	å 2.022	100
183	FM-0059443	Shasta	Main Courthouse	45-A1		FCPS power supply - FAP failed LVL III PM.	\$	3,022	\$ 3,022	100
						HVAC - Replace (1) defective sand/separator system. The Cooling Towers currently have a sand/separator system				
104	EN 4 00 E 0 4 4 4	l as Amaslas	Downey Courthouse	10 444	2	for the condenser water that is non-operational, causing strainers to be clogged, and inadequate condenser water flow.	Ļ	40.400	ć 40.504	02.7
184	FM-0059444	Los Angeles	Downey Courtilouse	19-AM1	2		Ş	48,488	\$ 40,584	83.7
			Santa Monica			Interior Finishes – Abate & properly dispose of 430SF ACM Vinyl Floor Tiles & 430SF ACM old carpet in Admin Office 232. Abate & dispose 340SF of ACM Black Mastic & 340SF ACM new Carpet installed on top of existing mastic in 2nd flr Secured Hallway. Carpet was removed from the Admin Office & secured hallway exposing ACM in underlying				
185	FM-0059446	Los Angeles	Courthouse	19-AP1	1	vinyl tile and mastic.	>	47,187	\$ 47,187	100
1						Fire Protection - Remove existing doors (55) and door frames to install new fire rated door frames, fire rated doors				
100	EN 4 00 E 0 4 4 7	Los Angeles	Dasadana Caustla	10.11	_	and new code compliant door hardware. Current doors, frames and hardware are non-compliant. This work is in	,	450 535	¢ 400.000	60.3-
186	FM-0059447	Los Angeles	Pasadena Courthouse	19-J1	2	response to the Fire Marshal citation.	\$	158,527	\$ 109,938	69.35
1			Carata Daulaana			Fire Protection - Replace Fire Alarm panel with new and transition monitoring to Alpha Fire & Security from Stanley				
10-	FN 4 00F0 4 4 5	Courte Doub	Santa Barbara	42.64		Alarms. Fire Alarm panel is outdated and triggering false intrusion alarms, triggering dispatch to the facility by the	_	2.022	4 222	
187	FM-0059448	Santa Barbara		42-C1	2	SB Sheriff's Department.	\$	3,820	\$ 3,820	100
100	FN 4 00F0 4F3	Calaurana	Calaveras Superior	05.04		Interior Finishes - Replace shattered window in room 129 - Window needs to be replaced so that room is ready to	_	6.055		100
188	FM-0059450	Calaveras	Court	05-C1	2	occupy. (PBT09192016)	\$	6,928	\$ 6,928	100

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Butte County			HVAC - Replace failing BAS laptop with new desktop system - laptop having problems, sent to vendor to recover/repair software and or hardware, still having issues, system will lock up, leaving no control of courthouse				
189	FM-0059451	Butte	Courthouse	04-A1	2	settings.	Ś	4,406	\$ 4,406	100
103	1101 0033-131	Datte	Courtilouse	01711	_	Interior Finishes - Replace (1) Restroom door and (1) door closer - Public Restroom door damaged not closing	7	1,100	7 1,100	100
190	FM-0059452	Los Angeles	Norwalk Courthouse	19-AK1	2	properly, and restroom is unsecured.	\$	3,574	\$ 3,039	85.03
			East County Regional			Electrical - Replace generator battery charger wall unit. The backup generator's battery charger has failed and is no				
191	FM-0059453	San Diego	Center	37-I1	2	longer working.	\$	2,659	\$ 2,659	100
192	FM-0059454	Los Angeles	Norwalk Courthouse	19-AK1	1	HVAC -Replace 20 HP motor controller for AHU #5. VFD motor controller has failed, no air on the 5th floor.	\$	13,695	\$ 11,645	85.03
						HVAC - Restore shaft motor and replace bearings for AHU 3. AHU #3 is inoperable, the shaft motor has failed and				
			Bakersfield Superior			the bearings are worn and inoperable. Shaft to be rebuilt and bearings replaced to return cooling to Courtroom 17	١.			
193	FM-0059455	Kern	Court	15-A1	2	and the Law Library.	\$	5,253	\$ 3,290	62.64
194	FM-0059456	Los Angeles	Pomona Courthouse South North County	19-W1	2	Elevators, Escalators, & Hoists - Elevator#2 Replace alarm bell unit to provide power for the operation of the bell for not less than one hour. Remove access key switch and replace with blank plate. Elevator #3 Replace emergency lighting unit to operate as intended and shorten ropes so that top car clearances are not reduced below requirement. To address DIR compliance issues.	\$	8,409	\$ 7,664	91.14
			Regional Center -			COUNTY MANAGED - HVAC - Chiller #2 has failed and needs to be overhauled to restore full cooling capacity to the				
195	FM-0059457	San Diego	South	37-F1	2	central chiller plant service the NCRC Campus. County to provide temporary chiller during repairs.	\$	35,700	\$ 35,700	100
196	FM-0059458	Los Angeles	Pomona Courthouse South	19-W1	2	HVAC - Replace 148 2" diameter by approx. 100" long steel tubes. Boiler #1 all 148 tubes leak, water leaks onto the floor daily. Damaged tubes are a safety hazard as tubes could break and flood the basement.	\$	22,265	\$ 20,292	91.14
197	FM-0059459	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Fire protection - Repack fire pump, and replace gasket and ring. New nuts and bolts to be provided. Pump packing gland is bent, causing the pump to leak. Must be replaced to prevent pump failure in emergency.	\$	5,054	\$ 4,067	7 80.48
198	FM-0059461	Los Angeles	Torrance Courthouse	19-C1	2	HVAC - Remove existing malfunctioning 7.5HP motor, pulley & bushing on cooling tower. Install (1) new 7.5HP motor, (1) new pulley & (1) new bushing. Cooling Tower #1 Southside Motor A has a bad bearing causing the VFD drive to shut off on high temperature.	\$	4,937	\$ 4,203	85.14
199	FM-0059462	Los Angeles	Van Nuys Courthouse West	19-AX2	1	Plumbing – Replace (5) 1 x 1 ceiling tiles in the 2nd floor clerk's office. Unclog drinking fountain that was intentionally clogged by the inmate. Water leaked from the 3rd floor to the 2nd floor clerk's office. Containment was erected with drying equipment in the clerk's office, then testing was executed.	\$	35,100	\$ 28,248	80.48
			Wiley W. Manuel				l.		[
200	FM-0059463	Alameda	Courthouse	01-B3		COUNTY MANAGED - HVAC - Chiller - Rebuild failed 250 ton chiller.	\$	60,336	\$ 60,336	5 100
201	FM-0059464	Los Angeles	Torrance Courthouse	19-C1	1	HVAC - Replace failing VFD with (1) new 15HP-ABB VFD with Bypass. 4th floor AHU#5 Supply fan VFD is tripping on high temperature.	\$	9,815	\$ 8,356	85.14

# FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
202 FM-0059465	Los Angeles	Clara Shortridge Foltz Criminal Justice Center	19-L1	1	Fire Protection - Water leaking in the 19th floor room 19-923, 19th floor secured hallway adjacent to room 19-950, and 19th floor secured hallway adjacent to men's staff restroom. Leak originated in the roof due to two (2) pinhole leaks on a 2-inch fire standpipe and water accumulated in between the roof & concrete.	\$ 54,320	\$ 37,367	68.79
202 FNA 0050467	Nama	Naga luvanila Caust	20.61	2	Fire protection - Replace (2) missing ½ chrome QR sidewall sprinklers in the spare sprinkler box. Replace (2) missing ½ chrome QR pendant sprinklers in the spare sprinkler box. Install missing 911 sign. Replace (5) corroded ½ brass QR uprights in the Sally Port. Replace (1) painted ½ brass 155 degree upright sprinkler in the Janitors Closet. Replace (1) missing chrome 401 escutcheon in Room 123. Tag the fire sprinkler riser with a five year certification	\$ 2 724	1 000	F1 2F
203 FM-0059467 204 FM-0059468	Napa Los Angeles	Napa Juvenile Court Chatsworth Courthouse	28-C1 19-AY1	2	when these repairs are completed. Plumbing - Install twenty (20) new 1 ½ copper pipe for the riser from fixture distribution manifold inside access space to new ball valve above. Install two (2) 1 ½ Pro-Press ball valve inside access closet to replace existing frozen ball valve. Install a new cushion isolation strut. Water pipe is leaking between cell 5 & 6, from failed 1 ½ copper water pipe.	\$ 3,724	\$ 1,909	51.25
205 FM-0059469	Los Angeles	Van Nuys Courthouse East	19-AX1	2	Electrical - Replace damaged wiring to the nearest junction box, replace T-8 Lighting and sockets. Entire bank of lights are out in the clerk's office causing a low light working environment. Correct this issue to prevent injury to court personnel.	\$ 3,627 5,144	\$ 5,144	100
206 FM-0059471	Imperial	Imperial County Courthouse	13-A1	2	HVAC - Replace failed 25 ton compressor unit on the HVAC system. Unit is currently inoperable and the system is currently operating on a redundant unit. This work is necessary to ensure redundancy is back in place and the system is fully operational through these critical units. HVAC - Replace failed components on chiller #1 including a TXV, filter drier, transducer, pressure transducer, high	\$ 18,650	\$ 18,650	100
207 FM-0059473	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	pressure switch, site glass, and solenoid coil. Chiller #1 is currently inoperable and off line leaving only one chiller in operation (no redundancy) to provide cooling to the Court MDF room.	\$ 7,111	\$ 7,111	100
208 FM-0059474	Kern	Bakersfield Superior Court	15-A1	1	Elevators, Escalators, & Hoists - Replace worn and deteriorating cables and ropes with new. Elevator Car 2 Regulatory Compliance PM uncovered worn cables and ropes and to be replaced to return car to full compliancy. Elevators - Replace stepping relays for elevator #2. Existing relays are worn and are causing the elevator to not	\$ 54,985	\$ 34,443	62.64
209 FM-0059475 210 FM-0059476	Los Angeles Los Angeles	El Monte Courthouse Torrance Courthouse	19-01 19-C1	2	operate. Vandalism - Replace 16SF of cement backer-board wall, patch and paint. After-hours work. In-Custody damaged the wall in the basement lock up area, making a large hole.	\$ 3,384 5,010	\$ 1,967 \$ 5,010	58.12 100
211 FM-0059477	Los Angeles	Pomona Courthouse South	19-W1	2	Plumbing - Replace 14 feet of 5 inch cast iron pipe and fittings. 5 inch cast iron drain line is deteriorated and leaking. Environment testing and remediation needed due to leaking sewage line. HVAC - Remove and relocate existing temperature sensor to the adjacent office space (50'). The sensor is in a south	\$ 13,856	\$ 12,628	91.14
212 FM-0059478	Solano	Old Solano Courthouse	48-A3	2	facing, glass enclosed hallway and causes the adjacent office to get very cold. Relocating the sensor will remedy the problem. Electrical - Replace one (1) 60 Amp automatic transfer switch with one (1) upgraded 80 Amp, 480 volt automatic	\$ 2,551	\$ 2,551	100
213 FM-0059479 214 FM-0059480	Los Angeles Los Angeles	Pasadena Courthouse Alhambra Courthouse		2	transfer switch. Existing switch is nonoperational, which is a safety hazard. Vandalism - An individual clogged the men's urinal on the 3rd floor with paper towels. Water leaked down to the second and first floor. Multiple Floor to Ceiling Containments were set up (84 SF, 130 SF, & 70 SF). Water remediation was required and nine ceiling tiles were replaced.	\$ 9,413	\$ 6,528	69.35 86

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACIUITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Energy Efficiency – Electrical – Implementing energy efficiency lighting measures. Re-lamping and lighting retrofits for interior and exterior lighting throughout courthouse facility: exchange inefficient lighting (T12s, T8s, T5s, wall				
215	FM-0059481	Lake	South Civic Center	17-B1	3	packs, etc.) to more modern, energy and cost efficient lighting technology.	Ś	19,586	\$ 14,494	74
	FM-0059482	Contra Costa	Walnut Creek Courthouse	07-C1		Energy Efficiency – Electrical – Implementing energy efficiency lighting measures. Re-lamping and lighting retrofits for interior and exterior lighting throughout courthouse facility: exchange inefficient lighting (T12s, T8s, T5s, wall packs, etc.) to more modern, energy and cost efficient lighting technology.	\$	46,212		
						Energy Efficiency – Electrical – Implementing energy efficiency lighting measures. Re-lamping and lighting retrofits				
247	514 00 5 0403	A I I -	Fremont Hall of	04.114	_	for interior and exterior lighting throughout courthouse facility: exchange inefficient lighting (T12s, T8s, T5s, wall	_	440 764	440446	70.4
21/	FM-0059483	Alameda	Justice	01-H1	3	packs, etc.) to more modern, energy and cost efficient lighting technology. Energy Efficiency – Electrical – Implementing energy efficiency lighting measures. Re-lamping and lighting retrofits	\$	148,761	\$ 118,116	79.4
						for interior and exterior lighting throughout courthouse facility: exchange inefficient lighting (T12s, T8s, T5s, wall				
218	FM-0059484	Kern	Taft Court Bldg.	15-F1	3	packs, etc.) to more modern, energy and cost efficient lighting technology.	Ś	14,358	\$ 14,358	100
			Shafter/Wasco Courts			Energy Efficiency – Electrical – Implementing energy efficiency lighting measures. Re-lamping and lighting retrofits for interior and exterior lighting throughout courthouse facility: exchange inefficient lighting (T12s, T8s, T5s, wall	,	,	, , , , , , , , , , , , , , , , , , , ,	
219	FM-0059485	Kern	Bldg.	15-E1	3	packs, etc.) to more modern, energy and cost efficient lighting technology.	\$	20,706	\$ 18,625	89.95
220	FM-0059486	Santa Clara	Downtown Superior Court	43-B1	2	HVAC - Cafe A/C failed - Replaced failed (1) liquid line drier, (1) distributer tube cap. Flush system with nitrogen and condenser coil to remove restrictions, pressure test with nitrogen for leak test. Recharge system with fresh refrigerant. One (1) Spot cooler for temporary cooling - Affecting court café cooling system.	\$	7,867	\$ 7,867	100
			Santa Clara							
221	FM-0059487	Santa Clara	Courthouse	43-G1	2	Electrical - Replace (1) failed coolant seal and (1) alternator - currently affecting courts emergency power capability.	\$	4,049	\$ 4,049	100
222	FM-0059489	San Bernardino	San Bernardino Courthouse	36-A1	2	Elevators, Escalators, & Hoists - Remove all foreign equipment and piping unrelated to the elevators in the elevator mechanical room and patch wall once removed. Install door hardware that automatically locks. Install vent in elevator machine room door. This work is necessary in order to comply with item #'s 1, 2, 5, 6, 7, and 8 noted on a recent preliminary order SWO 2406915 & 2406916.	Ś	9,539	\$ 9,123	95.64
	0000 100	Jea.ae	oour arrouse	507.1		COUNTY MANAGED - HVAC - Water intrusion from condensation on HVAC unit caused mold and water remediation	Ψ	3,555	3,123	33.01
223	FM-0059490	Los Angeles	Hall of Records	19-AV1	1	requirement.	\$	3,707	\$ 3,707	100
224	FM-0059491	Los Angeles	Chatsworth Courthouse	19-AY1	2	Electrical - Provide and install new level probe monitor and provide calibration certificate. Generator diesel tank "level probe" is not working and generate a loud alarm sounding inside building, and cannot monitor fuel spill.	\$	4,862	\$ 4,074	83.8
		5	Inglewood			Elevators, escalators, & hoists - Replace brakes on elevator #4. Brakes are failing, causing the elevator to stop	Ė	,-,-	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
225	FM-0059492	Los Angeles	Courthouse	19-F1	2	approximately 2 feet below floor level.	\$	13,509	\$ 10,072	74.56
226	FM-0059493	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Fire Protection - Replace one (1) six inch butterfly valve on sprinkler system. Valve is leaking.	\$	5,177	\$ 3,806	73.51
						Roof - Replace 250 sq. ft. of single ply roofing material & re-waterproof 50sqft of exterior wall that water is				
227	FM-0059494	Contra Costa	Family Law Center	07-A14	2	weeping into the building stairwell.	\$	14,671	\$ 14,671	100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Fire Protection - Replace OS&Y Valve and handle. Remove FDC connection from underground. Bring above ground and replace connection with new updated connection. (8") OS&Y Valve is missing handle to operate when needed.				
			Parking Structure-Lot			The valve itself is corroded and needs to be replaced. The (4") FDC or Fire Department Connection is underground,				
228	FM-0059495	Los Angeles	53 Pasadena Court	19-J3	2	corroded and inoperable should it be needed in an emergency.	Ś	4,033	\$ 2,797	69.35
		<u> </u>				Fire Protection - Replace 2 door arm closures. Post exit signs and exit arrows on the West and East side of building.		,	, , ,	
229	FM-0059497	San Diego	Kearny Mesa Court	37-C1	2	Fire Safety Correction Notice 01-37-11-0090.	\$	3,326	\$ 3,326	100
			Civic Center			Fire Protection - Replace 14 failed heat detectors. Work to be done during off hours to prevent possible disruption				
230	FM-0059498	San Francisco	Courthouse	38-A1	2	to court proceedings. Faulty heat detector to cause false fire alarm.	\$	6,240	\$ 6,240	100
						HVAC - BAS install new software onto new workstation with updated OS to address licensing issue - 1. Back up database, license, and TCP/IP configurations, 2. Configure a new BAS workstation with Windows 7, 3. Load and configure BAS software on the new machine, 4. Upload saved databases to the new machine, 5. Verify the				
			Northern Branch			operation of the new machine, 6. Provide project management, installation, and commissioning.7. Service rates to				
231	FM-0059499	San Mateo	Courthouse	41-C1	2	apply to conditions outside this agreement.	\$	12,766	\$ 10,623	83.21
232	FM-0059500	Los Angeles	Airport Courthouse	19-AU1	2	Elevators, Escalators, & Hoists - Replace failed drive motor on Elevator #1 and adjust floor to floor settings. The drive unit keeps blowing amp traps, and-causing the elevator to stop responding. Elevator currently out of service. Grounds and Parking Lot - Remove and replace approx. 736sq. ft. of concrete, 90 sq. ft. of asphalt, and remove 2	\$	31,249	\$ 24,115	77.17
222	FM-0059501	Riverside	Family Law Court	33-A1	2	large Tijuana trees with approx. 200sq. ft. of roots located at the entrance courtyard to the Court. The trees have roots that are lifting concrete and causing significant tripping hazards. The roots will need to be completely removed or concrete will remain a hazard. Concrete will need to be broken up and removed with new concrete poured after roots have been removed.	ė	15,272	\$ 15,272	100
233	1141 00000001		. a.m.y Law Court	22 VI		Elevators, Escalators, & Hoists - Re-stud damaged fire access panel door on the elevator operating panel and	7	13,414	۲۵,272	100
234	FM-0059502	San Bernardino	San Bernardino Justice Center	36-R1	2	replace failed hinge assembly. Custody Elevator #H2 has a damaged fire access panel door and in-custody are able to open the fire access panel door, creating a potential safety security issue.	\$	5,339	\$ 5,339	100
						COUNTY MANAGED - Interior Finishes - Relocate the 753 SF Superior Court IT office located on the HOJ 4th floor to the HOJ 6th floor by renovating 800 SF of existing office, break room and storage area now occupied by the County of San Diego Probation office. Child Support, Mental Health and Revenue and Recovery office in the HOJ will need				
235	FM-0059503	San Diego	Hall of Justice	37-A2	2	to renovate a portions of the 4th, 5th and 6th floors.	\$	163,045	\$ 163,045	100
236	FM-0059504	Los Angeles	Pasadena Courthouse	19-J1	2	Interior Finishes - Replace damaged ceiling (4' X 5'), wall (3' X 5'), replace damaged framing. Basement ceiling crumbling due to age. Falling pieces could cause head injury or trip hazard to personnel: ACM environment. Plumbing - Remove and dispose of ACMs; Replace 5 disconnected porcelain drinking fountains with stainless Steel	\$	8,128	\$ 5,637	69.35
227	EM OOFOEOE	Contra Costa	George D. Carroll Courthouse	07-F1	2	fountains, with filtration; Install filters on the 2 existing stainless fountains and on the 2 breakroom sinks; install 9 new shutoff valves; Cut walls to accommodate new fountains; touch up paint; Dispose of removed items existing drinking fountains are disconnected because they are rusted and stained; The water was tested and found to be drinkable but filtering was recommended.	ė	62 050	¢ 47.004	74.00
23/	FM-0059505	COIILIA COSTA	Courtilouse	U/-F1		uninable but internig was reconfinenced.	Þ	63,850	\$ 47,881	74.99
	FM-0059506	Los Angeles	Norwalk Courthouse	19-AK1	2		ċ	6,651	\$ 5,655	85.03

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Bellflower			Exterior Shell - Barrier Fence - Construct a new galvanized metal fence, 2' h X 16.5' w X 14.5' on top of the wall to prevent trespassing in the diesel tank enclosure. Homeless people are camping out in the diesel tank enclosure.				
239	FM-0059507	Los Angeles	Courthouse	19-AL1	2	They are jumping over the diesel tank wall to hide their belongings and are smoking in that area. Interior Finishes - Removal and disposal of loose 9x9 VCT floor tiles from 3rd, 4th, and 5th floor secure hallways	\$	7,954	\$ 6,199	77.94
240	FM-0059508	Los Angeles	Norwalk Courthouse	19-AK1		approximately 120 pcs. Multiple floor tiles coming loose in back hallway on 3rd, 4th & 5th floors. Causing a tripping hazard for employees working in the areas.	\$	6,808	\$ 5,789	85.03
241	FM-0059509	Alameda	Wiley W. Manuel Courthouse	01-B3		Plumbing - Replace failed leaking floor drain in the 3rd floor Jury Men's Restroom to include surrounding concrete and tile floor finishes.	\$	7,715	\$ 6,465	83.8
241	FIVI-0059509	Alameua	Courtilouse	01-03		and the noor misnes.	Ş	7,715	\$ 0,403	03.0
242	FM-0059511	Riverside	Larson Justice Center	33-C1	1	Elevators, Escalators, & Hoists - Replace failed hydraulic motor for the judges elevator. Elevator is currently non- operational. Judges are using public elevators which is causing a concern for their safety riding with public.	\$	19,899	\$ 19,899	100
243	FM-0059512	San Diego	County Courthouse	37-A1	1	Electrical - Re-Lamp Dept. 4 Courtroom due to "inadequate lighting/low light conditions caused from over 50% of the lights are burned out. All work to be performed after hour in known ACM environment. Set up a 30ft x 30ft containment, replace 100 T8 lights and 11 ballasts, clean diffusers, perform air testing, and dispose of ACM waste.	\$	9,804	\$ 9,804	100
244	EM 0050512	France	D. F. Siala Counth auga	10.01	2	Plumbing - (1) Cut out and replace leaking water line joint above the ceiling in the first floor Self Help restroom and re-insulate piping; (2) Remove approximately 25 sf of damaged hard deck ceiling and install new sheetrock, mud, sand smooth and paint to match existing ceiling; remove and reinstall bathroom partitions and lighting sensor - A	ć	0.653	¢ 0.053	100
244	FM-0059513	Fresno	B.F. Sisk Courthouse	10-01	2	joint in the water line leaked, causing damage to the hard deck ceiling. Electrical - Security Cabling - Provide, install, terminate, test and label about 480 feet of 6-strand MM fiber, OM4 with LC connectors from DVR Room A204 to Server Room B245; provide and install (2) wall mount fiber enclosures;	Ş	9,652	\$ 9,652	100
245	FM-0059514	Fresno	Juvenile Delinquency Courthouse	10-P1	2	provide and install (3) 2-inch Hilti Fire Sleeves - Fiber cabling to replace existing copper cabling that intermittently fails, crashing the building video surveillance system, and to connect to the new DVR Cisco network switch provided by the JCC tech refresh program.	\$	5,989	\$ 5,989	100
246	FM-0059515	Los Angeles	Bellflower Courthouse	19-AL1	1	Plumbing - Pipe Leak - Replace 14' of 2" main domestic copper line that is defective. Containment was set-up and water remediation was performed. The leaking pipe dripped down to Holding Cell D and onto the floor.	ć	18,615	\$ 14,509	77.94
240	I IVI-0033313	LOS Aligeies	Van Nuys Courthouse	13-ML1		HVAC - Replace failed 20 HP VFD (AHU #11 Supply), 7.5 HP VFD (AHU #11 Return), 7.5 HP VFD (AHU #12 Hot Deck)	٧	10,013	14,509	77.94
247	FM-0059516	Los Angeles	West	19-AX2	1	which is because no air flow to multiple areas to the courthouse.	\$	21,226	\$ 17,083	80.48
248	FM-0059518	Los Angeles	Norwalk Courthouse	19-AK1	1	HVAC - Replace failed 1/2 HP pump. Boiler #4 pump is not providing hot water to the HVAC system. Elevators, escalators & hoists - Elevators 9 & 10 - Install earthquake devices to elevators 9 & 10 to satisfy	\$	12,388	\$ 10,534	85.03
249	FM-0059522	San Francisco	Hall of Justice	38-B1	2	requirements of preliminary order issued by state inspector.	Ś	16,016	\$ 16,016	100
,5	5555522		Stanley Mosk	30.51		Elevators, escalators, & hoists - Remove and replace traveling cables on elevator #3. Existing cables got wet and	_	10,010	, 10,010	100
250	FM-0059527	Los Angeles	Courthouse	19-K1	2	shorted out. Elevator is down until cables can be replaced.	\$	16,463	\$ 16,012	97.26

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACIUTY MODIFICATION PROGRAM SHARE % OF COST
			Clara Shortridge Foltz			Plumbing - 19th Floor Secured Hallway adjacent to 19-707, one 1ft x 1ft ceiling tile has fallen. The County drained an AHU resulting in water leaking down through the ceiling causing the tile to fall. Technician found no plumbing				
			Criminal Justice			leak. Water originated from ductwork condensation HVAC system adjusted to alleviate condition. Remediation				
251	FM-0059528	Los Angeles	Center	19-L1	1	vendor replaced (1) 1'x1' ceiling tile.	\$	37,610	\$ 37,6	0 100
			Bill Santucci Justice			Interior Finishes - Remove damaged Data Boxes in court rooms and install new updated data boxes The Data				
252	FM-0059531	Placer	Center	31-H1	2	boxes in the court rooms are damaged causing a trip hazard.	\$	2,900	\$ 2,90	0 100
						Security - Holding Area - Remove and replace old control panel software with new. Current software is freezing and				
						causing elevators to stop uncontrollably resulting in entrapments and leaving cell doors unlocked. This is causing a				
						grave security concern, compromising the safety of the deputies and in-custodies. Vendor has identified the				
						software as the issue. Work includes firmware update to ECON controllers, along with comprehensive testing and				
253	FM-0059532	Riverside	<u> </u>	33-C1	1	onsite hardware and software training.	\$	14,781	\$ 11,9	5 80.81
			Bellflower							
254	FM-0059534	Los Angeles	Courthouse	19-AL1	2	HVAC - Replace failed hot water circulating pump on boiler 2. Boiler is not working.	\$	4,220	\$ 3,2	9 77.94
						Roof - Restore approx. 9,600sqft of flat roof. Prep existing roof. Reseal curb corners, pipe penetrations, and coping				
						cap seams. Prime roof with All Knight Primer at a rate of 1/2 gallon per square. Install one coat of White Star				
					_	Coating at a rate of two gallons per square. Broadcast white rock in the White Star coating. Manufacturers 10-Year	_			
255	FM-0059535	San Joaquin	Lodi Branch- Dept. 2	39-D2	2	Warranty included.	Ş	98,733	\$ 98,7	3 100
						Fire Protection - Resurface deteriorating above ground diesel storage tank and add decal to prevent further rust &				
250	EN4 00E0E3C	Los Angolos	Compton Courthouse	10 401	2	leaks. Apply 2-part epoxy coat on 332sf of the tank (top & 4 sides). Water was found in the secondary containment of the AST causing rust, damaging the tank.	ċ	7.001	4.6	
250	FM-0059536	Los Angeles	Compton Courthouse Gordon Schaber	19-AG1		Of the AST causing rust, damaging the tank.	Ş	7,081	\$ 4,68	3 66.13
			Sacramento Superior			Grounds and Parking Lot- Safety - Saw-cut (27) linear feet of 6" thick concrete steps and reshape stair edges in (8)				
257	FM-0059538	Sacramento	Court	34-A1	2	locations that may cause a tripping hazard - Public safety.	ċ	7,370	\$ 7,3	0 100
237	1101-0033338	Sacramento	Modesto Main	34-A1		HVAC - Replace (2ea) 2-7/16" failed return fan motor bearings - return fan down no air supply to entire courts wing	Ą	7,370	7,5	0 100
258	FM-0059539	Stanislaus	Courthouse	50-A1	2	of facility.	Ś	24,288	\$ 24,28	8 100
	0000000			507.1		Electrical - Install two new circuits from breakers 1 and 3 in the Historic Courthouse. Run 200' of conduit and wire.	Ψ	2 .,200	Ţ 2.,j=.	100
259	FM-0059540	Napa	Historic Courthouse	28-B1	2	Install two new outlets.	Ś	6,412	\$ 6,4:	2 100
						HVAC - Replace two (2) EZ float systems. One for cooling tower #1 and one for cooling tower #2. Water level in the	·	<u> </u>	Í	
			Chatsworth			cooling towers cannot be maintained correctly, causing cavitation in the pumps due to low water levels.				
260	FM-0059541	Los Angeles	Courthouse	19-AY1	2	Temperature control cannot be maintained due to constant variance of water levels.	\$	8,765	\$ 7,34	5 83.8
			Van Nuys Courthouse			HVAC - Replace failed (4) bearings, (1) coupling, (1) drive pulley on supply, (4) new belts fan on AHU #7 that has				
261	FM-0059542	Los Angeles	East	19-AX1	1	caused no supply air on the 7th floor.	\$	12,100	\$ 10,8	9 89.74
						HVAC - Replace Exhaust fan #3. Fan motor is overheating and bearings are wearing down. Should motor fail,		-		
262	FM-0059543	Los Angeles	Pasadena Courthouse	19-J1		exhaust to all restrooms will not work causing health hazard.	\$	5,419	\$ 3,7	8 69.35
			San Fernando			Exterior Shell - Replace (1) Lift Master operator to the sally port exit gate that is not operating correctly which is				
263	FM-0059544	Los Angeles	Courthouse	19-AC1	2	causing a safety concern.	\$	4,376	\$ 3,6	0 83.41
1		l	Van Nuys Courthouse			Exterior Shell - Replace (14) damaged slats and the bottom edge of the roll-up gate. Sally Port exit gate in the rear	١.		l .	
264	FM-0059545	Los Angeles	West	19-AX2	1	of the building was closed on a Sheriff's bus.	\$	17,555	\$ 14,1	8 80.48

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
265	FM-0059546	Los Angeles	Downey Courthouse	19-AM1	2	HVAC - Replace one (1) circulation pump for Liebert drycooler. Pump has a leak and is not allowing condenser to work at its peak, which is compromising its ability to keep IT equipment cool.	Ś	7,075	\$ 5,92	
	FM-0059547	Kern	Taft Courts Bldg.	15-F1	2	Electrical - Replace (12) 8" commercial Halide canned lights with LED retrofit kits and bulbs in Courtroom - Metal halide ballasts and bulbs to be replaced with Energy Efficient LED replacements.	\$	6,593		
267	FM-0059549	Orange	Betty Lou Lamoreaux Justice Center	30-B1	2	Fire Protection - Replace failed heat exchanger and gaskets for the fire pump diesel engine. During the weekly fire pump run, the system started to overheat and went into high temperature alarm due to the failing heat exchanger. The replacement of the heat exchanger is necessary due to age of the equipment and for the equipment to run properly without failure and compromise the facility.	\$	6,248	\$ 4,99	5 79.95
268	FM-0059550	Los Angeles	Norwalk Courthouse	19-AK1	2	Interior Finishes - Replace failing ceiling plaster in the Basement locker room. Its deteriorating and ceiling has a large visible hole. Replace ceiling drywall, patch and paint ceiling. Restore approximately 77 sq. ft. of plaster ceiling.	\$	8,422	\$ 7,16	1 85.03
269	FM-0059552	Alameda	Hayward Hall of Justice	01-D1	2	Plumbing - Replace failed 100 gallon high efficiency condensing type domestic water heater.	\$	18,174	\$ 16,04	8 88.3
270	FM-0059553	Los Angeles	El Monte Courthouse	19-01	2	Interior Finishes - Replace failed (1) one double doors and hardware, doors do not close properly. Fire doors do not secure properly. Fire and life safety concern	\$	10,579	\$ 6,14	9 58.12
271	FM-0059555	Los Angeles	El Monte Courthouse	19-01	2	HVAC - Rebuild Condenser pump #3. Pump is leaking and not working.	\$	3,950		
272	FM-0059556	Los Angeles	Downey Courthouse	19-AM1	2	Interior finishes-Install forty-nine (49) new evacuation signs. Signage needed for proper exit of building during an emergency. Correction notice by City Fire Department.	\$	11,231	\$ 9,40	0 83.7
273	FM-0059557	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Holding Cell - Replace (1) defective electrical lock cylinder. Lock-up Holding Cell door is not opening properly.	\$	2,569	\$ 1,79	8 69.99
			Stanley Mosk			Electrical - Remove electrical floor monument and install electrical outlet onto wall to feed power to printers.		•		
2/4	FM-0059558	Los Angeles	Michael D. Antonovich Antelope	19-K1	2	Electrical floor mount with extension cords are causing a tripping hazard. HVAC - Install (1) new motor brush kit and factory install grounding kit. Chilled water pump motor is failing and	\$	3,823	\$ 3,82	3 100
275	FM-0059559	Los Angeles	Valley Courthouse East County Regional	19-AZ1	2	making loud sound from the motor bearings resulting in loss of cooling to the building. Elevators, Escalators, & Hoists - Replaced two (2) control transformers, one (1) photo-eye and a safety edge cord. In-	\$	4,917	\$ 3,61	4 73.51
276	FM-0059560	San Diego	Center	37-I1	2	Custody Elevator #9 had a burning smell when traveling due to two (2) failed control transformers.	\$	9,062	\$ 9,06	2 100
277	FM-0059561	Los Angeles	Whittier Courthouse	19-AO1	1	Plumbing - Replace 10 feet of 1" domestic water line that is leaking through the wall of the employee restroom behind the sink. Water remediation, containment had to be performed.	\$	38,756	\$ 38,75	6 100
278	FM-0059564	Orange	Central Justice Center	30-A1	2	Plumbing - Remove and replace 142 sq. ft of drywall and 100 ln. ft of cove base and remediate (treat, clean, dry) approx. 2800 sq. ft of jury rooms, courtrooms and cells on the 8th, 9th, and 10th floors due to flooding caused by an inmate. Roof- Replaced (1) defective roof drain and sealed 40x30 feet section of roof. Replaced 8 ceiling tiles, and replaced	\$	34,153	\$ 31,13	7 91.17
279	FM-0059565	Los Angeles	Whittier Courthouse	19-AO1	1	12x12 feet of carpet that was damaged. Water remediation. Roof leaked and affected 5 different areas from rain water.	\$	37,650	\$ 32,54	1 86.43

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACIUTY MODIFICATION PROGRAM SHARE % OF COST
			Pomona Courthouse			Roof - Replaced 40 sq. ft. of roof. Rain water was leaking down to the 7th floor Lieutenants office from roof top through ceiling, approx. 1 gallon of rain water. 16 sq. ft. of carpet wet/affected, containment and water					
280	FM-0059566	Los Angeles	South	19-W1	1	remediation.	Ś	46,082	\$	41,999	91.14
	FM-0059567	Fresno	Fresno County Courthouse	10-A1	2	Interior Finishes - Float and sand area of damaged wall panel in Department 54 courtroom and using adhesive install new 10 mil walnut wall veneer panel approximately 40" x 96". Stain to match existing as close as possible and paint edge of veneer black at panel joint - Wall damaged by in-custody individual.	\$	2,342		2,342	100
282	FM-0059568	Contra Costa	Richard E. Arnason Justice Center	07-E3	2	Exterior Shell - Install new threshold and pivots. Work to include coordinating electronics with subcontractor, remove door, threshold and top pivot; Dig out failing concrete (One bucket), under threshold and replace. Failing concrete and split threshold are causing the door to scrape and not close properly.	\$	13,264	\$	13,264	100
283	FM-0059574	Stanislaus	Hall of Records	50-A2	2	Grounds and Parking Lot - Install 40lf of 7ft tall chain link fence with man-gate around condensing unit - homeless persons are placing blankets over condensing unit at night causing unit to not function.	Ś	3,639	Ś	3,639	100
284	FM-0059575	Mendocino	County Courthouse	23-A1	2	Interior Finishes - Modify door swing in Courtroom F, Swing to return to original design and swing into children holding room. Reuse all existing hardware including special soundproofing material. patch ad Paint door frame as needed. The new swing will place the bailiff between the in-custody and unfettered access to the bench and judge. This is a safety concern.	\$	3,321	\$	3,321	100
285	FM-0059576	Amador	New Amador County Courthouse	03-C1	2	Security - Replace failed Pan Tilt Zoom surveillance camera, located in north parking lot, attached to light pole. This camera provides the Bailiffs with the capability to move the camera in all directions, zoom in and out. It is the primary camera for the front of building to see who is entering, leaving or loitering. It also provides a view of the parking lot. Security view of staff and public. It is the primary camera for the front of the building.	\$	9,734	\$	9,734	100
206	FM-0059577	Kern	Bakersfield Superior Court Modular	15-A2	2	HVAC - Replace failed PKU 7 and PKU 8 with Energy Efficient 2 ton Bard Heat Pump Wall Mount Units. PKU 7 & 8 need to be replaced due to failed compressor for PKU 7 and Calculated leak rate of 30% annually for PKU 8.	¢	12,705	Ś	12,705	100
	FM-0059578	San Luis Obispo	Paso Robles Courthouse	40-J1		Grounds and Parking Lot - Remove branches to mitigate safety hazard. Branches currently falling in the area of the south court house entrance walkway. Park benches also located in the area of the falling branches. Task needed for three large valley oak trees to have dead and dying branches removed. Remove dense areas to minimize risk of branches failing and reduce weight on extended limbs.	¢	3,500		3,500	100
		·	Stanley Mosk			Plumbing - 3rd Floor Main Jury Assembly Room #308, water leaking through ceiling, six (6) 1ft x 1ft ceiling tiles wet/affected. Water leaking from 2" cast iron pipe in the attic space, piping connected to the 4th floor Jury Room #408 drinking fountain. Plumber cleared drain line on drinking fountain. Remediation vendor replaced (6) 1'x1'	ç	-		,	
	FM-0059580	Los Angeles	Stanley Mosk	19-K1	1	ceiling tiles. Plumbing - 2nd Floor Women's Public Restroom, sink overflowed spilling water onto the tile flooring. 1in of water covers the 15ft x 20ft tile floor. Water leaked down to the 1st floor room 109, affecting four (4) 2ft x 2ft ceiling tiles, water leaked onto a office desk. Plumber cleared clogged drain line causing sink to overflow. Remediation vendor	\$	37,985		36,944	97.26
289	FM-0059581	Los Angeles	Courthouse Chatsworth	19-K1	1	replaced (4) 2'x2' ceiling tiles. Electrical-Retrofit twenty-six (26) lights with LED equivalent light fixtures using lift. Lights are burnt out, causing a	\$	30,550	\$	29,713	97.26
290	FM-0059582	Los Angeles	Courthouse	19-AY1	2	safety issue. LED retrofit will allow less energy usage and longer fixture life expectancy.	\$	25,890	\$	21,696	83.8

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Grounds and parking lot - Remove approx. 100 SF of asphalt to find water leak in irrigation line in two places, repair				
291	FM-0059584	Los Angeles	Glendale Courthouse	19-H1	2	leaks, and replace asphalt. Water is currently shut off to avoid wasting water, affecting the current landscaping.	\$	10,788	\$ 9,76	7 90.54
292	FM-0059585	Alameda	Fremont Hall of Justice	01-H1	2	HVAC - Replace failed air handler fan motor variable frequency drive (VFD)	Ś	7,102	\$ 5,63	79.4
	00055005					HVAC - Replace (2) deteriorated Bearings & install grounding Kit for AHU #6 Supply Fan Motor. Supply motor	-	.,===	7 5,55	
			Metropolitan		_	bearings have deteriorated, creating noise pollution & disrupting Court proceedings. Bearing failure will result in				
293	FM-0059586	Los Angeles	Courthouse	19-T1	2	loss of comfort cooling/heating, affecting the entire 5th floor. HVAC - Hot water expansion tank has a small rusted hole on the bottom of the tank causing a water drip. Weld	\$	4,819	\$ 4,55	94.54
						patch the hole on the tank to prevent major water leaks that would impact court operation, and cost a significant amount of money on other repairs. Vendor will test the tank after repair and return equipment to normal				
294	FM-0059587	Los Angeles	Alhambra Courthouse	19-I1	2	operation.	\$	2,912	\$ 2,50	1 86
295	FM-0059588	Los Angeles	Metropolitan Courthouse	19-T1	2	HVAC - Replace non-functioning (1) Compressor, (1) Contactor, (1) Filter Drier, (1) Run Capacitor & (1) Condenser fan motor. Add (4) lbs. of new R22 refrigerant. Condenser Unit is 1 of 3 necessary to keep elevator equipment cool to maintain operation.	\$	5,077	\$ 4,80	94.54
296	FM-0059589	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Remove/replace approx. 800SF contaminated carpet, (16) 2'x2' & (75) 1'x1' saturated ceiling tiles & (4) cubicle partitions. Sewage drain line back up on 5th flr affected 4th flr rms 403 & 403-K including (8) light fixtures. Work performed in known ACM environment. Remediation required due to category 3, black water contamination.	\$	54,850		
		_				Exterior Shell - Perform leak protection measures around HVAC and roof penetrations - Evidence of ongoing leak				
297	FM-0059590	Monterey	Juvenile Courthouse	27-E1	2	issues present, current leaks into courtroom and chambers detected.	\$	7,513	\$ 3,76	7 50.14
298	FM-0059591	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	Elevators, Escalators, & Hoists - Replace faulty mag switches (6 total) for the three (3) custody elevators. All 3 Custody Elevators occasionally fail due to the failure of the selector to confirm that it has passed each floor landing. Mag switches allow the selector to keep track of the floor selections.	¢	8,745	\$ 6,65	1 76.05
230	1101 0033331	Dernaramo	Metropolitan	3011	_	Exterior Shell - Board-up & Replace broken 25.9"x79" tempered glass for West Main entrance door. Glass was	7	0,743	ψ 0,03	70.03
299	FM-0059592	Los Angeles	Courthouse	19-T1	1	vandalized by an unknown individual. Incident occurred after hours.	\$	12,956	\$ 12,24	94.54
300	FM-0059593	San Bernardino	Fontana Courthouse	36-C1	2	Elevators, Escalators, & Hoists - Replace failing push button interface board. This work is necessary as there have been a couple of instances of intermittent issues associated with the top floor call button failing to activate and call the elevator. Grounds and Parking Lot - Landscaping - Cut up and remove large tree branch broke and fell onto the sidewalk and	\$	6,253	\$ 5,13	82.17
301	FM-0059594	Los Angeles	Stanley Mosk Courthouse	19-K1	1	street, off the corner of 1st and Hill Streets. Large branch removed by Landscape vendor; ABM called Arborist to examine tree and 3 others were found to be dead and were removed.	\$	8,850	\$ 8,60	3 97.26
302	FM-0059595	San Bernardino	San Bernardino Justice Center	36-R1	2	Elevators, Escalators, & Hoists - Replace failed Gen2 belt monitor on public elevator #7. This work is necessary as this is a critical safety issue requiring the elevator to be locked out until the failed belt monitor is replaced.	\$	4,003	\$ 4,00	3 100
303	FM-0059596	San Diego	East County Regional Center	37-l1	2	Elevators, Escalators, & Hoists - Replace power unit for the Dumbwaiter. Work to include replacing motor, pump, hydraulic valve, oil tank reservoir tank and hydraulic. Ground floor storage area Dumbwaiter is not working due to a Failed Hydraulic Unit.	\$	13,008	\$ 13,00	3 100

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
304	FM-0059597	Santa Clara	Hall of Justice (East)	43-A1	2	Door lock - Replaced (1) failed panic bar and trim lock for Dept. 24.	Ś	4,026	Ś	4,026	100
	FM-0059598	Fresno	B.F. Sisk Courthouse	10-01	2	Security - Remove and replace (1) hard drive for NVR1 (c drive); provide labor to reload back up files and set up all macros and software required; provide testing of the NVR and its macros used for recording and alerts - NVR1 hard drive is failing, dropping off-line and will not hold recordings.	\$	2,645		2,645	100
206	FM-0059600	Los Angeles	Torrance Courthouse	10.61		Vandalism - Board-up & Replace (1) 42"x 84" tempered glass pane on the main Entrance Door. An individual from the public kicked the glass door causing it to shatter.	Ś	12,956	\$	11,031	85.14
	FM-0059604	Tulare	South County Justice Center	54-l1		Fire Protection - Identify, remove and replace faulty 2-inch fire tamper control valve in Stairwell 2 on the first floor landing - The faulty device is causing a constant ground fault supervisory alarm on the fire alarm panel.	\$	2,894		2,894	100
308	FM-0059605	Los Angeles	Norwalk Courthouse Civic Center	19-AK1	1	Roof- Roof Leak - Replaced (2) 3 round roof drains, replaced (23) ceiling tiles, and replaced (8) carpet squares. Water remediation, and containment. Rain water was leaking from a roof drain into the 7th floor Jury Assembly Room in two areas. Electrical - Locate and correct coolant leak at emergency generator motor; drain/pressurize system; replace	\$	54,176	\$	46,066	85.03
309	FM-0059606	San Francisco	Courthouse	38-A1	2	seals/gaskets; test - Coolant contaminated oil discovered during PM.	Ś	22,992	Ś	22,992	100
			Santa Maria Courts,			Plumbing - Restore burst copper ceiling hot water line in Department 5 Chamber's restroom - Hot water line burst			, T		
310	FM-0059607	Santa Barbara	Bldgs. A + B	42-F3	1	at t junction and caused water intrusion to Judge's chambers restroom.	\$	19,143	\$	4,409	23.03
			Fremont Hall of			Vandalism - Replace (6) 24"x 36" mirrors in public restrooms which have been vandalized with etched gang					
311	FM-0059608	Alameda	Justice	01-H1	2	signs/offensive language graffiti.	\$	3,922	\$	3,114	79.4
312	FM-0059609	Napa	Criminal Court Building	28-A1	2	Fire protection - 1. The main control valve for the building, a wall mount Post Indicator Gate Valve doesn't shut all the way and lets the water pass by. Replace the 6 gate valve with flange x flange 6 gate valve with a 10 take out. 2. The Main feed at the 1st floor does not have any earthquake bracing. Install earthquake bracing. 3. The Main feed at the 3rd floor does not have an earthquake brace on standpipe. Install earthquake bracing.	Ś	12,645	Ś	12,645	100
						Plumbing - Replace 3' of 1" Copper Pipe & fittings. Copper pipe leaked from roof into 2nd flr secured hallway.	т.	,-,	7		
			Santa Monica			Replace (3) saturated 1'x1' ceiling tiles & Remediate 2'x20' VCT flooring due to category 2 contamination. Work					
313	FM-0059611	Los Angeles	Courthouse	19-AP1	1	performed in ACM know environment.	\$	63,230	\$	63,230	100
						HVAC - Replace failed compression plastic cooling lines for Variable Speed Drive systems on chiller 1 and chiller 2 (6					
314	FM-0059612	Fresno	B.F. Sisk Courthouse	10-01	2	lines each) with field installed, welded copper cooling lines.	\$	9,368	\$	9,368	100
315	FM-0059615	Los Angeles	Michael D. Antonovich Antelope Valley Courthouse	19-AZ1	2	Fire Protection - Replace panel batteries power supply, two (2) duct detector cover plates, and two (2) IQ panels. Remount smoke detector. During PM under SWO 2662460 these items failed and need to be rectified. Plumbing - Replace 10 feet of 2 inch cast iron pipe, and replace 10 feet of 5 inch cast iron pipe. Water remediation and containment. The waste line above the 1st floor ceiling was cracked and the smell created a health and safety	\$	3,859	\$	2,837	73.51
316	FM-0059617	Los Angeles	Pasadena Courthouse	19-J1	1	issue.	\$	22,500	\$	15,604	69.35
		J				Plumbing - Remove/replace cracked 2" cast iron P-trap pipe. Water leaked from 11th flr men's RR dept. F to 10th flr	Ė	,			
317	FM-0059618	Los Angeles	Compton Courthouse	19-AG1	1	Jury room contaminating approx. 130SF surface. Remediate category 2, grey water.	\$	32,550	\$	32,550	100

# FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
318 FM-0059620	Los Angeles	Chatsworth Courthouse	19-AY1	2	HVAC-Replace two (2) new bearings on AHU #3. Existing bearings are noisy and leaking lubricant.	Ś	5,506	\$ 4,614	83.8
	LOS Aligeles				COUNTY MANAGED - Interior/Exterior Finishes - Adjust height of interior stair rail throughout (4 levels), modify approach to building beginning at parking lot, add ramp to approach, modify ADA parking, modify basement restroom to include ACM abatement. Facility does not meet current ADA standards, complaint filed with the	J.			
319 FM-0059621	Monterey	Monterey Courthouse	27-C1	2	County who is managing party. HVAC - Dept. 1, 4 and 5 reheat coil controls valves and stats failed. Remove 3 each actuators and room sensors. Install 3 each new room sensors, electronic actuator and electronic thermostat. Installation requires new control wiring to court rooms. Complete wiring as required. Performed start up and operational testing of new equipment. Work to be performed after court hours. Currently reheat coils are controlled manually to maintain court room	\$	300,840	\$ 300,840	100
320 FM-0059622	Santa Cruz	Main Courthouse	44-A1	2	temperatures.	\$	7,609	\$ 7,609	100
		Van Nuys Courthouse			Plumbing - Unclogged drinking fountain that leaked from the 4th floor holding cell to the 3rd hallway. Replace (1)				
321 FM-0059625	Los Angeles	West New Madera	19-AX2	1	2x2 ceiling and erected 4x10 containment. HVAC - Replacement of the 3rd floor Jace for the EMS/DDC system. This controls sends communication from HVAC devices on the 3rd and 4th floor back to the Building Automation System (BMS) and without it we cannot control	\$	18,500	\$ 14,889	80.48
322 FM-0059626	Madera	Courthouse	20-F1	2	the HVAC on each floor.	\$	4,268	\$ 4,268	100
323 FM-0059627	Contra Costa	,	07-A3	2	HVAC - Replace Failed 25hp VFD Drive for AHU04 (court-exclusive) - Existing unit has failed and the AHU is running at full speed. Failure to replace the VFD will result in erratic space temperatures and wasted energy. Elevators, Escalators, and Hoists - Freight Elevator #1 stuck on 9th floor with doors open and not responding to calls. Elevator Tech on site evaluating problem. Only Freight Elevator in building. Tech found doors out of alignment	\$	7,993	\$ 7,993	100
224 514 0050620	Los Angeles	Stanley Mosk	10 1/1	4	and made temporary adjustments to return elevator to service. New FM is entered to replace the defective	4	10.250	ć 40.350	100
324 FM-0059628	Los Angeles	Courthouse Van Nuys Courthouse	19-K1	1	elevator doors. Elevators, Escalators, & Hoists - Remove and replace door operator motor, control board and cable assembly.	\$	10,250	\$ 10,250	100
325 FM-0059629	Los Angeles	West	19-AX2	2	Elevator # 1 doors are not opening.	\$	4,246	\$ 3,417	80.48
326 FM-0059630	Los Angeles			2	HVAC - Replace (1) VFD for AHU #6. Air handler for the 5th floor is continually tripping due to a faulty VFD.	\$	9,933	\$ 8,457	85.14
327 FM-0059631	Los Angeles	Metropolitan Courthouse	19-T1	2	HVAC - Remove nonfunctioning Air Handler Unit from ceiling and install (1) new replacement AHU, weld in & install (1) filter drier and sight glass, evacuate system & add 13 lbs of new R422D refrigerant. Air Handler C is leaking water near elevator equipment which can cause damage equipment & shut down the elevators.	\$	7,134	\$ 6,744	94.54
328 FM-0059632	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Replace approx. 10' of cracked 3" cast iron pipe, replace (5) 1'x1' saturated/damaged acoustic ceiling tiles. Pipe leaked in 7th flr DA's space affecting a 5'x5' section of ceiling tiles & VCT flooring. Work performed in known ACM environment. Remediation required due to Category 2, grey water contamination.	\$	32,575	\$ 21,542	66.13
329 FM-0059633	Los Angeles	Parking Structure Lot 48 Van Nuys Court Complex	19-AX6	1	Exterior Shell – Replaced (3) rods, (45) links and made necessary adjustments to the roll down gate in Judge's secure parking. Gate failed and bound up when going down.	\$	8,500	\$ 6,841	80.48

#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Roof - Install reinforcement to support (8) Roof rafters that have been found to be damaged. The roof is sagging				
330	FM-0059634	Los Angeles	Mental Health Court	19-P1	1	about 6 inches affecting department 95A and 95 Judges Chambers. This is current a safety issue.	\$	55,500	\$ 55,500	100
331	FM-0059635	Orange	Civil Complex Center ("CXC")	30-A3	2	Roof - Remove and replace two 2' x 4' leaking skylights, 34 of damaged roof edge, a failed 2' x 8' section of fascia board, failing split wall corner, and 15' of fractured cricket to correct leaks. Recent rains revealed multiple leaks in the Civil Complex Center roof, if not addressed, will cause serious damage to the building.	\$	4,688	\$ 4,274	91.17
			Van Nuys Courthouse		_	HVAC - Remove and replace two (2) air compressors. The air compressors are no longer serviceable and are not				
332	FM-0059636	Los Angeles	East	19-AX1	2	functioning properly. Grounds and Parking Lot - Restore approximately 29,000 SF of landscaping that was damaged by fire. Repair	\$	32,060	\$ 28,771	89.74
333	FM-0059637	Lassen	Hall of Justice	18-C1	2	irrigation and install weed barrier and cover with landscape rock on south side and north side of property - Recent fire damaged irrigation and burnt.	\$	28,500	\$ 28,500	100
334	FM-0059638	Fresno	B.F. Sisk Courthouse	10-01	2	Security - Replace failed outdoor PTZ security camera located in sallyport parking lot with one Vicon SN220W-L Outdoor/Pendant Network PTZ Dome, 1080p, ONVIVF-compliant camera, and program into existing video surveillance system.	\$	5,743	\$ 5,743	100
335	FM-0059641	Shasta	Main Courthouse	45-A1	2	Electrical - Emergency Generator - Replace and relocate a new 100kw 480v generator with integral fuel tank outside the building. The existing basement located 100kw generator is 61 years and can no longer pass a load test. There are no repair parts available and cannot be restored. The existing electrical room and fuel tank are no longer EPA compliant.	\$	275,000	\$ 191,703	69.71
	FM-0059643	Los Angeles	Pasadena Courthouse			Plumbing - Replace 10 feet of 4" cast iron waste line pipe and connectors that has a 4' crack leaking water onto the basement concrete floor next to the chillers.	¢	32,580	\$ 22,594	69.35
	FM-0059644	Los Angeles	Airport Courthouse	19-J1		Elevators, Escalators, & Hoists - Public passenger elevator #3 is stuck on the 1st floor and not responding. No entrapments.	\$	8,250	/	77.17
			Clara Shortridge Foltz Criminal Justice			Plumbing - Replaced a 3 foot section of 2" Cast Iron pipe and 2 No-Hub Couplings. 19th FIr. Conference Room 9-714 water leaking through ceiling from a cracked drain line in the Mechanical Room directly above the Conference				
338	FM-0059645	Los Angeles	Center	19-L1	1	Room. Water has affected one (1) 2ft x 2ft ceiling tile.	\$	36,650	\$ 25,212	68.79
220	FM-0059646	San Diego	County Courthouse	37-A1	2	HVAC - Replace one flex line coupling, and re-insulate 6 ft of 8 in piping and pump assembly. Chilled Water Pump #3 leaking due to failed flex coupling; water leaked onto basement pump room floor.	ć	2,872	\$ 2,224	77.42
339	<u> </u>	San Diego	South County Justice	57-A1	2	Exterior Shell - Replace 4 ea. failed upper door pivots on the main entry and exit doors with four new Rixson E-H345 door pivots - Pivots are completely worn with no more adjustments possible, causing doors to be misaligned and	Ş	2,072	\$ 2,224	77.42
340	FM-0059647	Tulare	Center	54-I1	2	not close properly.	\$	7,816	\$ 7,816	100
341	FM-0059648	San Diego	County Courthouse	37-A1		Elevators, Escalators, & Hoists - Replaced safety stop switch on 3rd floor escalator going down to the 2nd floor. It's non-operational due to faulty safety stop switch. HVAC - Replace failed Chiller internal components - (1 each) Oil level switch, Oil heater, Filter, drain condenser and	\$	4,135	\$ 3,201	77.42
342	FM-0059652	Santa Clara	Palo Alto Courthouse	43-D1		O-rings and gasket. Refrigerant will need to be recovered in tanks to drain oil and replace. Weekend work to shut down Chiller. HVAC - Replace failed Chiller internal components - (1 each) Oil level switch, Oil heater, Filter, drain condenser and O-rings and gasket. Refrigerant will need to be recovered in tanks to drain oil and replace. Weekend work to shut down Chiller. HVAC - Replace failed condensing unit and fan coil unit to maintain temperature and protect court critical	\$	18,462	\$ 12,192	66.04
343	FM-0059654	Los Angeles	Glendale Courthouse	19-H1	2	equipment. Failing unit services critical computer room equipment in room that must maintain temperatures of 70-75 degrees max.	\$	10,926	\$ 9,892	90.54

#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE		PRELIMINARY ESTIMATE		PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Interior Finishes - Remove and replace (1) broken piece of clear tempered / laminated glass with speak thru hole, letter pass thru and polished edges on the exposed edges of the glass replacement. Approx. sixe 62 x 63. Glass will									
			New Madera			be silicone to adjacent pieces - The middle section glass in shatter and needs to be replace before any further									
344	FM-0059657	Madera	Courthouse	20-F1	2	damage is done.	Ś	4,237	Ś	4,237	100				
						HVAC - Install a split HVAC system unit to provide air conditioning in the senior administrator's office. There is	Т.	.,		.,					
345	FM-0059658	Los Angeles	Norwalk Courthouse	19-AK1	2	currently no air to that location which causing health issues.	\$	41,710	\$	41,710	100				
						Elevators - Public elevators 1-4 floor tiles. Replace 120sq.ft of rubber tiles in Elevators 1-4. Work to performed in a									
						ACM environment. The current tiles are damaged with holes and cracks, causing a trip hazard in all the public									
346	FM-0059659	Los Angeles	Norwalk Courthouse	19-AK1		elevators.	\$	13,922	\$	11,838	85.03				
						Plumbing - Replace 10' of 4" cast iron waste line that is leaking water down into the 5th floor lockup cell. No									
347	FM-0059663	Los Angeles	Norwalk Courthouse	19-AK1	1	damage to the metal ceiling and the floor is made of concrete.	\$	38,600	\$	38,600	100				
			Parking Structure Lot 94 Airport			Fire Protection - Replace (1) faulty smoke detector in elevator lobby. Smoke detector failed and affected operations									
2/10	FM-0059664	Los Angeles	Courthouse	19-AU2	1	of the public elevator & employee elevator. Both elevators recalled to the first floor & stopped operating.	خ	6,950	خ	5,363	77.17				
346	FIVI-0033004	LO3 Aligeles	Courtifouse	13-AU2	1	Fire Protection - Replace packing, O Rings, lantern rings, case gasket, shaft sleeve and fittings for the Fire Pump -	۲	0,530	٦	3,303	//.1/				
			Bakersfield Juvenile			Minor rebuild of Pump will increase performance and extend lifetime as recommended during findings in annual									
349	FM-0059668	Kern	Center	15-C1	2	PM.	\$	4,061	\$	2,711	66.76				
								,		,					
						Fire Protection - Remove deadbolt lock (1); install new panic hardware (2) w/upper rods only; cover holes -									
350	FM-0059670	San Francisco	Hall of Justice	38-B1	2	Courtroom doors have non compliant deadbolt lock and one failed panic bar making it a non compliant exit.	\$	10,651	\$	10,651	100				
						HVAC - Mechanical room AHU 19, 2nd floor - Remove and replace defective shaft, bushings, and bearings with new.									
						Work includes mechanical analysis, laser alignment, and balancing. The air handler unit is not functioning properly,									
351	FM-0059671	Orange	Central Justice Center	30-A1	2	making very loud noises and disturbing the neighboring courtrooms.	\$	8,217	\$	7,491	91.17				
252	514 0050675	W =	Amin / Laurant Burnah	45.114	_	Electrical - Replace inoperable Control Board for Emergency Stand-by Generator - control board burnt out and no	_	0.440	_	F 727	50.04				
352	FM-0059675	Kern	Arvin/ Lamont Branch Calaveras Superior	15-H1	2	longer powering up Generator in the event of power loss to the facility. HVAC - The airtrol tank has developed a leak thru a cracked machine welded seam in the tank. We had made an	\$	9,419	\$	5,737	60.91				
353	FM-0059676	Calaveras	Court	05-C1	2	attempt to repair.	خ	6,830	خ	6,830	100				
333	1101-0033070	Calaveras	East Los Angeles	03-01		Fire Protection - Restore building fire system fire pump. Building Fire System Fire Pump is not drawing in water, no	٧	0,030	٦	0,830	100				
354	FM-0059681	Los Angeles	Courthouse	19-V1	2	water in the event of a fire.	Ś	14,870	Ś	11,557	77.72				
							7	,	T						
			Metropolitan			HVAC - Replace two (2) failing 300-ton York centrifugal chillers and related cooling towers. Work to include									
355	FM-0059682	Los Angeles	Courthouse	19-T1	2	engineering, plan review, and ACM abatement. This original equipment was retrofitted 10 years ago.	\$	2,254,788	\$	2,131,677	94.54				
			Modesto Main			Exterior Shell - Replace 2 broken windows in south (secured) stairwell. Apply opaque film on interior and mirrored									
356	FM-0059685	Stanislaus	Courthouse	50-A1	2	tint on exterior - windows are elevated and will require lift (windows were shot out).	\$	6,697	\$	6,697	100				
						Fire Protection - Replace defective components on two (2) fireman phones. During "fireman phone jacks									
		l				inspection" we found two (2) phone jacks on the 3rd floor without communication to the fire control and with	١.		Ι.						
357	FM-0059686	Los Angeles	Pasadena Courthouse	19-J1	2	firefighters during an inspection.	\$	4,650	\$	3,225	69.35				

#	FM NUMBER	LOCATION	LOCATION FACILITY NAME		Clara Shortridge Foltz	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACIUTY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Clara Shortridge Foltz Criminal Justice			Plumbing - Replace 10' of 2" domestic water line with pin whole leak causing water to drip down light fixture onto a						
358	FM-0059687	Los Angeles	Center	19-L1	1	3'x3' section of carpeting next to the witness stand.	Ś	42,555	\$ 42,555	100		
330	1101 0033007	LOS Angeles	center	13 11		Plumbing - Detention Drain Line - Saw/cut and remove and replace 3ft x 6ft section of concrete to remove drain	٧	42,333	7 72,333	100		
						cable stuck in the drain line. Plumbing vendor called out several times to unclog due to cable stuck in the drain line.						
359	FM-0059689	Orange	North Justice Center	30-C1	2	Original clog and cable are causing sewage backups.	Ś	14,500	\$ 14,500	100		
333	0000000			50 01		HVAC - Restore deteriorating Chiller water pump for chiller #1, pump is leaking and wasting water. Remove and	Υ	1.,500	ψ 1.,500	, 100		
360	FM-0059691	Los Angeles	Pasadena Courthouse	19-J1	2	disconnect (1) CHW Pump for rebuild. Install (1) replacement coupling.	Ś	10,870	\$ 7,538	69.35		
						Interior Finishes -Replace 251 sq. ft. of carpet with 12x12" carpet tiles and 200ft of 4" of rubber cove base to	т		,,,,,,,			
			South County			mitigate risk hazard. Jury Lounge carpet is very worn with multiple carpet patches where seams are frayed. This is a						
361	FM-0059692	San Diego	Regional Center	37-H1	2	high traffic area and currently posing as a significant trip hazard.	Ś	13,871	\$ 13,871	100		
301	0033032		Tragitation Control	07.112		Plumbing - Replaced approximately 4 feet of 3 inch Cast Iron drain pipe. Remediation vendor replaced (4) 2'x2'	Υ	10,071	ψ 10,071	100		
						ceiling tiles and cleaned water from 3'x2' section of tile flooring. Water is leaking from the 4th floor, Janitor's Closet						
			Stanley Mosk			mop sink drain pipe (3" cast iron drain pipe) down to the 3rd floor Judge's lounge secured hallway, wetting (4) 2'x2'						
362	FM-0059693	Los Angeles	Courthouse	19-K1	1	ceiling tiles and a 3'x2' section of tiles flooring.	Ś	37,325	\$ 37,325	100		
302	1101 0033033	Los / ingeles	Santa Monica	13 1(1	_	Exterior Shell - Replace (3) broken 30"x30" glass window panes along 1st and 2nd flr front façade. High lift	7	37,323	ÿ 37,3 <u>2</u> 3	, 100		
363	FM-0059695	Los Angeles	Courthouse	19-AP1	2	equipment required. Broken glass is a safety hazard for employees.	¢	2,828	\$ 2,220	78.49		
	FM-0059696	Los Angeles	Edmund D. Edelman Children's Court	19-Q1		Interior Finishes- Replace 1,060 sq. ft. of damaged floor tiles in the 2nd floor clerk's office. Current tiles are currently causing a trip hazard for employees.	\$	10,147				
365	FM-0059697	Solano	Hall of Justice	48-A1	2	Exterior shell - Repair doors 2 that are currently unusable due to failed door pivots; LOTO security sounder and sensors; Remove double doors; Remove and replace (2) failed door closer pivots, and (2) failed bottom door pivots; Re-install doors with new hardware, at correct elevation. Door is unusable because of worn out hardware.	\$	4,574	\$ 3,331	72.82		
200	ENA 00E0C00	Los Angeles	Albanabaa Caustbausa	10.11	,	Elevator - Custody elevator #5 replace failing operation selector unit. Sheriffs personnel is forced to use judges	ć	0.464	¢ 0.420	0.0		
366	FM-0059698	Los Angeles	Alhambra Courthouse	19-11	2	elevator #4 to transport inmates.	>	9,464	\$ 8,139	9 86		
267	ENA 00E0C02	Los Angolos	Van Nuys Courthouse	10.472	,	Elevators, Escalators, & Hoists - Replace switches, leveling device, and inductors- Elevator is out of service due to	ے ا	4 572	¢ 3.000	00.40		
36/	FM-0059699	Los Angeles	West	19-AX2	2	not leveling on the floors.	>	4,572	\$ 3,680	80.48		
368	FM-0059701	Los Angeles	Pasadena Courthouse	19-J1	1	Plumbing- Replace 4ft of 3 from the domestic hot water supply and return pipes. The 2 pipes are currently leaking. ACM environment, and containment. Water is leaking from a domestic hot water supply and return line from 14ft up in East side Basement Mechanical Room on to the concrete floor and from above the generator room on to the concrete floor.	\$	41,585	\$ 28,839	69.35		
			North County									
			Regional Center -			COUNTY MANAGED - HVAC - Central Plant. Ten (10) rooftop exhaust fans have failed or are failing. Remove old fans						
369	FM-0059702	San Diego	South	37-F1	2	and replace with new fans. Install electrical as needed and test operation when complete.	\$	3,945	\$ 3,945	100		
			Clara Shortridge Foltz			Plumbing - Water is leaking from the ceiling of the 19th floor, secure hallway wetting (2) 1x1 ceiling tiles. Plumbing						
			Criminal Justice			vendor found no leaking pipes. Water sourcing from condensation on the HVAC ductwork. Tech adjusted room						
370	FM-0059703	Los Angeles	Center	19-L1	1	temp. to alleviate condensation problem.	\$	38,890	\$ 38,890	100		

#	FM NUMBER	LOCATION	, ,		PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Vandalism - Mirrors were etched - Replace (1 each) mirror with anti-graffiti film - Sand, patch and paint partitions in				
371	FM-0059705	Santa Clara	Hall of Justice (East)	43-A1	2	the men public restroom on 1st floors.	\$	7,148	\$ 7,14	3 100
						Fire Protection - Remove (1) damaged fire rated door & surface mount closer w/NRP BB Hinges. Existing door is				
372	FM-0059706	Los Angeles	Compton Courthouse	19-AG1	2	splitting compromising its integrity.	\$	4,407	\$ 2,91	4 66.13
							\$ 1	2,283,200	\$ 11,168,85	1

ITEM#	CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	тотаг	ESTIMATED CFR COMMITMENT (CFR Term)
						Establish annual budget to address multiple small projects, under \$50,000 each (for either non-rule 10.810				
1	19-CFR046	Los Angeles	All	All	Annual Budget	·	Ongoing	TCTF	Ş	650,000
				810 West Main		Two-year lease extension for storage of Civil, Criminal, Traffic, and Family Law files. (1/16/2017 -				
2	24-CFR014	Merced	24-F2	Street	Lease Extension	1/15/2019).	Two Years	TCTF	\$	65,904
						Establish annual budget for facilities-related projects either rule 10.810 or non-rule 10.810 allowable) in all				
3	24-CFR015	Merced	All	All	Annual Budget	Merced court facilities.	Ongoing	TCTF	\$	25,000
4	34-CFR007	Sacramento	34-E1	William Ridgeway Family Relations Courthouse	Facility Modification	Convert open office space into a Family Child Support courtroom, as well as two attorney/client conference rooms, a bench, installation of spectator seating, and add a restroom to judicial chamber. This will streamline child support operations and reorganize the juvenile dependency calendars to reduce backlogs.		TCTF	s	166,600
H	5 · C · · · · · · · ·	oud: umento	0.22	San Bernardino	Facility	Installation of two Automatic Transfer Switches (ATS) and tie-in to building emergency generator to provide			T	200,000
5	36-CFR036	San Bernardino	36-R1	Justice Center	Modification	, , ,	One-Time	Non-TCTF	\$	325,000
6	40-CFR008	San Luis Obispo	40-F1	1120 Mill Street	Lease Extension	Three-year lease extension for office space. (4/1/2017 - 3/31/2020)	Three Years	TCTF	\$	307,377
7	50-CFR021	Stanislaus	50-A2	Hall of Records	Lease Extension	Five-year lease extension for office and storage space. (1/1/2017 - 12/31/2021)	Five Years	TCTF	\$	725,563