

JUDICIAL COUNCIL OF CALIFORNIA

455 Golden Gate Avenue · San Francisco, California 94102-3688

www.courts.ca.gov

REPORT TO THE JUDICIAL COUNCIL

For business meeting on: June 23-24, 2016

Submitted by Trial Court Facility Modification Advisory Committee Hon. Donald Cole Byrd, Chair Agenda Item Type Information Only

Date of Report June 13, 2016

Contact Patrick McGrath, 916-643-8051 patrick.mcgrath@jud.ca.gov

Executive Summary

The Trial Court Facility Modification Advisory Committee (TCFMAC) has completed its facility modification funding for the third quarter of fiscal year 2015–2016. In compliance with the *Trial Court Facility Modifications Policy*, the advisory body is submitting its *Trial Court Facility Modification Quarterly Activity Report: Quarter 3, Fiscal Year 2015–2016* as information for the council. This report summarizes the activities of the TCFMAC from January 1, 2016, to March 31, 2016.

Previous Council Action

The Trial Court Facility Modification Working Group was established by Judicial Council policy in 2005. The working group first met in April 2006 and operated under the *Trial Court Facility Modifications Policy*,¹ adopted by the Judicial Council in 2005, the latest revision of which was on December 12, 2014. The working group's primary oversight responsibilities included reviewing statewide facility modification (FM) requests and approving FM funding.

On April 25, 2013, the working group's status was elevated to that of advisory committee. The committee operates in accordance with rule 10.65 of the California Rules of Court, which was

¹ As adopted in 2005, the policy was known as the *Prioritization Methodology for Modifications to Court Facilities*. When it was revised in 2012, the name also changed. See <u>www.courts.ca.gov/documents/jc-20120727-itemG.pdf</u>.

approved on January 1, 2015. The committee was assigned additional oversight responsibility for the operations and maintenance of existing facilities, noncapital-related real estate transactions, energy management, and environmental management and sustainability.

An updated Court-Funded Facilities Request (CFR) approval process was submitted and approved by the Judicial Council on August 23, 2013, requiring all CFRs to be reviewed and approved by the TCFMAC. These submittals may include lease-related costs (e.g., lease payments and operating costs, repairs, or modifications required by a lease); allowable court operations expenditures under rule 10.810 of the California Rules of Court (e.g., equipment, furnishings, interior painting, flooring replacement or repair, furniture repair, or records storage); and other facility improvements that are not allowable court operations expenditures under rule 10.810 (e.g., facilities operations, maintenance, repairs, and modifications, but not capital projects), if they would improve a court's functioning or reduce ongoing court operating costs.

Reports previously approved by the Judicial Council are available at <u>www.courts.ca.gov/2567.htm</u> under Research and Reports: Conditions in Our Courts.

Methodology and Process

Funding decisions were based on the prioritization and ranking methodologies in accordance with the *Trial Court Facility Modifications Policy*. Facility modifications are assigned one of six priority categories: Priority 1–Immediate or Potentially Critical; Priority 2–Necessary, but Not Yet Critical; Priority 3–Needed; Priority 4–Does Not Meet Current Codes or Standards; Priority 5–Beyond Rated Life, but Serviceable; and Priority 6–Hazardous Materials, Managed but Not Abated. These categories are based on methods commonly used by private-sector facility management firms. Facility modifications that are determined to be Priority 1 are to be addressed immediately and regardless of whether the court occupies a shared-use facility. With current budget constraints, the TCFMAC predominantly approves FM projects at the Priority 1 and Priority 2 levels. Delaying TCFMAC approval of these projects would cause continued court closures, operational failures, and undue risk to continued court operations.

Policy and Cost Implications

During the third quarter of fiscal year (FY) 2015–2016, the TCFMAC reviewed and approved a total of 199 facility modifications for a total projected cost of \$6,822,611. The Facility Modification budget is responsible for \$5,766,285 with the respective counties throughout the state being responsible for the remainder. These approved projects were primarily Priority 1 emergency projects and Priority 2 urgent projects. There were, however, three Priority 3 energy efficiency projects also approved. Included among the urgent projects were several HVAC unit replacements and three Phase I Designs for large-scale roof, HVAC, and exterior shell projects. The emergency projects included a high percentage of remediation work for failed plumbing and associated water damage. See Attachment A for a detailed list of all approved projects during the third quarter of FY 2015–2016.

During this quarter, seven projects required additional funds in excess of \$50,000 from their original estimates. The Facility Modification budget responsibility of these cost increases totaled \$536,975. Projects that required excess costs of this magnitude were largely projects for which project managers encountered unforeseen site or equipment conditions.

Also during this quarter, eight CFRs were reviewed and approved by the TCFMAC, including leases for the Superior Courts of Orange, Sacramento, San Bernardino, San Diego, and Santa Clara Counties and facility modification CFRs for the Superior Courts of San Diego and Santa Barbara Counties. See Attachment B for a detailed list of CFRs approved by the TCFMAC during the third quarter of FY 2015–2016.

Implementation Efforts

The committee conducted an in-person meeting in Sacramento on January 15, 2016, and one via teleconference on February 19, 2016, to review FM funding requests and to discuss the topics below:

- The committee conducted its regular review of facility modification projects lists: A (Emergency and Priority 1); B (FMs Under \$50K); C (Cost Increases Over \$50K); D (FMs Over \$50K Eligible for Funding); E (Court-Funded Facilities Requests); and F (Funded FMs on Hold).
- The committee received an in-depth presentation on the council's seismic study of court facilities. A previous study completed during the initial courthouse transfer process will be leveraged to develop a ranking and prioritization report for facilities containing high seismic risk, and will follow similar functions as federal and other state offices.
- The committee received an informational update on water conservation in court facilities. Several potential water savings projects have been identified and staff are researching prices and rebates for replacing high consumption restroom plumbing fixtures. Staff continues to hold Best Management Practices meetings with the courts in order to identify implementation strategies for water conservation.
- The committee prepared and submitted its 2016 Annual Agenda. The agenda provides an overview and details on the committee's key objectives and timelines for projects over the course of the calendar year.
- The committee reviewed and approved the *Trial Court Facility Modification Quarterly Activity Report: Quarter 2 of Fiscal Year 2015–2016.*
- During this quarter, committee Chair Judge Byrd also visited the Superior Court of Lake County in February to review the new capital project and meet with the court.

Completed courthouse project spotlights

The examples below are of facility modifications projects that have been completed during this quarter. These examples illustrate the varied problems that California courthouses regularly face, from emergency repairs and mitigation to projects identified during preventive maintenance rounds and readings. Under any circumstance, it is the committee's goal, with Judicial Council facility management staff, to provide dedicated service and resolution to court users and employees throughout the state.

Priority 2 Project—Energy Efficiency HVAC at Hayward Hall of Justice, Alameda County—

FM-0051431. In support of the Judicial Council's goal of reducing energy consumption and long-term utility costs, Judicial Council service provider Enovity performed a detailed evaluation of the building's 40-plus year-old HVAC system to identify opportunities to improve the efficiency of the system. Enovity identified several modern control strategies that would increase efficiency, including the installation of variable frequency drives (VFDs). Enovity installed VFDs on two large return fans. The VFDs will modulate the motor speed more efficiently and thereby supply only the amount of air needed to maintain the desired building temperature and airflow. Without the VFDs, the motor speed is either "100% on" or off. The central Building Automation System (BAS) controlling the fans was reprogrammed to allow the building engineer to run the equipment more efficiently. The VFDs were delivered to the roof by crane and installed over two weekends to avoid disruption to the court's operations. Local utility company incentives for the project were approximately \$24,000, and the annual electrical savings are estimated at \$47,000.

The final project cost was \$217,204, giving this project a 4.6-year payback.



Before & During: Dissembling one of the large return air fans (*left*).

After: Staging the new VFD motors (below).



Priority 2 Project—Exterior Windows Repair & Replacement at Placer County Historic Courthouse—FM-0002953. Eighty percent of the windows in the historic courthouse had failed due to dry rot and wear, and were beyond repair. The balance of the windows were showing signs of wear and would soon be in disrepair. After coordinating with Placer County and the court and obtaining approval from the State Historic Preservation Officer, 54 wooden windows were replaced. Overall, the project met its goals of reducing noise transmission, reducing weather impacts, improving energy efficiency, improving safety through high impact polycarbonate glazing, preserving some historic windows for 20+ more years, and also improving the building's aesthetics. From a project management perspective, the project was completed on time and also came in under budget of its original expected cost of \$1,025,200. The final project cost was \$793,760.



Before: Old, rusted windows (left). After: Refreshed, wooden window (right).

Priority 2 Project—Exterior Windows Repair & Replacement at Santa Clara County Old Courthouse—FM-0020267. About 50% of the windows at this courthouse had failed due to wear, termite damage, and dry rot. The balance of the windows were beginning to fail. The project included the removal and repair of 87 wooden windows, with replacement of glazing and/or wood for those that were beyond repair. This included the abatement of lead paint. The new glazing on the windows helped with noise transmission and temperature comfort, and the repairs ultimately restored every window to an operable condition. The final project cost was \$753,253.



Before: Old, damaged windows (left).

During: A lift is used to work on the windows from the exterior *(below)*.



Next Steps

The *Trial Court Facility Modification Quarterly Activity Report: Quarter 4, Fiscal Year 2015–2016* will be submitted to the Judicial Council in August 2016.

Attachments

- 1. Attachment A: TCFMAC-Funded Project List: Quarter 3, Fiscal Year 2015–2016
- 2. Attachment B: Court-Funded Facilities Requests (CFRs): Quarter 3, Fiscal Year 2015–2016



#	FM NUMBER	LOCATION	FACIUTY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACIUTY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Plumbing - Replace 20' of 2" Black cast iron pipe & fittings under ACM conditions. Employee restroom drain line				
1	FM-0057118	Los Angeles	Compton Courthouse	19-AG1	1	cracked and leaked from 2nd flr to ground level.	\$	13,819	\$9,139	66.13
2	FM-0057119	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing - Replaced approx. 15 ft. of 2 inch black cast iron drain piping. Replace (30) 12x12x 5/8 damage ceiling tiles and remediate water damage. Water is dripping from 4th floor ceiling inside Department J Courtroom. Plumbing - Replace 4' of failed 6" ductile piping on the incoming main fire supply line. Excavate 7'x10' area to	\$	12,561	\$12,561	100
3	FM-0057125	Los Angeles	Pasadena Courthouse	19-J1	1	provide access and remediate water damage once replacement line is installed. Work is immediately adjacent to 480 electrical supply lines so special cutting equipment is required during installation. Work is required to maintain fire system in the facility.	\$	75,100	\$52,082	69.35
4	FM-0057150	San Bernardino	New San Bernardino Courthouse	36-R1	1	Plumbing - Replace approx. 96 SF of drywall ceiling. Remediate water damaged in the 1st floor HR storage room caused by a leaking supply line fitting in the 2nd floor Women's staff restroom.	\$	7,461	\$7,461	100
5	FM-0057155	Los Angeles	San Fernando Courthouse Van Nuys Courthouse	19-AC1	1	Electrical - Building ATS failed to transfer power to emergency generator. Replace 600A ATS, replace (10) 500 MCM copper lugs, install 20 LF of 500 MCM copper wire, and install (10) 500 MCM compression connections.	\$	33,397	\$27,856	83.41
6	FM-0057159	Los Angeles	East	19-AX1	1	HVAC - Replace (1) failed actuator. Failed actuator is causing Room 110 to be extremely cold. ACM environment.	Ś	6,520	\$5,851	89.74
	1111 0007 200			10 / 011	-	Roof - Water leak through the 7th floor into the 6th floor ceiling of Department S. Replace (6) 1'x1'tiles on both	Ŷ	0,010	<i>40,001</i>	00171
7	FM-0057160	Los Angeles	Norwalk Courthouse	19-AK1	1	floors. Replace (1) damaged smoke detector within an ACM environment.	\$	16,585	\$16,585	100
8	FM-0057161	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing - Remove and replace a 35 LF of leaking 2inch drain pipe within an ACM environment. Vandalism - Replace (1) broken main entrance glass door (31.5x71) in front of the courthouse. A person threw a	\$	16,291	\$16,291	100
9	FM-0057163	Los Angeles	Courthouse	19-S1	1	rock breaking one of the glass doors.	\$	10,025	\$9,132	91.09
10	FM-0057193	Los Angeles	Mental Health Court	19-P1	1	Plumbing - Replace 4 ft section of the main sewage line on the 1st floor, in the public hallway. Remediation within ACM Environment of 8Wx15Lx8H are. Main sewage line is cracked and the public restrooms had to be closed due to the back-up.	\$	44,438	\$31,689	71.31
11	FM-0057194	Los Angeles	Compton Courthouse	19-AG1	1	Elevators, Escalators, & Hoists - Shorten elevator hoist ropes 16" on Elevator #5. The ropes is overstretched and tripping the comp sheave safety switch.	Ś	9,885	\$6,537	66.13
	FM-0057196	Los Angeles	Pasadena Courthouse		1	Plumbing - Replace failed lines from the water cooler including work in an ACM environment. Water remediation required in 4th fl. Dept. A chambers, 5th fl. Dep. D and Dep. D-1 chambers, ceiling into the 4th Floor, Dept. A - Supervising Judge's Chambers, damaging (16) 2'x2' ceiling tiles and the wall.	\$	22,653	\$15,710	69.35
1.0	EN4 0053400	A la ma a -l -	Wiley W. Manuel	01.02	4	Plumbing - Remediate flood damage in 5th floor holding area 108 and 4th floor holding area 104 (Approx.	¢.	F 275	6F 375	100
	FM-0057199 FM-0057201	Alameda Los Angeles	Courthouse Inglewood Courthouse	01-B3 19-F1	1	1800sqft). Flood was caused intentionally by in-custody plugging the toilet. Elevators - Custody elevator #5. Remove and restore Generator, strip and rewind armature, dip and bake parts, strip and rewind A/C end, dip and bake parts, replace all D/C field wires, replace 2 sleeve bearings, and replace brushes and lead wires.	\$ \$	5,375	\$5,375	100 74.56
			Stanley Mosk		-	Elevators, Escalators, & Hoists - Replace handrail guides/brackets for Escalator 2-1. Handrail and guide failed. This		,	,,	
15	FM-0057205	Los Angeles	Courthouse	19-K1	1	is a safety hazard.	\$	7,650	\$7,440	97.26



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Plumbing - Replace a cracked pressure regulator valve and remediate water damage in an ACM environment. A				
16	FM-0057208	Los Angeles	Alhambra Courthouse	19-I1	1	leak was reported coming from the sink in a cell on the second floor and leak onto the 1st floor public hallway.	\$	8,673	\$7,459	86
			Van Nuys Courthouse			Plumbing - Replace failed toilet gaskets and remediate water damage in an ACM environment. Water is leaking				
17	FM-0057209	Los Angeles	East	19-AX1	1	from the ceiling into the 4th floor Department U, affecting (4) 2" x 2" tiles.	\$	14,567	\$13,072	89.74
						HVAC - Chiller #1 tripping on high motor temperature - Rebuild existing chiller; work to include two (2) new filter				
			Chatsworth			driers, a new sight glass, "O" rings and gasket, 10 Lf. Of 1 5/8" copper tubing and associated couplings and elbows,				
18	FM-0057217	Los Angeles	Courthouse	19-AY1	1	and four (4) new 1 5/8" refrigeration ball valves.	\$	33,885	\$28,396	83.8
19	FM-0057219	Los Angeles	Alfred J. McCourtney Juvenile Center	19-AE1	1	County Managed - Exterior Finishes - Replace 3 broken exterior window. All (3) window are 2x4 in size. This includes emergency response.	\$	2,348	\$2,348	100
						Plumbing – Install (1) ¾ 90 deg. elbow, and ¾ copper cap and remediate water damage, remove & replace 160				
			Van Nuys Courthouse			lineal feet of cove base, and prepped/mudded/sanded 25'x10' wall. Water is leaking from a 3/4" copper supply				
20	FM-0057221	Los Angeles	West	19-AX2	1	line, saturating the wall of the Basement conference room and breakroom B129.	\$	14,505	\$11,674	80.48
			Metropolitan			Electrical - Replace failed switch handle to ATS that controls the elevators. Due to brief power outage, no elevators				
21	FM-0057227	Los Angeles	Courthouse	19-T1	1	at the courthouse are functioning. The ATS can't reset.	\$	12,565	\$11,879	94.54
						Plumbing - Mechanical RM-823 domestic hot water tank has a quarter size hole at bottom of tank. Weld plate to				
			Stanley Mosk			cover hole and 2 additional areas. Replace approx. 1,300sf of ceiling tiles. Tank supplies hot water to 9th flr	١.			
22	FM-0057231	Los Angeles	Courthouse	19-K1	1	restrooms and kitchen. Work is done under ACM environment.	\$	48,500	\$47,171	97.26
						Elevators, Escalators, & Hoists - Shorten Elevator hoist ropes 16" on Elevator #4. The ropes are overstretched &				
23	FM-0057232	Los Angeles	Compton Courthouse	19-AG1	1	tripping the comp sheave safety switch.	\$	9,885	\$6,537	66.13
						Elevators, Escalators, & Hoists - Elevator #11 is leaking hydraulic fluid from the jack shaft packing. Repack shaft to				
24	FM-0057233	Los Angeles	Compton Courthouse	19-AG1	1	stop leaking.	\$	9,986	\$6,604	66.13
						Plumbing - Replace failed push button for drinking fountain and replace (19) ceiling tiles. In custody jammed push				
25	514 005 7224		Van Nuys Courthouse	10 412	4	button to drinking fountain on the fourth floor causing water to leak down pipe chase into the 2nd floor ceiling	Ś	0.000	Ć7.054	00.40
25	FM-0057234	Los Angeles	West	19-AX2	1	above the window #7 Clerk's Area.	Ş	9,880	\$7,951	80.48
						Numbing Deplece 201 of 2" Disel Cost land drain Dise /Fittings Deplece 4 of 1" spilling tiles Dependints block water				
20	FM-0057235	Los Angeles	Compton Courthouse	10 401	1	Plumbing - Replace 20' of 2" Black Cast Iron drain Pipe/Fittings. Replace 4' of 1" ceiling tiles. Remediate black water contamination. Water Leaked from the 7th flr public women's RR to 6th flr Dept. P Courtroom.	Ś	14,887	\$9,845	66.13
20	FIVI-0057235	LOS Aligeles	compton courthouse	19-AG1	1		Ş	14,887	\$9,845	00.13
27	FM-0057239	Riverside	Banning	33-G1	1	Elevators, Escalators & Hoists – Remove and replace obsolete and damaged door operator and replace with new MOVFR II door operator; including new gate switch, door linkage, and all necessary wiring to the existing controller. This is the only elevator in the building and its outage is severely affecting operations within.	Ś	16,256	\$6,442	39.63
<u> </u>					-	Elevator - The ropes for Elevator #6 is overstretched and tripping the comp sheave safety switch which is causing	-		<i>40,11</i>	55.05
						entrapments. Elevator hoist ropes must shortened and tested for proper operation before releasing back into				
28	FM-0057117	Los Angeles	Compton Courthouse	19-AG1	2	service.		\$3,761	\$2,487	66.13
	1	00.00			-				<i>+_,</i>	
			Metropolitan			Interior Finishes - Reinforce approx. 25ft ceiling tile support brackets in an ACM environment. Spline Ceiling tiles;				
29	FM-0057120	Los Angeles	Courthouse	19-T1	2	support brackets are not holding creating a safety issue. Ceiling is located in a court exclusive space.		\$4,847	\$4,847	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Exterior Shell -Remove and replace approximately 15 linear feet and 6 wide damaged concrete and adjacent			
20	FNA 0057494		Beverly Hills	10.101	•	asphalt. Bottom of ramp at the loading dock in the rear of the building has damaged concrete, this is a trip hazard	¢4,202	¢2,402	70 50
30	FM-0057121	Los Angeles	Courthouse	19-AQ1	2	and a safety concern.	\$4,392	\$3,493	79.52
31	FM-0057122	San Diego	South County Regional Center	37-H1	2	COUNTY MANAGED Plumbing: Replace storm water pumps and approximately 300 linear feet of deteriorated storm drains and sewer piping from roof top to detention level. Scope of work includes permitting, inspection and county project management fees. Due to age and current condition of plumbing system had resulted in water intrusion throughout the facility.	\$30,464	\$30,464	100
			Parking Structure-			Elevators, Escalators, & Hoists - Install new governor cable and re-babbit cable. Elevator #1 governor cable is worn	<i>+•••</i> , •••	+••).•	
32	FM-0057130	Los Angeles	Edelman Court	19-Q2	2	and stretched.	\$4,499	\$3,149	69.99
33	FM-0057131	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Elevators, Escalators, & Hoists - Install carbon generator brushes for eight elevators. Elevator generator brushes are deteriorating and need replacing for Parking Elevator #1, Public Elevators #2 through #6, and Children's Elevators #7 & #8. Elevators will begin to fail and could lead to potential entrapments, and downed elevators.	\$3,299	\$2,309	69.99
			Wiley W. Manuel		_	Vandalism - Replace (1) Tempered / laminated security glass 7" X 32 3/4" X 1" thick glass pane window in holding	4	4	
34	FM-0057132	Alameda	Courthouse	01-B3	2	cell 110-1. Window was broken by in custody causing a security issue.	\$1,307	\$1,307	100
35	FM-0057133	San Joaquin	Manteca Branch Court New San Andreas	39-C1	2	Plumbing - Install 2" backflow prevention device (with concrete pad, cage, and bollards) on the domestic water system as required by the City of Manteca per code. Item identified during the water audit. Fire Protection - Install three new remote test switches to currently inaccessible duct detectors (1-2-150, 1-2-157 &	\$10,279	\$10,279	100
36	FM-0057134	Calaveras	Courthouse	05-C1	2	1-2-138) to facilitate completion of code required testing of the fire protection system.	\$6,287	\$6,287	100
37	FM-0057135	Santa Cruz San	Watsonville Courthouse Rancho Cucamonga	44-B2	2	Elevators - Remove and replace jack seals on five (5) elevators cars - Elevator packing is leaking from (5) Elevator hydraulic ram seals and can cause elevator to shut down if not replaced, any number of elevator reduction would have a direct impact on access to the courts for staff/public/Judicial Officers. Electrical - Install (2) 2pole 208/240 - 30amp circuits with twist lock outlets and (1) 120V -receptacle in the 1st floor	\$15,838	\$15,838	100
38	FM-0057141	Bernardino	Courthouse	36-F1	2	civil department. This work is needed to accommodate Appellate Court equipment.	\$3,511	\$3,511	100
	FM-0057142	Riverside	Southwest Justice Center	33-M1	2	Exterior Shell - Restore (2) pair of rear entry exit doors that have failed due to building settling. Doors at this time do not open and are limiting public and employee access/egress to the building.	\$6,726	\$5,032	74.82
40	FM-0057143	Orange	Central Justice Center	30-A1	2	HVAC - Replace 2 HP water heating pump. Bearings are failing. Failure would result in loss of domestic hot water for areas of the 3rd floor.	\$8,089	\$7,375	91.17
41	FM-0057149	Solano	Law And Justice Center	48-A2	2	HVAC - Remove and replace (1) return fan motor and associated drive belts on Air Handler #16 - Motor bearings are beginning to fail and would affect courtrooms and chambers.	\$5,667	\$5,667	100
42	FM-0057157	Los Angeles	Santa Monica Court Annex	19-AP3	2	HVAC - Replace burnt economizer communication modules and fan motor. BAS system is non-functional which is affecting the A/C system of the entire Annex Building.	\$5,148	\$4,041	78.49
43	FM-0057158	Tulare	South County Justice Center	54-11	2	Exterior - Vandalism - Replace (1) broken window (47 1/4" x 105 7/8") on 2nd floor overlooking the sallyport. Existing window was shot at and had both panes cracked.	\$5,837	\$5,837	100
44	FM-0057162	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	Plumbing - Replace a failed 3/4" ball valve and install new copper fitting. Hot water is constantly leaking from a bathtub faucet located in the Shelter Care Restroom. ACM environment.	\$2,303	\$1,612	69.99



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			South County		_	Elevators, Escalators, & Hoists - Shorten Hoist Ropes on Car #9. During a service call it was found that the stretching	4		
45	FM-0057164	San Diego	Regional Center	37-H1	2	of the cable ropes do not meet with code or operational specifications.	\$7,200	\$7,200	100
			Harbor Justice Center- Newport Beach						
46	FM-0057165	Orange	Facility	30-E1	2	HVAC - Replace failed exhaust fan. Parts are no longer available for failed fan.	\$4,600	\$3,879	84.32
						Elevators, Escalators, & Hoists - Lighting -Replace failed lighting controller, ceiling mount, and power supply. 90% of			
47	FM-0057166	Riverside	Larson Justice Center	33-C1	2	the lighting have failed and is a safety hazard to employees, jurors, and public.	\$13,173	\$10,645	80.81
48	FM-0057169	San Bernardino	Rancho Cucamonga Courthouse	36-F1	2	HVAC - Replace faulty Main Base Board and Auxiliary Contacts. Chiller is experiencing intermittent faults for compressor overload. This work must be performed to ensure reliable cooling for the Courts MDF room.	\$7,467	\$5,679	76.05
49	FM-0057170	Los Angeles	Sylmar Juvenile Court	19-AF1	2	COUNTY MANAGED - HVAC - Install (2) new mini-split HVAC units 20 x 15 ft glass store front to enclose the weapon screening area with double doors. Current building design does not support cooling requirements for weapons screening. Work impacts common space and county is absorbing 65% of overall project cost. Elevator, Escalators, & Hoists - Key switches for custody elevators #5 & #10 are worn and non-operational. Key	\$32,080	\$32,080	100
50	FM-0057171	Los Angeles	Airport Courthouse	19-AU1	2	switches are required for elevator operation to access floors in custody elevators. Replace high security key switches on custody elevators #5 & #10 Car Operating Panels and hall fixtures for basement, 3rd, 7th, 8th, and 9th floors.	\$26,475	\$20,431	77.17
-1		0	Harbor Justice Center- Newport Beach		2	HVAC - Cooling Tower - Replace fan propeller assembly, bushings, shaft, bearings and belt. Fan assembly and	¢35 504	ć24 570	04.22
51	FM-0057174	Orange	Facility Fresno County	30-E1	2	bearings are near failure. Graffiti - Remove graffiti etched in the wood veneer on doors and courtroom entrance vestibules in 28 locations	\$25,591	\$21,578	84.32
52	FM-0057175	Fresno	Courthouse.	10-A1	2	throughout the facility. Graffiti is visible in public areas of the courthouse.	\$28,278	\$28,278	100
52	FIVI-0057175	FIESHO	Courtilouse.	10-A1	Z	Elevators, Escalators, & Hoists - Replace failed door detector edge and sight guard on Elevator #1. Elevator #1 is not	<i>320,210</i>	\$20,270	100
52	FM-0057176	Los Angeles	Whittier Courthouse	19-AO1	2	working due to damaged door detector edge and sight guard.	\$3,550	\$3,550	100
55	1101-0037170	LOS Angeles	Whittier courthouse	13-A01	2	Plumbing - Replace failed domestic hot water heater with a new 75 gallon hot water heater. A hole developed in	JJ,JJ0	Ş3,330	100
						the bottom of the existing hot water heater causing the burner assembly to get wet, the pilot light will not stay lit			
54	FM-0057177	Orange	West Justice Center	30-D1	2	resulting in complete loss of hot water to the entire facility.	\$4,000	\$3,627	90.68
		Los Angeles	Compton Courthouse		2	HVAC - Replace damaged chilled water pump coupling inserts and condenser water pump motor coupling inserts. Coupling inserts are damaged, worn and cracked and needs to replaced to prevent system failure.	\$3,023	\$1,999	
		San				Elevators, Escalators, & Hoists - Public Elevator #1 the data port on the CPU is bad. Currently computer diagnostics cannot be performed. Replace existing CPU #CP27C with failed comm port with new #CP37 CPU complete with			
56	FM-0057179	Bernardino	Fontana Courthouse	36-C1	2	software.	\$14,999	\$12,325	82.17
			Municipal Court Building - Northern			HVAC - Remove and replace failed, existing 11" inline duct blower (1) - Blower motor seized and overheated			
57	FM-0057181	San Mateo	Branch	41-C1	2	causing smoke, setting off alarm.	\$2,553	\$2,124	83.21
58	FM-0057183	Santa Clara	Hall of Justice (West)	43-A2	2	Plumbing - Replace (1) failed storm water sump pump - Possible flooding due to failed pump.	\$7 <i>,</i> 844	\$7,844	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			San Fernando			Fire Protection - 6" FEBCO Series 860 Domestic Backflow has check valve seats damage. Replace (2) check valve seat			
59	FM-0057184	Los Angeles	Courthouse	19-AC1	2	assemblies. Deficiencies found during PM SWO# 2504987.	\$3,973	\$3,314	83.41
			Morgan Hill		_		4	4	
60	FM-0057185	Santa Clara	Courthouse	43-N1	2	HVAC - Replace (1) failed 4 burner assembly - Failed boiler currently impacting the court's heating capacity.	\$1,769	\$1,769	100
			Morgan Hill		_	HVAC - Replace (1) failed impeller and (1) pump volute housing. Failed boiler currently impacting the court's	4		
61	FM-0057186	Santa Clara	Courthouse	43-N1	2	heating ability.	\$3,931	\$3,931	100
62	FM-0057188	Los Angeles	Van Nuys Courthouse East	19-AX1	2	Elevator - Replace failed advancing motor and remediate damage to contactors and associated circuits. Elevator #3 was not landing properly at floors and the doors would open fully as car was 4 -6 away from landing and was still in motion.	\$4,477	\$4,018	89.74
63	FM-0057195	San Diego	North County Regional Center - South	37-F1	2	COUNTY MANAGED - HVAC - Replace ceramic fiber module panels on side and rear of boiler # 1 in Central Plant. This work was performed by the County under Emergency Repairs.	\$2,492	\$2,492	100
			Hayward Hall of			Electrical - Replace (6) failed holding cell interview phones. Existing phones damaged by in-custodies causing			
64	FM-0057197	Alameda	Justice	01-D1	2	inability to communicate with attorneys.	\$2,457	\$2,457	100
65	FM-0057198	Riverside	Larson Justice Center	33-C1	2	Grounds and Parking Lot - Remove 21 dead trees. The current drought and water restrictions created unsafe conditions such as trip, fire, pest infestation, and security issues. Work is to be executed after hours.	\$11,110	\$8,978	80.81
66	FM-0057210	San Diego	North County Regional Center - South	37-F1	2	Grounds and Parking Lot - Replace current roller drive operators with (2) chain drive slide gate operators with loop detectors and modify gate to work with the new operators. The gate operators frequently fail trapping Judges in the secure parking area. Roller drive system slips on the rail during high humidity and wet conditions.	\$14,919	\$14,919	100
						Plumbing - Replace damaged and non-functioning sump tank and pump. The sump pump is cracked and not			
67	FM-0057211	Los Angeles	Pasadena Courthouse	19-J1	2	functioning which could cause a flood if not replaced.	\$3,724	\$2,583	69.35
1			East Los Angeles			HVAC - Install (1) new Blast Tube, (1) new Flange and (1) new Diffuser. Boiler #2 has a damaged blast-tube and			
68	FM-0057212	Los Angeles	Courthouse	19-V1	2	diffuser.	\$7,301	\$5,674	77.72
					_	Elevator - Shorten 16" of overstretched Elevator ropes. Custody Elevator #7 got stuck on the 7th floor with 2		4-	
69	FM-0057218	Los Angeles	Compton Courthouse	19-AG1	2	deputies entrapped due to overstretched ropes.	\$3,761	\$2,487	66.13
70	FM-0057220	Los Angeles	Santa Monica Courthouse	19-AP1	2	Interior Finishes - Replace (1) 60"x72" Bullet Resistant Glass at Teller/Traffic window. Existing glass has a 60" crack, compromising the glass integrity.	\$9,125	\$9,125	100
71	FM-0057223	Los Angeles	Chatsworth Courthouse	19-AY1	2	Electrical - Replace Main Power and Processor Board . UPS System is on alarm and circuit board is burnt and shorted out. System failure affects the emergency lights in the court rooms and some hallways.	\$9,232	\$7,736	83.8
						Plumbing - Install new 3" gate valve and factory repair kit. The device failed and does not comply with	A	A	
72	FM-0057224	Los Angeles	Burbank Courthouse Clara Shortridge Foltz Criminal Justice	19-G1	2	health/water department regulations.	\$5,228	\$4,745	90.76
73	FM-0057226	Los Angeles	Center	19-L1	2	Plumbing - Installed new Comfort heating make-up water line and plumbing. Water line is damaged and is leaking.	\$6,931	\$4,768	68.79
74	FM-0057229	Los Angeles	Metropolitan Courthouse	19-T1	2	Fire Protection - Replace (33) defective & aged smoke detectors; Replacement is code required.	\$9,074	\$8,579	94.54



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
75	FM-0057230	Los Angeles	Pasadena Courthouse	10 11	2	Fire Protection - Replace (3) 75 feet fire hoses, and replace (1) fire hose nozzle. Units failed testing must be replaced for compliance.	\$3,442	\$2,387	69.35
75	FIVI-0057250	LOS Angeles	Pomona Courthouse	19-J1	2	HVAC - Boiler #2 restoration - Install Six (6) boiler tube plugs. Boiler #2 tubes have deteriorated and required the	\$5,442	\$2,567	09.55
76	FM-0057240	Los Angeles	South	19-W1	2	tubes to be plugged.	\$3,879	\$3,535	91.14
	FM-0057241	Placer	South Placer Justice Center	31-H1	2	Electrical - Replace 36 fixtures and ballasts in confined space above the ceiling with LED conversion fixtures - 10% of the lights have failed. The ballast for these fixtures are in an inaccessible area that does not permit safe access to change out the ballast if required, this project will remove the need to replace any ballast in the future.		\$7,681	100
78	FM-0057243	Alameda	George E. McDonald Hall of Justice	01-F1	2	Fire Protection - Fire suppression system - Replace two failed and leaking inspector test valves discovered during quarterly inspection.	\$3,210	\$3,210	100
79	FM-0057244	Los Angeles	Pasadena Courthouse	19-J1	2	Electrical - Replace defective exit and bug eye lights. Multiple emergency lights (exit signs and bug eyes) not working throughout the building. Defects found from annual EML-level IV PM.	\$4,580	\$3,176	69.35
80	FM-0057245	San Diego	North County Regional Center - Vista Center	37-F2	2	HVAC - Replace existing valve and actuator, with one (1) two-way shut off valve and (1) electronic actuator. Chilled water isolation valve is not closing all the way and cannot supply air warmer than 55 degrees.	\$7,580	\$7,580	100
01	FM-0057246	San Bernardino	San Bernardino Courthouse - Annex	36-A2	2	Elevators, Escalators, & Hoists - Replace faulty worm shaft seal and brake shoes at Public Elevator #1. Restore elevators Recall Peek-a-Boo function so that doors will not automatically open when in fireman recall mode. The existing worm shaft seal is defective and allowing worm gear oil to leak from the gear case.	\$14,640	\$14,640	100
	FM-0057247	San Diego	North County Regional Center - South	37-F1	2	Elevators, Escalators, & Hoists - Replace failing Communication Circuitry between the car top controls and the main controller in the equipment room, replace the floor selector wiring and tape selector guides. Communication between car and control equipment above is intermittent, causing intermittent operation and rider entrapment.		\$5,434	100
82	FIVI-0057247	Sall Diego	Courthouse/Sheriff	37-F1	Z	Interior Finishes - 2nd Floor ADA Restroom - Construct (1) ADA accessible restroom on the second floor near the	\$5,434	\$5,434	100
83	FM-0057248	Sierra	Station-Jail	46-A1	2	elevator - The building does not currently have an ADA accessible restroom.	\$49,500	\$49,500	100
			Santa Clara			HVAC - Replace leaking, rusted 40 year old 65 ton Cooling Tower, VFD included. Existing equipment has leaks and			
	FM-0056888 FM-0057152	Santa Clara San Bernardino	Courthouse Juvenile Dependency Courthouse	43-G1 36-P1		failed component replacements. Increased number of hot calls is affecting operations. Plumbing - Replace duplex domestic water skid with Grundfos Duplex domestic water skid, install (2) 5HP VFD drives, replace 15 LF of 2" copper pipe, replace (2) 2" brass unions, replace (2) 4.5" aluminum pressure gauges, replace (2) 2" copper tees, and replace (2) 2" ball valves. Duplex booster pump's main board has failed and parts are no longer available.	\$ 260,489 \$ 57,952	\$ 260,489 \$ 31,601	54.53
					_	Plumbing - Replace existing 8" Fire Main Check Valves and 4" Domestic Water Line Check Valves with Backflow Preventers. During PMs for the domestic and fire main backflows it was discovered that both systems had been	÷ 57,552	- 51,001	54.55
	FM-0057236	Los Angeles	Downey Courthouse	19-AM1	2	missing the backflow preventers. Elevators, Escalators, & Hoists - Complete Elevator System Renovation - Work to include doors, operators, and controllers, hydraulic power units and associated equipment. Code upgrades will also be included which consist of HVAC, FACP and Fire Suppression Equipment. Evaluation by our third party consultant has found the system to be	\$ 96,125		83.7
87	FM-0010335	El Dorado	Johnson Bldg.	09-E1	2	at risk and in a poor operating condition.	\$ 385,000	\$ 385,000	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	EACH ITY MODIFICATION		FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Harbor Justice Center-			HVAC - BAS - Replace failed Siemens chiller control system with new non-proprietary Automated Logic system.					
88	FM-0055034	Orange	Newport Beach Facility	30-E1	2	Multiple components of the current system are failing on a daily basis and have resulted in complete shutdown and difficult restarts of the vital building system. Work to be completed on off-hours to not impact operations.	\$	535,000	Ś	451,112	84.32
00	1101 0055054	Orange	l'aciirty	50 11	2	HVAC - Roof top hot water piping has deteriorated. Replace 200 LF of 2" copper piping, install (10) 2" copper	Ŷ	333,000	Ŷ	431,112	04.52
			Santa Monica			couplings, install (2) 2" butterfly valves, install (1) 2" ball valve, install (16) pipe saddles and clamps, reinsulate 200					
89	FM-0057094	Los Angeles	Courthouse	19-AP1		LF of hot water piping, and replace 210 SF of aluminum insulation jacket.	\$	78,596	\$	61,690	78.49
00	FNA 0052020	Venture	Liell of Justice	56.44		COUNTY MANAGED - Security - Basement Holding Area - Camera System Upgrade. Upgrade Basement Holding	÷	120.000	ć	120.000	100
90	FM-0052826	Ventura	Hall of Justice	56-A1		Camera System Recommended by County/MP. Interior Finishes - 30% of Dept 105 Public seating are damaged, un-repairable & a safety hazard to public	\$	120,000	\$	120,000	100
01	FM-0056971	Los Angeles	Compton Courthouse	19-061		attempting to use. Conduct Environmental testing & set-up 29'x15'x8' containment. Demo 93 existing damaged chairs. Existing anchoring bolts have sheared off requiring drilling new anchoring points. Drill 168 holes (42ft x 4 holes per ft) for new chair anchoring. Install 93 new American Seating plastic seating (similar style to existing) & secure w/epoxy.	Ś	90,973	Ś	90,973	100
51	110-0050571	LUS Aligeles	compton courtilouse	13-701		Roof - Install new 30,000 sf, 80 mil PVC membrane roofing system to replace existing built-up asphalt roof. Install	Ļ	50,575	Ļ	30,373	100
92	FM-0057213	Tulare	Dinuba Division of the Tulare Superior Court			new coping cap and raise all roof curbs to a minimum of 8. Existing roofing is failing with severe blistering and cracks.	\$	665,000	\$	332,500	50
						HVAC - Replace failed AHU Hot and Cold Coils and Condensate Pans- Install new stainless steel condensate Drain					
			Humboldt County			pans (AHU 6,7 &8), install new Heating & Cooling coils (AHU 4,5,6,7 & 8) including ACM abatement and condensate					
93	FM-0057216	Humboldt	Courthouse (Eureka)	12-A1	2	pumps for Pans in AHU 5,6,7 & 8.	\$	379,860	\$	379,860	100
94	FM-0057187	San Diego	South County Regional Center	37-H1		Interior Finishes - Remove 5 existing sound wall panels and install new fixation system to back of panels to prevent delaminating from walls, restore material on edges of panels and reinstall in courtroom. Sound panels are falling off walls, fabric on panels is detaching. Panels are contacting patrons/staff and is a safety issue.	\$	57,943	\$	57,943	100
95	FM-0055154	Lassen	New Susanville Courthouse	18-C1	2	HVAC BAS - Upgrade the building automated system (BAS) to allow full function control of all HVAC equipment throughout the building. The upgrade will allow full control access the maintenance shop desktop computer and by remote access via the internet, and resolve overheating in the first floor security office, trend before and after. This remote courthouse experiences harsh climate and frequent equipment outages. Full functioning control access through the BAS is critical to maintain court operations.	Ś	90,000	Ś	90,000	100
	0033134		Bakersfield Superior	10 01	-	Interior finish - Floor tile - Remove and Replace 1926 SF of loose, cracked and lifting ACM floor tiles with new	Ŷ	50,000	Ŷ	50,000	100
96	FM-0057200	Kern	Court	15-A1	2	12"x12" vinyl tiles and 180 LF of wall base. Floor tiles are cracked and lifting.	\$	83,676	\$	52,415	62.64
97	FM-0057173	Merced	New Downtown Merced Courthouse	24-A8		Exterior Shell - Restore exterior building shell. Caulk windows (96 ea), retexture exterior stucco. Apply an elastomeric paint coating to entire exterior (26,400 sf), including the Sally Port to be coated with an elastomeric paint. Exterior has extensive damage from water penetration and ledges have deteriorated allowing water penetration into the building.	\$	120,000	\$	120,000	100
						Energy Efficiency - Grounds and Parking - Parking lot lighting - Retrofit the existing parking lot lighting from high					
			Carol Miller Justice			pressure sodium lighting to new more efficient LED lighting. Remove and replace total of 13 light poles with two					
98	FM-0031636	Sacramento	Center	34-D1	3	fixtures per pole. Better Energy Efficiency.	\$	35,000	\$	35,000	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION		FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Energy Efficiency - HVAC - Install four (4) 15 HP and one (1) 10 HP 480V ABB Variable Frequency Drive (VFD) with					
99	FM-0057144	Orange	West Justice Center	30-D1	3	bypass for Chillers #1, 2, and 3. Abrupt starts have damaged couplings between the pumps and motors.	\$	41,475	\$	37,618	90.7
			Gordon Schaber Sacramento Superior		-	Energy Efficiency - Electrical - Replace existing Compact Fluorescent lamps (CFLs) in all Courtrooms and Elevator Lobbies throughout the court with R-30 LED lamps - The existing CFLs throughout the building have failed, by replacing the existing CFLs with LED, this project will significantly reduce energy consumption and heat load		, -		- /	
100	FM-0056913	Sacramento	Court	34-A1		throughout the facility.	\$	68,000	\$	68,000	100
			New San Andreas			Grounds and Parking Lot - Replace broken domestic water line in drive area. Trench and replace slurry and asphalt					
101	FM-0057265	Calaveras	Courthouse	05-C1		damaged by broken line . Water line broke currently shut off to building.	\$	20,000	\$	20,000	100
102				10.01		HVAC - Replaced cold deck actuator to AHU #3, 24V power reheat valve actuator and sensor thermometer. Building	~	40.000	~	12.026	74.04
102	FM-0057266	Los Angeles	Mental Health Court	19-P1		is too cold and unable to maintain heating. Roof - Replace 1'x1' ceiling tile on 2nd floor , 2'x'2 are of ceiling tiles on the 6th floor and seal mastic around roof drain on roof. Remediation in an ACM environment. Rain water leaked through the roof into the 2nd Floor West	\$	19,388	\$	13,826	71.31
103	FM-0057277	Los Angeles	Pasadena Courthouse	19-J1	1	Wing Secured Hallway Depart. R chambers and 6th Floor Depart H.	\$	35,651	\$	24,724	69.35
		Los Angeles	Norwalk Courthouse Clara Shortridge Foltz Criminal Justice Center	19-AK1 19-L1		Roof - Replace (4) 1'x1' ceiling tile on 1st floor, Rm 109J and (1) 1'x1' ceiling tile on 7th floor Rm 701C & , and (6) 1X1 ceiling tiles in Room 104E in ACM environment. Rain water leaked through the roof into the 1st floor and 7th floor. Plumbing - Mainline stoppage in 10 inch main line from AHU room MS-504 out to street main. Sewage water flooded P-level steam room MB-312 (50x30 area), S-level AHU room MS-504 (20x60 area), S-level loading dock (70x64 area), and S-level trash room (42x30 area). Filled a total of (2) 4,800 gallon, (1) 2,200 gallon, and (1) 2,500 gallon, explanation of flooded processing and several steam room flooded processing of the steam room flooded procesing of the steam room floode	\$	46,265		<u>39,339</u> 68,815	85.03
		Los Angeles Orange	North Justice Center	30-C1		gallon trucks of sewage. Decontamination of flooded areas required. HVAC - Replace two (2) failed twin city return fans with new fan wall assembly, housings, galvanized steel base and casings, and VFD panel. Relocate existing VFD system to the mechanical room to accommodate new fans. Current fans, installed in 1981, have cracked housing.	\$ \$	100,036		175,000	68.79 100
		Los Angeles	El Monte Courthouse	19-01		Roof - Renovate area between the splash block and the roofing. Water remediation. Rain water leaked into the 3rd floor Clerk's Probation office wetting (1) 1'x3' ceiling tile and the 3rd floor Conference Room wetting (1) 1'x1' ceiling tile.	\$	16,835		9,785	58.12
108	FM-0057304	Los Angeles	Norwalk Courthouse	19-AK1	1	Plumbing - Replace failed grid strainer, p-trap and galvanized nipple. Which allowed public to clog the sink resulting in flooding in 1st floor and public security entrance. Remediate water damage under ACM protocols.	\$	25,875	\$	22,002	85.03
100	FM-0057313	Los Angeles	Compton Courthouse	19-461		Elevator - Replace failed elevator memory board to the main computer. Elevator #2 is struck on the 1st floor and not responding.	ć	3,451	Ś	2,282	66.13
	FM-0057313		Van Nuys Courthouse East	19-AG1 19-AX1		Plumbing - Replace (105) new 1x1 ceiling tiles, and installed new 8x2 section of insulation on HVAC duct(8) ceiling tiles under ACM conditions due to water damage. Water leaked through the ceiling into the 3rd floor secured hallway.	\$ \$	18,210		16,342	89.74
111	FM-0057323	Los Angeles	Pasadena Courthouse	19-J1	1	Plumbing - Replace damaged drinking fountain, 10X10 floor tile area, and remediate water damage under ACM conditions. Main sewage backed up through the drinking fountain drain in front of the public elevators on the first floor.	\$	22,300	\$	15,465	69.35



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Clara Shortridge Foltz								
			Criminal Justice			Plumbing - Replace 12 section of 4 cast iron line, (10) 2x4 ceiling tiles, (9) T-bars under ACM conditions. Scaffolding					
112	FM-0057340	Los Angeles	Center	19-L1	1	required up to 25' to reach damaged piping. Sewage line failed and clogged system.	Ş	42,359	\$	29,139	68.79
						Plumbing - Replace (34) 1'x1' ceiling tiles. Water remediation under ACM environment. Water is leaking from a 6"					
112	FNA 0057242		Pomona Courthouse	10 14/1	4	sewage pipe through the ceiling damaging (10) ceiling tiles on the 3rd floor Dept. G and (24) ceiling tiles on the 2nd	~	25.000	ċ	25.000	100
113	FM-0057343	Los Angeles	South	19-W1	1	Floor.	Ş	25,000	\$	25,000	100
						Interior Finishes - Remove and replace urine laden ceiling tiles for room 102 and 101 Lobby (550 SF) and demo (480 SF) of laden ceiling tiles, patch 16 SF of plaster. Work completed under ACM conditions. This is a current health and					
114	FM-0057349	Los Angeles	Mental Health Court	19-P1	1	safety issue to the employees working in area.	s	42,941	Ś	30,621	71.31
114	FIVI-0057549	LOS Aligeles		19-11	1		Ş	42,941	Ş	50,021	/1.51
		San	New San Bernardino			Exterior Shell- Replace 8 slats, 1 bottom door bar, and 4 wind-locks on North sally port bus bay roll-up door that					
115	FM-0057352	Bernardino	Courthouse	36-R1	1	was struck by a Sheriff's vehicle and rendered it inoperable.	Ś	8,235	Ś	8,235	100
116	FM-0057360	Los Angeles	Compton Courthouse	19-AG1	1	Plumbing - Replace 20' of 2" Cast iron pipe and (6) 1'x1' wet Ceiling Tiles under ACM protocols. Remediate black water contamination. Water leaked from a cracked drain, 9th flr Judges RR to 8th flr room 807. Plumbing - Replace failed circulator water pump on Boiler #4. Domestic hot water pump motor burned and was not	\$	18,457	\$	12,206	66.13
117	FM-0057368	Los Angeles	Norwalk Courthouse	19-AK1	1	maintaining hot water to the building.	\$	3,742	\$	3,182	85.03
						Elevator -Replace failed elevator communication traveler cable for Elevator #6. Elevator communication traveler		,		,	
118	FM-0057376	Los Angeles	Compton Courthouse	19-AG1	1	cable is not communicating from the main control panel to the elevator car.	\$	35,888	\$	23,733	66.13
119	FM-0057377	Los Angeles	Norwalk Courthouse	19-AK1	1	Vandalism - Replace 9'x3' exterior window. Exterior window for the Court Administrator's Office has been shattered by unknown person. Window will be boarded up for safety until replacement glass is on site.	\$	6,892	\$	5,860	85.03
120	FM-0057124	Los Angeles	Pasadena Courthouse	19-11	2	Grounds and Parking Lot - Remove 1210 SF of 4" thick concrete walkway, cut & remove tree roots, grade surface for 2" of crushed aggregate, pour 1210 SF of new concrete walkway and 121 LF of new planter curb. Judge's sidewalk that leads into building is filled with tree roots and uneven surfaces creating trip hazards.	Ś	45,832	Ś	31,784	69.35
120	111 0037124	2007/1180100		1.5 31	2	HVAC - Replace (2) mechanical seal assemblies, (2) deflectors, (1) radial ball bearings, (1) thrust bearing, (2)	Ŷ	-+3,03Z	Ŷ	51,704	05.55
121	FM-0057249	Los Angeles	Pasadena Courthouse	19-J1	2	inboard lip seals, (2) gland o-rings, (1) impeller key. Chilled water pump #1 is leaking.	\$	21,166	\$	14,679	69.35
		<u>_</u>	Morgan Hill			Fire Protection - Replace (2) failed horn/strobes and (4) horn/strobe back-up power batteries. Work is required by		,		,	
122	FM-0057250	Santa Clara	Courthouse	43-N1	2	code.	\$	11,628	\$	11,628	100
			Sunnyvale			HVAC - Replace failed (1) leaking connection circuit 3 and (1) leaking valve. Chiller parts failed affecting the court					
123	FM-0057260	Santa Clara	Courthouse	43-F1	2	cooling capacity.	\$	4,137	\$	4,137	100
			Downtown Superior			Elevator - Replace missing rope guard. Lack of guard is impacting the operation of courts elevator. Work required					
124	FM-0057264	Santa Clara	Court	43-B1	2	by code.	\$	9,209	\$	9,209	100
			East County Regional			Interior Finishes – Convert existing fire door to Dutch door including fire rated hardware. Court consolidation required relocation of the Restraining Order Office to a non-secure area. Conversion will maintain original security segregation design and intent. Since relocation, security incidents and confrontations have occurred putting court					
125	FM-0057267	San Diego	Center	37-I1	2	employees at risk.	\$	4,239	\$	4,239	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION		FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Edmund D. Edelman								
126	FM-0057268	Los Angeles	Children's Court	19-Q1	2	HVAC - Replace one contactor kit for M1 & M2 contacts for Chiller #2. Existing contacts are worn out.	\$	6,597	\$	4,617	69.99
127	FM-0057269	Los Angeles	Edmund D. Edelman Children's Court	19-Q1		Exterior Shell - Replace (1) 35 3/4" x 83 1/4" x 1 3/4 hollow metal door with new. Door leading into the Supply Fan Room on the roof is failing and pulling away from the door jam.	\$	2,807	\$	1,965	69.99
128	FM-0057270	Los Angeles	Edmund D. Edelman Children's Court	19-Q1	2	HVAC - Replace defective refrigerant monitor transmitter and strobe/horn. Work required by code.	Ś	4,678	¢	3,274	69.99
120	1101-0037270	LOS Aligeies	children's court	13-Q1		Exterior Shell - Install a new hollow metal ADA door (35-3/4"x6'-11") with stationary inactive leaf. Existing exterior	Ļ	4,070	Ļ	5,274	05.55
129	FM-0057271	Los Angeles	Torrance Courthouse	19-C1		wooden doors are peeling, have wood chips falling off, and must be replaced.	Ś	8,337	Ś	7,098	85.14
130	FM-0057274	Orange	Central Justice Center	30-A1		Plumbing - Emergency dry-out and remediation due to black water flood. Black water intrusion from 1st floor drains due to root blockage in lateral line on the County side. 1st floor men's and women's restroom near Facilities Management, Civil restroom, basement corridor walls and ceiling, and adjacent carpeting were impacted. Remediation to P1 FM.	\$	17,714	\$	16,150	91.17
131	FM-0057275	Orange	Central Justice Center	30-A1		Plumbing - Emergency dry-out and remediation. Replace damaged card access mother board and ACM testing. Braided hot water supply hose to sink burst causing water damaged to ceilings and walls in public stairwell from 3rd floor to the basement and card access mother boards damaged to Elevators 10 & 11. Remediation to P1 FM.	\$	26,514	\$	24,173	91.17
						Plumbing - Reupholster 19 courtroom audience seats and backs. A 2" cast iron drain pipe above the ceiling cracked and leaked water onto the seats. Need to be reupholstered to prevent safety and health hazards. Remediation to					
132	FM-0057285	Los Angeles	Norwalk Courthouse	19-AK1	2	P1 FM.	\$	9,472	\$	9,472	100
			Sunnyvale			Ground and Parking Lots - Remove (1) fallen tree during rain storm, it is on the sidewalk and causing a hazard					
133	FM-0057286	Santa Clara	Courthouse	43-F1	2	currently impacting the courts safety protocol and public.	\$	5,373	\$	5,373	100
			Bakersfield Superior				.				
134	FM-0057287	Kern	Court	15-A1		HVAC - Replace failed Fan Supply Motor 15. Fan Supply Motor has burnt out.	\$	2,614	\$	1,637	62.64
125		Santa Barbara	Santa Maria Courts	42-F5		Roof Request - Restore 100sqft of cap sheet and mechanically fasten new base sheet adjacent to drain. West side of roof has evident of dry rot.	ć	2 271	ć	2 252	06.40
132	FM-0057288		Santa Maria Courts	42-۲3		Roof Request - Remove 200 square feet of clay tiles and mechanically fasten new felt underlayment - leak evident	Ş	3,371	Ş	3,253	96.49
136	FM-0057289	Santa Barbara		42-F4		and plywood deck to be replaced where dry rot evident.	Ś	4,270	Ś	4,270	100
100			Bakersfield Juvenile			HVAC - Replace faulty front end controller for the BAS. Front end controller for the Building Automation System	Ť	.,	Ŧ	.,_,0	100
137	FM-0057290	Kern	Center	15-C1		(BAS), controller has failed and no longer provides connectivity with Central Plant.	\$	5,843	\$	3,901	66.76
138	FM-0057291	Orange	Central Justice Center	30-A1	2	HVAC - Replace 40 hp motor for the return fan. Motor has failed and is need of immediate replacement.	\$	8,181	\$	7,459	91.17
			Wiley W. Manuel			Vandalism - Replace 5x8 glass pane broken by projectile to include board-up services while tempered glass is					7
139	FM-0057292	Alameda	Courthouse	01-B3	2	ordered.	\$	4,924	\$	4,126	83.8
140	FM-0057293	San Diego	County Courthouse	37-A1		Plumbing - Cap two leaking mechanical lines and replace two 12x12 ceiling tiles under ACM environment. Leaking hot water lines that serve the VAV for Room 4009 damaged floor, wall and ceiling tiles.	\$	3,501	\$	3,501	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACILITY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
			Can Famanda								
1 4 1	FNA 005 7205		San Fernando	10 4 61		Plumbing - Replace (4) failed non-mercury, wide angle float switches and (1) epoxy coated float anchor with	Ś	4 200	\$	2 5 1 1	02.41
141	FM-0057295	Los Angeles	Courthouse	19-AC1	2	stainless steel chain. Sewage Pump Flow switch is failing, causing back up throughout lock up.	Ş	4,209	Ş	3,511	83.41
1.42	EN4 005720C		Bellflower	10 41 1	2	Elevators, Escalators, & Hoists - Replace (1) drive board. The drive board for Judges elevator #4 has failed and is	ć	2 4 2 2	ć	2 4 2 2	100
142	FM-0057296	Los Angeles	Courthouse	19-AL1	2	currently non-operational. Plumbing - Install new one (1) 4" x 4' pipe, one (1) 4"x 6" coupler T, two (2) 4" couplers, three (3) reducers from 4"	Ş	3,432	Ş	3,432	100
1 4 7	EN4 00E7202	Contro Costo	Family Law Contar	07 414	2	to 3/4", and (1) 3/4" flex line. Remove leaking pipe connection above ceiling - Existing coupler T has split apart thus	\$	c 000	Ś	C 000	100
143	FM-0057302	Contra Costa	Family Law Center	07-A14	2	causing a water leak. COUNTY MANAGED - HVAC - Remove and replace leaking Hot Water (HW) and Chilled Hot Water (CHW) valves in	Ş	6,099	Ş	6,099	100
	514 005 7005			27.42	-	Jury Assembly Lounge. Work is needed properly maintain room temperature and mitigates risk of saturated ceiling	<u>^</u>	2 000	~	2 000	100
144	FM-0057305	San Diego	Hall of Justice	37-A2	2	tiles falling on patrons.	Ş	3,000	\$	3,000	100
			Van Nuys Courthouse			Elevators, Escalators, & Hoists - Shorten ropes on elevators #1 to correct length. Elevator ropes have stretched and					
145	FM-0057306	Los Angeles	West	19-AX2	2	are tripping comp sheaves leading to entrapments.	Ş	4,000	\$	3,219	80.48
			Chatsworth		_	Plumbing - Replace floats and drill holes in discharge pipes for bleeding air. Septic tank floats have failed and could					
146	FM-0057307	Los Angeles	Courthouse	19-AY1	2	cause the sewage water to overflow.	Ş	6,086	Ş	5,100	83.8
						Plumbing - Domestic Backflow - Remove and replace the failed domestic water backflow located near the lower					
			Southwest Justice			level, rear entrance. During annual testing the backflow valve failed and cannot be rebuilt. Replacement needed to					
147	FM-0057308	Riverside	Center	33-M1	2	pass the Water District annual inspection and testing.	\$	5,638	\$	4,307	76.4
						HVAC - Remove & Replace (26) burner tubes, install (2) new burner tubes for pressure switch, install (26)					
						replacement burner gaskets, install (1) new replacement spark ignitor & install (1) new replacement cable					
			Metropolitan			assembly. The existing (26) burners for Boiler #2 are cracked & splitting apart. The gaskets and igniter are					
148	FM-0057310	Los Angeles	Courthouse	19-T1	2	deteriorating & can fail preventing the boiler from turning on.	\$	5,480	\$	5,181	94.54
			Downtown Superior			Interior Finishes - Replace and abate approximately 150 square feet of existing failed ACT floor tile in the basement					
149	FM-0057311	Santa Clara	Court	43-B1	2	men's employee restroom Current condition is a safety issue.	\$	4,815	\$	4,815	100
			Wiley W. Manuel								
150	FM-0057312	Alameda	Courthouse	01-B3	2	HVAC - Heating coil pneumatic control valve - Replace failed three way valve including two 2 inch dielectric unions.	\$	6,526	\$	5,469	83.8
1						Electrical - Replace failed 100A circuit breaker - 3 Phase panel has dropped one leg impacting court electrical					
151	FM-0057314	Napa	Historical Courthouse	28-B1	2	system.	\$	5,164	\$	5,164	100
1			Kearny Mesa Traffic			Exterior Shell - South West public hallway window broke, structural stress caused window to break. Replace 94					
152	FM-0057315	San Diego	Court	37-C1	2	3/4"H x 55 3/4"W x 1/4" thick window and add window tint.	\$	4,098	\$	4,098	100
1						Plumbing - Install new 8" copper piping, (1) 8" CTS copper companion flange, (1) 8" Vic Copper 90, (5) 8" Vic Copper					
			Metropolitan			coupling gaskets, and (1) 8" Bolt Kit. Lay out and cut 8" riser, 10" from the exiting 90 to prevent water from leaking.					
153	FM-0057316	Los Angeles	Courthouse	19-T1	2	Water is leaking from 8" water supply line.	\$	13,395	\$	12,664	94.54
			Metropolitan			HVAC - Replace deteriorated Chiller site glass for Chiller #1. Refrigerant monitoring alarm was activated by Chillers					
154	FM-0057317	Los Angeles	Courthouse	19-T1	2	not coming on line. Chiller site glass has deteriorated & requires replacement to prevent refrigerant leak.	\$	2,211	\$	2,090	94.54
			Central Arraignment			County Managed - Electrical - Replace Automatic Master Clock System. Existing interior Master clock system has					
155	FM-0057319	Los Angeles	Court	19-U1	2	completely failed. Judges & Court rely on a working Clock in order to conduct their day to day operation.	\$	31,581	\$	31,581	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE		FACILITY MODIFICATION	BRAM	FACILITY MODIFICATION PROGRAM SHARE % OF COST
156	FM-0057320	Orange	West Justice Center	30-D1	2	HVAC - Replace two (2) failing cooling tower fan blades and components. While performing the inspection of cooling tower CTW02, multiple cracks were identified on the fan blades.	Ś	16,846	\$	15,276	90.68
130	FIVI-0037320	Orange	West Justice Center	50-D1	2	Elevators, Escalators, & Hoists - Shorten ropes on elevators #1, 2, 3, 8, 9 & 10 to correct length. Elevator ropes have	Ş	10,640	Ş	15,270	90.08
157	FM-0057321	Los Angeles	Compton Courthouse	19-AG1	2	stretched and are tripping comp sheaves leading to entrapments.	\$	49,814	\$	32,942	66.13
107				10 / 101	-	COUNTY MANAGED - HVAC - Correct/replace failed VAV box serving Courtroom 4A - failed VAV causing	Ŷ	10)011	Ŷ	52,512	00110
158	FM-0057324	San Mateo	Hall of Justice	41-A1	2	temperature issues and disrupting Court operations.	\$	2,639	\$	2,639	100
						Electrical - Replace full battery string in the server room Liebert UPS unit. The unit has multiple batteries with acid		· · ·			
159	FM-0057325	Fresno	JJC Delinquency Court	10-P1	2	residue all over the casings which require full string replacement.	\$	6,094	\$	6,094	100
						Grounds and Parking Lot - Demo existing concrete, correct slope, install wheel stops in front of electrical boxes, add					
						heat tape to existing downspout. Judge's parking is sunken/uneven; creating a black ice slip hazard and water					
160	FM-0057326	El Dorado	Johnson Bldg.	09-E1	2	hazard.	\$	14,500	\$	14,500	100
161	FM-0057329	Merced	New Downtown Merced Courthouse	24-A8	2	Electrical - Replace failed building main surge protector on breaker panel - The surge protector has stopped working.	\$	6,349	\$	6,349	100
			Tracy Agriculture			Exterior Shell - Vandalism - Board up approx. 390 sqft of exterior windows and doors to prevent entry on vacant					
162	FM-0057331	San Joaquin	Building	39-E4	2	building. Recent building inspection revealed homeless encampment within structure.	\$	1,266	\$	1,266	100
163	FM-0057332	Stanislaus	Turlock Superior Court	50-D1	2	Grounds and Parking Lot - Restore approx. 17,000 SF of asphalt. Work to include fill and seal cracks. Restripe parking lot and add ADA signage per code. There are extensive cracks in the existing asphalt. Sealing the cracks will prevent moisture penetration that would cause more extensive repairs in the future.	\$	8,793	\$	8,793	100
			Inglewood								
164	FM-0057333	Los Angeles	Courthouse	19-F1	2	Plumbing - Replace failed 6" main fire backflow. Main fire backflow failed annual testing.	\$	10,644	\$	7,936	74.56
						Holding Cells - Replace (1) failed keypad lockset to open the door from the holding area to the courtroom					
165	FM-0057334	Santa Clara	Hall of Justice (East)	43-A1	2	department 24 - creating unsecure access from holding to courtroom.	\$	2,719	\$	2,719	100
166	FM-0057335	Stanislaus	Modesto Main Courthouse	50-A1	2	Exterior Shell - Grind and fill cracks in steps, and landing for front entry steps to main courthouse (380sqft). Seal coat entire area with masonry penetrating water proofer sealer - Water is seeping through masonry steps causing water to puddle in basement janitorial room.	\$	2,363	\$	1,839	77.82
167	FM-0057342	Alameda	County Administration Bldg.	01-A2	2	Electrical - Replace failed court room buzzer to include power supply transformer and wires as existing are plastered into the walls and ceiling and are untraceable.	\$	2,839	\$	2,839	100
			Metropolitan			HVAC - Rebuild failing boiler pump for Boiler #3. The boiler pump on the primary loop is starting to fail and					
168	FM-0057345	Los Angeles	Courthouse	19-T1	2	affecting building heat.	\$	4,393	\$	4,153	94.54
169	FM-0057346	San Diego	East County Regional Center	37-I1	2	Grounds and Parking Lot - Restore approx. 17,000 SF of asphalt. Work to include fill and seal cracks. Restripe parking lot and add ADA signage per code. There are extensive cracks in the existing asphalt. Sealing the cracks will prevent moisture penetration that would cause more extensive repairs in the future.	\$	2,444	\$	2,444	100
170	FM-0057348	Kern	Mojave-Main Court Facility	15-l1	2	COUNTY MANAGED - Plumbing - Remediate and restore ACM affected wall of roughly 150 square feet behind sink in secured clerk's restroom - Leaking sink uncovered ACM, Microbial and Lead findings in secured clerk's restroom.	\$	17,706	\$	17,706	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE		PRELIMINARY ESTIMATE	FACIUTY MODIFICATION	PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						Grounds and Parking Lot - Restore 17 linear ft of curb in front of building. Pour 20 linear ft of concrete (curb) in the					
474				10.01	2	front north planter and extend curb by 3 linear ft at the rear of the building. Flooding occurs when rain water flows	<i>.</i>	6 206	~	5 622	00.70
1/1	FM-0057353	Los Angeles		19-G1		from the sidewalk to the building.	\$	6,206	\$	5,633	90.76
172	FN4 0057055		Beverly Hills Courthouse	19-AQ1	2	Electrical - Replace Breaker/Bucket starter kit for Hot Water Pump # 6. This affects the operation of the boiler hot	Ś	6,888	Ċ.	5,477	79.52
1/2	FM-0057355	Los Angeles	Parking Structure Lot	19-AQ1	Z	water pump.	Ş	0,000	Ş	5,477	79.52
			94 Airport			Elevators, Escalators, & Hoists - Replace 4 static switch leveling units and 10 new (IDEC) relays. Public Elevator #12					
173	FM-0057356	Los Angeles	Courthouse	19-AU2	2	drops below the landing, causing a safety issue.	Ś	2,889	Ś	2,229	77.17
1/5	110 0037330	LOS Angeles	courtilouse	13 402		HVAC - Replace two (2) Heating Valve Actuators. Hot water supply and return valves no longer working and not	Ŷ	2,005	Ŷ	2,225	,,
174	FM-0057357	Los Angeles	Airport Courthouse	19-AU1	2	responding to signals from the BAS.	Ś	4,168	Ś	3,216	77.17
		Loo / ingeleo		10 / 10 1	-	COUNTY MANAGED - HVAC - Replace 12" VAV box at Courtroom 2A Conference Room - Failed VAV causing	Ŷ	1)200	Ŷ	0)210	
175	FM-0057358	San Mateo	Hall of Justice	41-A1	2	temperature issues and disrupting Court operations.	\$	13,000	\$	13,000	100
			Metropolitan			Vandalism - Remediate gang related graffiti around the exterior of building walls & walkways approx. 300sf., (2)		,			
176	FM-0057361	Los Angeles	Courthouse	19-T1		planters, (4) ADA signs and (3) 12"x8" cover plates.	\$	3,796	\$	3,589	94.54
		San Mateo	Hall of Justice	41-A1		Security - Install two (2) new Von Duprin Panic bar assemblies and four (4) custom 6" x 24" push plates - Existing entry door hardware has failed and is not code compliant, critical for safe egress and security. Elevators- Replace defective traveling Cable Hangers in Employee Elevator #6 and Judge's Elevator #7. These	\$	6,101		6,101	100
1/8	FM-0057364	Los Angeles	Airport Courthouse	19-AU1		hangers are needed to relieve the strain on the wires connection under the elevator. HVAC - Remove and replace: (1) failed supply fan wheel, (1) shaft, and (2) bearings; Align sheaves; Replace sensor	Ş	8,402	Ş	8,402	100
179	FM-0057365	Solano	Hall of Justice	48-A1	2	wiring. Supply fan has failed. Unit is operating via the return fan only.	Ś	14,181	\$	14,181	100
175	110 0037303	5010110				Plumbing -Replace (4) 12" x 12" VCT floor tiles to match existing tiles in the break room with ACM abatement. Break	Ŷ	14,101	Ŷ	14,101	100
180	FM-0057366	Los Angeles	Monrovia Warehouse	19-BA1	2	room floor tiles are damaged and missing.	Ś	4,343	Ś	4,343	100
		0				Elevators, Escalators, & Hoists - Replace failed main power supply and two (2) loop selector power supplies for	Ŧ	.,	7	.,	
181	FM-0057367	Los Angeles	Downey Courthouse	19-AM1	2	public elevator #2. Public Elevator #2 with the doors closed, not responding.	\$	3,240	\$	2,712	83.7
			Civic Center			Exterior Shell – Entry Door Restoration - Renovate door threshold to allow 1,200 lbs. door to operate. Building					
182	FM-0057369	San Francisco	Courthouse	38-A1	2	settlement creating a safety issue with doors not being able to be secured properly.	\$	6,933	\$	6,933	100
			South County Justice			Exterior Shell - Renovate two jury assembly doors to public terrace. Current condition and originally design allows					
183	FM-0057370	Tulare	Center	54-I1		unhindered access to the building at all times.	\$	3,061	\$	3,061	100
184	FM-0057374	Los Angeles	Pasadena Courthouse	19-J1	2	HVAC- Replace (1) 6" 3-way pneumatic valve, (1) direct acting pneumatic actuator, (3) 6" bolt, nut, gasket kits, and reinsulate 50 LF of 6" pipe. 3-way pneumatic chilled water valve and actuator are non functional and leaking causing cold calls.	\$	35,186	\$	24,401	69.35
195	FM-0057375	San Bernardino	New San Bernardino Courthouse	36-R1		Exterior Shell - Replace (2) custom made 54"x33"x3/16" stainless steel decorative panels and replace (2) custom made 113" x 33" x 3/16" stainless steel decorative panels. Southside exterior stainless steel wall panel has been hit by vehicle and damaged beyond repair.	Ś	36,183	Ś	36,183	100
		Orange	Central Justice Center		2	Roof - Patch approximately 288sq feet of 3rd floor West wing penthouse roof and one pipe penetration. Recent rains revealed a water intrusion, leaking into the secured hallway and C61 courtroom.	\$ \$	3,617		3,617	100



#	FM NUMBER	LOCATION	FACILITY NAME	BUILDING ID	PRIORITY	SHORT TITLE	PRELIMINARY ESTIMATE		FACILITY MODIFICATION PROGRAM SHARE OF PRELIMINARY ESTIMATE	FACILITY MODIFICATION PROGRAM SHARE % OF COST
						HVAC - Rebuild leaking condenser pump, replace (1) mechanical seal assembly, (1) shaft seal, (1) casing gasket, (1)				
187	FM-0057380	Los Angeles	Santa Monica Courthouse	19-AP1	2	suction housing gasket. Condenser water pump #5 has a damaged seal and the pump is currently leaking water during operation.	\$ 3,96	5\$	3,113	78.49
107	1101 0037 300	LOS Aligeres	courtilouse	15 AT		Interior Finishes - ACM abatement - Replace 60 sf of missing and failed ACM VCT and associated mastic. Current tile	Ş 3,50		5,115	70.45
188	FM-0057381	Lake	South Civic Center	17-B1		condition pose a health hazard.	\$ 4,47	3\$	4,478	100
						HVAC - Air Handler#1 & #2 - Remove and replace the failing bearings and shaft of the air handler #2 supply fan and				
100	FNA 0057202	Diverside	Southwest Justice	22.144		failing non-driven return fan bearing of air handler #1. The bearing is currently making considerable noise and a	ć 10.22		12 401	76.4
189	FM-0057383	Riverside	Center	33-M1		complete failure will result in airflow disruptions within the supported areas. Roof - Replace approximately 1000 sq. ft. of existing roof membrane and fire rated board with new .060 TPO	\$ 16,23	2\$	12,401	76.4
			Kearny Mesa - Traffic			membrane and reinstall existing drain ring. Modular trailer roof has numerous leaks, is bubbling and is				
190	FM-0057385	San Diego	Court KM3 Trailer	37-C2	2	deteriorated. Numerous repairs have been made and leaks continue to happen.	\$ 6,77) \$	6,770	100
191	FM-0057386	Orange	North Justice Center San Fernando	30-C1	2	Elevators, Escalators, & Hoists - Replace elevator pit feed line at the shut-off valve and the isolation couplings in the elevator equipment room. Hydraulic fluid is leaking from both locations. Failure to conduct the work shall result in loss of pressure in the hydraulic system creating a safety issue to the public. HVAC - Replace motor to condenser pump #3. Condenser motor #3 was not functioning properly which could cause	\$ 13,72	7 \$	12,397	90.31
192	FM-0057387	Los Angeles	Courthouse	19-AC1		the pump to fail.	\$ 3,25	4 \$	2,714	83.41
193	FM-0057388	Los Angeles	Van Nuys Courthouse West	19-AX2	2	Elevators, Escalators, & Hoists - Replace electronic door sensor. Electronic door sensor is not working properly on Elevator #7, causing the doors to not close or close erratically.	\$ 6,49	3\$	5,230	80.48
194	FM-0044819	Los Angeles	Van Nuys Courthouse East	19-AX1		Elevators, escalators, and hoists - Rebuild Unitec Selector in Elevator #4. Public elevator #4's selector is malfunctioning causing the car to not level properly potentially resulting in entrapments to passengers.	\$ 74,10	5 Ś	66,503	89.74
		0	Van Nuys Courthouse			Elevators, escalators, & hoists - Replace 2400 LF of 5/8" elevator rope, rope shackles, and car door safety edge.	, , ,			
195	FM-0057299	Los Angeles	West	19-AX2	2	Elevator #3 was damaged by water during a previous flood on the 3rd floor.	\$ 90,84	2\$	73,110	80.48
196	FM-0004079	Contra Costa	Bray Courts	07-A3		Roof - Replace 20,615 SF of built up roofing system with a new single ply roofing system; Replace 600 LF walkway pads; Move plumbing and HVAC equipment to allow installation of the roof. Existing roof is 29 years old and has had a number of leaks, mostly around the mechanical equipment that is spread around the roof.	\$ 648,08	2 \$	554,240	85.52
197	FM-0057262	Los Angeles	Metropolitan Courthouse	19-T1	2	DESIGN - HVAC - Phase 1. Replace two (2) 300 ton centrifugal chillers. Cooling medium is provided by two 300 ton York centrifugal chillers. The chillers are original equipment, but were retrofitted 10 years ago with R123 from R11.	\$ 225,00	D \$	212,715	94.54
198	FM-0039887	Del Norte	Del Norte County Superior Court	08-A1	2	DESIGN - Roof- Phase 1. Replace approx. 30,000 sq. ft. of metal roofing and 2400 sq. ft. of modified bitumen roofing that is starting to fail, local conditions resulting in heavy winds and rain has caused failures on metal roof attachment points and valleys.	\$ 74,064	4 \$	45,379	61.27
199	FM-0057336	Los Angeles	Downey Courthouse	19-AM1		DESIGN - Phase 1 - Exterior Shell - Renovate failing wall area leading into the sally port per the recommendations within the engineering study. Work to include excavation and bracing of wall areas, removal of trees contributing to wall system failure, replacement of failed drainage system.	\$ 155,000 \$ 6,822,61		129,735 5,766,285	83.7



CFR NUMBER	COUNTY	BUILDING ID	FACILITY NAME	LEASE, LICENSE, OR FM	CFR DESCRIPTION	CFR TERM	FUND SOURCE	ESTIMATED CURRENT YEAR COSTS	(Includes existing costs prior to CFR term)	ESTIMATED BUDGET YEAR COSTS		TOTAL ESTIMATED CFR COMMITMENT (CFR Term)	REVIEW NOTES - OREFM, JBCPO, & FSO
					Convert existing Rule 10.810 MOU into Rule 10.810/Small Project IBA to allow for								
7-CFR023	San Diego	37-A2	Hall of Justice	Annual Budget	small CFR FMs (less than \$15,000 each) throughout the fiscal year.	One-Time	TCTF	\$	15,000	\$ 15,00	0 \$	15,000	Pending
		42-F4		Facility Modification	needs of the jury operations. Removal of the wall and fixed theatre seating (and replacement with accordion wall and stackable seating) could turn the two rooms into one multi-purpose room better serving the public called to jury duty in Santa Maria as well as creating a flexible meeting and training facility on the court campus.	One-Time	Non-TCTF	\$	128,653	\$ 128,65	3 \$	128,653	Pending
4-CFR006	Sacramento	TBD	Hall of Justice		6/30/16. The new location will house Civil Settlement Conference, Civil Law & Motion, and Legal Research. The new location has a better lease rate per SF, recently upgraded mechanical systems, and provides the court with a little more	Five Years	TCTF	\$	-00	\$ 30,8	83 \$	405,294	Pending
						_, ,,							
5-CFR033	Bernardino	36-S2	Lot	Lease	provide 196 "no-tee" parking spaces for public and jury parking. (2/1/16 - 1/31/21)	Five Years	Non-TCTF	Ş	37,500	Ş 90,0	00 Ş	450,000	Pending
7-CFR022	San Diego	37-11	,	Lease	lease renewal with MDA El Cajon One, LLC would allow court users and jurors to	Five Years	TCTF	\$	84,7 <u>84</u>	\$ 87,1	58 \$	456,625	Pending
			Probate	Lease	Lease extension from 5/1/16 - 7/31/16 to support Probate Investigating Unit. This is	Three							
3-CFR009	Santa Clara	43-B3	Investigators	Extension	the last extension option.	Months	TCTF						Pending
		42.5.					TOTE	~		<u>~</u>			
3-CFR010	Santa Clara	43-B4				Months	ICTF	Ş	-00	Ş -	UO \$	66,435	Pending
)-CFR024	Orange	30-C1				One Year	TCTF	Ś	-	\$ 47.33	4 \$	47.334	Pending
2 3 3	7-CFR023 2-CFR010 4-CFR006 5-CFR033 7-CFR022 3-CFR009 3-CFR010	7-CFR023 San Diego Santa 2-CFR010 Barbara 4-CFR006 Sacramento 5-CFR033 Bernardino 7-CFR022 San Diego 3-CFR009 Santa Clara	7-CFR023 San Diego 37-A2 2-CFR010 Santa 42-F4 4-CFR006 Sacramento TBD 5-CFR033 Bernardino 36-S2 7-CFR022 San Diego 37-I1 3-CFR009 Santa Clara 43-B3 3-CFR010 Santa Clara 43-B4	NN HHHHH7-CFR023San Diego37-A2Hall of Justice2-CFR023Santa Barbara42-F4Santa Maria Courts, Bldg F4-CFR006SacramentoTBDHall of Justice3-CFR033Bernardino36-S2Lot7-CFR022San Diego37-11East County Regional Center7-CFR022San Diego37-11East County Regional Center8-CFR009Santa Clara43-B3Investigators8-CFR010Santa Clara43-B4AdministrationNorth JusticeNorth JusticeNorth Justice	O O B L J 7-CFR023 San Diego 37-A2 Hall of Justice Annual Budget 2-CFR010 Barbara 42-F4 Santa Maria Courts, Bldg F Facility Modification 4-CFR006 Sacramento TBD Hall of Justice New Lease 5-CFR033 Bernardino 36-S2 Temporary Parking Lot Lease 7-CFR022 San Diego 37-I1 Regional Center Extension 8-CFR009 Santa Clara 43-B3 Investigators Extension 8-CFR010 Santa Clara 43-B4 Administration Extension	O D <thd< th=""> <thd< th=""> <thd< th=""></thd<></thd<></thd<>	O D B L D Convert existing Rule 10.810 MOU into Rule 10.810/Small Project IBA to allow for small CFR FMs (less than \$15,000 each) throughout the fiscal year. One-Time 7-CFR023 San Diego 37-A2 Hall of Justice Annual Budget Small CFR FMs (less than \$15,000 each) throughout the fiscal year. One-Time Santa Santa Santa Maria Facility The wall separating the two existing jury assembly rooms severely limits the current needs of the jury operations. Removal of the wall and fixed theatre seating (and replacement with accordion wall not stackable seating) could turn the two rooms into one multi-purpose room better serving the public called to jury duty in Santa One-Time 2-CFR010 Barbara 42-F4 Courts, Bldg F Modification Maria as well as creating alfexible meeting and training facility on the court campus. One-Time New full-service lease to replace existing space at 800 9th Street, which expires 6/30/16. The new location will house Civil Settlement Conference, Civil Law & Motion, and Legal Research. The new location has a better lease rate per SF, recently upgraded mechanical systems, and provides the court with a little more square footage to address some of the existing space deficiencies. (7/116 - Five Years) 3-CFR033 Bernardino 36-S2 Temporary Parking Lease Lease parking lot near Historic Courthouse and San Bernardino Justice Center to provide 196 "no-fee" parking spaces for public and jury parking. (2/1/16 - 1/31/21) Five Year	O O B L O L 2-CFR023 San Diego 37-A2 Hall of Justice Annual Budget small CFR FMs (less than \$15,000 each) throughout the fiscal year. One-Time TCTF 2-CFR023 San Ta Santa Santa Santa Maria Facility The wall separating the two existing jury assembly rooms severely limits the current needs of the jury operations. Removal of the wall and fixed theatre seating (and replacement with accordion wall and stackable seating) could turn the two rooms into one multi-purpose room better serving the public called to jury duty in Santa 2-CFR010 Barbara 42-F4 Courts, Bidg F Modification New full-service lease to replace existing space at 800 9th Street, which expires 6/30/16. The new location will house Civil Settlement Conference, Civil Law & Motion, and Legal Research. The new location has a better lease rate per SF, recently upgraded mechanical systems, and provides the court with a little more square footage to address some of the existing space deficiencies. (7/1/16 - 1/31/21) Five Years TCTF 5-CFR033 Bernardino 36-S2 Lot Lease provide 196 "no-fee" parking spaces for public and jury parking. (2/1/16 - 1/31/21) Five Years TCTF 5-CFR033 Bernardino 36-S2 Lot Lease provide 196 "no-fee" parking spaces for public	No. No. <td>Big Less Do State State</td> <td>Note Note <th< td=""><td>Name Non-UCT S 128,000 S 15,000 S</td><td>set solution set solution <th< td=""></th<></td></th<></td>	Big Less Do State State	Note Note <th< td=""><td>Name Non-UCT S 128,000 S 15,000 S</td><td>set solution set solution <th< td=""></th<></td></th<>	Name Non-UCT S 128,000 S 15,000 S	set solution set solution <th< td=""></th<>